

Corrosion in a Hydrocarbon
Conversion System
An Industrial Experience of Attacky
On Metals by Synthesis Gass
From Methane-Oxygen Combustion 16
High Temperature Deterioration in
Atmospheres Containing
Carbon Monoxide and Hydrogen 21
Corrosion of Metals at
Mandapam Camp, India 25
Case Histories of Ratings vs Corrosives
of Polyester Fiber Glass Equipment 29

### INDEX TO VOLUME 15

Tables of Contents Technical and Technical Topics Sections; Alphabetical Subject and Author Indexes; Subject Index, Vol. 15 Corrosion Abstracts Section; Errata, Vol. 15

Portland, Tulsa, Central Oklahoma Section Short Courses Set 69, 7
Characteristic Properties of Polyurethane Protective Coatings 9
Corrosion Control Practices in the Wilmington Water Flood Operation 99
Cathodic Protection of Southern Pacific's High-Pressure Products Pipe Line 104
D

Also: Discussions; Epoxy Resins Resist Gamma Radiation; New Products, Men in the News, Corrosion Abstracts

Complete Contents on Pages 2 and 3



from the makers of Dimetcote...

# ZINKOFF

THE FIRST 100% INORGANIC SELF-CURING ZINC COATING.









- A radically new concept in zinc coatings for protecting steel.
- Under development for many years and first patented in 1957.
- ✓ Applied in one coat completely self-curing.
- Can be used wherever galvanizing is satisfactory actually gives superior protection.
- Completely nonflammable, nontoxic.
- Insoluble in all petroleum products.
- Outstanding resistance to weathering, salt and fresh water.
- Applied by brush, spray or roller.
- ✓ Cathodically protects steel.
- Resists temperatures up to 600°F.
- ✓ Complete protection for as little as 5¢ per square foot material cost.


For complete information write . . .

How does Zinkote compare with Dimetcote? Although similar, each has certain unique advantages depending upon the particular requirements of the job. We will be glad to give you a specific recommendation.



Dept. GL • 4809 Firestone Boulevard • South Gate, California 921 Pitner Ave. 360 Carnegie Ave. 2404 Dennis St. 6530 Supply Row Evanston, III. Kenilworth, N.J. Jacksonville, Fla. Houston, Texas

The Pioneer Manufacturer of Inorganic Zinc Coatings



# CORBAN

new "squeeze" technique gives extended well protection The new "squeeze" method of applying Corban®—Dowell's polar-type corrosion inhibitors—is setting new records for long-time corrosion protection in oil and gas wells.

The "squeeze" method involves pumping liquid Corban back into the producing formation. The Corban is then gradually produced back with your normal production over an extended period of time. As it is produced, Corban plates out in a protective film on the metal equipment contacted by the well fluids.

The "squeeze" with Corban has given long-term protection—six months and more—to many problem wells, particularly those with high pressure.

Ask your nearest Dowell station or office for case histories of wells squeezed with Corban, and for a recommendation engineered for your wells. Corban is now readily available from any of the 165 Dowell offices. Dowell serves the oil industry in the United States, Canada, Venezuela and Argentina. Dowell, Tulsa 1, Oklahoma.

Products for the oil industry OOWELL

DIVISION OF THE DOW CHEMICAL COMPANY

Page

Pitt

Frie

Rut S Wes

T

E

C

Ind

Ind



Published monthly as its official journal, by the National Association of Corrosion Engineers, Inc., at Houston, Texas, U.S.A., as a permanent record of progress in corrosion control. Second class postage paid at Houston, Texas.

Vol. 15

December, 1959

No. 12

### EDITORIAL STAFF

IVY M. PARKER—Editor JAMES T. LONGINO Technical Editor DALE MILLER Editorial Assistant

### **EDITORIAL REVIEW COMMITTEE**

FRED M. REINHART, Chairman, National Bureau of Standards, Washington 25, D.C.

Mark F. Adams	T. L. Hoffman
A. L. Alexander	Harry J. Keeling
Joseph Bigos	Frank E. Kulman
W. W. Binger	Hugh L. Logan
W. B. Brooks	Thomas A. Lowe
W. E. Bunting	Dwight G. Moore
I. C. Dietze	Charles C. Nathan
A. C. Elm	J. W. Nee
Otto H. Fenner	V. B. Pike
N. D. Greene	A. H. Roebuck
John J. Halbig	D. H. Thompson
B. C. Haworth	L. E. Trishman
	R. M. Wainwright

#### CORRESPONDENTS

H. Howard Bennett—Petroleum Refining
K. G. Compton—Telephone, Telegraph and Radio
S. W. Shepard—Non-Metals
Leonard C. Rowe—Transportation Industry
V. V. Kendall—Fresh and Salt Water
T. F. Degnan—Chemical Industry
Gordon B. Smith—Non-Ferrous Metals
Norman D. Groves—Pulp, Paper, Mining and Food
V. M. Kalhauge—Petroleum Production and
Pipe Lines
C. P Larrabee—Ferrous Metals

### BUSINESS STAFF

Herbert W. Dieck-Power Thomas J. Summerson-Light Metals

NORMAN E. HAMNER Managing Editor and Advertising Manager T. J. HULL (Executive Secretary NACE) Business Manager

Address all communications to:

### 1061 M & M BUILDING

Houston 2, Texas

SUBSCRIPTION	RATES	(Post	Paid)
Non-Members of NAC	E, 12 issue	s	.\$11.00
Non-Members of NAC Single copies, 1957			. 2.00
NACE Members, Sing			
1957 to date	********		. 1.00
All Issues 1945-56 Inc	lusive, Per	Copy	. 2.00
Libraries of Education and Public Librarie States and Canada,	s in the Un 12 issues.	ited	
NACE Members Recei of Their Membership			
Foreign remittances postal or express me negotiable in the U. S in U. S. funds. Enter October 31, 1946, at a Texas, under the act	oney order f, for an eq red as seco the Post Of	or ban uivalent nd class fice at H	k draft amount matter
CORROSION Is In neering Index and A nology Index.			

### CONTENTS

### **TECHNICAL SECTION**

Corrosion in a Hydrocarbon Conversion System	-9-
By F. A. Prange	13
Discussion: William B. Segraves, page 15; Reply by F. A. Prange, page 15	
An Industrial Experience of Attack on Metals by Synthesis Gas	
from Methane-Oxygen Combustion	
By F. Eberle and R. D. Wylie	16
Discussion: Andrew Dravnieks, page 20; Reply by F. Eberle, page 20	
High Temperature Metal Deterioration in Atmospheres Containing	
Carbon-Monoxide and Hydrogen	
By W. B. Hoyt and R. H. Caughey	21
Corrosion of Metals at Mandapam Camp, India	
By K. S. Rajagopalan, M. Sundaram and P. L. Annamalai	25
Case Histories and Ratings vs Corrosives of Polyester Fiber	
Glass Equipment	
By Robert E. Barnett and Thomas F. Anderson	29

### DISCUSSIONS

Observations on the Mechanisms and Kinetics of Aqueous Aluminum Corrosion. Part 1—Role of the Corrosion Product Film in Uniform Aqueous Corrosion of Aluminum. Part 2—Kinetics of Aqueous Aluminum Corrosion: P. M. Aziz and Hugh P. Godard, Page 36, Reply by R. L. Dillon, Page 36.

Oil Refinery Applications of Thick-Film Synthetic Coatings: Charles M. Stanbury, Emile E. Habib, Austin K. Long, DuWayne Christofferson, Page 36; Reply by R. W. Maier, Pages 36 and 37.

Impedance Characteristics of Isolated Aluminum Oxide Films: F. E. DeBoer, Page 37; Reply by D. F. MacLennan, Page 37.

Behavior of AZ 63 Alloy and Magnesium—1 Percent Manganese Alloy Anodes in Sodium Chloride Electrolyte: J. L. Robinson, Page 37; Reply by J. H. Greenblatt, Page 37.

Performance of Organic Coatings in Tropical Environments: Seymour J. Fiebach, Page 37; Reply by A. L. Alexander, Page 37.

Corrosion Resistance of Titanium and Zirconium in Chemical Plant Exposures: E. G. Brink, Wayne H. Keller, Page 37; Milton Stern and Claude R. Bishop, Page 38; Reply by P. J. Gegner, Pages 37 and 38.

Corrosion of Types 316 and 317 Stainless Steel by 75 Percent and 85 Percent Phosphoric Acid: C. M. Schillmoller, Page 38; Reply by A. R. Morgan, Page 38.

Cathodic Protection of Lead Cable Sheath: R. B. Mears, L. C. Eddy, Vernon B. Pike, Frank E. Kulman, J. J. Pokorny, Pages 38 and 39; Replies by W. H. Bruckner, Pages 38, 39 and 40.

Duct Anode Development and Experience in Protection of Underground Cables from Corrosion: David T. Jones, Page 40.

Stress Corrosion Cracking of Oil Country Tubular Goods: H. Lee Craig, Jr., Joe Chittum, Page 40; Reply by R. L. McGlasson, Page 40.

Copyright 1959 by the National Association of Corrosion Engineers. Reproduction of the contents, either as a whole or in part, is forbidden unless specific permission has been obtained from the Publishers of CORROSION. Articles presented represent the opinions of their authors, and not necessarily those of the Editors of CORROSION, nor the Officers or Members of the National Association of Corrosion Engineers. Manuscripts to be considered for publication should be forwarded, together with illustrations, to the Editor of CORROSION, 1061 M & M Building, Houston 2, Texas.

ol. 15

Page

. 13

. 16

. 21

. 25

. 29

Cor-

eous

sion: e 36.

M.

Page

Boer,

An-

r J.

kpo-

e R.

cent

gan,

non

W.

und

Jr.,

### CONTENTS

### INDEX TO VOLUME 15 (Facing Page 40)

Table of Contents to Technical and Technical Topics Sections
Alphabetical Subject Index

Alphabetical Author Index
Subject Index, Corrosion Abstracts Section

Title Page, Volume 15 Errata-Volume 15

### **NACE NEWS**

Page	Page
Pittsburgh Section Plaque	Technical Meetings Are Well Attended at October Conference in Cleveland
Friend Appointed NACE Representative for ASA69	Chicago Section
Rutter Heads Committee to Plan Short Course69	Eastern Wisconsin Section
Western Region News Portland Section Plans April 27-29 Short Course	Northeast Region News Philadelphia Section
San Francisco Bay Area Séction69 Portland Section69	Two Chairmen Named to Head Work on Plastic Coated Pipe74
South Central Region News	Photos of Denver Conserence74
Tulsa Section Sponsors 11th Annual Short Course71	Several Denver Meetings Had "Standing Room Only"75
Central Oklahoma Section Plans 1960 Short Course71	About 600 Attend Busy Sessions at Regional Meeting
Alamo Section	Board of Directors
Tulsa Section	Technical Tours Held
East Texas Section	Annual Fellowship Hour
Houston Section71	Controlled by Electrical Method76
Shreveport Section71	Section Calendar
LaQue to Address Joint NACE- ASTM Meeting Feb. 971	15 Symposia Co-Chairmen Listed for 1960 Dallas Conference
North Texas Section71 Corpus Christi Section71	6 NACE Members Teach at California Short Course
Canadian Region News Edmonton Section	Southeast Region News Atlanta Section
Conference Dates71	East Tennessee Section78
North Central Region News Photos of Cleveland Conference72	National and Regional Meetings and Short Courses79
Index to Corrosion Abstracts	
TECHNICA	I TOPICS
I ECITIVICA	L TOPICS
Characteristic Properties of Polyure By E. R. Wells	
Corrosion Control Practices in the Operation	Wilmington Water Flood99
Cathodic Protection of Southern P Products Pipe Line—Whole Syste	acific's High-Pressure
Discussions	106

### Technical Topics Scheduled for January

Precision Parts Are Cast from Epoxy Resin Systems, by Elliott N. Dorman and William Ibsen

Engineering Approach to a Chemical Plant Coating Program: Part I—Records That Help Keep Track of Costs and Prove Results; Part 2—Training Men to Make the Program Work, by Newell D. Casdorph

Rust Preventive Properties of Nonylphenoxyacetic Acid in Some Petroleum Products, by Robert M. Pines and John D. Spivack

Spivack

Corrosion Considerations in Selection of Rocket Engine Materials, by R. A. Geiger, Fred T. Schuler and Robert E. Mowers

### **GENERAL NEWS**

Epoxy Resin Coatings Resist Intense	rage
Gamma Radiation	.81
Belgian Corrosion Study	.81
Book News	.81
Porcelain Electrode Developed for Salt Study	.82
Electric Cars May Use Nickel- Cadmium Batteries	.82
Rapid Aluminum Welding	.82
Plastic Engineers' Society to Meet January 12-15	.83
Maintenance Conference	.83
Metal Deformation	.83
New Flux for Aluminum	.83
Catalogs List Research	.83
New Products	.84
Men in the News	.90

### REARRANGEMENT OF INSIDE PAGES

Beginning with the January 1960 issue, the inside contents of CORROSION will be rearranged from their present to the following sequence, front to back: Contents Pages, Technical Topics, Technical Committee Activities, NACE News, General News, Corrosion Abstracts, Directories of Technical Committees, Corporate Members and Regions and Sections (on rotating basis) and Technical Section.



save on steel! save on acid! save on pickling costs!

### ... with Amchem Rodine!

Exhaustive comparison tests with competitive materials prove time and again Amchem Rodine's superiority in performance, with substantial savings in costs, acid and steel in the bargain.


Amchem Rodine pickling acid inhibitors retard the attack of acid on the metal without lessening its capacity to remove scale. Not only do they save in metal and acid, but they reduce production costs and their efficiency

improves the quality of the pickled product as well.

If you are now using an inhibitor in your pickling bath, you'll want to investigate the three way savings highly concentrated Amchem Rodine can effect. Find out now about this superior Amchem inhibitor development, ask about our full time technical and engineering assistance program, and check Amchem for service you can depend on long after the sale!

Write for free Bulletin 1381 with handy selection chart showing characteristics of and uses for typical Rodine Pickling Acid Inhibitors and Bulletin 1448 on Amchem Cuprodine, the simple non-electrolytic immersion process for producing bright, adherent copper coatings on carbon and stainless steels.





Effect of Uninhibited Acid

This microphotograph of a low-carbon sheet steel panel pickled in uninhibited sulfuric acid shows deep etching and the pitted character of the surface after 5 minutes in the solution.



Effect of RODINE-INHIBITED Acid

Panel pickled for 5 minutes in Rodineinhibited sulfuric acid, then microphotographed. Only scale pockets and roll marks are visible; no pitting of the low-carbon sheet steel occurred!



Amchem Rodine is another chemical development of Amchem Products, Inc., Ambler 32, Pa. • Formerly American Chemical Paint Company Detroit, Mich. • St. Joseph, Mo. • Niles, Calif. • Windsor, Ont. / Amchem, Rodine and Cuprodine are registered trademarks of Amchem Products, Inc.

th, hly ow nt, ing

any

Inc



DON'T YOU THINK

IT WOULD BE
MUCH MORE
PRACTICAL
IF WE SENT FOR

BRIDGEPORT'S

FREE NEW BOOK—
'SOLVING CORROSION
PROBLEMS IN INDUSTRY'!"

solving corrosion problems

If you convey anything through condensers or heat exchangers, this 20-page Bridgeport book is must reading. It tells how to lick problems involving two corrosive media...by using bi-metal Duplex Tubes ... each metal surface designed to resist corrosion from the media to which it is exposed.

Each industry has its own corrosion problems, and this fact-packed book illustrates ways to solve many of them. For your personal copy, just write, on your company letterhead, to the Bridgeport Brass Company, Bridgeport 2, Connecticut. Please address Dept. 5806.



BRIDGEPORT BRASS COMPANY

Bridgeport 2, Connecticut • Sales Offices in Principal Cities Specialists in Metals from Aluminum to Zirconium

### Directory of NACE Regional and Sectional Officers

### CANADIAN REGION

T. R. B. Watson, Director; Corrosion Service Ltd., 17 Dundonald St., Toronto 5, Ontario, Canada Harrison G. Burbidge, Chairman: Aluminum Co. of Canada, 1700 Sun Life Bldg., Montreal, Quebec, Canada

Canada
John R. Grey, Vice Chairman; Gas
Distribution Dept., B. C. Electric
Co., 3725 Lougheed Highway,
Burnaby 2, B. C., Canada
Havelock H. Yates, Secretary-Treasurer; Physical Science Centre, McGill University, Montreal 2, Quebec, Canada

#### Calgary Section

. G. Mainland, Chairman; Imperial Oil Limited, 300-9th Avenue West, Calgary, Alberta, Canada

Calgary, Alberta, Canada

W. Abercrombie, Vice Chairman;
Aluminum Co. of Canada Ltd.,
No. 8, 308-8th Avenue West, Calgary, Alberta, Canada

N. Gell, Secretary-Treasurer;
Canadian Western Natural Gas Co.,
Ltd., 140-6th Avenue West, Calgary, Alberta, Canada

S. M. Lytch, Trucka Reitaneil

S. McIntosh, Trustee; Britamoil Pipe Line Co., P. O. Box 130, Calgary, Alberta, Canada

### • Edmonton Section

D. J. McQuarrie, Chairman; Imperial Pipe Line Company, Ltd., 11140 -109th St., Edmonton, Alberta, Can-

ada L. Gattenmeyer, Vice Chairman; Canadian Protective Coating Ltd., 9420 - 91st St., Edmonton, Alberta, Canada

Canada O. A. Hindley, Secretary-Treasurer; Rice Engineering & Operating Ltd., 10509 - 81st Ave., Edmonton, Al-berta, Canada

### · Hamilton-Niagara Section

. W. Hyslop, Chairman; United Gas & Fuel Co., of Hamilton, Ltd., 82 King St. E., Hamilton, Ontario.

### · Montreal Section

H. N. Hewitt, Chairman and Vice Chairman; Canadian Petrofina Ltd., P. O. Box 70, Hochelaga Station, Montreal, Quebec

. A. Mueller, Secretary-Treasurer; Research Chemist, Pulp and Paper Research Institute of Canada, 3420 University St., Montreal, Quebec

### Toronto Section

F. Farrer, Chairman; Trans-Northern Pipe Line Co., 696 Yonge St., Toronto, Ontario, Canada K. G. Dellenbach, Vice Chairman; Sarnia Products Pipe Line, Waterdown, Ontario, Canada J. Balmer, Secretary; Consumers' Gas Co., 36 Mutual St., Toronto, Ontario, Canada

D. J. Cowan, Treasurer; Corrosion Service Ltd., 17 Dundonald St., Toronto, Ontario, Canada

### Vancouver Section

. H. Townsend, Chairman; P. O. Box 63, North Vancouver, B. C., Canada

John S. Whitton, Vice Chairman; Swanson Wright & Co., Engrs., 2210 West 12th Ave., Vancouver 8, B. C., Canada

Wilfred J. Perry, Secretary; Insul-Mastic & Building Products Ltd., 586 West 6th Ave., Vancouver 9, B. C., Canada

Dave M. Allan, Treasurer; Trans Mountain Oil Pipe Line Company, 400 East Broadway, Vancouver 10, B. C., Canada

B. H. Levelton, Trustee; B. C. Re-search Council, University of B. C., Vancouver 8, B. C., Canada



### NORTH CENTRAL REGION

E. F. Moorman, Director; Interna-tional Harvester Company, Engi-neering Materials Research 7 South 600 County Line Road, Hinsdale,

600 County Line Road, Hinsdale, Illinois
C. Weast, Chairman: Case Institute of Technology, 10900 Euclid Avenue, Cleveland 6, Ohio
M. McConnell, Vice Chairman; Geo. J. Meyer Manufacturing Company, Meyer Pl. & Dunmore Court, Cudahy, Wis.
W. Ambler, Secretary-Treasurer; American Zinc, Lead & Smelting Company, P. O. Box 495, East St. Louis, Ill.

### Chicago Section

• Chicago Section

Ivan J. Acosta, Chairman; Crane
Company, 4100 S. Kedzie Avenue,
Chicago 32, Ill.

Daniel G. Keefe. Vice-Chairman;
Swift & Co., Res. Lab., Union
Stock Yards, Chicago 9, Ill.

Wayne H. Schultz, Secretary; Dearborn Chemical Company, 375
Merchandise Mart Plaza, Chicago
54, Ill.

David B. Sheldahl, Treasurer; Sinclair Research Laboratories, Inc.,
400 E. Sibley Blvd., Harvey, Ill.
Harold C. Boone, Trustee; Peoples
Gas Light & Coke Co., 122 S.
Michigan Avenue, Room 1732, Chicago 3, Ill. Gas Light Michigan A cago 3, Ill.

### • Cleveland Section

John Scott, Chairman; Truscon Lab-oratories, 1372 Primrose Drive, Mentor, Ohio Peter P. Skule, Vice Chairman; East Ohio Gas Co., 1717 East Ninth St., Cleveland 14, Ohio

V. H. Hooker, Secretary-Treasurer; Harco Corporation, 4600 East 71 St., Cleveland 25, Ohio . F. Bosich, Trustee; Diamond Al-kali Co., P. O. Box 430, Paines-ville, Ohio

### Detroit Section

Lewis Gleekman, Chairman: Wyan-dotte Chemicals Corp., 1609 Biddle Ave., Wyandotte, Mich.

Euel Vines, Vice Chairman; Koppers Co., Inc., Tar Prod. Div., 301 West Eight Mile Road, Detroit 3, Mich. Carl Durbin, Treasurer; Chrysle Corp., Central Engrg., P. O. Bo 1118, Detroit 31, Mich.

Leonard C. Rowe, Secretary; Re-search Lab., General Motors Corp., P. O. Box 188, North End Station, Warren, Mich.

David Hill, Trustee; Timken Detroit Axel Co., 100-400 Clark Ave., De-troit, Mich.

#### · Eastern Wisconsin Section

Dave Walczyk, Chairman; A. O. Smith Corp., Dept. 9753, P. O. Box 584, Milwaukee 1, Wis.

584, Milwaukee 1, Wis.
Thomas Quick, Vice Chairman; 806
Third St., West De Pere, Wis.
Harold F. Haase, Secretary-Treasurer;
Consultant, 2202 South 28th St.,
Milwaukee 15, Wis.
David Walczak, Trustee; A. O. Smith
Corp., Dept. 9733, P. O. Box 584,
Milwaukee 1, Wisconsin

#### · Greater St. Louis Section

Greater St. Louis Section
 Oliver W. Siebert, Chairman; Monsanto Chemical Company, W. G. Krummrich Plant, Monsanto, Ill.
 Walter B, Meyer, Vice Chairman; St. Louis Metallizing Company, 625
 South Sarah Street, St. Louis 10, Mo.

E. Gent Johannes, Secretary; Mineral Products Co., 1834 Gravois St., St. Louis 4, Mo.
David E. Morris, Treasurer; Mallinckrodt Chemical Works, Uranium Division, P. O. Box 472, St. Charles, Mo.

A. Orman Fisher, Trustee; Engineer-ing Dept., Monsanto Chemical Co., 800 North Lindbergh, St. Louis 24, Missouri

### Kansas City Section

Jack L. Grady, Chairman; J. L. Grady Co., 427-20 West 9th St. Building, Kansas City, Mo.
Daniel R. Werner, Vice Chairman; American Tel. & Tel. Co., 811 Main St., Room 850, Kansas City 5, Missouri

Hobart Shields, Secretary-Treasurer; Standard Oil Co. (Ind.), Sugar

lobart Shields, Secretary-Freasurer, Standard Oil Co. (Ind.), Sugar Creek, Mo. ack L. Grady, Trustee; J. L. Grady Company, 20 W. 9th St. Bldg., Room 427, Kansas City 5, Missouri

### Southwestern Ohio Section

R. L. Wood, Chairman; 8670 Mon-santo Drive, Cincinnati, Ohio W. M. Spurgeon, Vice Chairman; 2034 Dallas Ave., Cincinnati 39,

2034 Dallas Ave., Cincinnati 39, Ohio A. D. Caster, Treasurer; 2864 Mc-Farland Park Dr., Cincinnati 11, Ohio S. C. Jones, Secretary, Cincinnati Gas & Electric Co., 2120 Dana Ave., Cincinnati 7, Ohio

### NORTHEAST REGION

Frank E. Costanzo, Director; 253 Ryan Drive, Pittsburgh 20, Pa.

Wayne W. Binger, Chairman; Alcoa Research Laboratories, P. O. Box 1012, New Kensington, Pa.

A. F. Minor, Vice Chairman; American Tel. & Tel. Co., 195 Broadway, New York 17, N. Y.

James H. Cogshall, Secretary-Treas-urer; Pennsalt Chemicals Corp., Corrosion Engineering Products Dept., Natrona, Pa.

### Baltimore-Washington Section

James W. McAmis, Chairman, Washington Gas Light Co., 1100 H. Street, N. W., Washington 1, D. C.

Street, N. w., Washington I, D. C. Herbert F. Lewis, Vice-Chairman; South Galvanizing Co., 1620 Bush St., Baltimore 30, Md. Neil B. Garlock, Secretary-Treasurer; 1500 Rhode Island Ave., N. W., Washington 5, D. C.

#### · Central New York Section

Hendrik Van Droffelaar, Chairman; 54 Churchill Road, Prescott, On-tario, Canada

Gordon Watt, Vice Chairman; James Watt Company, 111 Teall Avenue, Syracuse, N. Y.

### · Genesee Valley Section

Paul Lahr, Chairman; Goulds Pumps, Inc., Box 330, Seneca Falls, N. Y. John H. Carlock, Vice Chairman; 28 Austin Drive, Penfield, New York

Grant Pike, Secretary-Treasurer; Dollinger Corp., 11 Centre Park, Rochester, N. Y.

Greater Boston Section
 Benjamin F. Barnwall. Chairman; Lithcote Corp., P. O. Box 63, Millbrook, Duxbury, Mass.
 L. Malcolm Mosher. Vice-Chairman; Bethlehem Steel Corp., Shipbuilding Division, Quincy 69 Mass.

O

CO

H

th

co

ne

m

fe

id

cu

do

Ca

Manson Glover, Secretary-Treasurer; 215 Pleasant Street, Stoughton, Mass.

### • Kanawha Valley Section

W. G. Mathews, Chairman; Columbian Carbon Company, P. O. Box 873, Charleston, W. Va.

R. Gosnell, Vice Chairman; Union Carbide Chemicals Co., South Charleston 3, W. Va.

William J. Foster, Secretary; 4501 Noyes Ave., S. E., Charleston 4, W. Va.

. L. Davisson, Treasurer; Union Carbide Chemicals Co., South Charleston 3, W. Va.

### • Lehigh Valley Section

Lawrence H. Dale, Chairman; A.C.F. Industries, Berwick, Pennsylvania Seymour C. Frye, Vice Chairman; Bethlehem Steel Co., Bethlehem, Pennsylvania

Roger N. Longenecker, Secretary-Treasurer; The Glidden Co., Read-ing, Pennsylvania

### Metropolitan New York Section

. F. Minor, Chairman; American Tel. & Tel. Co., 195 Broadway, New York 7, N. Y.

C. Lattin, Vice Chairman; Ebasco Services Incorp., Two Rector Street, New York 6, N. Y.

N. Palica, Secretary-Treasurer; Consolidated Edison Co. of New York, Nine South First Avenue, Mount Vernon, N. Y.

### Niagara Frontier Section

M. Stern, Chairman; Metals Research Lab., Electro Metallurgical Co., Niagara Falls, N. Y. E. K. Benson, Vice Chairman; New York Telephone Co., Buffalo, N. Y.

(Continued on Page 10)

. 15

Ash-H. O. C. man; Bush

W.,

man; On-

man; lding

lum-Box

4501 n 4,

nion outh

nan; hem,

tary-

ican way,

# KRALOY

# FIRST PVC RIGID CONDUIT INSPECTED AND PASSED BY **UNDERWRITERS LABORATORIES!**



KRALOY PVC CONDUIT is sold only through wholesale electrical supply houses.

### NOTE WEIGHT COMPARISON - KRALOY PVC vs. ALUMINUM vs. STEEL CONDUIT

U.L. required minimum weight per 100 ft. including couplings, lbs.

Trade Size	1/2"	3/4"	1"	11/4"	11/2"	2"	21/2"	3"	31/2"	4"	5"	6"
KRALOY PVC	15.0	20.0	29.0	40.0	47.0	63.0	101.0	131.0	159.0	187.0	253.0	326.0
ALUMINUM	27.4	36.4	53.0	69.6	86.2	115.7	182.5	238.9	287.7	340.0	465.4	612.9
STEEL	79.0	105.0	153.0	201.0	249.0	334.0	527.0	690.0	831.0	982.0	1334.0	1771.0

For complete information on KRALOY PVC CONDUIT and installation directions, mail the coupon or write to Kraloy Plastic Pipe Co., Inc., 4720 East Washington Blvd., Dept. C-12, Los Angeles 22, Calif.

Cat. No. KE-1058 versus steel, versus even aluminum conduit:

KRALOY ...

Kraloy Plastic Pipe Co., Inc., Dept. C-12 4720 East Washington Blvd., Los Angeles 22, Calif.

Gentlemen: Please send me your new Brochure on KRALOY PVC CONDUIT which gives complete information and installation directions.

NO CONDUIT REPLACES KRALOY

ideal conduit...ideal for direct burial and slab work. Installation costs can be cut drastically with light weight KRALOY PVC RIGID CONDUIT. Consider the

dollars to be saved in handling and installing U-L listed KRALOY CONDUIT

### Directory of NACE Regional and Sectional Officers

(Continued From Page 8)

R. Bishop, Secretary-Treasurer: Metals Research Lab., Electro Metallurgical Co., Niagara Falls, N. Y.

Philadelphia Section

Philadelphia Section
 J. K. Deichler, Chairman; Mechanical Inspection Dept., Atlantic Refining Co., Refining Division. 3144
 Passyunk Avc., Philadelphia. Pa.
 E. D. Bossert, Vice Chairman; 190
 South Trooper Road, Norristown, Pa.
 D. F. Woolley, Jr., Secretary-Treasurer; 303 Landsende Road, Devon, Pa.

• Pittsburgh Section

R. W. Maier, Chairman; Gulf Oil Corporation, Gulf Building, Pitts-burgh 19, Pa. Grant L. Snair, Vice-Chairman; Al-legheny Ludlum Steel Corp., Appli-cation Development Department, Brackenridge, Pa.

legheny Ludwin and Cation Development Department, Brackenridge, Pa. John B. Vrable, Secretary; New York State Natural Gas Corp., 2 Gateway Center, Pittsburgh 22, Pa. William L. Mathay, Treasurer; United States Steel Corporation, Applied Research Lab., P. O. Box 38, Monroeville, Pa.

· Schenectady-Albany-Troy Section

Clark, Chairman: Alco Products, Inc., Schenectady, N. Y. L. Williams, Vice Chairman: Knolls Atomic Power Laboratory, General Electric Co., Schenectady, N. Y.

F. Quinlan, Secretary-Treasurer; Material and Process Laboratory, General Electric Co., Schenectady, N. Y.

Southern New England Section

Southern New England Section
E. A. Tice, Chairman; The International Nickel Company, 67 Wall Street, New York, N. Y.
Archer B. Hamilton, Vice-Chairman; The Hartford Gas Company, 233 Pearl, Hartford 4, Conn.
William W. Steinert, Secretary-Treasuerer; A. V. Smith Company, P. O. Box 476, West Hartford, Conn.

• Wilmington Section

T. F. Degnan, Chairman; 701 West 22nd, Wilmington 2, Delaware James M. Brady, Secretary Treasurer; Haveg Industries, Inc., 900 Green-bank Road, Wilmington 8, Delaware

### SOUTHEAST REGION

John B. West, Director; Aluminum Company of America, 1615 Peach-tree St., N. E., Atlanta, Ga.

Robert D. Williams, Chairman; 1401 Kingscross Drive, Charlotte 7, N. Carolina

George M. Jeffares, Vice-Chairman; Plantation Pipe Line Co., P. O. Box 1743, Atlanta, Ga.

John B. Paisley, Jr., Sec.-Treasurer; American Tel. & Tel. Co., 1 Brown Marx Bldg., Birmingham, Ala.

James L. English, Asst. Scc.-Treas-urer; Oak Ridge National Lab., 223 Virginia Rd., Oak Ridge, Tenn.

· Atlanta Section

Associates, Inc., 1008 Crescent Avenue, N. E., Atlanta, Ga. James P. McArdle, Jr., Vice-Chair-man; American Telephone & Tele-graph Company, 917 Hurt Build-ing, Atlanta, Ga.

Emmett Gray, Secretary-Treasurer; Public Housing Administration, Room 737, Peachtree—Seventh Bldg., 50 Seventh St., N.E., At-lanta 23, Georgia

• Birmingham Section

Ralph M. Cunningham, Chairman; Steele & Associates, Inc., 616 Caro-lyn Courts, Biscayne Highlands, Birmingham, Ala.

John B. Paisley, Jr., Vice-Chairman: American Tel. & Tel. Co., 1534 Brown Marx Bldg., Birmingham, Ala.

Marion M. Fink, Secretary-Treasurer; Tennessee Coal & Iron Div., U. S. Steel Corp., Electrical Lab., P. O. Box 599, Fairfield, Ala.

Lawrence Hicks, Assistant Secretary-Treasurer; Southern Natural Gas Company, P. O. Box 2563, Bir-mingham 2, Ala.

Ray G. Penrose, Chairman; Alumi-num Co. of Americaa, 1000 Wach-ovia Bank Bldg., Charlotte, N. C.

Robert H. Gardner, Jr., Vice Chairman; Koppers Co., Inc., Tar Products Div., P. O. Box 1688, Charlotte, N. C.

David B. Anderson, Secretary-Treas-urer; International Nickel Co., Inc., P. O. Box 262, Wrightsville Beach, N. C.

• East Tennessee Section

James A. McLaren, Chairman; Oak Ridge National Laboratory, Div. of Union Carbide Corp., P. O. Box P, Oak Ridge, Tennessee

Frank A. Knox, Sec.-Treas.; Oak Ridge National Laboratories, UCNC, Building 4501, X-10, Oak Ridge, Tenn.

• Jacksonville (Fla.) Section

Henry T. Rudolph, Chairman; Atlantic Coatings Co., P. O. Box 2976, Jacksonville 3, Fla.

2976, Jacksonville 3, Fla.

Herman D. Collete, Jr., Vice Chairman: Division Engineering, Florida Power & Light Co., Daytona Beach, Fla.

Donald C. Hendrickson, Secretary-Treasurer; City of Jackson ville Electric & Water Utilities, 34 South Laura St., Jacksonville 2, Fla.

Miami Section

Power & Light Co., P. O. Box 3100, Miami 30, Fla.

H. Bollinger, Vice Chairman; Peoples Water & Gas Co., P. O. Box 1107, North Miami, Fla.

B. M. Botsford, Secretary-Treasurer; 30 N. E. 69th St., Miami 38, Fla.

· Ohio Valley Section

Harold J. Smith, Chairman; General Electric Co., Appliance Park, Bldg. 5, Room 249, Louisville, Ky.

John S. Heintzman, Secretary-Treas-urer; Southern Bell Tel. & Tel. Co., 534 Armory Place, Room 404, Louis-ville, Ky.

• Tidewater Section

George R. Lulsey, Chairman; Vir-ginia Electric & Power Co., P. O. Box 1194, Richmond, Virginia Murray S. Spicer, Vice-Chairman; The Chesapeake & Potomac Tele-phone Co. of Virginia, 703 East Grace Street, Richmond, Virginia

Ous J. Streever, Secretary-Treasurer; Newport News Shipbuilding & Dry Dock Company, Newport News,

### SOUTH CENTRAL REGION

J. A. Caldwell, Director and Chair-man; Humble Oil & Refining Co., Box 2180, Houston, Texas

Gas Pipe Line Co., P. O. Box 1407, Shreveport, La.

Dan H. Carpenter, Sec.-Treas., P. O. Box 8456, Oklahoma City 14, Okla. M. Thorn. Assistant Secretary-Treasurer; Southwestern Bell Tele-phone Co., P. O. Box 2540, San Antonio, Tex.

Jack P. Barrett, Trustee-at-Large; Pan American Petroleum Corp., P. O. Box 591, Tulsa, Okla.

Alamo Section

Leon Ashley, Chairman; United Gas Pipe Line Co., P. O. Box 421, San Pipe Line Co. Antonio, Tex.

C. Kneuper, Vice Chairman; City Public Service Board, P. O. Box 1771, San Antonio, Tex.

Raford N. Dobie, Secretary-Treas-urer; City Public Service Board, 511 S. Salado St., San Antonio, Texas

Max F. Schlather, Trustee; United Gas Pipe Line Co., P. O. Box 421, San Antonio, Tex.

Central Oklahoma Section

Geo. W. Evans, Chairman; South-western Bell Telephone Co., 2462 N. W. 37th Place, Oklahoma City 12, Okla.

Frank B. Burns, Vice Chairman: General Asphalts, Inc., P. O. Box 305, Wynnewood, Okla.

Truel E. Adams, Secretary-Treasurer; Consolidated Gas Utilities Corp., P. O. Box 1439, Oklahoma City 1,

Frank Burns, Trustee; General Asphalts, Inc., P. O. Box 305, Wynnewood, Okla.

• Corpus Christi Section

William R. Taylor, Chairman; Gas Dept., City of Corpus Christi, P. O. Box 1622, Corpus Christi, Tex. Fred C. Reeb, Vice Chairman; Pipe Line Service Corp., P. O. Box 578, Corpus Christi, Tex.

James Leon Lankford, Secretary-Treasurer; Lankford Painting Co., Inc., P. O. Box 4009, Corpus Christi, Tex.

Paul Laudadio, Trustee; Briner Paint Mfg. Co., 3713 Agnes St., Corpus Christi, Tex.

• East Texas Section

W. R. Carroll, Chairman; Humble Oil & Refining Company, P. O. Box 127, Overton, Texas Omar L. Emrick, Vice Chairman; Tidewater Oil Company, P. O. Box 8, Scroggins, Texas

Gene E. Smith, Treasurer: Lone Star Steel Company, 1012 Bledsoe St., Gilmer, Texas

lke H. Hartsell, Secretary; Tretolite Company, P. O. Box 1181, Glade-water, Texas

Jim Orchard, Trustee; Nocor Chemi-cal Company, P. O. Box 54, Long-view, Texas

• Greater Baton Rouge Area Section Arthur H. Tuthill, Chairman; Valco Engineering, Inc., P. O. Box 2918. Baton Rouge, La.

Donald C. Townsend. Vice Chairman; Ethyl Corp., P. O. Box 341, Baton Rouge, La.

W. E. Doescher, Jr., Secretary-Treasurer; Levingston Supply Co., P. O. Box 2670, Baton Rouge, La. R. M. Eells, Trustee: Esso Standard Oil Co., P. O. Box 551, Baton Rouge, La.

• Houston Section

C. B. Tinsley, Chairman; Southwestern Bell Telephone Co., 1714 Ashland, Room 227, Houston,

Ashland, Room A., Texas

A. Melvin, Vice-Chairman; Carbo-line Company, Box 14284, Houston
21. Tex.
L. Weis, Secretary-Treasurer; Diamond Alkali Company, Box 686, Pasadena, Tex.
T. Payton, Trustee; Texaco, Inc. Laboratory, Box 425, Bellaire, Texas

• New Orleans Section

Keith J. Ebner, Chairman; Texaco Inc., P. O. Box 7, Harvey, La. Earl D. Gould, Vice-Chairman; Con-tinental Oil Co., P. O. Drawer 68, Harvey, La.

Joe Redden, Secretary-Treasurer; Napko Paint and Varnish Works, P. O. Box 13216, New Orleans, La.

L. Grosz, Trustee, The California Company, P. O. Box 128, Harvey, La.

• North Texas Section

R. B. Bender, Chairman; Tejas Plastic Material Supply Co., Box 11302, Ft. Worth, Tex.

Donald F. Taylor, Jr., Vice Chairman: Otis Engineering Corp., Box 35206, Dallas 35, Tex.

Jerry R. McIntyre, Secretary-Treas-urer; Atlantic Refining Co., Box 2819, Dallas, Tex.

Glyn W. Becsly, Trustee; Dallas Power & Light Co., 1506 Commerce St., Dallas, Tex.

### • Panhandle Section

L. A. Thompson, Chairman; Cela-nese Corp., Pampa, Texas

L. J. Roberts, Vice Chairman; S. W. Public Service Co., Amarillo, Texas

J. F. Headrick, Secretary-Treasurer; Phillips Petroleum Co., Phillips, Texas

V. R. Ogilvie, Trustee; Plas-Tex Co., Borger, Texas

#### • Permian Basin Section

Roscoe Jarmon, Chairman; Permian Enterprises, P. O. Box 4132, Odessa, Tex.

Kirk A. Harding, First Vice Chair-man; Gulf Oil Corp., Box 362, Goldsmith, Tex.

. C. Booth, Second Vice Chairman; Plastic Applicators, Inc., Box 2749, Odessa, Tex.

. F. Weeter, Secretary-Treasurer; Magnolia Petroleum Co., Box 633, Midland, Tex.

John Gannon, Trustee; Texaco Inc., Box 1270, Midland, Tex.

### · Rocky Mountain Section

Herbert L. Goodrich, Chairman; American Tel. & Tel. Co., 810-14th St., Denver, Colo.

Burton K. Wheatlake, Vice Chairman; B. K. Wheatlake Co., 1318 So. Milwaukee St., Denver 10,

Wm. P. McKinnell, Jr., Secretary-Treasurer; Ohio Oil Co., P. O. Box 269, Littleton, Colo.

John R. Hopkins, Trustee; Protecto Wrap Co., 2255 So. Delaware St., Denver 23, Colo.

### · Sabine-Neches Section

Paul McKim, Chairman; Socony Paint Products Company, P. O. Box 2848, Beaumont, Texas

John L. Henning, Jr., Vice Chairman; Gulf Oil Corp., P. O. Box 701, Port Arthur, Texas

Elmer N. Coulter, Secretary-Treas-urer; Cities Service Refining Corp., Basic Laboratory, Lake Charles, Louisiana

Jesse Baker, Trustee; 2950 Lucas Drive, Beaumont, Texas

### • Shreveport Section

John I. Wise, Chairman; Arkansas-Louisiana Gas Co., Box 1734, Shreveport, La.


P. Naremore, Vice Chairman; Arkansas Fuel Oil Corp., P. O. Box 1117, Shreveport, La.

Grady Howell, Secretary; Tube-Kote, Inc., 700 Dodd Drive, Shreveport, La.

D. A. Tefankjian, Treasurer; 178, Bruce Street, Shreveport, La. A. Sullivan, Trustee; 2302 Thorn-hill, Shreveport, La.

(Continued on Page 12)

Proved by 200-hour torture test!



Each of the five lengths of pipe shown was covered with a different protective coating—both tapes and mill coatings. They were then fastened in a barrel containing abrasive tumbling chips and continually tumbled for 200 hours. This unretouched photo shows the results: only the "SCOTCHRAP" Pipe Protection Tape, far right, survived intact!

This controlled test was designed to measure the resistances of various coatings to backfilling and soil stresses. It clearly demonstrates the superior abrasion and puncture resistance and excellent bond strength you get *only* with "SCOTCHRAP"—the toughest polyvinyl chloride plastic tape. These properties are so superior that with normal care, no protective overwrap is needed. Add the excellent electric properties, and you have the reasons why we believe "SCOTCHRAP" is the best total coating buy you can make.

FOR MAXIMUM ABRASION RESISTANCE . . .

EXCELLENT PUNCTURE RESISTANCE . . .

MAXIMUM RESISTANCE TO SOIL STRESS . . .

PLUS EXCELLENT ELECTRICAL PROPERTIES



SEND FOR FREE MANUAL! New "Tape it Easy" booklet gives application methods, useful specifications, for "SCOTCH-RAP" Pipe Protection Products. Write 3M Co., St. Paul 6, Minn., Dept. EAM-129.

### SCOTCHRAP Pipe Protection Products

The term "Scotchrap" is a registered trademark of Minnesota Mining and Mfg. Co., St. Paul 6, Minn. Export Sales Office: 99 Park Avenue, New York 16, N.Y. In Canada: P.O. Box 757, London, Ontario.

MINNESOTA MINING AND MANUFACTURING COMPANY



Plas-11302, Chair-, Box

l. 15

Dallas merce

Treas-Box

Cela-S. W. Texas surer; iillips,

rmian dessa, Chair-362,

man; 2749, surer; 633, Inc.,

man; )-14th Chair-1318 r 10,

otecto St.,

Paint 2848, man; Port Treas-Corp., arles,

Lucas ansas-1734,

man; O. Kote, port,

horn-

### Directory of NACE Regional and Sectional Officers

(Continued From Page 10)

#### · Teche Section

John D. Stone, Chairman; Sunray Mid-Continent Oil Co., Box 1265 O.C.S., Lafayette, La.

Sam E. Fairchild, Vice-Chairman; Texas Pipe Line Co., Box 1145 O.C.S., Lafayette, La.

J. Cernik, Secretary; Union Oil Co. of California, Box 421, Abbeville, La.

Phil C. Brock, Treasurer; Dowell Division of the Dow Co., Box 1785 O.C.S., Lafayette, La.

O. L. Bassham, Trustee; The Treto-lite Company, Box 1223 O.C.S., Lafayette, La.

#### • Tulsa Section

ark D. Muir, Chairman: Dowell Division of Dow Chemical Co., P. O. Box 536, Tulsa 1, Okla.

Cecil O. Smith, Vice Chairman; Carter Oil Co., Box 801, Tulsa, Okla.

ay Amstutz, Secretary, Earlougher Engineering, P. O. Box 4597 Tulsa 24, Oklahoma

Herbert M. Cooley, Treasurer; Beth-lehem Steel Co., 1908 First Na-tional Bank Bldg., Tulsa 3, Okla.

N. Hunter, Jr., Trustee; Service Pipe Line Company, P. O. Box 1979, Tulsa, Oklahoma

#### · West Kansas Section

Roy Junkins, Chairman; Cities Service Oil Co., Box 751, Great Bend,

ice Oil Co., Box 751, Great Bend, Kan. Ray E. Walsh, Vice Chairman; Atlas Fowder Co., 1230 Grant, Great Bend, Kan. Cliff Koger, Trustee, Cities Service Oil Co., Bartlesville, Okla.

### WESTERN REGION

E. H. Tandy, Director; Standard Oil Company of California, P. O. Box 97, El Segundo, Cal.

R. I. Stark, Chairman; Pacific Gas & Electric Co., Dept. of Pipe Line Operations, P. O. Box 3246, Bakers-field, Cal.

neid, Cal.

A. E. Storm, Vice Chairman: Tide-water Oil Co., Associated, Cal.

R. L. Davis, Secretary-Treasurer;
Superior Oil Co., 538 Mission St.,
South Pasadena, Cal.

### • Central Arizona Section

Central Arizona Section Harold B. Newsom, Chairman; Rust-Proofing, Inc., P. O. Box 1671, Phoenix, Arizona William B. Lewellen, Vice-Chairman; Deer-O-Paints and Chemicals Ltd., P. O. Box 990, Phoenix, Arizona Lee Homrighausen, Secretary; Arizona Public Service Co., P. O. Box 2591, Phoenix, Arizona H. B. Newsom, Trustee; Rust-Proofing, Inc., P. O. Box 1671, Phoenix, Arizona

#### · Los Angeles Section

J. I. Richardson, Chairman; Amercoat Corporation, 4809 Firestone Boule-vard, South Gate, Cal. Harry J. Kipps, Vice-Chairman; 10954 South Kane Avenue, Whittier, Cal.

Cal.
Phil Burch, Secretary-Treasurer; Klaas
Bros., Inc., 2012 Hyperion, Los
Angeles 27, Cal.
Carl E. Hedborg, Trustee; Research
Dept., Union Oil Company of California, P. O. Box 76, Brea, Cal.

### Portland Section

ohn Van Bladeren, Chairman; Northwest Natural Gas Co., 132 N. W. Flanders St., Portland 9,

Northwest Natural Gas Co., 132
N. W. Flanders St., Portland 9,
Ore.
Otto Hudrlik, Vice Chairman; The
Flox Co., Inc., 5329 N. E. Union
Avenue, Portland, Ore.
Ralph M. Mattison, Secretary-Treasurer; 132 N. W. Flanders St., Portland 9, Ore.
Rodney V. Moorman, Trustee; Bonneville Power Administration, P. O.
Box 3537, Portland 8, Ore.

#### · Puget Sound Section

Robert T. Mercer, Chairman; 618 W. Highland Drive, Seattle 99, Wash. Norman H. Burnett, Vice-Chairman; 230 South 187th Street, Seattle 88, Wash.
Claude Copley, Sccretary-Treasurer; Walter N, Boysen Co., 2226 Elliott Avenue, Seattle 88, Wash.

#### • Salt Lake Section

Salt Lake Section
L. G. Haskell, Chairman; Salt Lake
Fipe Line Co., P. O. Box 117,
Salt Lake City, Utah
Frank L. Pehrson, Vice-Chairman;
P. O. Box 1650, Salt Lake City,
Utah

7. G. Handy, Sec.-Treas.; Reilly Tar & Chemical Corp., 408 Con-tinental Bank, Salt Lake City, Utah

#### • San Diego Section

Kenneth R. Christy, Chairman; Federal Housing Administration, 601 A Street, Room 201, San Diego 1, Cal.

Otto Hepner, Vice-Chairman; Alvarado Filtration Plant, La Mesa, Cal.

Dick Whidden, Secretary-Treasurer; Rocket Chemical Company, 4672 Alvarado Road, San Diego, Cal.

O. Waters, Trustee; 6326 Monte-cuma Road, San Diego 15, Cal.

#### San Joaquin Valley Section

Jack A. Bessom, Chairman; Richfield Oil Corp., Box 147. Bakersfield, Cal.

J. C. Chescheir, Jr., Vice Chairman; Tretolite Company of California, P. O. Box 1474, Bakersfield, Cal.


Bruce A. Grover, Secretary; Western Gulf Oil Company, Box 1392, Bak-ersfield, Cal.

### • San Francisco Bay Area Section

Roy O. Dean, Chairman; Pacific Gas & Electric Co., 4245 Hollis St., Emeryville 8, Cal.

John W. Caldwell, Secretary-Treas-urer; The Bunker Hill Co., 600 Market St., San Francisco 4, Cal. J. B. Dotson, Trustee; Pyromet Co., 429 South Canal St., South San Francisco, Cal.

### You Can Find the Article



Easily

27 pages, 8½ x 11, paper. Alphabetical subject, author and chronological index of 629 articles by 1056 authors published in the decade 1945-54. A real time saver for the corrosion worker.

1945-54

10-YEAR INDEX to CORROSION

### NATIONAL ASSOCIATION of CORROSION ENGINEERS

Phone CApitol 4-6108

1061 M & M Bldg.

Houston 2, Texas

### **Technical Articles** Scheduled for January

A Laboratoy Paint Test Program, by R. E. Gackenbach

Coal Tar Coatings and Surface Preparation, by W. F. Fair, Jr.

-Chemical Cleaning of Equipment in Refineries and Petrochemical Plants, by Lambert N. Klinge and Johan Selman

Selection of Alloys for Process Equipment, by A. J. Freedman, G. F. Tisinai and E. S. Troscinski

Corrosion of Hydrogen Reforming Furnace Tubes by Residual Welding Slag. by Kenneth L. Moore

Acid Proof Floor Construction With Membrane and Brick-A Report of NACE Technical Unit Committee T-6K, Corrosion Resistant Construction With Masonry and Allied Materials

Translation of Foreign Terms on Corrosion of Metals

Critical Evaluation and Improvement of Methods for Detecting Intergranular Corrosion Susceptibility in Aluminum Alloys, by Sara J. Ketcham and Wal. 15

an; tion,

lesa,

nte-

tern BakWATER PROBLEMS IN




### heat exchangers?

pipe lines?



### cooling towers?



### CALGON HAS THE ANSWER

Corrosion and other water damage to key points in cooling and service water systems can tie up an entire plant. Costly equipment can be damaged beyond repair. Replacement costs and the losses caused by unscheduled outages far outweigh the modest cost of adequate protection.

Call on Calgon Engineering Service to insure protection of the entire system. From cooling towers on through, the Calgon engineer can save you money and time. Experience with every type of water problem in all parts of the country, backed by complete laboratory facilities, is at your service.

Corrosion control with Calgon\* is only one of the many services available. A letter or phone call will bring a man with the water problem answers to work for you. \*Calgon is the Registered Trademark of Calgon Company for its sodium phosphate glass (sodium hexametaphosphate) products. The use of polyphosphates for the prevention of corrosion is covered by U. S. Patent 2,337,856.

### CALGON COMPANY

DIVISION OF HAGAN CHEMICALS & CONTROLS, INC.

HAGAN BUILDING, PITTSBURGH 30, PA. In Canada: Hagan Corporation (Canada) Limited, Toronto

## NATIONAL ASSOCIATION of CORROSION ENGINEERS

Executive Offices: 1061 M & M Bldg., Houston 2, Texas
Telephone CApitol 4-6108

Executive Secretary
Assistant Secretary and Exhibition Manager
Technical Committee SecretaryJ. F. VANDER HENST, JR.
Administrative Assistant for Regions and Sections
Publication Director
Editorial Assistant

Inquiries regarding membership, and all general correspondence should be directed to the Executive Secretary at the administrative headquarters of the National Association of Corrosion Engineers at 1061 M & M Building, No. 1 Main Street, Houston 2, Taxas.

The National Association of Corrosion Engineers is a non-profit, scientific and research association of individuals and companies concerned with corrosion or interested in it, whose objects are:

- (a) To promote the prevention of corrosion, thereby curtailing economic waste and conserving natural resources.
- (b) To provide forums and media through which experiences with corrosion and its prevention may be reported, discussed and published for the common good.
- (c) To encourage special study and research to determine the fundamental causes of corrosion, and to develop new or improved techniques for its prevention.
- (d) To correlate study and research on corrosion problems among technical associations to reduce duplication and increase efficiency.
- (e) To promote standardization of terminology, techniques, equipment and design in corrosion control.
- (f) To contribute to industrial and public safety by promoting the prevention of corrosion
- (g) To foster cooperation between individual operators of metallic plant and structures in the joint solution of common corrosion problems.
- (h) To invite a wide diversity of memberships, thereby insuring reciprocal benefits between industries and governmental groups as well as between individuals and corporations.

It is an incorporated association without capital stock, chartered under the laws of Texas. Its affairs are governed by a Board of Directors, elected by the general membership. Officers and elected directors are nominated by a nominating committee in accordance with the articles of organization. Election is by the membership.

### Advertising and Editorial Offices of CORROSION

Address all correspondence concerning advertising, circulation and editorial matters relating to CORROSION to the NACE executive offices, 1061 M & M Building, Houston 2, Texas. Inquiries concerning and orders for reprints of technical information published in CORROSION should be sent to this address also.

### OFFICERS and DIRECTORS

### **OFFICERS**

PresidentHUGH P. GODARD
Aluminium Laboratories, Ltd., Kingston, Ont., Canada
Vice President GEORGE E. BEST
Manufacturing Chemists Assn., Washington, D. C.
TreasurerA. L. STEGNER
Tennessee Gas Transmission Co., Houston 2, Texas
Executive Secretary
1061 M & M Bldg., Houston 2, Texas
DIRECTORS
Past-President

I dol I roomanii								
	L.	L.	WHITEN	ECK				1959-6
		Los	Angeles	Harbor	Dept.,	San	Pedro,	Cal.

SCI

co

los

of

in

ch

IL

in

ca

ph

to

hi

WI

riz du

an

lea

gi

ar

in

us

co

te

m

br

	Representing	Active	Membership	
R. McFARI	LAND, JR			. 1958-61
		- 01		

E.	G.	BRINK	i		 										*	1957-60
	Am	erican	Vis	cos	 C	ro	м	ar	cu	2	н	200	le.	. 1	Po	

J.	P.	BARRETT	,			1959-62
	Pan	American	Petroleum	Corp.,	Tulsa,	Okla.

E.	L.	SIM	ONS.																				19	59	-6	2
	Ger	neral	Elect	ric	C	0.	,	S	ch	ie	n	ec	te	ac	dy	1,	-	V.	. 1	1.						

C. G.

Represe	Co	гро	orate	Mem	bership		
GRIBBLE,	JR						1958-61
tal Goods	Corpe	ora	tion	. He	uston	Texas	

L. C. WASSON	1958-61
A. O. Smith Corp., Milwaukee, Wis.	
D E MISTED	1057 40

R. E.	KUSTER	. 1957-60
	ion Gas Co. of Canada, Ltd. atham, Ontario, Canada	

R. S. T	RESEDER					1957	-60
Shell	Development	Co.,	Emeryvi	lle,	Cal.		
CHY E	WILLIAMS					1050	2 40

### 

### Representing Regional Divisions E. H. TANDY.................(Western) 1958-61 Standard Oil Co. of California, El Segundo, Cal.

31011	dui	9 011	CO. 0	-	monnia,	-	angoni	40, 64	
JOHN	B.	WEST	r		(5	out	heast)	1957-6	0
Alun	ninu	m Co	mpany	of	America	a, ,	Atlanta	, Ga.	

F.	E.	COSTANZO	o			(Nort	theast)	1957	7-60
	Mai	nufacturers	Light	and	Heat	Co.,	Pittsbu	ırgh,	Pa.

6	MOORMA	M	-	North	Central	1050.62
	ernational					1737-02

J.	A.	CAL	DWI	ELL		. (Sc	uth	Cent	ral)	1959-6	2
-					Refining						_

#### T. R. B. WATSON ...............(Canadian) 1959-62 Corrosion Service Limited, Toronto, Ont., Canada

### Directors Ex Officio

- H. C. VAN NOUHUYS, Chairman Regional Management Committee 908 Boulder Crest Drive, Marietta, Ga.
- R. A. BRANNON, Chairman Policy and Planning Committee Humble Pipe Line Co., Houston, Texas
- R. S. TRESEDER, Chairman Publications Committee Shell Development Co. Emeryville, Cal.
- J. MAITLAND, Chairman Technical Practices Committee American Telephone & Telegraph Co., New York, N. Y.



National Association of Corrosion Engineers

An Association of Individuals and Organizations Concerned with Control of Corrosion 1061 M & M Building Houston 2, Texas

Vol. 15

ARD

EST

NER

ULL

9-60

8-61

7-60

9-62

9-62

B-61

8-61

7-60

7-60

9-62

8-61

Cal.

7-60

7-62

9-62

g

ttee

December, 1959

No. 12

### Corrosion in a Hydrocarbon Conversion System\*

By F. A. PRANGE

THIS IS ONE of a group of articles on high temperature corrosion describing elusive problems. Other articles concern themselves largely with metal loss. This paper considers some secondary effects which add to knowledge of the mechanism of damage.

A brief description of the butane dehydrogenation process1,2 at Plains Plant of Phillips Petroleum Company will aid in understanding the conditions. Butane is dehydrogenated to butene over a chromia-alumina catalyst at a temperature of about 1100 F. Tubes of 21/2 inch ID are used to contain the catalyst. At intervals the carbon which forms on the catalyst is burned off with regeneration gas of low oxygen content. During this phase the catalyst tube is kept hot enough to insure combustion, but the furnace gas serves to cool the tube. Low oxygen content is necessary to prevent the temperature during burnout from going too high and causing damage to the catalyst or carburization of the tube. Either the wrong alloy for tube material or carburization of the tube causes a red oxide dust to spread over the catalyst. This oxide dust is very catalytic and causes destructive cracking of the butane. Such severe cracking in turn results in a large amount of carbon and very rapid plugging. The whole undesirable process leading to oxide formation has been given the name "metal dusting."

The alloy for the plant tubes was selected on the basis of early pilot plant work. Some alloys gave very rapid plugging. The 27-chrome alloy and copper were inert. In the laboratory tests glass and silica were also inert.

After the 27-chrome tubes, welded into groups called harps, had been in use for some time, mechanical properties became critical. Exposure to operating conditions caused sigma phase to form and embrittle the tubes. At atmospheric temperature during the shutdowns for catalyst changes the 27-chrome was almost glass brittle. Because of considerable breakage, something better was desired. Laboratory studies made to find metals for miscellaneous parts led to use of 25-20 chrome-nickel for catalyst tubes and 18 chrome-11 nickel-21/2 silicon steel for the headers.

The laboratory studies and plant tests of the special alloys demonstrated some of the factors in the high temperature corrosion in butane dehydrogenation equipment. The laboratory tests were made in the fashion described below:

The metals were abraded with a clean fine file and the chips were mixed with catalyst particles and placed in Pyrex tubing. Butane was passed through the mass for 50 minutes at a temperature of 1112 F. Gradually during the cycle, carbon formed on the catalyst and this was burned off with 50 minutes of regeneration with air. The performance of the metals was evaluated by pressure drop across the tube during the butane cycle, by the amount of carbon formed, by the amount of olefin formed, by the rate of plugging and by the appearance of the metal chips.

Metals that performed well produced only a nominal pressure drop during the dehydrogenation phase through a large number of cycles. A metal of intermediate performance might show only a normal pressure drop for as many as 15 cycles, but then practically plug in two more cycles. Very poor metals like car-bon steel might plug in two cycles. Another characteristic of a very poor metal was that it degraded a great deal of the butane to products of lower grade than the desired butenes. The appearance of the metal also was important: Poor steels were completely covered with velvety buds of red oxide after the carbon was burned away; good metals showed few, if any, buds of oxide.

Composite ratings of some metals are shown in Table 1. In these tests high silicon cast iron plugged badly even before one regeneration cycle had occurred. Nickel had such a rapid buildup of carbon during the butane phase of the first cycle that it was impossible to pass butane through the mass for the full 50

While the 27-chrome harps were in use and after the laboratory tests, full scale tube tests were made in the plant. The test materials are shown in Table 2.

#### Abstract

Abstract
Under some inexactly defined conditions, steels and alloys are attacked by atmospheres resulting from oxidation of hydrocarbon. In a fixed-bed catalytic system for dehydrogenation of butane the metal loss which contaminates the catalyst with a fine oxide dust causes undesirable side effects. The way in which the metal loss occurs is described and the effects of alloying agents on both laboratory tests and actual equipment are mentioned. Some examples of metal dusting give a clue to the mechanism of metal loss, but are not complete enough to define it fully.

4.4.6

About the Author



F. A. PRANGE is employed by the Engineering Department of Phillips Petroleum Company, Since he joined the company in 1941 he has been working on the varied problems in corrosion and metallurgy connected with the production of and refining of oil and various processes. He was granted a BS in metallurgical engineering by Purdue University in 1940 and an MS in 1941.

Of these test metals only 302B, 310 and 316 tubes did not plug. The 316 tubes, though they did not plug, were always sluggish on burnout during the regenera-tion cycle. This indicated that the carbon formation was excessively high.

### TABLE 1—Ratings of Metals in Dehydrogenation Tests

Good	Poor
31 Cr-9 Ni	20 Cr-3 Ni
27 Cr	18 Cr-11 Ni
24 Cr-15 Ni	17 Cr-13 Ni-2 Mo
20 Cr-10 Ni-3.6 Mo	12 Cr
18 Cr-12 Ni-2.5 Si	9 Cr-1.4 Mo
30 Cr-65 Co-4 W	Duriron (High
	silicon cast iron)
	Iron
	Nickel

### TABLE 2—Analysis of Metals Used in

	Limit 19313
AISI Type	
Number	Nominal Analysis
302B	18 Cr-11 Ni-21/2 Si
304	18 Cr-10 Ni
310	
316	16 Cr-13 Ni-2 Mo
321	18 Cr-11 Ni-0.4 Ti
347	18 Cr-12 Ni-0.9 Cb

★ Submitted for publication February 20, 1959. A paper presented at the Fifteenth Annual Conference, National Association of Corrosion Engineers, Chicago, Ill., March 16-20, 1959. One of three papers on metal dusting sponsored by the ASTM-ASME Joint Committee on Effect of Temperature on Properties of Metals.

ap

the

pa

inc

SCa

rec

ste

sui

the

Th

lin

itie

of

op

alt

ch

wh

cia

sta

to

be

chi

per

pec 18

not

lov

dit

god

ast ian

car

am

of

iro

op



Figure 1—Catalyst tube containing rat-tail file. This shows how the iron-containing coke spreads outward in a radial fashion.



Figure 2—Carbon spreading inward from wall of a carburized tube.



Figure 3—Catalyst in Inconel tube shows how the nickel oxide pervades the entire catalyst mass.

After these tests were made, experimental harps of 302B and 310 analysis were installed. After a case fire overheated the tubes, the 302B tubes had loaded the catalyst with more dust than had the 310 tubes. The final decision was that the catalyst tubes were to be of 310 stainless and the headers of 302B stainless. The plant presently is using this equipment.

The discussion of metals in butane dehydrogenation is not complete without adding other information. Clues to the mechanism of damage are available in other incidents.

In one instance a carbon steel file was left in a tube as it was being filled with catalyst. After a short time on stream the tube plugged and was removed from service. When the carbon was partially burned off, the pattern shown in Figure 1 was apparent. The carbon "grew" outward in a radial fashion pushing the catalyst ahead of it. There was also some general contamination with oxide dust.

Figure 2 shows carbon formed in 27-chrome tubes after the tube became carburized due to fires in the catalyst case. The addition of a small amount of carbon very markedly damages the alloy. Carburization is a frequent cause of plugging. Apparently, chromium combined with carbon in the form of carbides is ineffective in preventing dusting.

To study the dusting process an Inconel tube (15% chromium, 7% iron, 78% nickel) was installed. This tube started to plug in a short time. Figure 3 shows how nickel oxide pervades the entire catalyst mass instead of being concentrated near the wall as in the carburized 27-chrome tube or near the contaminating source such as the file. The rate of migration of nickel is much higher than that of iron—not only in plant equipment but also in laboratory tests.

It was thought at first that the catalytic effect of steels had little relation to general metal loss. On this premise the case headers conducting the harp effluent gases away were made first of 5-chrome steel. From the standpoint of temperature alone—temperatures under 1100 F—the 5 chrome should have been adequate. Instead, general metal loss of a



Figure 4—Electron microscope picture of the iron oxide attached to a catalyst particle. Approx. 10,000 X.




Figure 5—Electron microscope picture of nickel oxide attached to catalyst particles. 10,000 X.




Figure 6—Elemental nickel layer on inside of a slightly carburized tube. Chromic acid etch. 250 X.

ol. 15

nickel X




Figure 7-Very localized carburization in a 27-chrome catalyst tube. Aqua regia etch. 75 X.

peculiar fashion occurred. The metal disappeared in such a uniform way that the thread form on internally threaded parts was unchanged while the diameter increased a few tenths of an inch. No scale was formed; there was just a fine red oxide on the surface. Twelve-chrome steel was used for replacement, but this suffered the same type of damage, although the damage was somewhat slower. The general metal loss in the effluent lines finally was cured by using austen-itic stainless equipment. This is but one of the experiences throughout Phillips operations that demonstrates that ordinary ideas of high temperature resistance do not apply to environments that are alternately oxidizing and reducing.

The resistance to the dusting action can be changed by small changes in analysis. In the chromium-iron series, 17 chrome was completely unacceptable while 27-chrome material was a commercially useful material. The austenitic stainless steels are even more sensitive to small changes in analysis. As might be expected from performance in 27 chrome-iron, 25-20 chrome-nickel steel performed well. From the performance of 17 chrome-iron it would not be expected that Type 304 stainless with about 18% chromium would be good. It was not. But Type 316 stainless with slightly lower chromium content and with the addition of 2% molybdenum was almost good enough. The addition of 2½% silicon to the 18-8 analysis gives even more astonishing results. This 21/2% silicon variant is almost equivalent to 25-20 chromenickel. The extra 7% chromium of 25-20 can almost be replaced by 21/2% silicon. Even on an atomic percentage basis the amount of silicon is less than the amount of chromium it replaces. Silicon by itself is not sufficient because the 14 siliconiron alloy was extremely poor.

Analysis of the coke formed during operation gave some surprising results.

The coke around the iron file mentioned previously contained magnetite (Fe<sub>3</sub>O<sub>4</sub>) and graphite as the only compounds with X-ray diffraction patterns. Metallic iron was not present nor was there any evidence of metallic carbides such as Fe<sub>2</sub>C and Fe<sub>3</sub>C. After carbon was burned off this coke, the only compound giving a pattern was Fe<sub>2</sub>O<sub>3</sub>. The electron microscope picture, Figure 4, shows that the resulting Fe<sub>2</sub>O<sub>4</sub> is in a tree-like form.

The nickel oxide from the Inconel catalyst tube is shown in Figure 5. Coke in the Inconel tube contained only NiO and graphite. No metal particles, at least of the size capable of giving definite pattern, were present. Thus, these X-ray diffraction studies on both iron and nickel alloys lend no credence to the theory occasionally mentioned that actual grains of metal are popped out and that metallic particles are the actual catalytic agent forming the undesired coke.

The curious nature of the corrosion process is illustrated by another example. After 10 years of service one of the 302B experimental catalyst tubes was removed because of bulging and coking. Scale on the outside of the tube indicated that it had been overheated. This overheating could have been the result of a fire in the furnace or it could have been simply a function of excessive coke formation. On the inside of the tube there was a thin black scale. Analyses by X-ray diffraction showed graphite, magnetite (Fe<sub>3</sub>O<sub>4</sub>) and metallic nickel. Figure 6 shows the details of the inside surface. The metallic nickel looks almost like a porous plating, as though the nickel had been deposited on this area after removal from some other area. The grain boundary appearance indicates that some car-burization of the base material had occurred. There was no evidence of any grains being pried out.

Just how localized carburization can be is illustrated in Figure 7. Either the carburization is just beginning or there were very few exposures to damaging conditions.

None of the foregoing phenomena adequately define the corrosion mechanism. While a few aspects are discernible, the picture as a whole is hazy. At first glance it might seem that oxidation phenomena govern the entire problem. This is contradicted by copper which has good metal dusting properties but poor oxidation resistance. Even in the stainless steel series, experience refutes a premise that oxidation resistance constitutes the entire variable. Type 316 stainless, which is not recognized as being more oxidation resistant than Type 347, is much better as a catalyst tube material. Although molybdenum detracts from oxidation resistance in some instances, it is beneficial to the dusting problem. Likewise, Inconel, which has superior oxidation resistance, performs poorly in butane dehydrogenation service.

To the author it seems that the movement of metal is best explained by a concept of a very unstable vapor phase compound. Examination of this thesis requires intricate techniques because ordinary analytical procedures cannot be used to study the highly unstable materials. Perhaps high temperature spectroscopy would aid in study of the problem.

### Acknowledgments

Preceding details include the work of the Phillips' research department in studying laboratory techniques and conducting plant studies at Phillips Plains Plant. The work of a great many people is gratefully acknowledged.

### References

- Butane Dehydrogenation—Pilot Plant Investigations. Karl Hachmuth and George Hanson. Chem. Eng. Progress, 44, No. 6, p. 421-430 (1948) June.
- (1948) June. 2. Phillips Butane Dehydrogenation Process—Special Plant Investigations. George H. Hanson and Harrison L. Hays. Chem. Eng. Progress, 44, No. 6, p. 431-442 (1948) June.

### DISCUSSION

### Question by William B. Segraves, Decatur, Ga.

In your laboratory test work did you try to pinpoint whether the reaction part or the regeneration part of your process cycle caused your metal dusting problem? This is in contrast to operating alternately on reaction and regeneration.

### Reply by F. A. Prange:

Apparently the metal loss in the butane dehydrogenation process occurs during the reduction cycle. As mentioned in the discussion of Duriron, plugging with a few alloys started before the first regeneration cycle had occurred. "Buds" were clearly discernible during the first hydrocarbon exposure.

Any discussion of this article not published above will appear in the June, 1960 issue.

### Attack on Metals by Synthesis Gas From Methane-Oxygen Combustion

By F. EBERLE and R. D. WYLIE

### Introduction

AN UNUSUAL case of metal wastage of uncooled gas deflection baffles, soot blower elements and other components of AISI Type 347 (18Cr-8Ni-Cb) and AISI Type 310 (25Cr-20Ni) in contact with hot "synthesis" gas occurred in the waste heat boiler of a synthesis gas reactor after only three weeks of initial operation. The gas was generated by burning methane with oxygen under controlled conditions and consisted predominantly of CO and H2 with some water vapor and entrained, finely divided graphite carbon. Subsequent investigations revealed that this wastage took place within a temperature interval of about 1650 F and 900 F.

### Design And Construction Features of Operating Unit

The operating unit consisted of a cylindrical steel tower, about 70 ft high with an inside diameter of 11 ft. Its functional details are apparent from the simplified section diagram shown in Figure 1. The lower part of the tower, about 27 ft high, contained the alumina fire brick lined furnace (a pressurized reaction chamber) with circularly arranged water-cooled burners near the bottom end. In this furnace, natural gas (methane) was burned with oxygen, recovered from the air and concentrated 90 percent, under controlled conditions so as to obtain "synthesis gas" intended for hydrocarbon synthesis by a modified Fischer-Tropsch method. This reactor was designed for a gas pressure of 347 psi and an operating pressure of 315 psi. The gas temperature in the furnace normally was to be 2300 F with a maximum of 3000 F for not more than 1/2 hour.

Above the reaction chamber was a waste heat boiler designed for steam of 675 lb pressure. This waste heat boiler consisted of 11 vertical generating tube bundles and other boiler components, arranged in a circle around the inside wall of the tower, but leaving a central opening for the passage of the effluent gases from the reaction chamber. Coneshaped baffles in this central opening, bolted to the surrounding boiler tubes with gusset plates, and alternating socalled finger baffles within the generating tube bundles to which they were attached deflected the upstreaming gases around the generating tubes, giving heat off to the latter and cooling down to 600-650 F at the outlet of the generator.



De

Abstract

Severe metal wastage was experienced on AISI Type 347 (18Cr-8Ni-Nb) and AISI Type 340 (22Scr-20Ni) used in the construction of a gas generator in which methane was burned with oxygen to produce carbon monoxide and hydrogen for fuel synthesis of the Fischer-Tropsch type. The mode of attack varied with temperature. At the highest temperatures, above 1650 to 1800 F, it consisted of straight oxidation, progressing interpranularly. With decreasing temperatures, heavy carburization with occasional signs of interspersed oxidation manifested itself. As temperatures declined further, cycling carburization, oxidation and reduction were observed, acidation and reduction were observed, accompanied by severe metal wastage.

Typically attacked metal surfaces consisted of a semi-scale containing tiny globules of metallic particles surrounded by carbon or graphite interspersed with oxide. Tests with specimens of numerous steels and alloys installed at various locations in the reactor showed that the most resistant materials were those which best resisted carburization. AISI Type 446 (27 chrome-iron), copper, and pack-calorized materials.





Wylie

Eberle

F. EBERLE is chief metallurgical engineer at the research center of Babcock & Wilcox Co. Formerly he was associated with the metal-lurgical staffs of Cadillac Motor Co., Leeds & Northrup Co. and Carnegie Illinois Steel Corp. He has a PhD in chemical and metal-lurgical engineering from the Technical Uni-versity of Munich.

R. D. WYLIE, assistant manager of quality control, The Babcock & Wilcox Company. He has a BS in metallurgical engineering, Uni-versity of Michigan, 1944. After World War Il duty with the navy and graduation from college he was employed at General Electric Company until 1948 when he joined his pres-ent employer as a metallurgist.


The internally water-cooled generating tubes never reached temperatures at which "wastage" occurred. Other significant elements involved in the wastage phenomenon were the sootblowing elements, tubing containing suitably arranged holes through which steam is blown over the boiler tubes to keep them free from deposits which would clog up the gas passages and interfere with heat transfer. There were 11 outer and 11 inner soot blowers, located before and behind the boiler tube bundles. The approximate temperature distribution in the waste heat boiler zone (explored with thermocouples) is indicated in the Section Diagram of Figure 2. These temperatures have been temporarily exceeded during some operating periods.


### Materials

in

al

The following materials were used for the construction of the major elements: The tower shell was made of 0.5Mo steel and the internally water-cooled









Figure 2—Approximate temperature distribution in waste heat boiler zone.



Approx. 1/3 X



Approx. 2/3 X

Figure 3—Section of a "wasted" AISI Type 310 soot blower tube removed from location between Baffles 11 (about 900 F) and 13 (about 700 F).

ting

at nifitage ele-

ar-

nem

up

ieat

11

and

The

in

red

the

em-

ex-

for

nts: Mo


led

S.

boiler generating tubes of plain carbon steel. Their temperatures were so low that they did not become involved in the wastage phenomenon.

The lowest of the center baffles, which were all swept by the reaction gases, was constructed of water-cooled studded tubing covered with refractory reinforced with Inconel wire. The next hottest center baffle, No. 3, was made of AISI Type 310 alloy and all the others (Nos. 5, 7, 9, 11 and 13) of AISI Type 347 stainless steel.

The "finger baffles" which were located in the boiler tube bundles and attached to the latter consisted of the same materials as the nearest center baffles, that is, the three lowest and hottest finger baffles were made of AISI Type 310 and the remaining ones of AISI Type 347. All



Approx. 2/3 X




Figure 5—Percent diameter reduction of 25Cr-20Ni Figure 4—Example of corrosion of AISI Type 310 soot blower tube adjacent to center baffles.




Figure 6—Oxidation-type pitting on surface of AISI Type 310 bolt of Baffle 3 (about 1700 F and possibly higher). Aqua regia etch, 100 X.




Figure 7—Example of pitting attack of the carburization-decarburization type observed on AISI Type 310 soot-blower tube between Baffles 5 and 7 (about 1500-1300 F). Aqua regia etch, 180 X.

re

baffle bolts whose heads were exposed to the hot gases, and the soot blower tubes were of AISI Type 310 alloy.

### Results of Inspection After First Operating Period

The first operating period lasted only 21 days and was terminated because of a failure of the burner cooling water circuit. During this time, the reaction temperature was out of control at least once. The plant had been operating only at about 15-25 percent of rated capacity with soot blowers active about every 30-45 min.

TABLE 1—Weight Changes of Material Samples Installed in the Generator During Second (14-Day) Operating Period

	PERCENT WEIGHT CHANGE AT BAFFLE								
Material	3	5	7	9	11	13			
1 1¼ Cr-0.5 Mo. 2 2¼ Cr-1 Mo. 3 5 Cr-0.5 Mo. 4 7 Cr-0.5 Mo. 5 9 Cr-1Mo.	7 9.3 8.9 5.2 5.5	23.2 22.1 30.6 28.3 23	59.2 45.1 51.7 50.3 58	58.3 20.2 25.9 26.3 24	53.7 44 36.7 35.2 34.5	8.2 6 5.6 5.2 5.3			
6 AISI Type 410. 7 AISI Type 446. 8 AISI Type 430. 9 AISI Type 304. 0 AISI Type 304L.	4.1 1.8 3 7.7 5.7	31.6 0.8 29.2 16.8 16.2	59.1 2.2 45 37.9 41.2	28 2 33.6 27.5 23.3	38.4 2.3 22.9 18.5 17.6	2.5 0.9 0.7 0.5 0.5			
11 AISI Type 316. 12 AISI Type 316L 13 AISI Type 347. 14 AISI Type 310. 15 Armco 17-14 CuMo.	4.7 2.9 2.9 2.2 2.4	19.1 21.3 6.2 2.4 24.2	28.8 22 23.4 19.1 63.4	15.4 15.8 16.4 13.5 48	12.4 14.7 27.5 58.9 11.6	0.1 +0.5 +0.2 +0.1 +0.8			
AISI Type 304, Aluminized. AISI Type 310, Aluminized. Inconel, Aluminized. AISI Type 310, Ceramic Coated. AISI Type 304, Ceramic Coated.	+2.8 2.2 +1.2 3.7 2.5	+2.3 2.2 +4.1 8.6 55	8.5 7 2 58.6	94.2	1.3 1 2.8 2.9	6.9 2.7 6.9 2.2 2.2			
Carbon Steel, Ceramic Coated Carbon Steel	2.6		82.1 39.5 40.2 4.4-9.2		0.3	18.2 1.8-2.6 2.8			

TABLE 2—Weight Changes of Material Samples Installed in the Generator During Third (41-Day) Operating Period

			PERCENT	WEIGHT	CHANGE A	AT BAFFL	Ε
Mate	rial	3	5	7	9	11	. 13
Carbon Steel			67.9	15.0	1.2 0.9 0.02 0.03	0.23 0.03 0.04 0.02 0.03	0.03
9 Cr-1 Mo AISI Type 410 AISI Type 430 AISI Type 446 AISI Type 316				69.0	0.07 0.002 +0.002 0.008 +0.003	$0.10 \\ 0.004 \\ +0.01 \\ 0.04 \\ +0.009$	1.1
AISI Type 310 18 Cr-35Ni Nickel Monel Inconel		0.65 $0.54$ $+0.21$ $+0.04$	33.0 0.18 1.0 0.9	56.0 0.07 17.6 +13.5	$\begin{array}{c} 0.004 \\ +0.02 \\ 0.06 \\ 0.09 \\ 0.004 \end{array}$	0.007 0.09 0.035 0.09	+0.4 0.07 0.04 0.02
1¼ Cr-0.5 Mo, P 2¼ Cr-1 Mo, P	ack Cal. ack Cal. ack Cal. ack Cal.		19.7 70.0	0.25 40.0	0.23 1.2 0.10 1.0	0.06	0.13 0.04
9 Cr-1 Mo, P AISI Type 410, P AISI Type 430, P	ack Cal	5.1	11.5	+5.7	0.07 0.08 +3.8 7.7 0.04	0.06	0.06
AISI Type 316L, P	ack Cal				0.95 0 0.03 2.0		
Monel, P Inconel, P Copper, P	ack Cal. ack Cal. ack Cal. ack Cal. pray Cal.			26.2	0.03 0.02 0 0.13	+0.03	0.47
2½ Cr-1 Mo, S 5 Cr-0.5 Mo, S 9 Cr-0.5 Mo, S	pray Cal. pray Cal. pray Cal. pray Cal. pray Cal.				+0.015 +0.002 +0.014 +0.10 0.06		
AISI Type 430, S AISI Type 446, S AISI Type 304, S	pray Cal. pray Cal. pray Cal. pray Cal. pray Cal.	0.55	2.6	0.29	0.07 0.09 0.08 0.09 0.016	0.06	0.07
AISI Type 316L, S AISI Type 310, S					0.025 0.04		

Visual inspection of the unit revealed that the lower section of the boiler tube banks was clogged with soot. The baffles, soot blower sections and related components in the 1700-1500 F temperature zone appeared to be relatively little damaged by corrosion, but all the uncooled structural components in the 1300-900 F gas zone had thinned to about one-half of their original thickness and some soot blower sections even to complete perforation. No damage was observed below about 800 F.

The type of corrosion encountered is illustrated in Figures 3 and 4.

In the high-temperature zone (1650-1700 F), the attack was of the pitting type. As temperatures decreased, it changed from a highly localized to a more or less general but still sporadic type of corrosion. The severest attack was observed in the general vicinity of 1100 F. This is indicated in Figure 5 which illustrates a wall-thickness survey made on one of the removed AISI Type 310 soot blower tubes.

### Metallurgical Examination of Affected Parts

This severe metal attack which occurred in such a short time at relatively low temperatures in so-called heat and corrosion resistant alloys came as a complete surprise so efforts were made to determine its cause. For this purpose, affected soot blower tubing, bolts and gusset plate samples from each baffle were sent to the metallurgical laboratories for examination. This examination revealed the following:

In the highest temperature zone (1700 F and possibly higher), that is at the level of the lowest baffles, the attack consisted predominantly of straight oxidation which progressed in an intercrystalline manner with the formation of a semi-scale (Figure 6). Corrosion in this zone was not significant.

As temperatures decreased to 1500 F and lower, pitting corrosion set in, apparently initiated by localized carburization which was again followed by oxidation or decarburization (Figure 7).

With further decrease in temperature down toward 1400 F, carburization seemed to get the upper hand. In this predominantly carburizing zone, the attack was only slight (Figure 8). However, here also were sporadic occurrences of alternating carburization and decarburization.

At still lower temperatures, down to about 1100 F, cycling carburization and decarburization became the predominant

In some sections, carburization was found followed by decarburization and again by dense carburization (Figure 9).

A significant observation was the discovery, in a semi-scale, of tiny globules of metallic particles surrounded by carbon or graphite interspersed with oxide (Figure 10). Below this semi-scale was a thin layer of oxide and, underneath the latter, decarburized and carburized metal.

7 ol. 15

vealed

r tube affles.

ompo-

rature little e un-

en to

was

red is

1650-

itting d, it

radic

ttack

ty of

ire 5

urvey

Type

oc-

ively and

com-

le to pose,

and

paffle

ories

re-

1700

the

tack

oxi-

Crvs-

of a

this

00 F

ap-

rizaida-

ture

ion

this

at-

ver, uri-

1 to

and

ant

was and

9).

dis-

ules

car-

cide

as a

the

ı the ed to kness

Scale Analysis

Scale analysis failed to shed much light on the corrosion phenomenon. It revealed only the presence of iron oxide and graphite. In one case, X-ray dif-fraction lines of the compound FeC were found. The technical literature reports that FeC converts to Fe<sub>3</sub>C at 1100 F.

Corrosion-Resistance Evaluation of Materials With Samples Installed in the Generator During Second Operating Period

In order to explore the possibility of finding materials of greater resistance to the observed attack than the AISI Type 347 and AISI Type 310 stainless steels, test specimens of various alloys and nonferrous metals were installed at each center baffle location of the unit during the subsequent operating period which consisted of two short runs of 4 and 10 days, respectively. These materials, listed in Table 1, were plain carbon steel, the conventional chromium-molybdenum high-temperature steels, the ferritic straight chromium and the austenitic iron-chrome-nickel stainless steels as well as other metals and alloys such as oxygen-free copper and aluminum bronze. Also included were ceramically coated specimens of carbon steel, AISI Types 304 and 310; pack-calorized AISI Types 304 and 310; and aluminized samples of AISI Type 304, AISI Type 310, and Inconel.

The samples had been measured and weighed before installation, but the resulting dimensional changes and weight losses proved to be of limited value for quantitative metal-loss evaluation because of the non-uniformity of the corrosive environment and the highly localized nature of the attack. Evaluation of their relative corrosion resistance therefore had to be based on over-all considerations of the extent of corrosion observed.

Some representative samples from each baffle location were metallographically examined to determine the nature of the attack. The latter was found to parallel that observed in the previously investigated generator components, that is, at Baffle 3 (highest temperature) the attack was caused by oxidation in the absence of carburization; at Baffle 5, carburization and oxide penetrations were in





Figure 11—Effect of CO:CO<sub>2</sub> ratio on carburizing-oxidizing atmosphere in contact with iron at tem-peratures between 800 and 1600 F.<sup>1</sup>



ATTACK ON METALS BY SYNTHESIS GAS FROM METHANE-OXYGEN COMBUSTION

Figure 8—Mild surface attack on AISI Type 347 gusset plate of Baffle 5 (about 1400-1500 F). Only carburization in evidence. Aqua regia etch, 100 X.




Figure 9—Metal attack at Baffle 9 (about 1100 F), showing a decarburized layer in the center of heavily carburized surface of AISI Type 347 stainless steel. Aqua regia etch, 250 X.



Figure 10—Semi-scale of graphitic carbon with imbedded iron particles, separated from base metal by a thin layer of oxide. Surface of AISI Type 347 gusset plate of Baffle 9 (about 1100 F). Unetched, 750 X.

evidence; at Baffle 7, carburization combined with surface decarburization; at Baffle 9, heavy carburization and carbide concentration at the surface sometimes with and sometimes without surface de-carburization, while in other cases a decarburized layer was present below the surface in the center of a carburized zone. At Baffle 11, corrosion was of the same general type as at Baffle 9, but its intensity was markedly decreased. At Baffle 13, corrosion was barely noticeable.

In summary, the attack was relatively light in the high-temperature zone (above about 1650 F) and ceased below about 900 F, but was severe and rapid at the intermediate temperatures.

The over-all evaluation of the materials revealed that those which suffered the least attack were all materials which resist carburization, that is, nickel, Monel, Inconel, 27Cr stainless, copper, and pack-calorized stainless steel.

For further confirmation of these findings, additional corrosion specimens were installed in the generator during the subsequent operating period which consisted of two 8-day and one 25-day runs, totaling about 1000 hours of exposure. The various materials used and the weight changes resulting from these tests are listed in Table 2. Nickel, Monel and Inconel again proved to be the most corrosion-resistant materials. The sever-

div

firs

car

tui

fre

ros

bo

art

ica

rol

rea tion sternic per los fee pr rerepa ab

> de ce at ca m

p

est corrosion observed in the last two alloys was some shallow intergranular attack.

### Discussion

The observations made during the examination of the affected metal parts and test specimens led to the conclusion that the following factors may have been involved in the wastage phenomenon:

- 1. Oxidation at Cycling Temperatures. Oxidation alone, observed only at the higher temperatures below the water-cooled baffle, appears to have been a minor cause. It manifested itself in the form of pits.
- 2. Cycling Carburization and Oxidation. This could have caused a "dusting" of metallic particles, possibly facilitated by thermal stresses due to sootblowing and by abrasion by particles entrained in the gas stream.
- 3. Cycling Oxidation and Reduction. It appears to be possible that surface oxide formed during sootblowing with steam was reduced to iron and graphite during the subsequent off-cycle. This possibility is supported by the metallo-

graphically found presence of metal particles in a graphitic-appearing deposit as well as by X-ray diffraction identification of graphitic carbon and traces of iron-graphite FeC on one of the affected soot blower elements.

4. Partial conversion of the outermost surface to solid carbide by continuous carburization and flaking off of the brittle layer.

The formation of iron and nickel carbonyl is not believed to have been a significant factor in the corrosion phenomenon. At the high temperatures at which wastage was observed, carbonyls are not apt to form. This is supported also by the fact that analysis of metal layers removed from affected surfaces of AISI Type 310 alloy has shown no changes in nickel content. Cycling or oscillating carburization and oxidation, or, oxidation and reduction therefore appears to be the most likely fundamental process involved. This possibility is indicated in the diagram of Figure 11 which shows the change from a carburizing to an oxidizing atmosphere as related to the CO:CO2 ratio of such a gas

mixture in contact with iron at temperatures between 800 and 1600 F. An analysis of the problem from this point of view appeared to be hopeless due to the continuous variations of gas composition, temperature, and pressure existing during the operation of the generator.

#### Reference

 Symposium on Furnace Atmospheres for Metallurgical Purposes. The American Chemical Society Division of Gas and Fuel Chemistry. Detroit, 1940.

#### DISCUSSION

Question by Andrew Dravnieks, Standard Oil of Indiana, Whiting, Ind.:
Were pack-calorized metals of any merit?

Reply by F. Eberle, Babcock & Wilcox Co., Alliance, Ohio:

Our yardstick for measuring the merit of a material or coating was whether it would resist the action of the gases sufficiently to give an economical life expectancy. By this token, none of the materials or coatings was rated satisfactory. The involved structural members were therefore redesigned for water cooling to keep metal temperature low enough to prevent metal attack.

### DISCUSSIONS ON TECHNICAL ARTICLES ARE SOLICITED

Discussions on technical articles published in Corrosion will be accepted for review without invitation. Discussions must be constructive, accompanied by full substantiation of fact in the form of tables, graphs or other representative data and be submitted in three typewritten copies. In cases where illustrations are submitted, at least one copy of figures should be of a quality suitable for reproduction.

Authors will be sent on request a copy of the NACE Outline for the Preparation and Presentation of Papers.

Discussions will be reviewed by the editor of Corrosion and will be sent to the author of the paper discussed for his replies, if any. Publication will be in the Technical Section with full credit to the authors together with replies. Discussions to papers presented at meetings of the association may be submitted in writing at the time of presentation or later by mail to the editorial offices of Corrosion, 1061 M & M Bldg., Houston 2, Texas.

er

in

rs

in

to

r Metal-nical So-nemistry.

### merit? Wilcox

r coole low

F. An

By W. B. HOYT and R. H. CAUGHEY

Introduction

High Temperature Metal Deterioration

In Atmospheres Containing

Carbon-Monoxide and Hydrogen\*

ETAL DETERIORATION may V occur in many forms which can be divided into two general categories. The first consists of irreparable impairment to one or more physical characteristics caused by changes to the metal's structure; the second category is metal loss from the exposed surfaces caused by corrosion or erosion, or a combination of both. Deterioration as described in this article belongs in the second category.

Metal loss usually results from chemical reaction between metal and its surrounding environment. Product of the reaction may be soluble in the environment, for example, attack by acidic solutions, or scales may be formed as when steel is exposed to air at elevated temperatures. In either case; rate of metal loss will be accelerated by velocity effects which tend to remove the reaction products and provide fresh, full strength reactants.

Metal loss also can occur as the direct result of attrition caused by impinging particles or rubbing parts which tear and abraid the metal surface. Although this type physical attack does not depend on corrosion, a combination of erosion and corrosion probably will be more destruc-tive than either effect in the absence of the other.

The type deterioration described here does not appear to fit the generally accepted corrosion mechanism by chemical attack or erosion by particles. In this case the metal has been attacked in gas mixtures whose constituents, taken singly, are known to be non-corrosive at the given pressures and temperatures. These gases are primarily hydrogen, carbon-monoxide, steam and methane with small percentages of carbon-dioxide, nitrogen and heavier hydrocarbons.

This article describes this particular type of metal deterioration, which is taking place in a plant producing gasoline from coal by the Synthol process.


### Plant Description

The plant in which this metal deterioration is occurring was designed to convert coal to gasoline and various petrochemicals. The plant consists of several units wherein the different process steps are carried out. The unit of primary concern in this article is the reforming unit in which gas is prepared for synthesis reaction to form gasoline and related hydrocarbons. Figure 1 is a generalized flow plan of the affected equipment with the gas compositions, average temperatures and pressures. Gas compositions are shown as percentage ranges because the unit has been operated under slightly varying conditions to accommodate varying feed gas composi-tions and to obtain varying end point requirements. It has not been found practicable to explore the effects of variations within these ranges on the rate of metal attack. So far as is known, attack may occur under all or only selected balances of gas composition within these

### General History of Deterioration

Metal loss in this system was first discovered after about 3000 service hours at the hot end of Type 310 stainless steel tubes in secondary preheaters. The attack was inside the tubes exposed to feed gas with tube metal temperatures approximately 1200 to 1300 F. Stainless steel (25 percent Cr-20 percent Ni) plate linings in the hot outlet header of these same preheaters were severely pitted. However, no evidence of attack was observed on the hot transfer lines of Type 304 stainless steel between the secondary preheaters and reforming reactors exposed to the same atmospheric and temperature conditions. Also, the hard facing trim of the block valve plugs in these transfer lines was severly washed or eroded. This hard facing was of a foreign composition containing cobalt.

This unit contains five parallel systems



ON	1	т		S	o	Ρ	м	0	C	AS	G
-	•	-	-	-	-	-	_	-	_	_	-
	-	_	-	-	_	_	_	_			-

	FEED GAS - STEAM	PRODUCT GAS
H <sub>2</sub>	35.0 - 48.0	47.0 - 48.0
CO	13.0 - 20.0	14.0 - 17.0
COE	0.8 - 3.0	5.0 - 7.5
CH4	10.0 - 18.0	4.0 - 6.0
Cg - C4	0.0 - 3.0	0.0
Ng	0.5 - 4.0	0.5 - 4.0
HEO (STEAM)	20.0 - 24.0	19.0 - 30.0
S	ABSENT	ABSENT

Figure 1—Generalized flow plan of equipment subject to metal deterioration.

#### Abstract

Abstract
Carbon steel and stainless steel equipment exposed to gas mixtures rich in hydrogen and carbon-monoxide at temperatures from 800 to 1200 F have been attacked with resulting loss of metal. Conditions under which this attack has been observed in a coal-to-oil synthesis plant and the nature of metal deterioration are described. Mechanism of this type attack is not fully understood although a possible gas-metal reaction is postulated.

3.2.2





Hoyt

Cauahev

ROBERT H. CAUGHEY is chief metallurgist with the M. W. Kellogg Company, New York City. Formerly he was associated with the U. S. Steel Corp. and A. O. Smith Corp. He has a BS in metallurgical engineering from Pennsylvania State University.

W. B. HOYT has been materials engineer of M. W. Kellogg Company, New York, N. Y., for the past 15 years. He received his metal-lurgical training at Brooklyn Polytechnic Institute.

of preheaters and reactors to accommodate varying quantities of feed gas as the product of the preceding units in the train; consequently all the preheaters had been off and on operation several times. The original start-up and shut-down procedures included the use of air during heating and as part of the purge cycle; consequently, it was conjectured that attack might be caused by alternate carbu-rization and oxidation. The operating procedures were changed to use nitrogen instead of air while the equipment is at temperatures over about 500 F.

After about a year of additional operation, leakage of the stainless steel tubes in the primary preheaters led to the discovery that these were being internally attacked at the hot end, similar to the attack in the secondary preheater tubes. At the primary preheaters, feed gas composition is the same except that steam has not been introduced; the tube metal temperature is approximately 900 to 1000 F

For some time it was believed that no attack was being caused by the product gas from the reforming reactors. However, about the time that attack was discovered on the primary preheater tubes, a few carburized spots were observed on the stainless steel insulation shields in the secondary preheaters' shell side. Within the last year, the beginning of attack has been found on the outside surface of the tubes' hot end in the primary preheaters.

In addition to stainless steel deterioration under high temperature gaseous attack, severe metal loss also has occurred on carbon steel tubes in the synthesis gas furnace. Here the gas composition is the

<sup>\*</sup> Submitted for publication January 29, 1959. A paper titled "Metal Deterioration in Atmospheres Containing Carbon-Monoxide at Elevated Temperatures" presented at the 15th Annual Conference, National Association of Corrosion Engineers, Chicago, Ill., March 16-20, 1959. One of three papers on metal dusting sponsored by the ASTM-ASME Joint Committee on Effect of Temperature on Properties of Metals.

Decer

Res

and

wer

cert

test

tiat

and

a si

pri

and

sur

bur

uni

bou

inte

fac

of

to

sta

Th

the

ap

hea

me

do

obs

tio

sho

in

spec



Figure 2—Tube failures in 1½-inch O.D. by 12 gauge Type 310 stainless steel used in secondary preheater exchanger exposed to product gas. Metal temperature was from 1200 to 1300 F.



Figure 3—Pitting on inside surface of Type 310 stainless steel tubing in a secondary preheater exchanger, exposed to feed gas. Temperature range was 1200 to 1300 F.




Figure 6—Failure of Type 310 stainless steel tubing in a primary preheater exchanger exposed to feed gas with metal temperatures from 900 to 1000 F. Tubing section at lower right was safe ended with Type 302B stainless steel.




Figure 4—Pitting of Type 310 stainless steel plate lining in a secondary preheater exchanger's hot outlet header, exposed to feed gas.



Figure 5—Penetration failure of a Type 310 stainless steel tubing exposed to feed gas in a primary preheater exchanger. Tubing was 1½-inch O.D. by 0.123-inch wall thickness. Metal temperature was 900 to 100 F.

same as the reformer product gas except that most of the water content has been

### Metallurgical Examination

Many material specimens removed from the affected equipment have been subjected to metallurgical examination to determine the mechanism of the attack with particular reference to the possible relationship of chemical composition, microstructure and mechanical properties of the materials involved.

Description of Samples Used

condensed out.

Representative tube failures which were removed from the secondary preheater unit are shown in Figures 2 and 3. The tubing is 1½ inch outside diameter by 12 gauge minimum wall thickness of Type 310 stainless steel. Internally, they were exposed to the feed gas composition (Figure 1) and externally to the product or effluent gases. Metal temperature in the attack region was estimated to be from 1200 to 1300 F. Severe

pitting of the inside surface and general metal loss as evidenced by development of holes through the wall occurred at the downstream, or hot end, of many tubes after about 3000 service hours (4½ months). No evidence of attack by the effluent gases was observed on the external tube surfaces other than formation of light oxide scale which discolored or blackened the surfaces.

Figure 4 shows the stainless steel plate lining removed from the hot outlet header of the same preheater which contained the tubing described. This lining was exposed to the same atmosphere but at a lower metal temperature than was the tubing. Although the surface was severely pitted, the degree of general metal loss was not as severe. The weld metal in the plate joint was not attacked. Also, the attack generally was sporadic with heavy metal loss at some locations and little loss at others.

Figure 5 shows a tube failure in the primary preheater exchanger. These samples represented 1½-inch O.D. by 0.123-inch wall thickness Type 310 stainless steel tubes. The penetration failure of the tube wall shown in the top sample of Figure 5 occurred after about 1½-years' service. They were exposed to the same feed gas composition as the secondary preheater tubes except that steam had not been introduced. Metal temperature of the tubes in the attack area ranged from 900 to 1000 F, or about 300 F cooler than in the tubes which failed in the secondary preheater unit. The attack was localized at the downstream or hot end of this unit.

Figure 6 is a tube from the primary preheaters, similar to tubing in Figure 5, which was safe-ended with a short section of new tubing of stainless steel, (High Silicon, Type 302B) after the original Type 310 material failed. This safe-ended tube was in service only about 1700 hours or 2½ months when removal of the entire tube was necessary because of the serious attack immediately upstream of the safe end on the old section of Type 310 stainless steel. The latter sec-

tion, previous to safe-ending, had no apparent attack after about 10,240 service hours or 14 months. The excessive metal loss as evidenced by the marked wall thickness reduction and pitting of the Type 310 composition were in contrast with the behavior of the Type 302B safe-end material.

Probably more significant, however, is the fact that Type 310 tubing was free of any apparent attack for 14 months, but after only 2½ months more, the damage shown in Figure 6 was experienced. This, it is believed, suggests that either an incubation period of uncertain duration may be necessary before rapid and damaging corrosion of the type shown will occur, or because of operational changes the prevailing and higher metal temperature of the hot end was extended upstream relative to safe-end location. The Type 302B composition safe-end in this case showed only mild attack in the form of sporadic carburization and pitting after the short exposure. Accordingly, it is not possible to conclude at this stage that the Type 302B composition offers a satisfactory substitute to minimize the effects experienced.

Little or no damage was experienced on external tube surfaces exposed to the product gases (Figure 1). In the past year, however, pitting attack has been found on the outside surfaces at the downstream or hot-end of the tubes in the primary preheater. Figure 7 shows this condition.

Although attack of the exchanger tubes and linings exposed to the feed gas in the secondary preheater had occurred, no attack of the Type 304 stainless steel transfer lines from this unit has been observed. The hard facing trim on the block valve plugs of these lines however, which were found to be badly attacked, was a stellite-like composition of foreign origin and contained cobalt. Figure 8 shows a cross section through this part. Notable is the almost complete loss of the hard face material (top of photograph).

Vol. 15

eed gas pe 302B

no apservice metal l wall of the ontrast

S safever, is s free onths.

e, the

xperi-

s that

ertain

rapid

type

opera-

nigher

d was

fe-end

sition

mild

rburi-

expo-

ole to

Type

actory

xperi-

enced

to the

past

been t the

es in

shows

tubes

as in

urred,

steel

been

n the

vever.

cked.

reign

ire 8

part.

oss of

hoto-



Figure 7—Failure of Type 310 stainless steel tubing exposed to product gas in a primary preheater exchanger with metal temperatures from 900 to 1000 F.




Figure 8—Cross section through block valve seat ring showing deterioration of hard facing, cobalt bearing trim used in a secondary preheater exchanger's hot transfer piping, exposed to feed gas conditions.

Results of Examination

Microscopic examinations of prepared specimens of each sample, supplemented by chemical analysis, X-ray diffraction, and ignition spectrographic procedures were used in checking the samples. In certain cases, supplementary mechanical tests were completed to further substantiate the observed effects.

Microscopic examination showed that in every case the severe surface pitting and heavy metal loss was associated with a surface phenomenon determined to be primarily carburization. Figures 9, 10, 11 and 12 are representative examples of surface conditions observed. Surface carburization was sporadic rather than uniform and more pronounced in the boundary surfaces of the pits than in the intermediate or surrounding plateau surfaces. Figures 10 and 11 are examples of this condition. Figure 11 is believed to show the pit formation in its initial stage in a highly localized surface spot. This represents an area where pitting of the surrounding surfaces was not visibly apparent. Carbon diffusion from the heavily carburized outer surface into the metal matrix takes place along a predominantly intergranular path. Figure 9 is a typical example of this.

General microstructure of the material observed in specimens representing locations far removed from the surface showed mostly evidence of intergranular carbide precipitation only. In the tube



Figure 9—Photomicrograph of Type 310 stainless steel tubing's inside surface. Tubing was exposed to feed gas (1200 to 1300 F.) in a secondary preheater exchanger. Magnification 225X, Aqua Regia etch.




Figure 10—Photomicrographs of Type 310 stainless steel tubing exposed to feed gas (1200 to 1300 F) in a secondary preheater exchanger. Photo A is cross section, Magnification 5X, macro etched. Photo B is inside surface of tubing, microstructure, Magnification 45X, Aqua Regia etch.

samples from the secondary preheaters, this evidence was accompanied by sigma phase development. Figure 13 shows evidence of both structures. Presence of these phases was not unexpected for stainless steels exposed to these time and temperature conditions.

Chemical analysis on selected specimens confirmed that this effect was carburization. Sample drillings were taken from the I.D. surface of preheater tubing shown by photomicrographs in Figure 9. A similar analysis was completed on a new, unused spare tube. Results with particular reference to the carbon and nitrogen content are given in Table 1.

The high carbon content of the I.D. surface of the affected tubing is considered confirmation of the carburizing effect.

Supplementary X-ray diffraction and ignition spectrographic analyses on suitable specimens of these same materials, including carefully removed scrapings from the I.D. surfaces of affected tubing, failed to disclose the presence of unexpected or unusual residual elements in the base material composition which might be assessed as a contributing factor. No unusual corrosion compounds were found which might have been a clue to the attack mechanism. X-ray diffraction analysis showed only the presence of iron oxides on the surfaces. No chloride or sulphate was found.

Free bend tests and hardness explorations also were made on selected sam-





Figure 11—Photomicrograph of Type 310 stainless steel plate lining surface microstructure. Lining was used as hot outlet header in a secondary preheater, exposed to feed gas at 1200 to 1300 F. Magnification 225X, Aqua Regia eth.






Figure 12—Type 310 stainless steel exchanger tubing. Microstructure of inside surfaces. Aqua Regia etched showing (A) primary preheater and (B) secondary preheater.

TABLE 1—Carbon and Nitrogen Content of New Tubing and Tubing Affected by Carburization Attack

Element	New Tubing	I.D. Surface Affected Tubing
C	0.09%	0.83%
N2	0.072%	0.079%

ples of the affected material, and the results were compared with similar tests made on unaffected material. Affected areas were brittle and hard. With the I.D. surface in tension, bend tests failed with application of the load; with the O.D. surface of unaffected tubing in tension, 180-degree bending was possible without failure. Hardness of the inside surfaces ranged from a Brinell of 382 to 393, converted from Vickers micro hardness results. The unaffected tubing showed an equivalent Brinell of 205, considered normal for the manufactured tube product.

F

for

atm

Cor

and

staf

WO

Co

Tes

itie

tha

est

of

org

tha

est

lik

U.

ger

Zo

the

the

of

It

Ele

cid

at

Co

ou

M

rir

80

tra

he

di

the

m

zir

th

13

to

bo

G

St

na

m

ar

m 1: M le

M

th Ir




Figure 13—Microstructures of exchanger tubing made of Type 310 stainless steel in (A) primary preheater and (B) secondary preheater. Magnification 225X, Aqua Regia etched.

### Discussion of Possible Theories

The metal loss described apparently does not fit the generally accepted ideas of corrosion by chemical attack or erosion by particles. Unfortunately, it has not been considered practicable to study this deterioration in situ by varying operating conditions individually or by comparing the resistivity of many different materials under identical conditions.

Successful operation of the plant forbids any appreciable changes in the operating conditions, and the integrated nature of the units does not permit continuous operation under steady conditions of gas composition. Furthermore, the expense involved in shutdowns to change tube materials or to install and remove samples has limited experimentation with new materials. Some work has been done with the exposure of samples of various materials in the hot outlet header of the primary preheaters and a few tubes have been safe ended with high silicon bearing Type 302B, aluminized Type 304 and Incoloy 804. As yet there has been insufficient service time on these to permit definite conclusions.

Several theories have been advanced to explain this corrosion. It has been suggested that this is a form of acid attack caused by the entrainment of acidic constituents in the feed gas, which

is partially composed of re-cycled gas from the product recovery units. Before introduction to the reformer unit, feed gas is passed through a large water wash tower which reduces contaminants to a few parts per million. Some water mist possibly might be entrained in the gas which would evaporate on passage through the tubes of the primary preheater and deposit acid droplets on the hot surfaces. This theory is difficult to support because of the surface revealed by microexamination and because no corrosion products were detected on the tube surface.

Another theory is that the attack is the result of cyclic conditions in which the metal surface is carburized and then oxidized,1 the thought being that carburization will effectively tie-up the chromium content, thereby destroying the normal oxidation resistance of the stainless steel. Although this sequence of conditions may have contributed to initial tube failure in the secondary preheaters, it does not explain subsequent attack after air was eliminated from the operating cycle. Also, if direct carburization of the metals by the gas atmosphere is a factor, it might be expected that the entire tube surface would be uniformly carburized instead of at local spots associated with pits.

A third theory which is considered worthy of careful consideration is as follows:

Under certain temperature and pressure conditions, some metals and metallic oxides catalytically promote the reaction of  $2\text{CO} \rightarrow \text{CO}_2 + \text{C.}^{2,3}$  Three of the most active metals are Fe, Ni and Co; Cr and Mo are relatively inactive. The carbon resulting from this reaction is chemically active and, because it is formed at the surface of the metal, the carbon can readily combine to form the metallic carbide, thereby carburizing the metal structure. Carbon resulting from this reaction forms as threadlike filaments which contain within them nuclei of the metal carbide.<sup>4,5</sup>

Therefore, it seems reasonable to theorize that within certain ranges of gas composition, temperature and pressure the metallic container may catalytically participate in the decomposition of carbon monoxide, and thereby small metallic particles will be lifted from the surface by the forming threads of carbon which are fragile and easily carried away in the gas stream. Under borderline conditions, this catalytic activity may start at local points on the surface, thus resulting in pits as the catalytic activity spreads radially from the original point.

Only where this active reaction occurs is there carbon available to carburize the metal.

This theory seems to be supported by appearance of the tube's inside surface which reveals that the attacked area varies from pits in the cooler portion of the tubes to severe attack in the hotter portion where the individual pits merge. That each gas composition has its own optimum temperature range for attack is indicated by location of attack at different metal temperatures in the primary and secondary preheaters in which gas compositions vary because of the addition of steam between the two.

The catalytic aspects of this theory seem to be supported by the relative resistance of the different stainless materials in the secondary preheaters and transfer lines. The most severely attacked material was the cobalt bearing hard facing valve trim, yet Type 304 stainless valve bodies, transfer line pipe and replacement valve trim were not attacked. In comparison, the Type 310 plate lining in the hot outlet of the secondary preheaters was severely pitted. This lesser resistance may be ascribed to the greater nickel content which is not balanced by the slightly greater chromium content.

### Summation

This article describes an unusual type deterioration which has been experienced on stainless steel equipment exposed to atmospheres containing carbon-monoxide and hydrogen at temperatures from 800 to 1300 F. This deterioration has taken the form of pitting and general metal loss without the formation of adherent scales but accompanied by carburization of the attacked metal surface. A tentative theory to explain this form of deterioration has been offered for consideration.

### Acknowledgment

The authors wish to acknowledge with appreciation the cooperation of the company whose unhappy experience has made this article possible.

### References

- Harry K. Uhrig. High Temperature Corrosion of Metals Under Alternate Carburization and Oxidation. Trans Electric Soc, 91, 641, 154 (1941).
- 2. Walter Baukloh. Destructive Effects of Gases Containing Carbon Monoxide and Carbon Dioxide. Die Chemische Fabrik, 13, 101-104 (1940) March 23.
- A. Jullard. R. Rayet and A. Lunde. A. Kinetic Study of Dissociation of Carbon Monoxide Accompanying the Reduction of Metallic Oxides. University of Brussels, June, 1948.
- L. J. E. Hofer, E. Sterling and J. T. McCartney. Structure of the Carbon Deposited from Carbon Monoxide on Iron, Cobalt and Nickel. J Physical Chem, 59, 1153 (1955) Nov.
- Paul H. Emmett (editor). Catalysis, Vol. 4: Hydrocarbon Synthesis, Hydrogenation and Cyclization. Rheinhold Publishing Corp., 1956.

### Corrosion of Metals at Mandapam Camp, India\*

By K. S. RAJAGOPALAN, M. SUNDARAM and P. L. ANNAMALAI\*

### Introduction

Vol. 15

occurs ize the ted by surface

d area tion of hotter merge.

ts own

tack is

at .dif-

rimary

ch gas addi-

theory

ive re-

mate-

's and

tacked

rd fac-

ainless

nd re-

acked.

te lin-

ondary

lesser

reater

ed by ent.

l type

enced

sed to

oxide

n 800

taken

metal

perent

zation

tative

riora-

ation.

with

com-

rrosion

Gases on Di-(1940)

Cinetic de Ac-Oxides,

cCart-from Nickel.

ol. 4: n and 1956.

FIELD exposure has become a wellestablished method to study the performance of protective treatments and atmospheric corrosion problems. The Corrosion Committee of the British Iron and Steel Association has nearly 20 test stations located in different parts of the world. Corrosion is of interest to 12 Committees of the American Society for Testing Materials and field testing activities of this organization go back to more than 40 years. It is of considerable interest to India to know that a comparison of the corrosivity data collected by the organizations mentioned above has shown that the rate of corrosion of steel is highest in marine atmospheric testing stations like Kure Beach, North Carolina, U.S.A.; Lighthouse Beach, Lagos, Nigeria; and Christobal, Panama Canal Zone. The latter two sites are located in the tropics.

India has a 4000-mile coast line and the climate prevailing in three-fourths of the land may be classified as tropical. It is in this context that the Central Electrochemical Research Institute decided to set up a corrosion testing farm at Mandapam Camp on the Southeast Coast to enable rapid assessment of various protective schemes. The location of Mandapam Camp and the Central Marine Fisheries Research Station in whose 80-acre campus the test farm of the Central Electrochemical Research Institute is situated are shown in Figure 1. It may be seen readily that tropical marine conditions are likely to be experienced in the severest form at this location. The monthly rates of corrosion of mild steel, zinc and copper at two sites located at 150 feet and 1350 feet from sea during the period November 1957 to December 1958 are reported in this paper.

### Experimental

Description of Experimental Sites

1350 Feet Site: This is situated on the top of a hillock overlooking the sea on both sides. The site is 1350 feet from the Gulf of Mannar and one mile from Palk Strait. The wind direction is predominantly southwest and southeast for six months in the year (April to September) and northeast and northwest for six months (October to March).

150 Feet Site: The site faces the Gulf of Mannar and the stands are located on level ground 150 feet from the water.

Methods of Exposure of Specimens

Open exposure was carried out on Monel and aluminum stands similar to those at the Kure Beach station of The International Nickel Co.4 The stands were

★ Submitted for publication January 15, 1959.

\* All with Central Electrochemical Research Institute, Karaikudi, India.

#### Abstract

Abstract

Monthly rates of corrosion of mild steel, zinc and copper at two sites located 150 feet and 1350 feet from the sea are reported. Coupons were exposed in under both open and sheltered conditions on racks oriented at 45 degrees facing south. Climatic conditions at the Mandapam Campsite are discussed in detail and means of keeping the records reported. Rates of corrosion of the test samples are discussed in relation to the observed climatic conditions. Differences between the open and sheltered tests are compared. Among the conclusions: There is no direct relation between the corrosion rate, distance from the sea and atmospheric salinity, although salinity is an important factor in the rate. Highest rates were observed in months with high mean temperature and accompanying high average humidity and salinity. 2.2.2

held at 45 degrees south as in the case of exposure of painted metal. The bottom end of the specimen frame was 2 feet nine inches from the ground. The specimens were supported by porcelain cleats which prevented contact with the metal frame.

Stevenson screen was used for the sheltered exposure. The Stevenson screen is a wooden box with a double roof, double louvered sides and slated bottom. It is a standard piece of meterological equipment<sup>5</sup> in this country and in the United Kingdom and has been widely used by the Corrosion Committee of Britain in its studies.6 It allows free circulation of air inside the box but entry of rain water is completely prevented. It is placed four feet from the ground on wooden legs. Both the small screen with internal dimensions 221/8 inches, x 123/8 inches x 163/8 inches and the larger screen (53 x 123/8 x 163/8) were used in the present studies.

Preparation and Cleaning of Specimens

Specimens measured 6 x 4 x 1/16 inch. They were abraded initially with O emery till a uniform finish was obtained. After abrasion, the specimens were degreased in methanol, hot benzene and acetone. Every exposure was carried out in duplicate and the mean of the two values which did not vary between themselves by more than 10 percent, was considered. The corrosion product of mild steel was removed by immersion in Clarke's solution for a period varying from 1 to 5 minutes depending upon the amount of rust formed. Care was taken to see that excess of stannous chloride was present and the solution did not turn yellow during derusting. The corrosion product on zinc<sup>8</sup> was removed by dip-ping for 1 to 2 minutes in sulfate-free chromic acid at 80 C and that on copper<sup>9</sup> by immersion in cold 5 percent sul-furic acid for 5 to 6 minutes. The weight losses obtained were corrected for blank loss. The chromic acid bath was discarded when it showed high blank losses following accumulation of chloride in the bath. Steel specimens were cut from



Figure 1-Location of Mandapam Camp.

mild steel sheets supplied by Tisco (C - 0.1 to 0.2, Mn - 0.4 to 0.5, phosphorus - 0.3 - 0.8, and sulfur 0.02 to 0.03) zinc from commercially pure (99.8) zinc and copper from sheets of commercial purity.

Determination of Atmospheric Salinity

The wet candle method described by Ambler<sup>2</sup> in which destarched surgical bandage is wrapped around a glass tube having an outside area of 1 sq.dm. and the two ends dipped in distilled water contained in a litre flask was employed.

### Results and Discussion

Climatic Conditions at Mandapam Camp

Monthly averages of maximum and minimum temperatures, relative humidity, wind velocity and rainfall are shown in Figure 2. The meterological station which supplied this data is located on a hillock on the other side of the 2 mile long Pambam Bridge shown in Figure 1. Owing to the nearness of the sea to both the places, it is not expected that there will be significant differences in regard to the climatic conditions at the two places. Common climatic conditions at the meterological station and at the test sites has, therefore, been assumed and the results interpreted on this basis.

It is seen from Figure 2 that the average maximum temperature increases from 80 F in December, 1957, to 90 F in April, 1958 and falls during the latter part of the year. The difference between the maximum and minimum remains fairly steady around 9 F (5 C). The average relative humidity remains above 75% which is where sodium chloride becomes hygroscopic. The constant difference in maximum and minimum of 9 F and the prevalence of average humidities above 75% show that during most days in the

Dece

will

of sa

been

Rate

Zinc

The

steel.

unde

giver

rom

rate

gm/

in I

n<sup>2</sup>/

alls

rate

steer

cond

the

und

in t

fron

peal

It d

Sep

Iun

read

gm

stee

zino

shel

mu

obs

stee

0.04

hill

tair

exp

per

ma

lar

diti

diff

the

is 1

diff

con

exp ble val

ros for sha two fled the bet

the ava the spe fas

in




Figure 2—Year's cycle of climatic conditions at Mandapam Camp.

TABLE 1—Climatic Conditions at Pamban
Compared With Two Tropical Testing Sta-

	Ave	rage p. °F	Average	Total Rain	
Station	Max.	Min.	(%)	(in)	
Lighthouse Beach, Lagos Christobal Pamban	87 84 85	77 77 79	86 82 80	17.8 130 49*	

<sup>\*</sup>Nov. 57-Oct. 58.




Figure 3—Atmospheric salinity recorded at two sites under sheltered and open conditions.

year there must have been several hours in which moisture condensation was taking place on the metal surface. The period would have been longer during months showing higher average humidity.

The 49 inches of rainfall at this station is distributed within three months during the year under consideration. It is seen that the wind velocity steadily falls during January to April when the northeast monsoon winds which began during the previous year subside and rise to a peak value in June with the onset of southwest monsoon winds. It falls in the subsequent months and again rises when the northeast monsoon winds set in for the year. Climatic conditions at this site are compared with those of Lagos, Nigeria and Christobol, Panama Canal Zone in Table 1. It is readily seen that the conditions at this site bear close resemblance to the other two tropical sites.

Atmospheric Salinity at Mandapam Camp

The part played by atmospheric salinity in corrosion at sea coast locations has been extensively considered by Ambler.<sup>2</sup> After investigating various methods for the determination of atmospheric salinity. Ambler came to the conclusion that better correlation could be obtained between salinity determinations made by the wet

candle method and corrosion than in methods where the salt content per cubic meter of air is determined. This method is also more relevant to corrosion studies as it measures the total quantity of salt deposited on a given surface area. He has, however, shown that moisture condensed at the dew point has invariably a high salinity value and shows little variation with distance from sea, the salinity at distances as much as 500 miles from sea being not very different from that obtained on the seashore itself. Thus. under conditions in which dew formation is a daily feature, a simple relationship between salinity and distance from sea may not be obtained. The wet candle method has been employed for the determination of salinity in the present study for the same reasons as pointed out by Ambler.

The variation of atmospheric salinity at the two sites under sheltered and open exposure conditions are shown in Figure 3. It is seen from this figure that a salinity value of 2200 mg/m<sup>2</sup>/day is recorded under open exposure conditions at the shore site in July and August, when the measurements were first made at this site. It falls steeply in September to the comparatively low value of 360 mg/m<sup>2</sup>/day, which further decreases to 38 mg/m<sup>2</sup>/day in December. At the hillock site under open exposure conditions, it is seen that it is approximately 1/10th that at the shore site in August, shows a steep fall in September as in the case of shore site but increases in December when the northeast monsoon winds became strong as shown by the wind velocity data (Figure 2). Under sheltered conditions, the salinity at the two sites is almost the same. This shows that the louvered sides of the Stevenson screen, or for that matter any other barrier, forms a very effective shield limiting the number of salt particles that would otherwise be deposited on the wet candle. Those that are deposited are apparently so fine and so easily carried by wind that they are present in approximately the same extent over a considerable distance from sea. Salinity values obtained at the two sites will then be the same. Variation of salinity figures in different months under sheltered conditions arises from variations in the total quantity of such fine mist in the air. This variation

TABLE 2—Monthly Rate of Corrosion of Mild Steel

	Rate of Corrosion in gm/sq dm								
	1350-ft Sit	e (hillock)	150-ft Site (shore						
Months	Sheltered Exposure	Open Exposure	Sheltered Exposure	Open Exposure					
November, 1957 December, 1957 January, 1958 February, 1958 March, 1958	0.065 0.085 0.047 0.11	0.27 0.125 0.09 0.14							
April, 1958. May, 1958. June, 1958. July, 1958. August, 1958.	0.06 0.23 0.33 0.26 0.18	0.06 0.35 1.16 0.52 0.67	0.15 2.17 0.8 0.54 0.52	4.57 4.0					
September, 1958 October, 1958 November, 1958 December, 1958	0.13 0.17 0.11 0.09	0.55 0.39 0.37 0.16	0.43 0.13 0.1 0.04	3.9 1.84 0.94 0.31					

TABLE 3—Monthly Rate of Corrosion of Zinc

	Rate	Rate of Corrosion in gm/sq dm							
	1350-ft Sit	e (hillock)	150-ft Site (shore)						
Months	Sheltered	Open	Sheltered	Open					
	Exposure	Exposure	Exposure	Exposure					
November, 1957 December, 1957 January, 1958 February, 1958 March, 1958	0.004 0.007 0.002 0.001 0.006	0.05 0.11 0.02 0.005 0.03							
April, 1958.	0.002	0.1	0.002						
May, 1958.	0.01	0.19	0.32						
June, 1958.	0.02	0.3	0.09						
July, 1958.	0.04	0.21	0.06						
August, 1958.	0.04	0.22	0.15						
September, 1958	0.18	0.19	0.24	1.05					
October, 1958	0.02	0.1	0.01	0.33					
November, 1958	0.006	0.13	0.003	0.13					
December, 1958	0.002	0.04	0.002	0.04					

han in er cubic method studies of salt ea. He re conrariably

Vol. 15

s little ea, the 0 miles t from mation ionship om sea candle detert study out by

salinity

d and

own in re that day is ditions August, made tember of 360 ases to At the condimately August, as in ases in onsoon by the

Únder at the shows venson er barmiting would candle. arently wind mately le dis-

tained same. fferent arises tity of riation

ore) pen osure

will not be as pronounced as in the case of salinity figures obtained under open exposure conditions, which is what has been observed.

### Rate of Corrosion of Mild Steel, Zinc and Copper

The monthly corrosion rates of mild steel, zinc and copper at the two sites under open and sheltered conditions are given in Tables 2, 3 and 4. It is seen from Table 2 that the monthly corrosion rate of steel reaches a value of 4.57 gm/sq dm at the shore site in the open in July, when a salinity of 2200 mgm/ m2/day was recorded.

This high corrosion rate is maintained n August and September after which it falls steeply to a value of 0.3 gm/sq dm in December. The monthly corrosion cates of zinc and copper also show a steep fall from September under these conditions. At the hillock site, for which the data are complete for the period under consideration, the corrosion rates in the open are comparatively low and are less than 0.15 gm/sq dm up to May from which month it steeply rises to a peak value of 1.15 gm/sq dm in June. It does not change much during July to September though it is lower than in June. It falls again in October and reaches once again a value of 0.16 gm/sq dm in December. This behavior of steel during the different months appears to be almost completely reproduced by zinc and copper (see Figure 4). Under sheltered exposure conditions, a maximum corrosion rate (2.2 gm/sq dm) is observed at the shore site in May for steel. It falls in the next six months to 0.04 gm/sq dm in December. At the hillock site, where the data are complete, a maximum (0.33 gm/sq dm) is obtained in June as in the case of open exposure but the rise and fall during the period April to September is not so marked. The behavior of copper is similar to that of steel. Under sheltered conditions, the behavior of zinc is somewhat different. At both sites, a sharp rise in the corrosion rate of zinc in September is noticed.

Changes in salinity values during the different months under study have been considered earlier. They do not follow the changes in corrosion rates under open exposure conditions as closely as Ambler's data indicate. The higher salinity values during December 1957 and December 1958 are not reflected in the corrosion rates of steel at the hillock site, for which both data are available. The sharp fall in salinity at the two sites between August and September is not reflected in the corrosion rates of any of the metals studied. The proportionality between salinity, distance from sea and corrosion rate appears to be observed only in July. Under sheltered conditions, it is seen that the salinity values at the two sites do not differ significantly for the months for which these data are available for both sites. Yet, corrosion at the two sites differs considerably, with specimens at the shore site corroding faster.

There is, however, some similarity be-




Figure 4—Rates of corrosion of mild steel, zinc and copper, by months, under sheltered and open exposure conditions at 1350 ft. site.

### TABLE 4-Monthly Rate of Corrosion of Copper

	Rate of Corrosion in gm/sq dm							
-	1350-ft Sit	e (hillock)	150-ft Site (shore)					
Months	Sheltered Exposure	Open Exposure	Sheltered Exposure	Open Exposure				
November, 1957 December, 1957 January, 1958 February, 1958 March, 1958	0.003 0.001 0.003	0.01 0.01 0.013						
April, 1958. May, 1958. June, 1958. July, 1958. August, 1958.	0.002 0.01 0.03 0.035 0.02	0.006 0.09 0.21 0.1 0.09						
September, 1958. October, 1958. November, 1958. December, 1958.	0.015 0.016 0.007 0.003	0.11 0.06 0.02 0.015	0.02 0.01 0.005 0.003	0.31 0.14 0.07 0.03				

T

of ·

che

all

ant

wri

req

wo

ticl

me

at

ser

cor

tor

cor

du'

Fer

tio

and

get

of

cia

tio

Ha

use

mo

oth

Be

ab

ch

rig

ap

sti

tie

OV

di

5-

la m 00 th

d

### -Quarterly and Yearly Corrosion Rates of Metals at Mandapam Camp (1350 Ft. From Seg)

	Rate of Corrosion in gms/sq dm												
	January 58	-March 58	April 58-	June 58	July '58-Sep	otember '58	October '58-	December 58	1958 3	early			
Metals	Sheltered	Open	Sheltered	Open	Sheltered	Open	Sheltered	Open	Sheltered	Open			
	Exposure	Exposure	Exposure	Exposure	Exposure	Exposure	Exposure	Exposure	Exposure	Exposure			
Mild SteelZincCopper	0.24	0.36	0.29	1.56	0.84	1.7	0.61	0.76	1.12	7.17			
	0.01	0.04	0.03	0.45	0.04	0.45	0.02	0.12	0.16	0.48			
	0.004	0.03	0.05	0.31	0.11	0.33	0.035	0.066	0.42	0.7			

tween the salinity curve and the corrosion curve at the hillock site especially for the period April to September. Ambler concluded from his study of corrosion along the seacoast in Nigeria that salinity is the determining factor in the corrosion of metals in the tropics. Data collected at Mandapam Camp indicate that while salinity is undoubtedly an important factor in determining corrosion rate under high salinity conditions, its effect can become overshadowed by weather conditions. In this connection, the work of Ellis<sup>10</sup> on the part played by weather conditions at the time of initial exposure in determining the corrosion rate of zinc and Larrabee's11 observation that weather conditions should also play a part in determining the rate of corrosion of steel has much interest to this work.

Results given in this paper clearly bring out the important role played by weather conditions. A maximum is reached in the case of every metal considered at both sites during those months when the weather conditions represented by humidity and mean temperature values as well as atmospheric salinity are most propitious for increased corrosion. While considering the meterological data, it was pointed out that the constant difference in maximum and minimum temperature values and the existence of humidities higher than 75 percent during most months indicate that in the months in which higher average humidity values are recorded, it is probable that moisture condensation periods due to temperature gradients also are longer. Field studies in the United States have shown that the duration for which moisture condensation takes place is an important factor governing the corrosion rate.12 Maximum corrosion rates at the present site are observed only during June to August, though humidities similar to those occurring during those months also are recorded during October to December. The increase in corrosion rate in June is much greater under open exposure conditions when the metal specimens are directly exposed to sunlight than under sheltered exposure conditions. The important part played by a small increase (7 F) in ambient temperature in the enhancement of the corrosion rate at this site is thus brought out.

It was mentioned earlier that there is an increase in the corrosion rate of zinc in September at both sites which is not readily understood. It is probably related to the air becoming stagnant under sheltered conditions when the southwest wind stops blowing and the northeast wind has not started. That this is so is indicated by the steep fall in salinity values between August and September at both sites as well as wind velocity data.

Experiments carried out in this laboratory have shown that under restricted circulation of air flow, the rate of corrosion of zinc increases sharply13 at high humidities. A considerable increase in white rust formation on zinc under storage conditions also was noticed during the last war.14

The quarterly and yearly corrosion rates at the hillock site for which the data are complete are given in Table 5. It may be seen from this table that the pattern of corrosion indicated by the monthly data are corroborated by the quarterly data for the same periods. The corrosion rate is highest during the period July-September in the case of all the metals and least during January-March. The data also show that the year can be conveniently divided into two periods April-September and October-March, the corrosion rate of steel in the former period being three times that during the latter under open exposure conditions. An average corrosion rate of 0.6 gm/sq dm/month under open exposure conditions and 0.09 gm/sq dm/month under sheltered conditions are recorded at this

### Conclusions

1. It has been shown with the help of meteorological data and monthly corrosion data for mild steel, zinc, copper and aluminum that very high corrosion rates comparable to those obtained at Lighthouse Beach, Lagos are obtained at the Mandapam Camp Testing Farm and that this test farm is, hence, eminently suitable for testing under tropical marine conditions.

2. There is no direct relationship between corrosion rate, distance from sea and atmospheric salinity as determined by the wet candle method, as pointed out by Ambler. Salinity is, however, found to be an important factor in determining the corrosion rate under oper exposure conditions.

3. A small increase in mean temperature causes considerable acceleration in the corrosion rate in the open when accompanied by both high humidity and salinity. The highest corrosion rates are observed in the months in which high mean temperature is accompanied by high average humidity and high salinity.

4. While there are some variations in the behavior of steel and zinc under similar conditions, the behavior of steel is paralleled by both zinc and copper though at lower corrosion rates. Copper appears to be more suited among nonferrous metals for the study of atmospheric corrosivity at sea-coast locations.

### Acknowledgment

The authors are thankful to the Regional Meteorological Centre, Madras for supplying them with meterological data, Dr. S. Jones, Chief Research Officer, Central Marine Fisheries Research Station, for providing the necessary facilities for carrying out the above study and Dr. K. S. G. Doss, D.Sc., FRIC., F.Inst. P., F.A.Sc., FNI, Director, Central Electrochemical Research Institute, for his encouragement. Thanks of the authors are also due to Shri G. Ramaseshan, Senior Laboratory Assistant, Central Electrochemical Research Institute for his assistance in the initial stage of the above investigation.

### References

- 1. F. L. LaQue, Proc. Amer. Soc. Test. Mat., 51, 495 1951).
- H. R. Ambler, and A. A. J. Bain. J. Appl. Chem., 5, 437 (1955).
   B. W. Forgeson et al. Corrosion, 14, 73t (1958).
   F. Champion, Corrosion Testing Procedures, published by Chapman and Hall (1952) p. 171.
   Meterological Handbook, published by the Indian Meterological Department, Government of India.
- dian India
- J. C. Hudson. Trans. Farad. Soc., 25, 177 (1929). Clarke. Trans. Electrochem. Soc., 69,
- 7. S. G. Cla 131 (1936). 8. E. A. Anderson, and C. E. Reinhard. Proc. Amer. Soc., Test. Mat., 39, 691 (1939).
- Amer. Soc., 1 est. Mat., 39, 691 (1939).

  9. B. B. Knapp. Corrosion Handbook, John Wiley & Sons (1952). 1077.

  10. O. B. Ellis. Appendix to Report of Committee B-3. Proc. ASTM 49, (1949) 152

  11. C. P. Larrabee, Corrosion, 9, 259 (1953)

  12. C. P. Larrabee. Trans. Electrochem. Soc., 87, 161 (1945)

- K. S. Rajagopalan and G. Ramaseshan. Jour. Sci. Ind. Res. 18B, 87, (1959)
   K. G. Compton. Trans. Electrochem. Soc., 91, 705 (1947)

### Polyester Fiber Glass Equipment\*

By ROBERT E. BARNETT and THOMAS F. ANDERSON

### Introduction

Vol. 15

Open posure

7.17 0.48 0.7

r oper

mpera-

tion in

en actv and

tes are h high

ed by

alinity.

ons in

r simi-

teel is

copper

Copper g non-

atmos-

ations.

e Re-

ras for

data,

officer,

Stafacili-

y and F.Inst.

Elec-

or his

uthors

eshan.

entral

e for

of the

at., 51,

Appl.

(1958).

edures, b. 171. he In-ent of

, 177

., 69,

Proc.

Wiley

mittee

3) c., 87,

Jour.

., 91,

NO MAKE data contained in this article representative of the wide use of polyester fiber glass equipment in the chemical, petroleum and allied industries, all major producers of corrosion resistant polyester fiber glass equipment were written to in the summer of 1958. A request was made for information they would like to have included in this article, to include pictures of the equipment, descriptions of construction, time at which the equipment was installed, service conditions to which subjected and conditions now. Pictures and case histories included in this article consist of contributions from Corite Products, Inc., duVere, Inc., Schori Process Division of Ferro Corporation, and Haveg Corporation. All of those contributing pictures and service histories found it difficult to get current information on the condition of some items. The authors will appreciate being advised of incorrect informa-

Over 200 commercially available polyester resins have been screened in the Haveg laboratories to determine their usefulness in corrosive applications. While most differ in varying degrees from others, it is possible to group all of them

into five broad categories:

Highly chemical resistant ......Type B Standard chemical resistant . . . . . . . . . . . . . . . . . Type C Food grade and solvent resistant . . . . . Type D Fire resistant, chemical resistant.....Type E

Because large differences exist in the ability of different polyesters to resist chemical attack, it is important that the right polyester resin be chosen for an application. Also, because proper construction and cure are essential for good quality, it is important to select a qualified fabricator.

### Resistance Table Provided

To assist in the selection of the proper type of polyester for a chemical application, chemical resistance tables with over 5,000 ratings are given in the appendices. These tables were compiled over a 5-year period from a combination of laboratory tests and field service information. At the beginning of the first table is a discussion explaining suggested methods of using the table. It will be noticed that the ratings in this table are broken down into recommendations for tank

★ Submitted for publication February 27, 1959. A paper presented at the Fifteenth Annual Conference, National Association of Corrosion Engineers, Chicago, Ill., March 16-20, 1959.





ROBERT E. BARNETT is plant manager at Haveg Industries, Inc., West Warren, Mass. Formerly he has done research for Socony Mobiloil and Lunn Laminates. He has a BS in industrial chemistry and a MS in physical chemistry from the University of Maryland.

THOMAS F. ANDERSON is director of re-search and development at Haveg Industries, Inc., Wilmington, Delaware. Formerly he was associated with Libbey-Owens-Ford Glass, Rohm & Haas Co., Redstone Arsenal Re-search Division and a National Defense Re-search Committee. He has a BS in chemistry from Ohio University.

service and recommendations for use in open hoods and connecting ductwork. Proper ratings for systems of closed hoods and closed-connection ductwork normally would fall in between the ratings shown for tanks and for open hoods. The data in this table are, of course, subject to revisison as additional field information becomes available. Any having service information on polyester fiber glass equipment which will extend or amend this table are urged to send it to the authors.

It has been found that polyester fiber glass structures are more rapidly attacked by corrosive environments when highly stressed, so it is particularly important to use proper construction in fabrication. Table 1 shows some representative properties of different constructions frequently used in the manufacture of chemical resistant equipment. Experience has now shown that a minimum of 5 to 1 safety factor over the measured physical properties of polyester fiber glass laminates is required in the design of equipment which will continue to give long, satisfactory service. As service conditions become more severe, both with regard to temperature and to corrosive characteristics, it is necesary to increase this safety factor to as much as 12 or 15 to 1.

In the discussion which follows, equipment is divided into classes, with the pictures of several units in each class. The equipment and the specific service conditions are described.

Abstract

Abstract

Polyesters used in situations where their chemical resistance is important are grouped into five types for convenience in considering their value under attack by industrial corrosives at varying temperatures. Data were compiled from information supplied by four of the major producers on polyester ducts, hoods and tanks as were I7 illustrations of equipment. Pictured equipment is described, environment indicated and durability reported. Corrodents involved include sulfonated fish oil, acidified oils, HCI containing benzene, nitric acid, hydrochloric acid and fumes, plating solutions, sulfuric acid and others at varying temperatures. Some of the characteristics of and reasons for using lined equipment are given.

of and reasons for using lined equipment are given.

The appendix consists of four tables in which polyesters are rated for service as open hoods and connecting ductwork and for tanks against a wide variety of industrial corrosives, plating solutions pickling and dipping solutions and stripping solutions. Over 5000 ratings are given as excellent, good, fair, poor and not recommended at temperatures of 80 F or less, 212 F or boiling point of solution, if lower; 160 F. 180 F. 6.6.8

### Uses for Lined Equipment

Occasionally for tanks, towers, covers, hoods, stacks and fume scrubbers, because of the rigidity required or because available equipment has sufficient strength but insufficient chemical resistance, it becomes economical to use polyester fiber glass lined equipment.


Because only the linings have corrosion resistance that solid polyster fiber glass tank has, the chemical resistance rating for a lining would fall somewhat below that given in the appendix. In general, in tank sizes in excess of 20,000 gallons, where the lined tank will satisfactorily handle the chemical applications, a cross-over point is reached in the economic considerations. In the construction of rectangular tanks, because of the high cost of stiffening the sides, or because of mechanical loads, linings sometimes are more economical for even small tanks.

The wall of a 55-foot diameter x 12foot deep, 200,000 gallon concrete tank after three years' service in '37 percent formaldehyde at 80-90 F in some areas had been eaten away as deeply as 6 or 7 inches and extensive repairs were required before application of a polyester fiber glass lining. Figure 22 shows this tank after being lined with polyester fiber glass. The tank shows no sign of attack after almost two years.

The extensive history now available on the use of polyester fiber glass equipment in the chemical, petroleum and allied industries, includes reports of an impressive array of successes and also examples of failures. Information gathered underlines the need for selection of the proper polyester and of putting polyester fiber glass constructions into the areas where they are best suited. It would appear that, based on the economics, greater use of polyester fiber glass equipment seems to be justified.

Many misunderstandings and misconceptions about polyester fiber glass equipment have been, or are being corrected, for example:

1. It no longer is the belief that the term 'polyester fiber glass' denotes one material. It is generally realized that the term denotes a family of materials with widely differing properties, so, all poly-



11

Figu Poly rubb F w

Figu este ben: stal

Figu Rass fibe ing Figu D x scru mix

Figu synt fum

Figu two tem

Figures Figures

Figu Fum 19 Figu Rep Vap H<sub>2</sub>So

Figure Figure Vap




Figure 1—Cylindrical tank, 10 x 10 feet, polyester fiber glass, 5-1 safety factor, 160 F. Neutralization of sulfonated fish oils. Violent agitation. Installed Nov. 1953, no sign of attack after 5½ years, still translucent.

Figure 2—Rectangular tank, 10 x 14 x 4 feet deep. Polyester fiber glass sheet lined steel. Built-in foam rubber expansion strips allow for differential. 150 F washing of acidiffed oils. Installed Feb. 1954, no attack after 5 years.

Figure 3—Cylindrical tank, 12 D x 17 feet, polyester fiber glass. Storage byproduct HCl containing benzene, 120-180 F. Outdoors, Southwest USA, installed Sept. 1956, no attack after  $2\frac{1}{2}$  years; some external discoloration.

Figure 4—Fume scrubber, tower 5 D x 10 feet, Raschig rings and support plates all of polyester fiber glass. 6500 cmf HNO<sub>3</sub> fumes and air. Incoming air approx. 200 F. Install Aug. 1956, no s:gn of attack after 2½ years.

Figure 5—Fume scrubbers packed towers. 42 inches D x 16 feet, polyester fiber glass. Interchangeable scrubbing of HCl and NH3. No visible fumes in mixed effluent. Installed May 1956, no sign of attack after 23/4 years.

Figure 6—Fume scrubber, 3 D x 15 feet, polyester synthetic lined polyester fiber glass. Scrubbing HF fumes. Installed April 1955, condition excellent after 4 years.

Figure 7—Cover 23-foot diameter, dished, made in two sections for shipping, polyester fiber glass. Room temp storage HCI. Installed Jan. 1957, condition excellent after 2 years.

Figure 8—Cover, flat, uncored, ribbed, approx., 14 feet D. Supports wooden stack with steel ribs, polyester fiber glass. Magnesium chloride reactor, installed 1958, condition unknown.

Figure 9—Hoods and tank, polyester fiber glass. Precious metal plating, temp. ambient to 200 F. Installed Dec. 1954, condition excellent after over 4 years.

Figure 10—Hood and fan. Hood 22-foot, undraft fan 36 D propeller type, polyester fiber glass. Fumes from 6% H<sub>2</sub>SO. at 21 F. Installed Dec. 1955, condition excellent after over 3 years.

Figure 11—Ductwork, 24-inch, polyester fiber glass. Replaced Monel duct that failed in two years. Vapors from oleum guench containing approx. 30% H:\$O<sub>4</sub>. Installed 1954, condition excellent after 3

Figure 12—Ductwork, 12 to 18 inches, polyester fiber glass. Removal of wide variety pickling and plating solution fumes. Installed 1954, condition excellent after 5 years.

Figure 13—Ductwork, 30-inch, polyester fiber glass. Vapors from warm acid drip; Hs504 and HCl at 140-160 F. Installed July. 1954, condition excellent after 5 years. Figure 14—Stack, 30-inch, polyester fiber olass. Fumes from 4% and 12-15% HNO<sub>2</sub> at 115 F. Installed July, 1954, condition excellent after 5 years.

Figure 15—Stack, 5, 6 and 7½-foot x 80 feet polyester fiber glass lined steel. Removal of fumes in refining of fissionable material. Installed Oct., 1957, condition excellent after 1½ years. Figure 16—Fume scrubber, 7 x 7 x 18 feet, polyster fiber glass. Scrubbing fumes from wire pickling line. Installed Dec., 1956, condition excellent after over 2 years.

Figure 17—Press box, 4 x 4 x 18 feet, polyester fiber glass and steel. Storage and handling acid-containina dye cake at temp. up to 180 F. Installed Nov. 1956, condition varied from excellent to charred in cases when sulfuric acid concentration exceeded 90 percent.

### TABLE 1—Physical Properties of Polyester Fiber Glass Laminates and Cold Rolled Steel

STRENGTH PROPERTY	CHOPPED STRAND MAT 20% glass 80%poly-	COMPOSITE CONSTR.	WEAVE	2-I ORIENTED WEAVE WOVEN ROVING 55% glass tested in strongest direction	PLAIN COLD ROLLED STEEL
TENSILE P. S. I.	8,000	8,000 to 30,000	21, 000	30,000	30,000 - 50,000
COMPRESSIVE P. S. I.	30,000	30,000	30,000	30,000	30,000 - 50,000
FLEXURAL P. S. I.	14,000	14,000 to 30,000	24,000	30,000	30,000- 50,000
FLEXURAL MODULUS P. S. I.	7 x 10 <sup>5</sup>	7 x 10 <sup>5</sup> to 2.5 x 10 <sup>6</sup>	1.5 x 10 <sup>6</sup>	2.5 x 10 <sup>6</sup>	30 x 10 <sup>6</sup>
INTER- LAMINAR SHEAR STRENGTH P. S. I.	2,000	2,000	1,800	1,800	20,000 - 40,000
% OF ULTIMATE TENSILE COMPRESSIVE & FLEXURAL STRENGTHS	20 %	20 %	20%	20%	> 80%
which can be carried as long term load				v	
% OF ULTIMATE SHEAR FOR LONG TERM LOAD	50%	50%	50%	50%	> 80 %

De

Col

EEEEE

EEEEEE

EEEEE

GEGEE EEEGE EEEEE EEEEG EEGEE

EEEEE

EEEEE

EEEEE

EEEEEE

EEEEE

EEEEG

EEEEE

EEGEE

EEEEE

EEEEE

ester fiber glass is not condemned because one grade has failed.

2. Experience has shown that polyester fiber glass equipment, of the right com-positions and properly handled, weathers extremely well.

Great advances are being made in improving physical and chemical properties of the polyester resins. For instance, chemical resistant polyester resin is far

superior now in toughness to those available only a few years ago. While progress in resin chemistry perhaps has been on a plateau, resins with better chemical resistance are in the development stage. Substantial advancements also are being made in reinforcements and fillers which will improve the over-all properties. Expanding uses of reinforced polyesters in the corrosion resistant field can be ex-

When considering the use of reinforced plastics keep in mind:

First. Use them where their high strength and light weight, coupled with corrosion resistance, recommend their use

Second. Get help from a competent company in selecting plastic materials.

Third. Do not consider them as cheap substitutes. Make sure equipment i properly designed and made.

### Ratings of Polyester Hoods, Ducts and Tanks vs Industrial Corrosives

### **APPENDIX**

### Ratings of Polyester Hoods, Ductwork and Tanks vs Industrial Corrosives

Open Hoods and Connecting Ductwork*						Duct	work*				Tanks								
	Гуре	4	7	уре В	3	1	Гуре (	2			Type A			Type B			Type D		
Cold	160 F	Hot	Cold	160 F	Hot	Cold	160 F	Hot		Conc. %	Cold	160 F	Hot	Cold	160 F	Hot	Cold	160 F	Hot
E E E E E	E E E	E E F E	E E E E	E E G	E E G F G	EEEE	E E G	P P P P	Acetic Acid	10 25 50 75 25	EEFE	E E G NR	F F NR F	E E E F G	G G G NR	P P P NR P	EEEEE	E E G NR	F F F NR
E G E E E	F E G E	E E F E	E G E E	FEGE	F G P G	E F E E	P G G G	F F P F	Acrylonitrile Alcohol, Amyl Benzyl Butyl	50	E F E G E	PEPE	F NR E NR F	G P E F	NR E P G	P NR G NR P	E G E G E	E E E	F NF E NF G
E E E	E E E	E E E	E E E	G G G E	F F G	E E E	G G G	1 1 1	Ethyl Methyl Aluminum chloride in ethanol Aluminum potassium sulfate	25	EEEE	EEEE	E E G	E E E	E E E G	G E G F	EEEE	E E G	EEEP
E E E E	E E E E	E G G G	E E E E	E E E E	G F G G	E E E E	G F G F	F P F P	Aluminum sulfate . Ammonia, aqueous . Ammonium bicarbonate . Ammonium carbonate .	5 20 100 10	EEEGE	E F G P F	G NR F NR	E G E G E	G F G P F	F NR F NR P	E G G E	G F F P	P NH P NH P
E E E E E	E E E E	G G E G	EEEEE	E E E E	G G G G	E E G E	F G F G	P P F NR F	Ammonium chloride Ammonium hydroxide Ammonium nitrate	50 100	GGEGE	PPEFE	NR NR G NR G	G G E G E	P P G P	NR NR F NR F	G G E G E	P P G P	NI NI P NI P
E E E E E	E E G E	E E F E	E E G E	EEEFE	G G P G	E E G E	G G F F	F F P	Ammonium persulfate	10 25 10	EEEGE	E E P E	G G NR G	EEEFE	G G P G	F F NR F	E E G E	G G F G	P P NI P
E E E E	EEEE	E E G E	E E E E	E E E E	G G G G	E E G E	F G F G	P P F P	Antimony trichloride Barium carbonate Barium chloride Barium hydroxide Barium sulfide	ió	EEEGE	E E E	G G G	E E G E	G G G	F F F	E E G E	G G F	P P P
G E E E E	G E E E	F F E E	G E E E	FFEEE	P P G G	G E E E	F G G	P P F F	Benzaldehyde Benzene Benzene sulfonic acid Benzoic Acid Boric acid		NR G E E	NR NR E E	NR NR G G	NR F E E	NR NR G G	NR NR F F	P G E E	NR NR G G	NH NH P P
EEEEE	G E E E	F G G E	G E E E	FEEGE	P G G F G	G E E E	F G G G	P F F F	Butyl acetate Butyric acid.  Calcium chloride.	25 50 100	GEEEE	P E G F E	NR G F P G	FEGGE	P G F P	NR F P P F	GEEEE	FGGGG	NI F P P
EEEEE	E E E G	E	E E E E	E E E E G	G	G G E E	F F G G	P F	Calcium hydroxide	10 20	ененен	G G F E F	G  G	E E E E G	G F G P	F  F	G E G E E	F F P G F	P
EEEEE	G E E E	E E G E	EEEEE	FEEGE	G G F G	G G G G	FFFF	P P P	Carbon tetrachloride Chlorine dioxide bleach Chlorine gas, dry Chlorine water, saturated. Chloroacetic acid.	iò	EE EE	P E G G	NR G F F	G E E E	P G F G	NR F P F	E G G E	F F G	P P P F

<sup>\*</sup> Ratings for closed\_hoods and connecting ductwork fall between ratings for tanks and ratings for open hoods and connecting ductwork.

Vol. 15

forced

rength corrocomcheap ent is

e D e E general, d Type

e are as lower; , slight recom-

D

F Hot F F F NR F

F NR E NR G

EEEP

P NR P NR

NR NR P NR P P P NR P

P P p

NR NR P P

NR F F P

P p

### POLYESTER FIBER GLASS EQUIPMENT **APPENDIX** (continued)

							twork								Tanks				
	Гуре	-	-	Туре		-	Туре				Туре А				Гуре І		Type D		
	160 F			160 F	Hot	Cold	1 160 F	Hot	Corrodent	Conc. %	Cold	160 F	Hot	Cold	160 F	Hot	Cold	160 F	Ho
EEEEE	EGGGE	GFFFE	EEEEE	G F G E	F P P G	EGFEE	F P P G	P P P P	Chlorobenzene Chromic acid	25 50 100	EGFGE	G F P P	F NR NR F	E G P F E	G F NR P G	F P NR NR	EGPFE	G F NR P G	F P NR NR
EEEEE	EEEEE	EGGGE	EEEEE	EEEGE	G G G F G	EEEEE	G G F G	P P P P	Citric acid.	5 10 20 30	EEEGE	GFFPE	F F P G	EEEGE	GFFPG	P P P NR F	EEEGE	GFFPG	P P P NR F
EEEEE	EEEE	EEEEE	EEEE	EEEGF	G G G F P	EEEE	G F G G F	FPFFP	Copper chloride		EEEG	EEEGP	G G G G NR	EEEGF	GGGGP	FFFFNR	EEEEG	G F G G F	P P P G NF
G E G E E	F G F E	PFPEE	G G F E	FFPEE	P P P G	G F E E	F F P G	P P P F	Dimethyl phthalate Diphenyl ether Ethyl acetate Ethylene chlorohydrin Ethylene glycol	100 25	FGFEE	PFPEE	NR P NR G E	FFPEE	P P NR G E	NR NR NR F	GGGGE	FFPFE	NF P NF P G
E E E G E	EEEFE	EEEPE	EEEGE	EEEEE	G G G P G	EEEGE	G G G P G	F F NR F	Ethylene dichloride Fatty acids	50 75 100	E E E N E	E E NR E	E E E NR G	E E NR E	E E E NR G	G G G N F	EEPE	EEEPE	EEENR
EEEEE	EEEEE	еннен	EEEEE	EEEE	G G G G	EEEE	GGGGG	FFFFFF	Ferric chloride Ferric nitrate Ferric sulfate Ferrous chloride Ferrous sulfate		EEEEE	EEEEE	G G G G	EEEE	G G G G	11111	EEEEE	GGGGG	PPPP
E E E G	E E 	EEE	EEEEG	E E E	G G · ·	EEEGG	E G G	G F F	Formaldehyde.  Formic acid.	10 25 37 25 50	EEEEG	EEE		EEGF	GGG : :		EEEG	EEE	**
E E G E E	G G P E	P P NR E E	EGEE	FFPEE	NR NR NR G	E E G E E	F F P E	NR NR NR G	Furfural Gasoline Glycerine	5 10 100 100	EEFEE	F F NR E	NR NR NR E G	G G P E	P P NR E G	NR NR NR G	EEFEE	F F NR E	NR NR NR E
EEEEE	EEEGE	EGGEE	EEEEE	E E E G E	G G F G	EEEEE	E G G G	G F F P	Heptane Hydrochloric acid. Hydrocyanic acid.	10 20 37 10	EEEEE	EGGFE	E F P	EEEEE	E G G F	G P P	EEEE	E F F	E P P NR
EEEEE	EGGEE	G E	EEEEE	E G E E	G G	EEEGE	F F F G	 F	Hydrogen peroxide.  Hypochlorite bleach Lactic acid	3 10 30	EEGEE	G F :GE	 P G	EEGEE	G F :G G	 P F	E G F G E	F F G	NR F
EEEEE	EEEEE	EGEEE	EEEE	EEEEE	G G G G	EEEEE	G G G G	1111	Lead acetate Linseed oil. Magnesium carbonate Magnesium chloride Magnesium sulfate		EEEE	EGEEE	G F G G G	EEEE	G F G G G	FPFFF	EEEEE	G G F G	PFPP
E E E E E	EEEG	E E : :	E E E E	EEEGF	G G · · ·	EEEE	G G G F	FFF	Maleic acid Mercuric chloride Mercurous chloride Methyl ethyl ketone	10	EEEEF	E E E G P	G G G NR NR	E E E	F G G G NR	P F F NR NR	EEEEF	F G G G	P P P NR NR
EEEEE	EEEE	EEEG	E E E E	EEEEE	G G G G	EEEEE	E G G G	G F F F	Naphtha Nickel chloride Nickel nitrate Nickel sulfate Nitric acid	 5	EEEEG	EEEEE	E G G F	E E E E	EGEGF	EFFF	EEEEF	E G G G P	E P P P NR
EEEEG	G E E F	FEE	E E E G	G E E P	F G G	G G E E G	F G G	P P F F	Oleic acid Oxalic acid Perchlorethylene	10 20	GFEEF	FPEEP	P NR G G NR	G F E E P	P P G G NR	NR NR F F NR	FFEEF	P NR E G P	NR NR E F NR
EEEEE	E G G E E	E P P E E	EEEEE	EGPEE	G P G G	EEEEE	G G P G G	F P F F	Perchloric acid Phenol Phosphoric acid	10 5 10 25 50	GE GE E	FFFEE	P NR NR G G	F G G E E	P F P G G	NR NR NR F	FEGEE	P F G G	NR NR P F
E E G E	E P P E E	E NR NR E G	E G F E E	E P P E E	G NR NR G G	EPPEE	G NR NR G G	F NR NR F	Phosphorus oxychloride Phosphorus trichloride Phthalic anhydride Potassium bicarbonate	85  10	E G NR E E	E NR NR E G	G NR NR G F	E F NR E E	G NR NR G G	F NR NR F F	EGFEE	G NR NR G F	F NR NR F
E E E E E	EEEEE	G G G G E	E E E E	EEEEE	G G G G	EEEEE	G F F G	P P P P	Potassium carbonate	100 10 25 100	EEEGE	G F F P E	P P P NR G	EEEGE	G F F P G	P P P NR F	EGGFE	F F P NR G	NR P NR NR
EEEE	EEEGG	GEEFF	EEEEE	E E E G F	G G P P	EEEFF	G G P P	F F NR NR	Potassium dichromate Potassium ferricyanide Potassium ferrocyanide Potassium hydroxide	10 25	EEEGG	EEEFP	G G NR NR	EEEGF	G G G P	F F NR NR	EEEFP	G G NR NR	P P P NR

<sup>\*</sup> Ratings for closed hoods and connecting ductwork fall between ratings for tanks and ratings for open hoods and connecting ductwork.

### **APPENDIX** (continued)

	Open	Hood	s and	Conn	ecting	Duct	work		*						Tanks	3			
Type A Type B				Type C					Туре А				Гуре I	Type D					
Cold	160 F	Hot	Cold	160 F	Hot	Cold	160 F	Hot	Corrodent		Cold	160 F	Hot	Cold	160 F	Hot	Cold	160 F	Ho
EEEE	G E E E	P E G G	EEEE	F E E E	P G G G	F E G G E	P G F G	NR F P P	Potassium nitrate Potassium permanganate Potassium persulfate Potassium sulfate	50	G E E E	P E E E	NR G G G	FEEEE	P G G G	NR F F F	PEEE	NR G G G	NR P P P
G E E E	P E E E	NR E E G	F E E E	P E E E	NR G G G	P E E E	NR G G G	NR F F F	Pyridine Silver nitrate Sodium acetate Sodium bicarbonate Sodium bisulfate	10	NR E E E	NR E E G	NR G G F	NR E E E	NR G G G	NR F F F	NR E E E	NR G G F	NR P P P
EEEEE	EEEEE	E G G G E	E E E E	E E E E	G G G G	E E E E	G F F G	F P P P	Sodium bisulfite Sodium carbonate Sodium chloride	10 25 100 10	E E G E	EFFFE	G P P P G	EEEGE	G F F P G	F P P NR F	E G G F E	G F P NR G	P P NR NR
EEEEEE	E E G G	EEEFF	EEEEEE	E E E F F	G G F P	EEEFFF	G G P P	F F NR NR NR	Sodium ferricyanide Sodium hydroxide	25 100 10 25 50	E E G G F	E E E F P	E E G NR NR NR	EEEGFF	G E G P P	F G F NR NR	EEEFPP	G E G NR NR NR	F G P NR NR
EEEEE	E E E E	G G G E E	EEEEE	EEEEE	GGGGG	G G G E E	F F G G	F F	Sodium hypochlorite  Sodium nitrate Sodium nitrite	5 10 15	E E G E E	G G E E	P G G	E G E	GG :GG	PFF	G G E E	F F G G	P P P
EEEEE	E E G G E	EEFFG	EEEEE	E E G G	G F F F	E E G G E	G F F G	F F P P	Sodium sulfate. Stearic acid. Sulfur dioxide. Sulfur trioxide. Sulfuric acid.	10	E	E	G E 	E E 	G G 	FF	E	G E ···	P E  P
EEEEE	E E E G	G G E G F	E E E E G	G G E G F	F F G F	EEEGF	G G G F P	P P F P		20 25 50 60 70	E E E E G	E E E E G F	F F G F	E E E G	GGGGF	P F F P	E E E F	F F G F	P P F P NR
G E E E	F E P E	P G P E NR	G E G E	F G P E	P F P G NR	P G G E G	NR G P G P	NR P NR F NR	Sulfuric acid, fuming Sulfuric acid, pickling Styrene monomer, inhibited Tartaric acid Tetrachloroethane		NR E G E	NR E NR E NR	NR G NR G NR	NR E E	NR G G	NR P F	NR E G E	NR F NR G NR	NR P NR P NR
EEEEE	G E G E	P G F E	G E E E	F E E G E	P G G F G	GGGFE	P F F P G	NR P P NR F	Toluene Trisodium phosphate Water	10 25 50 100	G E E G E	F F F E	NR P P NR G	F E G E	P F F P G	NR P P NR F	G G F E	F F P NR G	NR P NR NR
E	E E	E	E	E	G G	E	G G	F	Water vaporZinc sulfate	100	E	E	G	E	G G	F. F	E	G	PP

### Appendix 2—Polyesters vs Metal Finishing Plating Solutions

Open Hoods and Connecting Ductwork*					ork*			Tanks						
Type A Type B		Туре С			Тур	e A	Тур	e B						
Cold	180 F	Cold	180 F	Cold	180 F	Application and Corrodent	Cold	180 F	Cold	180 I				
E	E	E	Е	Е	P	Brass Plating 3% Cu(CN) <sub>2</sub> , 0.94% Zn(CN) <sub>2</sub> , 5.6% NaCN, 3% Na <sub>2</sub> CO <sub>3</sub>	Е	G	Е	P				
E	E	E	G	E	F	Bright Nickel (Harshaw)	E	G	E	F				
E	E	Е	Е	E	P	Bronze Plating 4.13% Cu(CN) <sub>2</sub> , 5.1% NaCN, 3% Na <sub>2</sub> CO <sub>3</sub> , 4.5% Rochelle Salts	E	G	E	F				
E E	E	E E	E G	E E	F F	Copper Plating 44.8% Cu(BF4)2 Acid: 19% CuSO4 · 5H <sub>2</sub> O, 8.3% H <sub>2</sub> SO <sub>4</sub> .	E E	G G	E	F				
E	Е	E	E	E	P	Copper Cyanide, Rochelle Salts Bath 10.5% Cu(CN)2, 14.3% NaCN, 6% Rochelle Salts	E	G	E	F				
E	G	E	G	F	P	Cyanide Zinc Barrel Plating 9% Zn(CN) <sub>2</sub> , 4.2% NaCN, 9% NaOH	G	P	G	P				
E	E E	E E	E E	E E	F F	Iron Plating 45% FeCl <sub>2</sub> , 15% CaCl <sub>2</sub> 20.3% FeSO <sub>4</sub> · 7H <sub>2</sub> O, 10.5% (NH <sub>4</sub> ) <sub>2</sub> SO <sub>4</sub> .	E E	G G	E E	G F				
Е	G	E	F	F	P	Lead Plating, Alkaline 7.5% Pb(C <sub>2</sub> H <sub>3</sub> O <sub>2</sub> ) <sub>2</sub> , 20% NaOH, 0.5% Rosin	G	P	G	P				
E	G	E	G	F	Р	White Brass Alloy Plating 6% Zn(CN) <sub>2</sub> , 1.1% Cu(CN) <sub>2</sub> , 3.5% NaCN, 5.3% NaOH	G	P	G	P				

<sup>\*</sup> Ratings for closed hoods and connecting ductwork fall between ratings for tanks and ratings for open hoods and connecting ductwork.

ol. 15

Hot

NR P P P

NR PPPP PPRR PPNNR PNRR PNRR NRR

P P P E

P P F P NR

NR P NR P NR

NR P NR NR P

P

B 80 F

F F

F F

P

G F P

#### Appendix 3—Polyesters vs Pickling and Dipping Solutions

Open Hoods and Connecting Ductwork*				g Ducty	vork*		Tanks				
Тур	e A	Тур	e B	Тур	e C		Тур	e A	Type B		
Cold	180 F	Cold	180 F	Cold 180 F		Application and Corrodent	Cold	180 F	Cold	180 F	
E	G E	E E	G G	F G	PF	Alkaline cleaning of metals 6% NaOH	G E	PF	G E	PP	
E	E	E	G	G	F	Brass, cleaning 6% Na <sub>3</sub> PO <sub>4</sub>	E	F	E	P	
E	E	Е	G	E	F	Copper and Alloys, cleaning 20% H <sub>2</sub> SO <sub>4</sub>	E	G	E	F	
EEE	E E E	E E E	G G G	E E E	FFF	Copper Pickling 9.7% Fe <sub>2</sub> (SO <sub>4</sub> ) <sub>3</sub> , 9.7% H <sub>2</sub> SO <sub>4</sub> 9% H <sub>2</sub> SO <sub>4</sub> 1.2% Na <sub>2</sub> Cr <sub>2</sub> O <sub>7</sub> · 2H <sub>2</sub> O <sub>1</sub> 3.6% H <sub>2</sub> SO <sub>4</sub>	EEE	G G G	E E E	FFF	
Е	E	E	E	E	F	Copper Matte Dipping 29% FeCl <sub>3</sub> , 18.5% HCl	E	G	E	F	
E	E G	E E	G F	E G	F	Iron and Steel, cleaning 6% H <sub>2</sub> SO <sub>4</sub> . 8.5% HCl, 23% H <sub>2</sub> SO <sub>4</sub> .	E	G F	E	F	
E	E G	E E	G	E G	FP	Magnesium and Alloys, cleaning 18% CrOs. 2.25% Na <sub>2</sub> COs·10H <sub>2</sub> O, 1.5% NaOH.	E	G F	E E	F	
						Monel, see Nickel					
E	E	E E	E G	E E	F	Nichel and Monel Pickling 2% CuClz, 15% HCl. 8% NaNOs, 8% NaCl, 20% HzSOs	E	G G	E E	F	
E	E	E	G	E	F	Nicbel and Monel Scale Removal 9.8% Fe <sub>2</sub> (SO <sub>4</sub> ) <sub>3</sub> , 3.6% HCl.	E	G	E	F	
Е	E	E	G	E	F	Nicbel-Silver Pickling 3% Na <sub>2</sub> Cr <sub>2</sub> O <sub>7</sub> , 22% H <sub>2</sub> SO <sub>4</sub>	E	G	E	F	
						Silver, see Nickel					
E	E	Е	G	E	F	Stainless Steel Scale Loosening, 9% H <sub>2</sub> SO <sub>4</sub>	E	G	E	F	
EEE	G E G	E E E E	G G G F	F E E G	P F F	Steel Cleaning 6% NaOH. 6% HsSO4. 50% HsSO4. 8.5% HCl, 23% H <sub>2</sub> SO <sub>4</sub> .	G E E	P G G F	G E E E	P F G F	
Е	E	E	G	E	F	Zinc and Alloys, cleaning 3% Na <sub>2</sub> SO <sub>4</sub> , 30% CrO <sub>3</sub> .	E	G	E	F	
E	E	E	G	E	F	Miscellaneous cleaning 2.25% HNO <sub>3</sub>	E	G	E	F	

#### Appendix 4—Polyesters vs Stripping Solutions for Salvage

Open Hoods and Connecting Ductwork*			g Ductw	vork*		Tanks				
Type A Type B		B Type C				e A	Type B			
Cold	180 F	Cold	180 F	Cold	180 F	Application and Corrodent	Cold	180 F	Cold	180 F
Е	Е	Е	G	Е	F	Anodized Oxide Coatings from Aluminum 2% CrO <sub>3</sub> , 10% H <sub>3</sub> PO <sub>4</sub> , 0.6% Wetting Agent	E	G	Е	F
E	G	E	G	E	P	Brass from Steel 7% (NH <sub>4</sub> ) <sub>2</sub> S <sub>2</sub> O <sub>8</sub> , 30.1% NH <sub>3</sub>	G	P	G	P
E	Е	Е	E	E	F	Chromium from Brass, Copper or Nickel 11% HCl	E	G	E	F
E	Е	E	G	E	F	Copper from Non-ferrous Metals 21% Na <sub>2</sub> S, 1.5% S	E	G	E	F
E	E	E	E	Е	F	Lead from Copper Alloys and Steel 1% H <sub>2</sub> SO <sub>2</sub> , 20% CH <sub>3</sub> COOH	Е	G	G	P
G	F	F	P	F	P	Lead and Alloys from Silver 1.5% H <sub>2</sub> O <sub>2</sub> , 95% CH <sub>3</sub> COOH.	P	NR	P	NR
E	E	Е	Е	E	F	Tin from Brass, Bronze or Copper 10.5% FeCl <sub>3</sub> , 15.7% CuSO <sub>4</sub> · 5H <sub>2</sub> O, 26.3% CH <sub>3</sub> COOH	E	G	E	F

<sup>\*</sup> Ratings for closed hoods and connecting ductwork fall between ratings for tanks and ratings for open hoods and connecting ductwork.

Any discussion of this article not published above will appear in the June, 1960 issue.

......5



# DISCUSSIONS

Observations on the Mechanisms and Kinetics of Aqueous Aluminum Corrosion. Part 1—Role of the Corrosion Product Film in Uniform Aqueous Corrosion of Aluminum by V. H. Troutner. Part 2—Kinetics of Aqueous Aluminum Corrosion by R. L. Dillon. Corrosion, Vol. 15, No. 1, 9t-12t (1959) Jan.

Comments by P. M. Aziz and Hugh P. Godard, Aluminium Laboratories, Ltd., Kingston, Ont., Canada:

Troutner has reported: "If the corrosion (of aluminum by high purity water) is determined by the solubility of the oxide film, the presence of dissolved aluminum ions could inhibit corrosion by a common ion effect. This effect has been observed.

In the second part by Dillon, the author stated: "It has been observed experimentally in dynamic test facilities at Hanford that, as deionized water is equilibrated with aluminum oxide at test temperature, it becomes less corrosive."

In independent work underway when these papers appeared, we had found a similar effect in distilled water at 60 When superpurity aluminum (99.99 Al) was immersed for a fixed time of 20 minutes in distilled water containing different amounts of aluminum ions (introduced by pre-exposing the water to aluminum coupons for varying time periods), the degree of oxidation (as measured by the weight increment) increased with the exposure time and approached a limiting value. Test coupons were 5 by 10 cm, and their surfaces were abraded with a wire brush before use. All weighings were made on an analytical microbalance; the water volume used was 6000 ml. A representative series of results is given in Table 1.

These data are interpreted by assuming that in aluminum-unsaturated water there is first weight loss and then film growth so that the weight gain figures in Table 1 are the resultant of the two processes whereas in fully saturated water only film growth occurs.

TABLE 1—Influence of Aluminum Ions on Oxidation in Distilled Water at 60 C

Pre-exposure Time													20-minute Weight Gain (micrograms/Dm				
15.						4											185
30.																. 1	235
60.							ĺ.						Û			1	256
90.																	1450
120.	٠															1	1925
240	٠	•	*		۰		•		-		0			*		1	4834
450	•	•		^	•		•	•							1	1	7272
																	7500
	ì																8290
1800.	î		Ĵ	ì													8255

It has been shown by using radiographic techniques¹ that, when aluminum is immersed in water, there is intense local action over the entire surface. Local cells soon passivate, probably by the precipitation of a film of aluminum hydroxide. Such a film will only precipitate when its solubility product is reached and the presence of aluminum ion in the water (solubility is very low) will speed up this precipitation (i.e. passivation).

We believe that this new observation may have considerable practical significance. It is generally accepted2,3 that the pitting of aluminum is autocatalytic. We believe further that once a pit survives the initiation stage it will continue to propagate independently of the reason for its origin.<sup>3</sup> It follows that any means of stifling initiation may prevent pitting that would otherwise develop during the early life of an aluminum surface in water. When the water is saturated with aluminum ions, the introduction of more such ions by local action will bring about immediate precipitation of protective aluminum hydroxide. In the absence of sufficient aluminum ions, local action will continue until saturation is reached, and by this time some pits may have established themselves. Pre-saturation of the first aqueous charge in an aluminum tank or pipeline might lead to prompt passivation without pitting that might otherwise occur and surface film thickening which would have greater resistance to pitting in the normal environment.

While we believe that the findings of Troutner and Dillon and our own data constitute the first published evidence to support the conclusion that corrosion of aluminum in water is influenced by the aluminum content of the water, it is interesting to note that such a mechanism was proposed as far back at 1911.<sup>4, 5</sup>

#### References

- P. M. Aziz. Radioactive Tracers in the Study of Pitting Corrosion on Aluminium. J. Electrochem Soc, 101, 120-123 (1954) March.
- E. Edeleanu and U. R. Evans. Causes of the Localized Character of Corrosion on Aluminium. Trans Faraday Soc, 346, 47 (1951) Oct.
- 3. P. M. Aziz and H. P. Godard. Influence of Specimen Area on the Pitting Probability of Aluminium. J Electrochem Soc, 102, 577-79 (1955) Oct.
- 4. Heyn and Bauer. Mitteilungen aus dem Koniglichen, Material prufungsamt, 29, 16 (1911).
- R. Seligman and P. Williams. J Inst Met (London), 23, 159-192 (1920).

#### Reply by R. L. Dillon:

It may be appropriate to mention that a document from the General Electric Company, Hanford Laboratories Operation, "Dissolution of Aluminum Oxide as a Regulating Factor in Aqueous Aluminum Corrosion," by R. L. Dillon, (HW-61089) will be issued shortly.

Oil Refinery Applications of Thick-Film Synthetic Coatings by R. W. Maier, W. B. Cook and R. B. MacQueen. Corrosion, Vol. 15, No. 4, 171t-178t (1959) April. De

str he ap

fe

sai

cu

ty

co

ro

tai

en

th

an

In

Co

M

ing

an

for

ple

ca

ing

in

11

(9

ne

H

fili

for

me

OX.

str

uci

sol

the

diz

ioc

the tha

Re

me

me

int

pai

rea

Question by Charles M. Stanbury, Horton Steel Works, Fort Erie, Ontario, Canada:

In your hot spray vinyl system you use a cold vinyl primer. Have you anything against the use of a hot vinyl prime?

Reply by R. W. Maier:

As a general policy, we followed the manufacturer's recommendations in these applications. The primer recommended under these hot spray vinyls was a cold applied material which was not a vinyl but was described as a drying oil modified zinc chromate primer. This would tend to be a better wetting primer than a vinyl. Note Austin K. Long's comment below.

Questions by Emile E. Habib, Dewey & Almy Chemical Co., Cambridge, Massachusetts:

1. Are the catalyzed epoxy medified phenolics 100 percent reactive or must they contain solvents?

2. What are the hot spray vinyls? You mentioned solvents. Are they organisols, plastisols or some other composition?

Reply by R. W. Maier:

1. The catalyzed epoxy-modified phenolics we tried all contained solvents. Whether or not anyone makes a 100 percent solids material, I do not know.

2. The hot spray vinyls described are not organisols or plastisols but solvent-type compositions, formulated with a high solids content and with high boiling solvents. As such, they have a relatively high viscosity and cannot be sprayed at room temperatures, but when heated to approximately 160 F, the viscosity is reduced to a point where the formulation can be sprayed.

Comment by Austin K. Long, Glidden Company, Cleveland, Ohio:

Primers for use under vinyls may be of other generic types, but primers are available which can also be hot-sprayed.

Questions by DuWayne Christofferson, Chicago, Illinois:

You have primarily used and discussed catalyst cured phenolic modified epoxy coatings. Why have you been using these in preference to straight catalyst cured epoxies?

Have you experience with straight catalyst cured epoxies inside (immersion service) of oil and gasoline storage tanks?

Reply by R. W. Maier:

At the time the paper was written,

ick-

B.

No.

forrio,

use

ning

the

hese

ded

cold

inyl

odi-

ould

han

nent

y &

lge,

ified

nust

You

sols,

hen-

nts.

per-

ent-

ooil-

ela-

hen

vis-

the

lden

e of

are

yed.

son,

ssed

hese ired

ight

ner-

rage

ten,

be

aside from the heavy consistency formulations used as tank seam sealers, we did not have any experience with the straight catalyst cured epoxies. We had hesitated to make any interior vessel applications due to their generally acknowledged chalking qualities. However, since the paper was written and a few months before its presentation, Port Arthur made a spray application after sandblasting of a red inhibitive catalyst cured straight epoxy primer and the same type finish (about 3 mils each coat) in a coral color to the exterior of two cone roofed 50-feet diameter by 30-feet high tanks used for treating 200 F waste oil emulsion with caustic. Slight pinholing of the primer was observed after application, and the finish coat began to chalk rather rapidly and presented a faded appearance after two months' exposure. But again, this is our only experience with this type coating.

Impedance Characteristics of Isolated Aluminum Oxide Films by D. F. MacLennan. Corrosion, Vol. 15, No. 6, 283t-285t (1959) June.

Comments by F. E. DeBoer, Argonne National Laboratory, Lemont, Illinois: Mr. MacLennan's attack on this problem is interesting, and his method for forming a framed oxide is clever.

It is interesting to note that his resistances are of the same order as those found by Burwell and May<sup>1</sup> for com-pletely anodized film. They also indicate that the HgCl<sub>2</sub> process for dissolving aluminum does affect the oxide layer in such a way as to cause higher resistance of the film. We anodized both 1100 (2S) aluminum and a high purity (99.999 percent) aluminum in a man-ner similar to MacLennan's and then separated the oxide from the metal by HgCl2. Our measurements, although somewhat inaccurate, show that these films have resistances of about 107 ohms per cm2 of film area. Also, the results for our two aluminum stocks were practically identical.

Thus, it seems likely that both of these metal stripping procedures change the oxide next to the metal. In the case of stripping with HgCl2 solution, the product of the reaction of aluminum with the solution is insoluble and thus transforms the anodic film to a high resistance film. On the other hand, the completely anodized film is porous, and the methanoliodine film is also of low resistance because of the solubility of the product of the reaction of aluminum with the methanol-iodine solution.

Reference

R. L. Burwell and T. P. May. Pittsburgh In-ternational Conference on Surface Reactions. Corrosion Publishing Co., Pittsburgh. Pa., 1948.

Reply by D. F. MacLennan:

It is not clear from Mr. DeBoer's comments what method of film resistance measurement he used. This is a point of interest if the resistances are to be compared.

It is to be expected that the insoluble reaction product, in the HgCl2 stripping procedure, would cause higher film resistances because this product adheres to the film. However, the solubility of the reaction product in the iodine-methanol procedure should result in clean, unchanged oxide films.

Behavior of AZ 63 Alloy and Magnesium-1 Percent Manganese Alloy Anodes in Sodium Chloride Electrolyte by J. H. Greenblatt and E. Zinck. Corrosion, Vol. 15, No. 2, 76t (1959) Feb.

Comments by J. L. Robinson, Dow Chemical Company, Midland, Michi-

In Dr. Greenblatt's original paper (*J. Electrochem Soc*, **103**, 539 (1956), he proposed  $Mg \rightarrow Mg + e$  as the principal anodic reaction for magnesium. The major argument for this reaction appeared to be that he found "that the quantities soluble Mg, insoluble Mg, Mg calculated from the current passed were in approximate one-to-one relationship with each other and all of these quantities are roughly half of the total weight loss.

Due to the nature of the cathode (silver-silver chloride) used in the experiments, the amount of magnesium in solution should be equal to that predicted by Faraday's law and divalent magnesium ion formation just as Dr. Greenblatt found. This must be true because the cathode reduction product is chloride ions, and thus soluble MgCl2 will form to conform with the principle of con-servation of charge. At the current den-sities used by Dr. Greenblatt, the expected anode efficiency would be in the range of 50 to 60 percent based on divalent ion formation. As the wasteful reactions for divalent magnesium ion formation would produce insoluble Mg(OH)2, it would be expected that this quantity of magnesium would also be roughly equal to the "calculated Mg" as Dr. Greenblatt found. Thus, such relationships cannot be interpreted as favoring the reaction Mg -> Mg++ e as opposed to the commonly accepted reaction Mg →

Reply by J. H. Greenblatt: We agree with Dr. Robinson's comments that the soluble magnesium should equal the calculated quantity for the reasons he has pointed out. Our contention in the original paper was the fact that the similar equality of the insoluble magnesium could not be explained by a priori assumptions if the anodic evolution of hydrogen was ascribed to self corrosion.

Self corrosion and the difference effect explain the production of hydrogen and insoluble magnesium and the dependence of the rate of formation of these products on current density. However, they can only explain the equality of rates in the two processes (self corrosion and current carrying reaction) as fortuitous. Postulating the existence of univalent magnesium does give an *a priori* reason for the equality, but it is realized that this is not proof of the existence of univalent magnesium.

Performance of Organic Coatings in Tropical Environments by A. L Alexander, B. W. Forgeson and C. R. Southwell. Corrosion, Vol. 15, No. 6, 291t-294t (1959) June.

Comments by Seymour J. Fiebach, Car-boline Company, St. Louis, Missouri: On page 293t, near the bottom of the page, the following statement is made: 'Synthetic rubbers and vinyls are conspicuously absent among the survivors listed in the marine atmosphere. However, these types might be expected to yield more rapidly to the intense solar radiation of the tropics."

Additional clarification will be appreciated. It has been my impression that vinyls and vinyl-alkyds stand up very well under these conditions.

Reply by A. L. Alexander:

Perhaps we were a bit unwise in our choice of the word "conspicuously" in describing the absence of synthetic rubbers and vinyls in the survivors of the coating types exposed to the propical at-mosphere. We would like to invite Mr. Fiebach's attention to the fact that our data described only those coatings which were still performing quite satisfactorily after a minimum of six years and in the case of the atmospheric exposure seven years of satisfactory service. These were not short term tests and constituted a most severe test for any coating.

Some of the vinyls were quite satisfactory for shorter periods, but from the large number of coatings studied only those which were most outstanding were reported in our paper. Our conclusions are based on data as presented, and certainly these data indicate that in atmospheric exposure the vinyls studied do not compare in durability with those materials reported in Tables 5 and 6.

Corrosion Resistance of Titanium and Zirconium in Chemical Plant Exposures by P. J. Gegner and W. L. Wilson. Corrosion, Vol. 15, No. 7, 341t-350t (1959) July.

Question by E. G. Brink, American Viscose Corp., Marcus Hook, Pennsylvania:

Do you feel that the type of specimen used in your pipe line corrosion tests gives a true picture of the corrosion pattern at the pipe wall since velocity effects and deposits can influence this pattern?

Reply by P. J. Gegner:

We recognize the limitations involved in obtaining corrosion data by means of specimens. Believing the specimen data to be indicative only, we started equipment tests almost immediately. So far, these equipment tests have confirmed the results obtained by means of the speci-

Comments by Wayne H. Keller, National Research Corp., Waban, Massachu-

This report has great value to industry in the unusual extent of its coverage. In

De

qua

aut

not

de

der

rec

Po

use

age

ind

pH

cor

age

and

tha

vir

she

sid

Re

of

res

of

ser

the

to

pro

of

cor

he

cor

are

lem

as

test

hea

me

sion

and

use

rate

unc

den

ent

in

det

Con

The

acc

rep

The

whi

stud

cor

bro

era

cor

tha

and

sur

pro

atta

cur

general, the findings agree very well with those reported elsewhere.

Since some of the earlier reports on corrosion resistance of zirconium were based on induction melted metal higher in carbon than the present product, it would be helpful to know the melting and fabrication history of the zirconium samples. Since the carbon is low, it is assumed that the product used is arc melted. Melting atmosphere would be of interest. (It was established by the writer that the sponge used was double melted by arc in vacuum by the consumable electrode process.) Also, the rolling and heat-treating histories will affect the corrosion behavior and would be of interest.

The behavior of the stainless steels tested in the concentration of the raffinate from solvent extractions, reported as nitric acid solutions is not necessarily surprising. Assuming that the solutions described as "typical of those found in the separation and concentration of nitric acid from . . . raffinates" was actual zirconium plant raffinate, it may contain sulfate ion up to 2 to 3 percent of the concentration of the nitric acid along with a saturation amount of sodium nitrate and varying quantities of many other nitrates, including ferric. The effect of such varied and varying composition may be expected to be rather different from that of nitric acid. Moreover, the quoted values of chlorides required to increase the attack by nitric acid on stainless steel was not the quantity required to initiate attack but was tolerated only by rather extensive preventive maintenance and replacement programs.1

The fact that zirconium stood up well comparably with tantalum under raffinate concentration service is one of its best recommendations. Continued reports of the results of these studies will be watched with great interest.

Reference
1. D. S. Arnold, A. Whitman and F. J. Podlipec.
Nitric Acid Recovery from Raffinate. Chem.
Engineering Progress, 52, No. 9, 362 (1956)
Sept.

Comments by Milton Stern and Claude R. Bishop, Union Carbide Metals Company, Niagara Falls, New York:

The authors are to be commended for providing the corrosion field with an unusually valuable report. It is quite evident that this test program provides particularly valuable data and that it has been competently planned and executed. Corrosion workers will be indebted for many years to the authors and Columbia-Southern Chemical Corporation for their foresight in embarking on this program and in making the information so generally available.

We have been working on the corrosion and electrochemical behavior of titanium on a laboratory scale for several years and have been particularly impressed by the ease with which the metal is passivated and the stability of the passive state in the presence of chlorides and chlorine. In fact, chlorine seems to behave like any other oxidizing agent in actually promoting passivity of titanium. Our laboratory tests on the resistance of titanium to solutions of

sulfuric acid with chlorine are confirmed by these plant tests. Tests conducted at 190 C show that chlorine is an effective passivator in hydrochloric acid as well as in sulfuric acid and indicate that the authors' current experiments on the influence of chlorine in hydrochloric acid environments will again show titanium to be an outstanding material of construction.

As brought out by the authors, titanium shows excellent corrosion resistance to a wide variety of media which, in general, can be classified as oxidizing in nature. It is well known that titanium is not particularly resistant to so called reducing acids, such as hydrochloric or sulfuric acids without the presence of oxidizing agents. In an investigation to overcome this defect, addition of relatively small percentages of a noble metal markedly improved the corrosion resistance to reducing environments.

For example, titanium containing palladium exhibits corrosion rates of 32 mpy in boiling 10 percent hydrochloric acid and 20 mpy in boiling 5 percent sulfuric acid. Rates for unalloyed titanium are well over 1000 mils per year in either solution. This is achieved without detrimental effects to titanium's excellent behavior in oxidizing media and results in a material with unusually broad resistance to a variety of different environments.

Although not advocated for service in the more aggressive solutions of sulfuric and hydrochloric acids, the palladiumbearing alloy has all indications of greatly extending the usefulness of titanium into environments in which it cannot now be used. It should be particularly valuable in those plants which periodically alternate between reducing and oxidizing conditions.

Reply by P. J. Gegner:

We are pleased to learn that some of our tests confirm laboratory results obtained by Doctors Stern and Bishop, particularly in regard to the influence of chlorine on rendering titanium passive in strong sulfuric and hydrochloric acid solutions.

We are very much interested in their comments on the effects of small additions of noble metals on the corrosion resistance of titanium to reducing environments. This promises to be another important milestone in the history of titanium. We are happy to offer the facilities of our company in evaluating these new alloys under plant operating conditions.

Corrosion of Types 316 and 317 Stainless Steel by 75 Percent and 85 Percent Phosphoric Acid by Albert R. Morgan, Jr. Corrosion, Vol. 15, No. 7, 351t-354t (1959) July.

Questions by C. M. Schillmoller, International Nickel Company, Inc., Los Angeles, California:

Have you an explanation why the Carpenter 20 and the Hastelloys did not show better resistance to hot phosphoric acid than Type 316 and 317 stainless steel? Also, was Nionel evaluated and what were your findings?

Reply by A. R. Morgan:

We have no explanation why Carpenter 20 and the Hastelloys were not more resistant than 316 and 317 stainless steel. It is our impression that the Alloy 803 mentioned in Table 8 is now called Ni-O-Nel.

Cathodic Protection of Lead Cable Sheath by W. H. Bruckner and Ole G. Jansson. Corrosion, Vol. 15, No. 7, 389t-394t (1959) July.

Question by R. B. Mears, U. S. Steel Research Center, Monroeville, Pennsvlvania:

What proof is there all the corrosion occurred in Cell B during the periods when the current was off?

Reply by W. H. Bruckner:

It appears that in preparing the article we omitted one observation regarding the appearance of the corroded portion of the gradient cathode Series B at the high pH end. We noted that the corrosion products near the air-soil interface had a yellow-red color, but near the bottom where perforation occurred there was also a considerable amount of redeposited lead. We have considered that the redeposited lead together with the experience of the cell of Series A operated at 14 pH justifies the conclusion we made. It is seen from the gradient cells that a sufficiently negative potential can give complete protection even at a pH of 14. The potential at the high pH end was not determined; however, it is indicated that since lead was deposited it was sufficient to provide complete protection while the cell received current. Thus the only opportunity for corrosion loss was during periods of open circuit.

#### Comments by L. C. Eddy, Hinsdale, Illinois:

The authors should be commended for their imaginative study and original approach to this complicated subject which has so many ramifications. This article is a fitting follow-up of two previous articles directly associated with this same general study.

The authors developed the "Gradient Cell" into a very useful tool. The cell gave the opportunity to observe the effect of a relatively wide variation of cathode current densities on adjacent areas while the other elements were well controlled. The "Gradient Cell" principle should be a very valuable tool in other investigations involving electrolytes and current densities. The cell in itself does not permit the direct evaluation of specific current densities, but that step if desired should not be difficult.

The authors' findings may be difficult for some of us to comprehend and to apply. In particular for us who have based our thinking on a limited metal plating experience or on field observations of corrosion results where the action is in a duct system and where the various forces and factors cannot be adeol. 15

and

pen-

nore

teel.

803

illed

able

Ole

No.

iteel

enn-

hen

ticle

ding

tion

the

orro-

face

bot-

here

re-

that

the

per-

sion

lient

ntial

at a

pH it is

sited

pro-

rent.

sion

cuit.

dale.

for

ap-

hich

ticle

s ar-

ame

lient

cell

ffect

node

vhile

lled.

d be

tiga-

rent

per-

cur-

sired

icult

d to

have

netal

erva-

ac-

the

ade-

quately observed or measured. Under the authors' definition, cathodic corrosion is not possible except at very high current densities (30,000 to 120,000 MA per square foot) which should be beyond the densities encountered in cable sheath corrosion. It is of academic interest to learn that the current required for such action increases so fast with the increased pH of the electrolyte. It was fortunate that recent findings from a lead study by Pourbaix were published and could be used.

The corrosion engineer can be encouraged by the laboratory findings which indicate that lead cable sheath in a high pH electrolyte can be protected from corrosion by maintaining it sufficiently cathodic. Then again he can be discouraged when he understands the number and degree of controls required to obtain that protection. The effort in simple form is to eliminate discontinuities in the environment. Or, the effort is to maintain a uniform environment for the cable sheaths which leads me to a greater consideration of jacketed cables.

Reply by W. H. Bruckner:

We enjoyed Mr. Eddy's commendation of our work and feel as he does that the research has done much to clarify some of the complications which may exist in service of lead sheaths. In the laboratory the variables can and must be separated in order to undertake their study. In the field, conditions may vary with respect to location and time sequence. Mr. Eddy provides the key to greater service life of lead sheath in his comment that dis-continuities in the environment should be eliminated. Unfortunately where discontinuities prevail and the conditions are severe, the only solution to the problem may be the use of jacketed cables, as mentioned by Mr. Eddy.

He mentions the use of the gradient test cell for other investigations. We have heard of a number of applications of this method by other laboratories for corrosion behavior studies of different metal and environmental systems. We have used it in the Cathodic Protection Laboratory for studies on steel and aluminum under cathodic protection. Where current densities need to be known for the gradient test, a sectional cathode or a probe in the electrolyte would be required to

determine these values.

Comments by Vernon B. Pike, Murray Hill, New Jersey:

The authors are to be commended in accomplishing the results of the study reported in this and two previous papers. They have made clear several factors which have been repeatedly observed in the cases of cathodic corrosion we have studied. Actually no cases of cathodic corrosion of lead cable sheath have been brought to my attention in the last several years. Examining the cases of such corrosion recorded in my files, I find that there were high current densities and build-up of substances at the lead surfaces by the cathodic currents. These products were believed to influence the attack on the lead at such times as the currents decreased.

Studies made at the Bell Telephone Laboratories on soils gathered from 47 widely separated places in the United States gave a band of voltages at which lead was at neutrality when plotted against the soil pH. This band was about 64 millivolts in width.

Reply by W. H. Bruckner:

We assume the experience that Mr. Pike cites regarding the decreased in-cidence of alkaline corrosion under cathodic protection conditions concerns the Eastern Atlantic area. This would indicate improved control of conditions of cathodic protection on lead cable sheath. It is suggested from Mr. Pike's comments that this control has been achieved by decrease in the alkaline product of cathodic protection. This product would be a minimum under conditions of minimum continuous protective current and maxium uniformity of cable environment.

Comments by Frank E. Kulman, Con-solidated Edison Company of New York, Inc., New York City:

The authors have shown that severe corrosion of lead in an alkaline environment can be caused by fluctuations in current flowing from the electrolyte to the lead cathode

Whether this corrosion is called cathodic corrosion or corrosion by cathodic products is not particularly important to the corrosion engineer. The corrosion engineer has maintained for many years that stray currents leaking from d-c railways have caused corrosion of lead sheath in areas where the potential of the lead was negative with respect to the earth and to the rail and a low resistivity electrolyte was present. The authors perhaps unwittingly corroborate what the cable corrosion engineer has intuitively known

Interestingly enough, the corroboration of the idea resulted in part from accidental failures of the impressed current circuit at times when the laboratory was unattended, that is, during evenings and

weekends.

It is felt also that the outcome resulted from the use of soil electrolyte and non-uniform current density on the lead cathode. The soil acted as a partial barrier to keep the alkaline polarization products from diffusing away from the lead. The non-uniform current density resulted in variations of alkalinity along the lead electrode and indirectly in variations in equilibrium potential of the lead referred to the adjacent soil. Thus, at the high current density end of the buried electrode, the pH was approximately 14 and the equilibrium potential of the lead approximately -0.6 volts. At the low current density end of the electrode, the pH was about 9 and the equilibrium potential about —0.3 volts. Thus, when the impressed current circuit was interrupted, the lead electrode with its surrounding electrolyte formed a 0.3-volt galvanic cell, the anode being surrounded by soil at pH 14 and the cathode by soil at pH 9. This would account for the severe corrosion found at one end of the electrode.

The galvanic cell which existed in the laboratory is an over simplification of the field condition where the lead sheath is electrically connected to iron pipes. Other investigators have shown that in an alkaline environment, lead is anodic to iron. Thus, interruption of an impressed current circuit would cause the portion of lead which received a high cathodic current to become anodic not only to the other portions of lead but also to large areas of nearby iron pipe. Needless to say, the corrosive attack would be greater with the lead connected to iron.

Reply by W. H. Bruckner:

Mr. Kulman aptly suggests the existence of concentration cells in a pH gradient and the reversal of potential of iron-lead cell in service with sufficient (alkalinity). It is also true as he points out that prior cathodic protection at excessive levels in soil produces the environ-ment of high alkalinity which accounts for the severe corrosion. There is however another factor which is cited and which has not previously been given field consideration and this is the clean, film free surface due to excessive cathodic protection. The clean surface has a maximum initial corrosion rate, thus short periods of corrosion on open circuit in-terspersed with periods of recleaning under cathodic protection could account for the rapid losses experienced in the Series B tests.

#### Comments by J. J. Pokorny, Cleveland Electric Illuminating Co., Cleveland, Ohio.

Mr. Pike has said that cathodic corrosion of cable sheaths does not occur very often and that he has not seen or heard

of a case in several years.

This is surprising because in Cleveland we find that between 40 and 60 percent of our lead cable sheath corrosion occurs in stray current areas where the cable sheath is cathodic. The corrosion of the sheath found in these areas is easy to identify and is characteristic of this type corrosion. The lead is corroded away in long grooves and patches and in these corroded areas it is usually covered with yellow, orange or red lead compounds. Re-deposited buttons and tongue shaped islands of gray lead are usually found between the grooves and pitted areas.

I am sure that the communication people in our area have experience very similar to ours. It is very difficult to believe, that the conditions in Cleveland are unique. I feel that this type of corrosion must be prevalent in other localities also, but the people have come to call this type corrosion something other than cathodic corrosion.

We feel that we must classify this type corrosion as cathodic corrosion because it is the negative polarity which creates the alkaline condition causing the initial corrosive attack on the lead. In order to mitigate the corrosive condition, we must remove or reduce the negative condition of the sheath by any one of several means available in any specific case.

T

Zi

to

sti

O

th

De

of

SO

Reply by W. H. Bruckner:

Mr. Pokorny's comments indicate experience at variance with that of Mr. Pike. We have also heard at various NACE meetings of current problems with alkaline corrosion of cathodically protected lead cable sheath. It is our hope that the data we have presented will help to reduce the incidence of such corrosion.

We have seen some examples of the corrosion pattern which Mr. Pokorny describes with long grooves or patches corroded out of the lead sheath where it contacted the duct or at the air interface of the water remaining in dip sections. The examples we have seen, however, were not accompanied by colored corrosion products or redeposited lead, thus indicating causes other than the cathodic protection system. As we have cited, service failure is the integrated effect of (1) any corrosion occuring during cathodic protection due to insufficient current, (2) any corresion occurring after cessation of cathodic protection due to low water level and (3) periodic stray current of sufficient level to cause positive polarity. We still prefer calling these corrosion due to cathodic products or alkaline corrosion because in every case active anodes exist except where adequate cathodic protection is maintained.

In summary, we would like to thank the discussers of the article for their interest and for confirming the authors' hopes of maximum effectiveness of the data in coping with service conditions of cathodically protected lead cable sheath.

Duct Anode Development and Experience in Protection of Underground Cables From Corrosion by J. E. Johnson. Corrosion, Vol. 15, No. 8, 423t-427t (1959) Aug.

Comments by David T. Jones, Pacific Telephone Co., Los Angeles, California:

We developed and installed a graphite anode in October, 1951, of a design ex-

plained in this article.

The anode was made from a standard commercial 3-inch by 60-inch graphite anode, which was cut into five 12-inch lengths, each length turned on a lathe to a 2-inch diameter. A ½-inch hole was drilled through the center lengthwise for a No. 6 insulated copper wire. Each end was counter-bored for about 3½ inches and at a ¾-inch bore. Wire insulation was removed for distances of 5 inches at intervals of 3 feet. The wire



Figure 1—Twelve-inch by 2-inch diameter graphite anode made from a 3-inch by 60-inch anode. Copper wire was used to string the anodes.

was threaded through the anodes and the bare portion positioned so that the center of the bare wire and anodes coincide.

One end of the counter-bore was plugged while molten wiping solder was poured into the area between the bare copper wire and graphite anode until it filled up to the bottom of the top counter-bored area. The two counter-bored spaces were filled with a sealing compound. The completed anode resembled a sausage string. One of the anodes is shown in Figure 1.

This anode system was in operation until early 1958, when failure occurred because of compound seal failure around the anode wire, allowing moisture to contact the wire which thus became part of the anode system.

We have used junk lead-sheathed cable or a special electrolysis lead control cable for over 20 years as duct anodes with excellent and efficient results.

The anodes on the sausage string were placed at 3-foot intervals in order to be located near the joints in the multi-duct vitrified clay conduit.

vitrined ciay conduit

Stress Corrosion Cracking of Oil Country Tubular Goods by R. L. McGlasson and W. D. Greathouse. Corrosion, Vol. 15, No. 8, 437t-442t (1959) Aug.

Questions by H. Lee Craig, Jr., Reynolds Metals Co., Richmond, Virginia:

1. What is the location, direction and extent of the crack which is produced in your notched specimen?

2. What surface preparation do you apply following the machining of the notch, including the removal of machining oils, etc.?

Reply by R. L. McGlasson:

1. The cracks initiated in all but two

of the several hundred specimens tested to date were at one side of the notch root rather than at its actual apex. This could be due to some minute and undetected sharp radius of curvature gradi-ent produced by the juncture of the straight tangential edge of the milling cutter and the radius portion of the cutter. As far as we know, however, this is not the case. It seems more likely that this off-center position represents the microscale boundary region of plastic and elastic deformation. It is in this region of high atomic distortion that the maximum susceptibility to hydrogen and/or stress cracking effects would be expected. Previous investigators have demonstrated theoretically and experimentally that this region occurs at about 45 degrees to the notch axis for hyperbolic notches.1

The two anomalous failures occurred at comparatively shallow metal stamp identification marks, well away from the notched region. These results indicate the extreme importance of cold work on

initiating these cracks.

The cracks proceed directly across the specimen from the point of initiation. The harder samples frequently crack completely through the cross-section. The softer ones usually have a thin region (1/8 to 1/4 of section) on the inner surface still intact. The softer ones always show some dimple on the sample edge, indicating that after initiation at least part of the crack propagation involves normal yielding. This effect is not readily apparent on the harder samples. Thorough metallographic study of these specimens has not been made; consequently, we have no data on the relation of the crack to microstructural morphology.

2. Following the machining, the specimens were washed thoroughly in naphtha, then in acetone. Several washes of each were used. No other cleaning was done. The notch surface is left in the as-

machined condition.

Reference
1. Hendrickson, Wood and Clark. Brittle Fractures in Mild Steel. ASM Trans, 50, 656-675 (1958).

Comments by Joe Chittum, Whittier, California:

We have tried to solve the problem of determining the stress that is applied to a specimen by putting the bar totally under tension.

The place where the stress corrosion cracking was produced was limited by limiting contact length between corrosive solution and bar.

Discussions of technical articles appear in the June and December issues only when they do not immediately follow the article to which they pertain. Discussions received from November through April will appear in the June issue and those from May through October in the December issue.

# ERRATA-CORROSION, Volumes 14 and 15

Comparison of Corrosion Engineering or Materials Engineering Functions in Various Chemical Plants by L. W. Gleekman. Corrosion, Vol. 14, 540t (1958) Nov.

1. 15

sted tch his un-

adi-

the

ling

the

this

hat

the

stic

this

the

gen

be

ave

eri-

oout

per-

rred

mp

the

cate on

the

ion. ack The

gion survays

dge, east lves

dily

horeci-

ıtly, the

tha, each

one.

as-

tures 8). tier, n of d to tally

by orroEntry under heading "Investigates Paint Problems" for General Chemical Div., Allied Chemical & Dye, Camden, New Jersey, should read:

instead of

The letter "X" will indicate that this company does investigate paint problems.

Zinc in Marine Environments by E. A. Anderson. Corrosion, Vol. 15, No. 8, 409t-412t (1959) August.

On page 411t, Tables 10 and 11 at bottom of this errata page should be substituted for Tables 10 and 11.

On page 411t, column 1, second line from the bottom should be changed to read:

vanized sheets were perforated after 26

Design and Materials for Reduced Pump Corrosion by Jack E. Piccardo. Corrosion, Vol. 15, No. 9, 473t-476t (1959) September.

Page 476t, middle column, first two lines of J. E. Piccardo's reply to A. V. Morrison should read as follows:

1. Cavitation erosion is a dynamic action within the fluid and cannot be overEffects of Foreign Metals on Corrosion of Titanium in Boiling 2M Hydrochloric Acid by Roger Buck, III, Billy W. Sloope and Henry Leidheiser, Jr. Corrosion, Vol. 15, 566t-570t (1959)

On page 570t, column 3, two sets of numbered references appear. The top set, numbered one through seven with all numbers in parenthesis, apply to Table 4 of the article rather than to the text. The six references immediately below this group apply to the text.

Abstract Section. Pages of the Corrosion Abstracts section in the January and February 1959 issues were numbered incorrectly in the lower outside margins where the "a" series numbers are carried. The January issue should have begun with 1a and ended with 18a. The February issue should have begun with 19a and ended with 28a. Corrected numbers are reproduced below for pasteup correction of these two issues:

3a 6a 7a 1a 2a 4a 5a 9a 10a 11a 12a 13a 14a 8a 15a 16a 17a 18a 19a 20a 21a 22a 23a 24a 25a 26a 27a 28a

TABLE 11—Calculated and Observed Coating Life

	WW-145-4-4	Time to 100	Time to Perfora		
Location	Weight of Coating (a)	Observed	Calculated	tion of Black Iron—Years	
Key West	2.5 2.0 1.5 1.25 0.75 None	> 26 > 26 > 26 > 26 > 26 > 26 > 26	99 79 60 50 30	3.9	
Sandy Hook.	2.5 2.0 1.5 1.25 0.75 None	> 25 > 25 > 25 17.9 15.2 11.3	30 24 18 15 9	7.3 (b)	
State College.	2.5 2.0 1.5 1.25 0.75 None	> 32 > 32 > 32 > 32 > 32 > 32 23.5	50 40 30 25 15	26	

(a) In ounces per square foot of sheet.(b) Average of sheets showing failure—final average may be higher.

#### **TABLE 10—Atmospheric Corrosion of Corrugated Galvanized Sheets**

			Time in Years To—							
Location	Steel Gauge	Weight of Coating (a)	First Rust	100% Rust	Sheet Perforation	Rust (b) Spots	Perforation from Below (b)			
Key West	22 16 22 22 22 22 22 22 22 22 22 28	None 2.5 2.5 2.0 1.5 1.25 0.75 0.75	> 26 > 26 > 26 > 26 > 26 > 21.5-> 26(c) 18.3(d) 18.7(d)	> 26 > 26 > 26 > 26 > 26 > 26 > 26 > 26	3.9 > 26 > 26 > 26 > 26 > 26 > 26 > 26 > 26	> 26 25.5 22.8 19.8 19.8 12.5(d) 13.1(d)	21.9-> 26 24.3-> 26 25.5 21.5 22.8 17.5(d) 18.9(d)			
Sandy Hook. Sandy Hook	22 16 22 22 22 22 22 22 22 22 22 22	None 2.5 2.5 2.0 1.5 1.25 0.75 0.75	11.8 13.1 9.9 7.6 6.8 4.8 4.9	> 25 > 25 > 25 > 25 17.9 15.2 11.3 11.1	7.3(d) > 25 > 25 > 25 > 25 > 25 > 25 > 25 > 25	(e) (e) (e) (e) (e) (e)	(e) (e) (e) (e) (e) (e) (e)			
State College	22 16 22 22 22 22 22 22 22 22 22 22 22 22	None 2.5 2.5 2.0 1.5 1.25 0.75	24.6 26.3(d) 22.5 17.1 14.6 10.0 11.1	> 32 > 32 > 32 > 32 > 32 > 32 > 32 > 32	26 > 32 > 32	(e) (e) (e) (e) (e) (e) (e) (e)	(e) (e) (e) (e) (e) (e) (e)			

In ounces per square foot of sheet coated both side.

Rust spots and perforation due to corrosion from below penetration zinc coating on upper side.
Only one sheet showed first rusting—remaining 16 showed no rust in 32 years.

A verage of sheets showing failure—final average may be higher.

Corrosion from below did not occur at this site.

REPR	INTS	The Corrosion of Iron in High-Temperature Water. Part I—Corrosion Rate Measure- ments by D. L. Douglas and F. C. Zyzes	50
	ished In Corrosion	Water has a Madeogen Effection Method by	
Remittances must accompany all orders fo	r literature the aggregate cost of which is le 5 will be invoiced if requested. Add 65c p	Corrosion of Metals in Tropical Environ- ments, Part 1—Five Non-Ferrous Metals and a Structural Steel, by B. W. Forgeson,	
package to the prices given below for B	ook Post Registry to all addresses outside the orders and remittances to NACE, 1061 M&	Descention of Laurelined Corrector in Sul-	.50
Bldg., Houston 2, Texas.		High Temperature Oxidation of Iron-Nickel	50
Aluminum The Performance of Alcan 65S-T6 Alumi	Electrical Measurements and Their Inter- pretation in Underground Cable Corrosion Problems by K. G. Compton	Alloys by M. J. Brabers and C. E. Birchenall	50
num Alloy Embedded in Certain Woods Under Marine Conditions by T. E. Wright,	Coatinas	Plants by C. P. Larrabeo and W. L.	50
H. P. Godard and J. H. Jenks	How to Determine a 'Comparable Cost' for Paints by V. B. Volkening and J. T. Wilson, Jr.	Corrosion and the Destination of Corrosion Products in a High Pressure Power Plant by Ross C. Tucker	50
by R. M. Aziz	Exposure in Cold Climates by W. F. Fair,	Methods for Increasing the Corrosion Resistance of Metal Alloys by N. D. Tomashov	50
fluoric Acid in Fuming Nitric Acid on Liquid-Phase Corrosion of Aluminum and Steel Alloys by Davis M. Mason and	Inhibitors	Corrosion of Zinc by Differential Aeration	50
An Eddy Current Gauge for Measuring	tors by A. J. Freedman and A. Dravnieks	SYMPOSIUM ON CORROSION BY HIGH PURITY WATER	
The Corrosion Behavior of Aluminum by	Treatments (Part 1 — Polyvalent Ion-	Introduction, John F. Eckel Corrosion of Structural Materials, A. H.	
Aqueous Corrosion of Aluminum—Part 2— Methods of Protection Above 200 C by	man and T. R. Newman	Roebuck, C. R. Breden and S. Greenburg. Corrosion Engineering Problems, D. J. DePaul.	
J. E. Draley and W. E. Ruther	Dicyclohexylammonium Nitrite, a Vola-	Importance of Data to Industrial Applica- tion. W. Z. Friend. Per Copy\$1.5	50
Structural Features of Corrosion of Alumi-	T. Skei and N. Stillman	Petroleum Production and Storage	
num Alloys in Water at 300 C by Kurt M. Carlsen	Some Experiences with Sodium Silicate as a Corrosion Inhibitor in Industrial Cooling	Naphthenic Acid Corrosion—An Old Enemy of the Petroleum Industry by W. A.	
Aluminum and the Anodic Behavior of the Pure Metal and Its Alloys in Chlo- ride Media by E. M. Khairy and M.	Waters by J. W. Wood, J. S. Beecher and P. S. Laurence Non-Chemical Factors Affecting Inhibitor	50 Analysis of Corrosion Pitting by Extreme Value Statistics and Its Application to	50
Reaction of Certain Chlorinated Hydrocar-		50 Eldredge	50
bons with Aluminum by A. C. Hampstead, G. B. Elder and J. C. Canterbury	Lois L. Taylor and John B. Kittenhouse	Interpretation of Tubing Caliper Surveys by Victor W. Maxwell and Ben D. Park	50
High Purity Aluminum in Water at High Temperatures by M. J. Lavigne	Nitrite Inhibition of Corrosion: Some Prac- tical Cases by T. P. Hoar	Froducts by Robert M. Files and John	50
Cathodic Protection	Type Inhibitors and Cathodic Protection	D. Spivack	,,
and Pipe Lines	Miscellaneous	G. W. Beckman	50
L. P. Sudrabin		50 by F. S. Lang and J. F. Mason, Jr5	50
Cathodic Protection of Oil Well Casings at Kettleman Hills, California by J. K. Bal- lou and F. W. Schremp	Some Aspects of the Corrosion Processes of Iron, Copper and Aluminum in Ethylene Glycol Coolant Fluids by P. F. Thompson	Corrosion Products of Mild Steel in Hydro- gen Sulfide Environments by F. H. Meyer, O. L. Riggs, R. L. McGlasson and J. D.	
Cathodic Protection of an Active Ship Using	Corrosion Control by Magic-It's Wonderful	An Electrical Resistance Method of Corro-	50
Zinc Anodes by B. H. Tytell and H. S. Preiser	Why Metals Corrode by H. H. Uhlig	sion Monitoring in Refinery Equipment by A. J. Freedman, E. S. Troscinski and A. Dravnieks	50
Polarization in the Corrosion of Ice Break- ers by J. H. Greenblatt	***************************************	THREE PAPERS ON	
The Application of Cable in Cathodic Pro- tection—Part I by M. A. Riordan and Part II by R. G. Fisher		SULFIDE CORROSION  A Note on the Value of Ammonia Treat-	
Economic Considerations in Pipe Line Corresion Control by L. G. Sharpe	Jones, Capt. J. F. Mosher, Rudolph Speiser	ment for Tank and Casing Annulus Cor- rosion by Hydrogen Sulfide by Walter F. Rogers	
Application of Cathodic Protection to 48 Well Casings and Associated Production Facilities at Waskom Field by G. L.	Corrosion and Metal Transport in Fused Sodium Hydroxide (Part 2—Corrosion of Nickel-Molybdenum-Iron Alloys) by G. Pedro Smith and Eugene E. Hoffman	Use of Ammonia to Prevent Casing Corro- sion by H. E. Greenwell, Rado Loncaric and Harry G. Byars	
Potential Criteria for the Cathodic Pro- tection of Lead Cable Sheath by K. G. Compton	Corrosion and Metal Transport in Fused Sodium Hydroxide—Part 3—Formation of	Electrochemical Studies of the Hydrogen Sulfide Corrosion Mechanism by Scott P. Ewing 1.0	00
Current Requirement for Cathodic Protection of Oil Well Casing by E. W.	Smith, Mark E. Steidlitz and Eugene E. Hoffman		
Haycock	J. D. Hromi		
and High-Silicon Iron Anodes in Sodium Chloride Electrolytes by S. Tudor, W. L.	The Growth of Ferrous Sulfide on Iron, by R. A. Jeussner and C. E. Birchenall	1-A Survey of the Literature) by Don-	
The Use of Magnesium for the External	Henry Hives	ald Warren	
Cathodic Protection of Marine Vessels by C. F. Schriber	A Minestin Standar of Anid Committee of Cod	The Effect of No, HNO2, and HNO2 on Corrosion of Stainless Steel by H25O4 by W. P. McKinnell, Jr., L. F. Lockwiid, R. Speiser, F. H. Beck and M. G. Fontana .5.	50
in the Presence of Alkali from Deicing Salts by Walter H. Bruckner and W. W.	Cavity Formation in Iron Oxide by D. W. Juenker, R. A. Meussner and C. E.	Inhibiting Effect of Hydrofluoric Acid in	
Microbiological Deterioration of Buried Pipe and Cable Coatings by F. E. Kulman	Relation of Corrosion to Business Costs	Austenitic Chromium-Nickel Steels, by Clarence Levoe, David Mason and John Rittenhouse	50

PIT in Ins Na the

fili ve

joi No cie Pla mo Ch Co the Ch tra hil the Po mc Ch Co


len alli W in

In

vat U. 17 vel



### NACE NEWS



PITTSBURGH SECTION was given this 9 by 7-inch bronze plaque for recognition of the section's participation in the Pittsburgh Bicentennial celebration. The section held an open house on March 5, 1959, at the Mellon Institute. Guest speaker for the occasion was C. J. Wessel, director of the Prevent.on of Deterioration Center, National Academy of Sciences. His talk was titled "The Scope of the Materials Deterioration Problem and the Approach to the Challenge." Pittsburgh Section members responsible for the open house included W. L. Matray, R. W. Maier, G. L. Snair, John Vrable and S. H. Kalin.

PITTSBURGH SECTION

#### Western Region News

Los Angeles Section heard Howard Keller of Jones and Keller, Inc., discuss fluid films for corrosion protection at the November 18 meeting.

San Francisco Bay Area Section held a joint meeting November 10 with the Northern California chapters of the Society of Plastics Industry and Society of Plastics Engineers, Raymond B. Seymour, president of Alcylite Plastics and Chemical Corp., talked on "Plastics vs Corrosion."

R. C. Canapary, product manager of the petroleum industry section of Nalco Chemical Company, will give an illustrated paper on high temperature inhibitors for hydrocarbon environments at the December 8 meeting.

Portland Section heard Raymond B. Seymour, president of Alcylite Plastics & Chemical Corp., speak on "Plastics vs Corrosion" at the November 12 meeting. Rodney Moorman of Bonneville Power

Rodney Moorman of Bonneville Power Administration spoke on corrosion problems at electric power sub-stations and allied equipment at the October 8 meeting.

Western Region's 1960 Conference will be Oct. 6-7 at the Sheraton Palace Hotel in San Francisco, Cal.

In 1958, there were over 11 million privately and publicly owned trucks on U. S. streets and highways, representing 17 percent of the total U. S. motor vehicle registrations.

# Portland Section Plans April 27-29 Short Course

About 18 hours of instruction and demonstrations are being planned for the Portland Section Short Course on Corrosion to be held April 27-29.

Nine major topics are being considered for the short course: fundamentals of corrosion, recognition of corrosion types, instrumentation, corrosion survey, corrosion control methods, protective methods, corrosion prevention, literature sources and demonstrations.

The section on protective methods will include coatings and cathodic protection. Inhibitors will be included in the section on methods of controlling corrosion.

General chairman for the short course is R. V. Moorman. Vice chairman is O. Hudrlik.

Others appointed to committees are listed below.

Program Committee: Chairman Nealley Wood, Charlton Laboratories, Samuel Grub, Portco Corp., Sid Moore, S. S. Moore & Associates, Thomas Hayes, Cornell, Howland, Hayes & Merryfield, and Bruce Nichols, Pacific Telephone & Telegraph.

Facilities Committee: Chairman George Merz, Portland General Electric, J. L. Williams, Fabri-Valve Co., of America, Joe Smith, Northwest Natural Gas Co.,

(Continued on Page 71)

# Trouard Will Represent NACE on ASCE Committee

S. E. Trouard, corrosion engineer for New Orleans Public Service, Inc., has been appointed NACE's official representative of the American Society of Civil Engineers Committee on Pipeline Crossings of Railroads and Highways. He is also representative for the American Gas Association Operating Section's Corrosion Committee on the ASCE Committee.



The ASCE Committee is charged with the responsibility of writing proposed specifications for pipeline crossings of railroads and highways that will be recommended to the American Standards Association for adoption into a standard code

#### Friend Appointed NACE Representative for ASA

W. Z. Friend of International Nickel Co., Inc., New York City, has been appointed NACE's representative on the American Standards Association Sectional Committee N-5 on Chemical Engi-

neering in the Nuclear Field.

90

The appointment came as a result of an invitation from American Standards Association for NACE to participate in the Sectional Committee deliberations, according to Hugh P. Godard, NACE president.

# Rutter Heads Committee To Plan Short Course

C. M. Rutter, chief corrosion engineer of the Equitable Gas Co., Pittsburgh, Pa., is general chairman for the 1960 Ap-

for the 1900 Appalachian Underground Corrosion Short Course scheduled for June, 1960, at West Virginia University, Morgantown, W. Va.



A meeting of the short course General Committee was held December 3 at the Penn-Sheraton Hotel in Pittsburgh, Pa.

Ci


CI

Inc

Inc

Sa Ph

Fa



# HOW TO CHECK OUT THE TOUGHEST TAPE EVER WRAPPED AROUND PIPELINE

Give it the works . . . that's what Polyken did to its latest development— Extra Strength No. 960

... Run it through every tape durability test a laboratory can apply.

...Wrap this rugged tape around 30 miles of 24-inch gas line in the swamp water and coral rock of southern Florida. Let an Iranian oil company use it on 200 miles of desert oil line. Put it to work for the Phillips Petroleum Co. in Texas and Canada.

If a tape coating can stand all this and still do the whole job cheaper than hot dope, you've got something special. Something permanent in pipeline protection—Polyken Extra Strength No. 960 Pipeline Roll.

Available at no extra cost.



Applying Polyken protection, as seen above, the Houston Texas Gas and Oil Corporation laid a 1600-mile gas line from Louisiana to Florida. Polyken saved them \$500 per mile by way of less men per job and more miles per day. Tape's ready. No primer, no drying or cooling, no fumes or fire hazard. And low equipment cost.

Get the full particulars on Polyken performance and economy from your Polyken representative or write Polyken Sales Division, 309 W. Jackson Blvd., Chicago 6, Ill.

# Polyken

Experienced in modern
PROTECTIVE COATINGS

THE KENDALL COMPANY

1. 15

ura-

ply.

1 30

amp

ern

any ine.

tro-

this

aper

ning

t in

ktra

tion

mile

niles

ying

orm-

309

S

# POLYKEN PROTECTIVE COATINGS DISTRIBUTORS

Atlanta, Georgia Steele & Associates, Inc.

Chicago, Illinois Sales Engineering Inc.

Cincinnati, Ohio Hare Equipment

Cleveland, Ohio

Denver, Colorado Patterson Supply

Des Moines, Iowa Donald Corporation

Fort Worth, Texas
Plastic Engineering & Sales Corp.

Harvey, La.
Allen Cathodic Protection
Company, Inc.

Houston, Texas Cathodic Protection Service

Kansas City, Missouri Industrial Coatings Engineering Co.

Long Beach, Calif. Barnes & Delaney

Memphis, Tenn. General Pipe & Supply Co.

Minneapolis, Minn. Simcoe Equipment Co.

Philadelphia, Pa. Harold N. Davis Co.

Plainfield, New Jersey Stuart Steel Protection Corp.

St. Louis, Missouri Shutt Process Equipment Co.

San Francisco, Calif. Incandescent Supply Co.

San Francisco, Calif. Phillips & Edwards Electric Co.

Seattle, Washington
Farwest Corrosion Control Corp.

Seattle, Washington
Pacific Water Works Supply Co.

# Polyken

Experienced in modern PROTECTIVE COATINGS

#### South Central Region News

#### Tulsa Section Sponsors 11th Annual Short Course

The 11th Annual Corrosion Short Course for Pipeliners sponsored by the Tulsa Section will be held in Tulsa Feb. 24-26, with headquarters at the Mayo Hotel, according to Paul Fisher, chairman of the Short Course Committee.

The three-day course, covering practical control of pipeline corrosion, is planned specifically for foremen, superintendents, field and junior engineers, technicians and inspectors. Experienced corrosion engineers will give non-technical presentations on the causes of corrosion, measurements and instrumentation, pipe coatings, galvanic anodes, impressed currents and miscellaneous corrosion control devices.

Corrosion control devices.

Corrosion engineers who will conduct lectures and discussion periods include Frank Harris, Service Pipe Line Co., Orville Everett, Oklahoma Natural Gas Co., Melvin Barb, Kerr-McGee Oil Industries, Inc., T. L. Canfield, Cathodic Protection Service, L. G. Maddox, Continental Pipe Line Co., W. A. Hutchison, Sinclair Pipe Line Co., Louis Hayward, Mid-Continent Pipe Line Co., and B. H. Davis, Gulf Refining Co.

The \$15 registration fee covers a

The \$15 registration fee covers a banquet and transportation to demonstration sites. Registration forms or further information may be obtained from Ray Amstutz, Box 4597, Tulsa, Oklahoma.

Other officials of the course are Dick Walton, Royston Laboratories, program chairman; Gene Donaldson, Pan American Research Center, arrangements; Hugh Brady, Corrosion Services, Inc., registration; Louis Hayward, Jr., Mid-Continent Pipe Line Company, field trip and A. Z. Partain, Pittsburgh Coke & Chemical Company, banquet.

#### Central Oklahoma Section Plans 1960 Short Course

Plans are underway for the 1960 Corrosion Control Short Course to be held September 28-30 by the Central Oklahoma Section and the Extension Study Center of the University of Oklahoma

September 28-30 by the Central Oklahoma Section and the Extension Study Center of the University of Oklahoma. The course is designed to meet the needs of industrial personnel, both engineering and operating, who are concerned with corrosion control and to help train new personnel in corrosion control fundamentals.

North Texas Section will have Jack P. Barrett of Pan American Petroleum Company as guest speaker at the December 14 meeting. He will speak on application of plastics in the oil and gas industry.

industry.
W. C. Koger of Cities Service Oil Company spoke on testing mixed sucker rod strings at the November 9 meeting.

At the October 19 meeting, Allan Shell of Mobil Producing Company's Research Laboratory spoke on cooling water corrosion and treatment.

Alamo Section had a program on instrumentation as applied to corrosion testing at the October 20 meeting. The technical program was conducted by the Wayne Broyles Engineering Corp., Houston.

Corpus Christi Section showed the NACE film "Controlling Corrosion" at its October 27 meeting.

East Texas Section held a discussion on corrosion problems in producing wells at its October 27 meeting.

Houston Section heard John W. Nee of Briner Paint Mfg. Co., Inc., Corpus Christi, speak on the effect of atmospheric environment on corrosion rates of steel at the November 10 meeting.

Shreveport Section had David M. Upbe-graff, Minnesota Mining & Manufacturing Co., St. Paul, Minn., speak on microbes and corrosion at the November 3 meeting.

# LaQue to Address Joint NACE-ASTM Meeting Feb.9

F. L. LaQue, International Nickel Co., Inc., president of the American Society for Testing Materials, will address a joint meeting of Southwest District ASTM and Houston Section NACE February 9. Mr. LaQue, formerly a president of NACE will speak on "Research in Corrosion."

#### Canadian Region News

Edmonton Section heard E. T. Thompson of the Sherwin-Williams Company speak on proper selections, use and performance of maintenance coatings at the October 22 meeting.

Canadian Region's Eastern Division Conference will be held January 17-20 in Toronto.

Canadian Region's Western Division Conference will be February 10-12 in Vancouver.

#### Portland Section-

(Continued From Page 69)

Chet Elston, Pacific Power & Light Co., and G. F. Eppley, Electrolytic Products Co.

Co.
Publicity Committee: Chairman Chal
Larson, Sheldon-Dunning, Inc., Dean
Burgan, Electric Steel Foundry, Robert
Baynham, Dearborn Chemical Co., and
Clyde Novak, Northwest Protective Coat-

Registration Committee: Chairman Curtis Lund, Pacific Telephone & Telegraph, Gene Walthal, Electric Steel Foundry, Robert Baunach, Henry Messenger, Pacific Telephone & Telegraph, and William Scarborough, Bonneville Power Administration.

ministration.
Printing Committee: Chairman Dan
Boone, W. P. Fuller & Co., Keene Shogren, Northwest Natural Gas Co., Del
Brown, Portland General Electric Co.,
John Moeller, School District No. 1, and
Jack Malmquist, W. P. Fuller & Co.

Dec

to

ta

Co

SO

pr

th

an

co

14"

siv



THIRTY TECHNICAL PAPERS presented at the 4th Annual North Central Region Conference included on one "Chemically Modified Coal Tar Coatings," by Francis R. Charlton, shown above, from Koppers Company, Verona, Pa.

#### North Central Region News

#### Technical Meetings Are Well Attended At October Conference in Cleveland

Technical meetings at the 4th Annual North Central Region Conference were well attended with many of them crowded. The conference was held October 20-22 at the Statler Hilton Hotel in Cleveland, Ohio. Total attendance was about 300.

Thirty technical papers on various corrosion control subjects were presented in five symposia. Five plants were visited as part of the conference program,

The so-called Russian expert, Louis Revnyak, entertained the large noon luncheon held October 21 with his humorous dissertation on the Russians and their "firsts."

Six NACE Technical Committees held meetings during the conference. These included T-6F, T-6H, T-5D, T-2L, T-5C-2 and T-7B.

The 1960 North Central Region Conference will be held October 1920 at the Shroeder Hotel in Milwaukee, Wis.

Southwestern Ohio Section prepared a small printed card for its members with all the meeting dates, speakers and technical program topics for 1959-60.

With no meeting scheduled this month, the section will hear Robert Pierce, Pennsalt Chemical Corp., speak on corrosion resistance and masonry construction at the January 26 meeting to be held in Cincinnati.

James Myers of Wright Air Development Center spoke on applications of refractory metals in space technology at the November 24 meeting in Dayton.

Corrosion inhibitors were discussed by Jerry Alert, General Electric Co., at the October 27 meeting held in Cincinnati.

Chicago Section scheduled Walter H. Bruckner, metallurgical engineering research professor at the University of Illinois, to talk on the effectiveness and problems of cathodic protection at the November 17 meeting.

Kansas City Section had Joe H. Pitts, Standard Magnesium Anode Corp., speak on the manufacture and design of magnesium anodes for the November 9 meeting.

Eastern Wisconsin Section scheduled a talk by G. A. Stein of A. O. Smith Corp., for its November 9 Technical meeting. His talk was titled "Why Plastics?"

Detroit Section held its October 29 meeting at the Stroh Brewery Company plant. A trip through the plant was followed by a discussion by the maintenance superintendent on brewery corrosion problems. A buffet luncheon was served also.



PROTECTIVE COATINGS SYMPOSIUM included a paper on "Epoxy Resin Protective Coatings," by N. A. Mason of Pittsburgh Plate Glass Co., Pittsburgh, Pa., presented at the 1959 North Central Region Conference.



CONFERENCE REGISTRANTS are shown getting tickets to attend the five plant visits which were scheduled as part of the North Central Region Conference. About 300 attended the conference in Cleveland.

#### **NEWS DEADLINE FOR CORROSION**

News intended for publication in CORROSION should be in Houston not later than the 10th of the month preceding month of publication. When events occur at or near this date, it sometimes is possible to hold space for news stories, provided advance notice is given. An estimate of the amount of space required should be included in the advance notice.

#### Northeast Region News

Philadelphia Section has scheduled its annual Christmas meeting for December 15. Norm Neilson of Du Pont will speak on modern research techniques applied to corrosion problems.

Kenneth Tator spoke on standards of surface preparation for coatings at the section's October 23 meeting.

Wilmington Section had Wayne Friend of International Nickel Co., Inc., speak on general corrosion problems in the chemical and petroleum industries at the November 16 meeting. l. 15

held hese -2L, Conthe

da with echthis bert eak o be lopy at by the ati. H. re-Iland the

itts, eak ageet-

d a

ing.

eetant. ved su-

lso.


15.

on

to

the

end eak the the



Erecting the all-welded, two-part chromiumnickel stainless steel recovery tower at Gary chemical works of United States Steel Corpora-

tion. Graver Tank & Mfg. Co., Inc. of East Chicago, Indiana, fabricated the 90-foot tower and tested it to pressures of 162 psi and 246 psi.

# Stainless steel tower goes up...corrosion comes down... in recovery of aromatic chemicals from coke oven gases

This chromium-nickel stainless steel tower recently took over an important job at the Gary Steel Works Coke & Coal Chemicals Div. of U. S. Steel. The big vessel receives hot absorption oils from other parts of the processing plant . . . puts them through its six-tray light oil section, and 15-tray light oil stripper . . . recovers benzene, toluene, and xylene.

It's a productive but highly corrosive process. So corrosive that it


knocked out a carbon steel tower in relatively short time. That's why for its replacement the Gary Works decided on Type 304 ELC chromiumnickel stainless steel. This nickel-containing stainless steel can take the corrosive effects of these gases and chemicals . . . it assures *long* service life.

For your corrosion problems, it will pay you to consider nickel-containing stainless steels. They are highly resistant to a wide range of organic and inorganic chemicals.

A 34-page booklet, "Corrosion Resisting Properties of the Austenitic Stainless Steels," is available to you upon request. If you'd like a copy, simply write:

THE INTERNATIONAL NICKEL COMPANY, INC. 67 Wall Street New York 5, N.Y.

INCO NICKEL
NICKEL ALLOYS PERFORM BETTER LONGER



# Successful

#### Two Chairmen Named To Head Work on Plastic Coated Pipe

Chairmen were named for two committees to be composed of persons interested in plastic coated pipe used in the petroleum industry at a meeting of T-1 in Denver. The meeting was one of 17 scheduled for technical committees at the 1959 South Central Region Conference held October 12-15. One committee, headed by Dorsey R. Fincher, Tidewater Oil Company, Houston, Texas, will be composed of pipe users; the other headed by Patrick R. Donnelly, Plastic Applicators, Inc., Houston, Texas, will be composed of pipe producers.

The aim is to coordinate the activities of both groups so that producers will have better information on users' needs and users will have more reliable information on producers' products.

This group, one of several initiated under the proposed reorganization of T-1, is to make its first report at the March NACE National Conference in Dallas.

#### Inhibitor Squeeze Results

Reporting on data collected on inhibitor squeeze results, R. H. Poetker, Sunray Oil Corp., Corpus Christi, Texas, said reports have been received on 300 wells using 32 chemicals, 92 percent of which had successful results. Significant among the findings indicated by the reports, he said, was the fact that the kind and quality of the diluent used for the inhibitor was important to its success. It also was learned that applications after the first appeared to give better results than the initial application.

T-1 on Corrosion in Oil and Gas Well Equipment sessions lasted all of Monday, October 1, most of Tuesday and part of Wednesday. During this time numerous reports of committees and their task groups were heard and discussed, and considerable time was spent considering the proposed reorganization of the committee's structure.

T

Among topics considered during the meeting were terminology problems in connection with interference studies on cathodic protection systems on oil well casings, and tools for the detection of external corrosion on oil well casings.

TECHNICAL MEETINGS held at the recent South Central Region Conference in Denver are shown. Photo One: Fred B. Hamel of Standard Oil Co., Cleveland, Ohio, who is chairman of Technical Committee T-8A, is shown talking before the T-8 group. Seated at the table, left to right, are T-8 officers: Secretary R. L. Merrick, Esso Research & Engineering Co., Linden, N. J., Chairman E. B. Backensto, Socony Mobil Oil Co., Inc., Paulsboro, N. J., and Vice Chairman Cecil Phillips, Jr., Humble Oil & Refining Co., Baytown, Texas. Photo Two: T-6D-1 Chairman S. L. Lopata, Carboline Co., 5t. Louis, Mo., is giving a report at the T-6D meeting. Seated at the table are T-6D Chairman R. H. Bacon, Dow Chemical Co., Texpoort, Texas, and Acting Secretary F. Parker Helms, Union Carbide Chemicals Co., Texas City, Texas. Photo Three: Frank B. Burns, General Asphalts, Inc., Wynnewood, Okla., opens the Pipe Line Corrosion Symposium. Photo Four: T-2B Chairman Richard J. Emerson, El Paso Natural Gas Co., El Paso, Texas, presides at the T-6Z meeting. Photo Five: Protective coatings in petroleum production are being discussed at the T-6E meeting with C. J. Fritts, Socony Paint Products Co., Houston, Texas, as chairman.

m-

in-

in

of

at

on-

mer.

on,

rs;

on-

on.

ro-

vi-

ers

ble

ted

of

in

bi-

er,

300

of

ant

re-

nd the It

ter

lts

ell on-

nd

me

nd lis-

on

he

in on ell of

wn. Co., ical T-8 T-8 B.

wo: St. ing. ion, ieccals rns, the -2B Gas

# Conference Held at Denver



NACE PRESIDENT-ELECT George E. Best was presented a ten-gallon hat, emblematic of acceptance into the brotherhood of the West. J. A. Calwell, Humble Oil & Refining Co., Houston, Texas, made the presentation.

#### Several Denver Meetings Had "Standing Room Only"

Most meetings of technical committees held during the Denver Conference in October were well attended. Some meetings were so crowded there was not even standing room left, and many who tried to be present could not get into the meeting rooms. This resulted in part from larger than anticipated attendance and in part from the fact that available meeting rooms were limited in size.

Some companies took advantage of the presence at the meeting of representative attendance from their companies to hold meetings devoted to company business.

pany business.

#### **Technical Tours Held**

Technical tours arranged for the Denver meeting were well attended, especially the Engineering Laboratories of the Bureau of Reclamation. The Ohio Oil Company's Research Center also was visited by two groups.

#### **Annual Fellowship Hour**

The annual Fellowship Hour, attended by more than 600 persons was, as is the custom, the best attended function of the Denver South Central Region meeting.



#### TECHNICAL REPORTS

on

# Marine Biological Deterioration

T-9 Observations on the Resistance of Natural Timbers to Marine Wood Borers. A Contribution to the Work of Group Committee T-9 on Marine Biological Deterioration, by C. H. Edmondson. Pub. 58-14. Per Copy \$.50.

#### About 600 Attend Busy Sessions at Regional Meeting

A smoothly functioning, business-like program made the October 12-15 Thirteenth Annual Conference of NACE's South Central Region worthwhile to almost 600 registrants. Of these, some 75 were women, attracted to the scenic beauties of the fall countryside in Colorado. A well-organized and completely satisfying social program was carried on during the meeting. The ladies' program was especially interesting and drew wide participation.

The program, arranged so that the program of technical committees meetings and the technical symposia were virtually separated, attracted good attendance at most sessions. Registration proceeded without undue delay.

In addition to the technical and social programs, numerous business sessions of regional groups were held. Among these was the annual business luncheon, attended by about 400 persons, at which regional officers and national officers were introduced. Also held were meetings of the regional board of trustees and the region's education committee. Both of these sessions were attended by representatives groups.

A three-man vocal and instrumental act was featured as entertainment at the annual banquet, and this was followed by dancing.

Besides the usual business of the luncheon, the region took the opportunity to present to Vice President George E. Best, incumbent 1960-61 president of NACE, a ten-gallon hat emblematic of his acceptance by the brotherhood of the West. An address by Chester Lauck, executive assistant, Continental Oil Co., formerly the "Lum" of radio's Lum and Abner team, concerned the necessity for business and businessmen to take active part in politics. Mr. Lauck stressed the importance

of getting the business viewpoint effectively presented to the public and effectively represented on political bodies.

# J. A. Caldwell Appointed To Board of Directors

J. A. Caldwell, senior research engineer for Humble Oil and Refining Company, Houston, Texas, was appointed to the NACE Board of Directors to represent the South Central Region. He will fill the unexpired term of the late J. C. Spalding.

The appointment was made at a meeting of the South Central Region Board of Trustees held during the region's conference in Denver, Oct. 12-15.



HOSTESSES for the ladies' program at the Denver Conference were Mrs. William P. Becker (standing) and seated, left to right, Mrs. H. K. Becker and Mrs. Herbert L. Goodrich.



DANCERS rest a few minutes following the South Central Region annual banquet at Denver.

# Corrosion of Anodic Surfaces Is Controlled by Electrical Method

Instrumentation which permits controlling corrosion of anodic surfaces by application of electrical currents of very small magnitude has been developed by team of researchers in the Ponca City laboratories of Continental Oil Com-pany. Their discovery and extensive data on its practical use, as well as some estimates of the importance of their method, were described in three technical papers during the Denver con-ference of NACE's South Central Re-

The three papers in the Refining and Chemical Process Industries Sympos-Chemical Process Industries Symposium presented during the afternoon of October 14 were Anodic Passivation Studies by J. D. Sudbury, O. L. Riggs and D. A. Shock; Anodic Control of Corrosion in a Sulfonation Plant by O. L. Riggs, M. Hutchinson and N. L. Conger; and Application of Anodic Corrector. Control in the Chemical Industrial rosion Control in the Chemical Industry by Shock, Riggs and Sudbury.

Far Reaching Effect Seen

Application of the new method may have a far reaching effect on the selection of materials for design of vessels handling corrosive fluids, especially those at temperatures to 500° F. A potential regular developed by the research team permits controlling corrosion of another supplies the second team of the second team to the second team of the second te sion of anodic surfaces through the application of very small currents. Geometry of the surface apparently has no influence on the efficiency of the system, experiments having shown that 60 feet of stainless steel tubing could be protected from a single cathods even though the system included numerous right angle and other bends.

Although the nature of the passive layer formed on the anodic surface is not clearly defined, data so far obtained indicate it is a very thin oxygen-containing amorphous firm with a resistance in the order of 10<sup>4</sup> to 10<sup>6</sup> ohms per square centimeter. This passive layer can be maintained by the application of small increments of current once the passive state has been reached.

Developed From Flade Effect

That such a method of controlling corrosion is possible has been known for some time. The discovery by Flade in 1911 that steel in sulfuric acid reached a passive state following the application of definite current values over a short time is a well known fact. The research team, proceeding on the assumption that modern instrumentation would make possible a satisfactory system today where earlier researchers had failed, managed to develop a device which permits reaching the passive state quickly, and then maintaining the passive state over a wide variety of temperatures, concentrations and velocities with very little current drain.
D. A. Shock, one of the members of

D. A. Shock, one of the members of the research team, in discussing the work pointed out that the Conoco de-velopment, designated as the "Anotrol" method, is an example of successful use of a discovery made by a researcher concerned only with so-called "pure science" "Development of a reliable and simple means of adding current increments to the anode in sufficient quantity to maintain the continuity of the oxygen-metal passive layer made the Anotrol method practical," he said.

Tested at Baltimore

The automatic potential controller and other aspects of the process were tested at the Baltimore, Md., sulfonation plant of Continental Oil Co. There it was proved that the device would reduce to negligible proportions corrosion of a mild steel oleum storage tank and a Type 304 stainless steel sulfonic acid neutralization vessel. Tests over a year showed good protection, measured in reduced iron concentration, improved concentration, improved product quality resulting from absence of iron salts and increased productivity the plant due to more rapid hydrocarbon separation resulting from absence of iron soaps.

Opportunity was taken during these tests to evaluate the effect of such variables as concentration, changes in surface area, temperature, effect on a variety of metals and effects of a variety of

chemical environments.

Application of the process to an oleum storage tank resulted in reduction of iron content from 500 to 600 ppm to 39 to 41 ppm; in a blowcase tank from 550 ppm to 59 ppm in 10 days.

Stress Corrosion Cracking

The researchers are making studies on the possibility of stress corrosion cracking resulting from the use of the system especially at high stress values. The four years of work has shown no evidence so far that stress corrosion cracking will occur, although some vessels have been passivated repeatedly in a variety of environments. No evidence of stress corrosion was noted in the vessels to which the process was applied at the sulfonation plant. These vessels have been operated at relatively low stress levels.

Ultimate uses of the system are assessed in the third paper of the series. In this paper it is brought out that the two major factors for a successful anodic mitigation system are (1) the solution must be a good conductor and (2) the metal-liquid system must be such that it exhibits the phenomena of an-


odic passivity.

Virtually all water solutions of the oxy-acids, the bases and oxy-acid salts are suitable. Emulsions of strong sulfuric acids and hydrocarbons have been found sufficiently conductive (up to 80 percent oil). Major exclusions are solutions containing halogen radicals which destroy passivity to such an extent that anodic passivation becomes either uneconomical or altogether impossible.

Numerous data were compiled to show the current density required to maintain the passive state of the anode. An analyof the data sometimes make possible an estimate of cost which can influence the decision between alloys or between alloys and steel as a material of construction for specific product

streams

Among the environments in which the process may find application are those involving the handling of nitrate and sulfate salts, some of the fuel element uranium processes and in such applications as alkaline digesters in the paper pulp industry.



TYPICAL ANODIC polarization curve. (Figure 1 from paper, "Anodic Control of Corrosion in a Sulfonation Plant".)



#### December

- Shreveport Section. Capt. Shreve Hotel. Plant Corrosion.
- West Kansas Section.
- Sabine-Neches Section
- Pittsburgh Section. Underground Roundtable. Discussion by six speak-
- Teche Section. Petroleum Club.
- Birmingham Section.
- North Texas Section.
- San Francisco Bay Area Section.
- East Texas Section. Longview Hotel in Longview.
- Philadelphia Section.
- Panhandle Section.

#### January

- North Texas Section.
- Shreveport Section, Capt. Shreve
- West Kansas Section.
- Pittsburgh Section, Microbiological Studies of Pipeline Back-Filled Ditches, by J. O. Harris, Kansas State University.
- San Francisco Bay Area Section.
- Baltimore-Washington Section.
- Chicago Section.
- Los Angeles Section.
- Detroit Section. Tank Lining Forum: L. Woerner, Automotive Rubber Co., L. J Barker, Union Carbide, and W. J. Crehan, Gatz.
- Tulsa Section. Panhandle Section.
- Southwestern Ohio Section. Corrosion Resistant and Masonry Construction, by Robert Pierce, Pennsalt Chemical Corp. To be held in Cincinnati.
- Edmonton Section. Sabine-Neches Section.

Lapel pins approximately 7/16 inches high, made of gold with inlaid red enamel and a ruby center, are available to NACE members only. Price is \$10. Address orders to Executive Secretary, 1061 M & M Bldg., Houston 2, Texas.

l. 15

POINT

reve

ak-

otel

ve

ical

led

sas

ım:

and

ro-

salt

in-

red ble 10.

ry,

as.

SOIL

"National"

GRAPHITE ANODE

Anode notes arbon Compan Barcelona Madrid SEVILLA MEDITERRANEAN SEA ROTA ATLANTIC OCEAN Gibraltar

PROTECTION OF 11,000,000 SQ. FT. OF UNDERGROUND TO RECTIFIER STEEL IN SPAIN

"National" graphite anodes for cathodic protection are used around the world. In 1958 four-hundred-sixty 3"x60" "National" graphite anodes\* were installed to protect the 620 mile Spanish J.U.S.M.G. pipeline from Rota to Zaragoza. The 12", 10", 8" and 6" diameter coated steel pipeline with attendant service pipelines of varying diameters, plus twentysix tank bottoms total approximately 11,000,000 square feet of steel under cathodic protection.

Because of the wide variations in soil resistivity along the pipeline, each anode and rectifier installation had to be individually engineered. Twenty-six rectifiers with outputs ranging from 20 volts DC to 200 volts DC, from 40 amps to

The graphite anodes were placed on 20 foot centers in 12" diameter x 120" deep holes surrounded by well tamped coke breeze backfill. The number of anodes in each bed varied, depending upon the current discharged and the soil resistivity. The system is designed to operate for more than ten years.

100 amps were used. Coke Breeze Backfill \*Wayne Broyles Engineering Company supplied the equipment

"National", "N" and Shield Device, and "Union Carbide" are registered trade-marks of Union Carbide Corporation

NATIONAL CARBON COMPANY · Division of Union Carbide Corporation · 30 East 42nd Street, New York 17, N.Y. OFFICES: Birmingham, Chicago, Houston, Kansas City, Los Angeles, New York, Pittsburgh, San Francisco • CANADA: Union Carbide Canada Limited, Toronto

and installed the cathodic protection system.

De

M

0

# 15 Symposia Co-Chairmen Listed For 1960 Dallas Conference

Fifteen co-chairmen of the technical symposia for the 1960 NACE Confer-ence have been named. The 16th Annual Conference will be held March 14-18 at the Memorial Auditorium in Dallas, Texas.

The 1960 Corrosion Show will be held in conjunction with the Dallas Conference.

The 15 symposia co-chairmen are listed below. They will be chairmen for the technical symposia for the 1961 NACE Conference to be held in Buffalo, N.Y.

The Pulp and Paper Industry Symposium has been postponed until the 1961 Conference in Buffalo.

Cathodic Protection: O. W. Everett, Oklahoma Natural Gas Co., Tulsa, Okla. Chemical Industries: Otto H. Fenner, Monsanto Chemical Co., St. Louis, Mo.

Corrosion in the Missile Industry: Edison H. Phelps, U. S. Steel Corp.,

Monroeville, Pa.
Corrosion Inhibitors: Donald L.
Burns, Gulf Oil Co., Port Arthur, Texas.
Corrosion Principles: C. P. Dillon,

Union Carbide Chemicals Co., Charleston, W. Va.
Educational Lectures: Norman D.

Groves, Carpenter Steel Co., Reading,

Pa.
Elevated Temperatures: David Roller,
Magna Products, Inc., Santa Fe Springs,

General Corrosion: Jerome M. Bialosky, Koppers Co., Inc., Verona, Pa. High Purity Water: W. K. Boyd, Bat-telle Memorial Institute, Columbus,

Oil and Gas Production: J. A. Caldwell, Humble Oil & Refining Co., Houston, Texas.

ton, Texas.

Pipe Line—General: Carleton L.
Goodwin, Portland Pipeline Corp.,
Portland, Maine.

Plastics: John Delmonte, Furane Plastice, Inc., Los Angeles, Cal.

Protective Coatings: Newell B. Casdoreb, Union Carbide, Chemicals, Co.

dorph, Union Carbide Chemicals Co., Port Lavaca, Texas. Refining Industry: R. B. Hamel, Standard Oil Co., Cleveland, Ohio. Utility Industries: A. W. MacKay, Detroit Edison Co., Detroit, Mich.

#### 6 NACE Members Teach at California Short Course

Six NACE members were on the staff Six NACE members were on the staff of the University of California's Short Course on Corrosion Engineering held November 2-6 on the Los Angeles campus. They were William Seyer, professor of engineering, University of California; Norman Hackerman, chairman, Department of Chemistry, University of Texas;
H. H. Uhlig, professor of metallurgy,
Massachusetts Institute of Technology;
Hugh P. Godard, NACE president associated with Aluminium Laboratories Ltd., Kingston, Ontario, Canada; Willard R. Scott, Jr., Magna Products. Inc., and C. M. Schillmoller, corrosion engineer and consultant, International Nickel Co., Inc.

The course was designed to emphasize the problems associated with high and low humidity change in marine atmosphere of the Pacific coast region and to review the fundamentals of corrosion reactions and corrosion control.

#### Southeast Region News

Atlanta Section held a dinner meeting on November 16, Guest speaker was K. G. Compton of Bell Telephone Laboratories, Summit, N.J.

East Tennessee Section had Norman Hackerman, chairman of the University of Texas Department of Chemistry, as or lexas Department of Chemistry, as its guest speaker at the October 22 meet-ing held in Oak Ridge. Dr. Hackerman's address was titled "Mental Dissolution and Its Retardation."

The 1960 Southeast Region Conference will be held Oct. 6-8 at the Dinkler-Plaza Hotel, Atlanta, Ga.

Portland Section's Corrosion Control Short Course will be held April 27-29.









Caldwell



Casdorph



Delmonte



Dillon



Everett



Fenner







Hamel



MacKay





Roller



# MATIONAL and REGIONAL MEETINGS and SHORT COURSES

1960

. 15

at

taff

eld msor

iia;

rt-

as;

gy;

as-

/ilic., gikel

ize

nd

to

G.

an ty as

n

ce

ol

January 17-20—Canadian Region Eastern Division. Toronto, King Edward Hotel.

February 10-12—Canadian Region Western Division, Vancouver, Hotel Georgia.

March 14-18—16th Annual Conference and 1960 Corrosion Show. Dallas, Texas, Memorial Auditorium.

Oct. 6-7—10th Annual Western Region Conference, Sheraton-Palace Hotel, San Francisco, Cal.

Oct. 6-8—Southeast Region Conference, Dinkler-Plaza Hotel, Atlanta, Ga.

Oct. 11-14—Northeast Region Conference. Prichard Hotel, Huntington, W. Va.

Oct. 19-20—North Central Region Conference. Schroeder Hotel, Milwaukee.
Oct. 25-28—South Central Region Conference, Mayo Hotel, Tulsa.

1061

March 13-17—17th Annual Conference and 1961 Corrosion Show, Buffalo, N. Y., Hotel Statler.

Oct. 4-6—Western Region Conference, Hotel Multnomah, Portland, Oregon.

Oct. 9-11—North Central Region Conference, St. Louis, Chase Park Plaza Hotel.

Oct. 24-27—South Central Region Conference, Houston, Shamrock Hotel.

Oct. 30-Nov. 2—Northeast Region Conference, New York City, Hotel Statler. Southeast Region Conference, Miami, Fla., in conjunction with Miami Sec-

tion's short course.

March 18-22—18th Annual Conference and 1962 Corrosion Show, Kansas City, Municipal Auditorium.

October 9-11-North Central Region Conference.

October 16-19—South Central Region Conference, Hilton Hotel, San Antonio, Texas.

Southeast Region Conference, Birming-ham, Ala.

Western Region Conference. San Diego, Cal.

#### SHORT COURSES

1959

December 7-11—University of Illinois Corrosion Control Short Course, Urbana Campus.

196

January 28-29—5th Annual Houston Section 2-Day Course in Practical Corrosion Control Systems. Rice Hotel, Houston.

February 24-26—11th Annual Tulsa Section Corrosion Short Course for Pipeliners. Mayo Hotel, Tulsa, Okla.

April 27-29—Portland Section Corrosion Control Short Course.

September 28-30—Central Oklahoma Section 1960 Corrosion Control Short Course, at University of Oklahoma, Norman.

October 3-5—Corrosion Control Short Course, sponsored by Western Region and University of California.

# GACO V-80 HOT SPRAY VINYL

5 mils of high solids vinyl in a single spray coat and process equipment is protected against corrosive fumes and high humidity. GACO V-80 Vinyl films are hard but flexible, resist abrasion and most corrosive agents, and are easily cleaned. Hot spray technique allows deposit of a low plasticizer quick-drying film with little overspray and excellent edge buildup resistance to sagging. Write for details.



#### FOR HEAVY-DUTY CORROSION SERVICE THE GACO CORROSION PROTECTION SYSTEM

Challenge: When paint or ordinary corrosion protection products won't do the job, specify GACO. A complete line: Neoprene, Natural Rubber, Vinyls, Liquids, Sheet, Putties... performance-proven in applications throughout the world. And A Complete Service. There's a GACO Corrosion Specialist in your area prepared to serve your needs. Write for further information—we'll forward case studies of interest.



THE MARK OF CORROSION PROTECTION

GATES ENGINEERING COMPANY
Wilmington 99, Delaware
Pioneer Leader in Protective Coatings

AUTHORIZED DISTRIBUTORS IN PRINCIPAL CITIES U.S.A. • AUSTRALIA • BELGIUM ENGLAND • FINLAND • FRANCE • ISRAEL • JAPAN • NORWAY • OKINAWA PHILIPPINE ISLANDS • PUERTO RICO • SWEDEN, IN CANADA: GACO PRODUCTS

TUBE-KOTE

Service Mark Reg. U. S. Pat. Off

a dramatic new coating recommended for today's

HIGHER and gas not been hIGHER
HIGHER
TEMPERATURE
WELLS

Tube-Kote Inc. has met the challenge of today's deep, hot wells. For the first time, here is a coating that will stand up to these more critical operating conditions.

You can use TK-7 safely in continuously operating temperatures between 350° and 400°F., and under pressures up to 12,000 psi. TK-7 withstands normal handling, caustic muds, acidizing procedures, and it meets the requirements of elongation and compression found in long strings.

It took Tube-Kote research two years to develop TK-7 — basically a phenolic with a tan color and flat gloss. It takes Tube-Kote's carefully controlled process to properly apply it. Tube-Kote Inc. is proud to recommend it for higher pressure, higher temperature oil and gas wells — where previous coatings have not been able to take it.

THE INDIISTRY PIONEE

scin

th

ar 10 ex

OUR 20th YEAR . . . THE

8 -

P. O. Box 20037 • Houston 25, Texas

Branch Plants: Harvey, Louisiana • Midland, Texas

EXPORT REPRESENTATIVES: LUCEY EXPORT CORP. 223 BROADWAY, NEW YORK 7, N.Y

# **Epoxy Resin Coatings Resist** Intense Gamma Radiation

A nuclear radiation-resistant epoxy resin coating has been developed for concrete and steel which will withstand prolonged exposure to high intensity gamma radiation. The coating was used recently in the construction of the Plum Brook Reactor of the National Aero-nautics and Space Administration near Sandusky, Ohio. The coating must maintain a waterproof barrier and must be capable of being decontaminated contaminated water escape.

Resistance of the coating to radioactive bombardment was tested by exposing panels to a 1½ million volt electron source. Electron bombardment was used instead of the gamma radiation to which the coating will be exposed in use in order to accelerate the testing. gamma rays, the test would have required 1000 hours instead of the 4½ used. Physicists say that gamma or electron radiation produces similar damage.

Coated test panels were passed back and forth through the electron beam at 10-second intervals. After 4½ hours of exposure, the epoxy coating had received a dosage of 1 x 10° rad units (roentgens). When test panels were (roentgens). When test panels were compared with the non-exposed control compared with the non-exposed control panels, there was no visible damage such as cracking, flaking, bubbling or blistering. The coating also withstood over 9500 hours of attack by boiling distilled water, jet fuel and salt spray. Performance of the coating was judged attifactors for services a few feet from satisfactory for service a few feet from the radioactive heart of the reactor.

The radiation-resistant coating is a two-part cold curing vehicle requiring a curing agent to complete the chemical reaction which hardens the resin. The same basic epoxy resin is used for the red primer coat, gray mastic coat (into which glass cloth is embedded) and the white finish coat. Coating thickness is 23 mils on the concrete, 16 mils on the steel.

The Plum Brook research reactor is housed in a 100-ft diameter airtight containment tank. Within this tank is a 70-ft diameter pool of water at the center of which will be the atomic reactor, bedded in a steel pressure vessel surrounded by a 2-ft concrete wall. The water acts as the neutron and gamma ray shield.

Branching out from the center are four concrete quadrants. They are joined by a circular concrete wall which varies in thickness from 2 to 4 feet. The new coating is designed to maintain a waterproof barrier for the containment of the water under a radiation intensity of the 60 megawatt power source.

In operation, all major experiments to be irradiated in the reactor have to be inserted through the water shield which fills the tank quadrants. At the conclusion of experiments, radioactive parts and materials will be removed from the reactor and be carried through a num-ber of water filled canals to the "hot

laboratories" for disassembly and inspection. This method of handling atomic experiments is regarded as a new

Concept in high power reactor design.

When completed, the \$11 million

Plum Brook Reactor will be one of the
nation's largest test facilities. One major objective on the installation will be to develop reactors for space propulsion. Other projects will include element evaluation tests, basic physics studies and the results of radiation damage to materials

The epoxy resin coating was developed jointly by the Shell Chemical Corp., New York, and the Patterson-Sargent Co., Cleveland, Ohio, coatings and paint manufacturers. Preparation, application of coating and glass cloth were done by Akron Sandblast and Metallizing Co., Barberton, Ohio.

#### Belgian Corrosion Study

Pre-determination of corrosion of metals and alloys was the subject of an European study session held at the University School of Brussels, Belgium,

Three papers were presented at the afternoon meeting. They were: Potential—pH Diagram; Theoretical Considerations on Corrosion, Inhibition and Passivation of Metals; and Potentio-static Studies—Applications to Un-alloyed Steels, Alloyed Steels and Discussions followed the

An inspection tour of the university's laboratories followed the meeting. The study session was sponsored by Centre Belge d'Etude de la Corrosion, a nonprofit technical association.


#### **Nace Technical Reports**

STRESS CORROSION CRACKING, 15 papers reprinted from Corrosion. Pub. 59-4. Postpaid,

HIGH PURITY WATER CORROSION. Sixteen papers reprinted from Corrosion. Pub. 59-3. Postpaid, per copy.....\$3

1957-58 NACE TECHNICAL REPORTS, 38 reports reprinted from Corrosion. Includes some Pub. 59-2 and 3 above. Postpaid, per copy.\$6.50

Remittances must accompany all orders for literature the aggregate cost of which is less than \$5. Orders of value greater than \$5 will be invoiced if requested. Send orders to National Association of Corrosion Engineers, 1061 M & M Bldg., Houston, Texas. Add 65¢ per package to the prices given above for Book Post Registry to all addresses outside the United States, Canada and Mexico.



FINAL COAT of a radiation-resisting paint is applied on concrete and steel in a quadrant of the Plum Brook Reactor, Sandusky, Ohio. Total thickness of the coating is 23 mils on concrete, 16 mils on steel.

#### NEWS

Symposium on Instrumentation in At-Symposium on Instrumentation in Atmospheric Analysis. 57 pages, 6x9, cloth. May, 1959. American Society for Testing Materials, 1916 Race St., Philadelphia 3, Pa. Per copy, \$2.25. Four papers presented at a meeting of ASTM Committee D-22 on Methods of Atmospheric Sampling and Analysis at Boston, Mass., June 23, 1958. Persons concerned with metering atmospheric pollution will find the in-

mospheric pollution will find the formation in these papers helpful. Data are given on methods for continuously analyzing contents as well as for periodical measurements.

The papers are: Light Scattering In-strumentation for Particle Size Distribution Measurements, Filtration Methods for Evaluation of Aerosol Contaminants, Relative Merits of Gas Chromatography, Colorimetry and Spectrometry for Air Pollution Studies, An Atmospheric Flu-oride Recorder. There are numerous references.

Compilation of ASTM Standards Relat-ing to Coated and Uncoated Iron and Steel Sheet and Strip, A-1, A-5, 148
pages, cloth, 6x9 inches. American
Society for Testing Materials, 1916
Rade St., Philadelphia 3, Pa. Per
copy \$3.00.

First compilation of ASTM standards relating to coated and uncoated iron and steel sheet and strip. There are 21 standards given including 11 specifications for steel sheet and strip, 3 specifications for metallic coated steel sheet, 2 for wrought iron sheet and one for metallic coating materials. Four test methods are given also.

Dec

PI

To

16t

be Hil

enc

cal

ing

sio

rep

pac

sig

ind

ing

Co

M

lut

to

ten

ph

M

the

bas

N

sol

fib

sol

ioi

C

reprus

# Porcelain Electrode Developed for Salt Study

A porcelain-capsule reference electrode has been developed by the National Bureau of Standards in work sponsored by the Atomic Energy Commission. This reference electrode should be of value in studying electrode potentials in molten salt systems. Accurate data on these potentials are important for investigating electrodeposition from molten salts, corrosion by molten salts, and thermodynamic properties of molten salt systems.

Reference electrodes are used widely in electrochemistry. Several types which have been used for molten salt systems are the silver-silver chloride electrode with a liquid junction, the platinum-platinum (II) electrode, the silver-silver chloride electrode in a graphite sheath for use in fluorine melts, and sodium, sodium alloy, or silver-silver chloride electrodes in glass capsules.

All these electrodes have some disadvantages. For example, those electrodes which make contact to the melt through a liquid junction are subject to fluctuations because of diffusion and mixing Capsule-type electrodes of glass are limited to use at a maximum temperature of about 500 C. The porcelain-capsule electrode, on the other hand, is stable at temperatures as high as 900 C. Moreover, its capsule construction prevents the salt inside the electrode from contaminating the melt under study.

The porcelain reference electrode consists of an outer unit prepared by joining a glass T-tube to a porcelain capsule. Sealed inside this enclosure is an inner unit consisting of a silver wire joined to a tungsten wire. Both are enclosed in a single ceramic capillary tube. Electrical connections can be made to the upper portion of the tungsten wire which extends outside the glass tube. The assembled électrode is filled with the desired amount of silver chloride and sodium chloride through the side arm of the glass T-tube. This portion is sealed off while the entire electrode is being evacuated.

Porcelain capsules of two compositions have been made, one containing 2.5 percent soda (Na<sub>2</sub>O) and the other 10 percent. Electrical measurements at different temperatures showed that the porcelain material containing 10 percent soda has the lower resistivity. The resistivities of both porcelains are many times lower than that of glass, the 10 percent Na<sub>2</sub>O porcelain having only one-hundredth the resistivity of glass at equivalent temperatures. Conduction is entirely by movement of sodium ions.

A first step in preparing the porcelain materials is the formation of a glass by dry-milling a mixture of sodium silicate (Na<sub>2</sub>SiO<sub>2</sub>), silica, and alumina and firing at 1100 C. The resulting glass is then milled with clays and water to produce a slip. The slip is formed into an electrode tube or capsule by casting in a mold of plaster of Paris. After drying, the porcelain capsule is fired at 1285 C.

The reproducibility and stability of the porcelain reference electrode were checked by measuring the potential of a cell in which identical electrodes were opposed. The results showed that the electromotive force of the electrodes was stable and reproducible to within a few millivolts under temperature cycling for almost six days. The fact that the electrode can be reused is an added advantage.

Supplementary Information

Additional experiments were conducted to study variation in the electromotive force of the porcelain electrode. Two electrodes with different silver chloride and sodium chloride concentrations were placed in a cell and cycled at random between 646 and 850 C for several days. Repeated readings at the same temperature agreed within about 1 mv. The data indicated that the porcelain electrode behaves normally with respect to temperature change.

Another important property of an electrode is its ability to return to equilibrium after accidental passage of cur-

rent. To check this property, a cell was polarized by passing a 0.1-amp current through it for 20 seconds at 800 C. A polarization of 6 mv was measured immediately after applying the current. This decayed to about 1 mv within 5 minutes. Reversal of the polarizing current gave an equal but opposite polarization which decayed within 5 minutes to about 0.3 mv. Within 20 minutes, the residual polarization was less than 0.1 mv. The results showed that the porcelain electrode is highly reversible to passage of current.

Although the performance of the porcelain electrode may be improved with further study, the present work shows that the electrode is stable and reproducible. These characteristics make the porcelain electrode desirable for use in electrochemical studies of fused salt systems.

Additional details have been published in an article by R. J. Labrie and V. A. Lamb entitled "A Porcelain Reference Electrode Conductive to Sodium Ions for Use in Molten Salt Systems," which appeared in the October, 1959, Journal of the Electrochemistry Society.

#### Electric Cars May Use Nickel-Cadmium Batteries

Research is being conducted on the feasibility of developing a modern version of the old electric car that faded from the American automobile scene because conventional batteries had such short lives.

A sintered plate, nickel-cadmium battery being studied is expected to last the life of the car and can be changed considerably quicker than other batteries

siderably quicker than other batteries.
Each cell of the new battery is made up of plates of carbonyl nickel powder sintered on a foundation of nickel wire mesh.

Biggest problem in developing the electric car is to find a method of extending the power plant's range but to keep the vehicle small and light. At present, batteries need recharging after less than 100 miles. To overcome this problem, American Motors and Sonotone Corp., Elmsford, N. Y., are exploring the feasibility of using a generator driven by a small auxiliary gasoline engine to recharge the battery during operation.

The electric car of tomorrow, as studies are being made, probably will be cheaper to operate than gasoline powered automobiles and probably will be practically trouble-free, eliminating costly service bills.

#### Rapid Aluminum Welding

Ultrasonic seam welding of light gauge aluminum sheet and foil in thicknesses ranging from 0.006 to 0.010 inches at speeds in excess of 30 feet per minute has been developed by Aeroprojects, Inc., and Aluminum Company of America. The new welding process is expected to increase production and save money for container and packaging manufacturers, automobile radiator makers and the electrical industry.

In 1958, 210,300 copies of 12 NACE Technical Committee Reports were distributed.

### **GOD BLESS 'EM**

Our competitors do more for us than our friends. Our friends are too polite to point out our weaknesses, but our competitors go to great expense to tell of them.

Our competitors are efficient, diligent and attentive. They make us search for ways to improve our products and our services.

Our competitors would take our business from us if they could. This keeps us alert to hold onto what we have. If we had no competitors, we might become incompetent, inattentive, and possibly lazy.

We salute our competitors; they have been good to us. We need the discipline they enforce upon us.

**ORchard** 

2-7566

God bless them all.

1150 McCarty Drive MAYES BROS.
HOUSTON, TEXAS

15

vas

ent red ent.

ari-

tes the 0.1 ceto

ws ro-

the

alt

ied A.

nce

ons

ich

nal

the

led

ne

ich

athe

011-

de

ler

ire he xto At nis 10-)ror

np-

be he

ng

ht

ite ts,

-15 ve

k-

E

#### Plastic Engineers' Society To Meet January 12-15

The Society of Plastics Engineers' 16th Annual Technical Conference will be held January 12-15 at the Conrad Hilton Hotel in Chicago, Ill.

An advance program of the confer-ence lists the following topics to be discussed:

January 12: polymer structure, physical properties, blow molding, fabricating and finishing, casting and plastics tooling, and plastics in buildings.

January 13: injection molding, extrusion, reinforced plastics, standards for reporting properties—thermosetting molding, plastics in electrical insulation,

packaging, and vinyl plastics.

January 14: New materials, mold design, forming, foams, metals for plastics molds and plastics in the automotive

industry. January 15: industrial design—coloring, radiation and missiles and rheology.

Additional information can be obtained from the Society of Plastics Engineers, Inc., 65 Prospect St., Stamford,

#### Maintenance Conference

"Working Against Air and Water Pollution" will be one of the many topics to be discussed at the 11th Plant Maintenance and Engineering Conference to be held at Convention Hall, Philadelphia, Pa., January 25-28.

Speaker on air pollution for this discussion topic will be William R. Bradley, American Cyanamid Company. R. W. Ladd of Delaware Refinery, Tidewater Oil Co., will speak on water pollution.

#### Metal Deformation

A conference on the response of materials to high velocity deformation will be held July 11-12 in Estes Park, Colo., sponsored by the Physical Metallurgy Committee, Institute of Metals Division, the Metallurgical Society of AIME.

Papers to be presented will be on crystallographic, metallographic and basic metallurgical phenomena that occur in metals under high strain rate.

#### New Flux for Aluminum

A new method makes it possible to A new method makes it possible to solder aluminum without complicated tinning and fluxing operations. A glass fiber brush is rubbed through molten solder on the metal surfaces to be joined. The brush abrades the metal, removing oxide for a firm, smooth joint. The new system was developed by Reynolds Metals Co.

#### Catalogs List Research

Two new catalogs listing research reports in the fields of cermets and rust prevention and removal have been published by the Office of Technical Services, U. S. Department of Commerce, Washington 25, D. C. The catalogs are titled "CTR-319 Cermets, 1940-59" and "CTR-305 Rust Prevention and Removal, 1934-59." The price is 10 cents each.

Over 20,000 cards have been issued by the NACE Abstract Punch Card Service.

# Proper application is half the battle!

You can't fight corrosion effectively with hit-or-miss methods . . . however good your material. You need full coverage of every crevice, recess, and sharp edge . . . and the only practical way is with non-contact application methods. Here's how:

Conventional spray eliminates thin edges . gives full-covering film build where it's needed most-on ridges, corners, projections subject to greatest wear and exposure. Methods that wipe, brush, or roll material onto surface by contact often leave these critical points with the least coverage.

Hot spray gives heavier film build . . . assures uniform viscosity of material . . . permits application of higher solid-content materials . . . reduces shrinkage that draws film thin over sharp corners during drying. Cuts down overspray, reduces pinholing. Permits painting when temperature is too low for conventional application.

Airless spray speeds painting of big areas . . . lays on full coats fast and with minimum spray fog. Sprays even heavy materials without the use of atomizing air.



Conventional spray equipment



Airless spray equipment



Catalyst spray equipment

If you have a corrosion problem that coating can solve—call on DeVilbiss. We offer the industry's most complete line of spray equipment—including catalyst guns for applying such new materials as flake fiberglass, and for laboratory or experimental use in applying foam-in-place urethane foams and

other plural component materials.

For details—call your DeVilbiss representative, or write us direct. We'd like to help you explore the many advantages of modern methods of application for all of today's coating materials. Our technical experience and research facilities are yours to draw on. The DeVilbiss Company, Toledo 1, Ohio.



THE DeVILBISS COMPANY Toledo 1, Ohio - Barrie, Ontario - London, England São Paulo, Brazil

**Branch Offices in Principal Cities** 

**Equipment** Services

## **NEW PRODUCTS**

Materials Literature

#### Aluminum

Killark Electric Mfg. Co., Vandeventer and Easton Aves., St. Louis, Mo., manufactures an aluminum fitting for concrete mounting that is claimed to be explosion proof. The new fitting, Series GRC, is available with blank cover for the company of the cover for the cover of the co use as a splice box and hub cover suitable for fixture hanging. The fitting is available in conduit sizes from one-half inch to one inch in a variety of hub styles.

#### **Boilers**

Water Service Laboratories, Inc., 615 W. 131st St., New York 27, N. Y., have published (Technical Bulletin No. 597) on priming and foaming in low preson priming and sure heating boilers.

Water Control System for side-stream Water Control System for side-stream boiler that automatically eliminates sludge and suspended solids has been introduced by the Sparkler-Filtrion Corp., North Chicago, Ill. The unit combines continuous sidestream filtration with chemical pretreatment, internal treatment, continuous minimum blowdown, feedwater preheating and degassing in one automated unit, Scaling corrosion and caustic embrittleing, corrosion and caustic embrittle-ment are reduced, according to the manufacturer.

#### Catalogs

Simplified Catalog Sheet covering spray guns for die lubrication is available from DeVilbiss Company, Toledo, Ohio. Included are automatic guns for applying lubricating oils or drawing compounds to dies and for applying coolants to abrasive wheel and belts.

New Chemicals Catalog is available from Dow Chemical Co., Midland, Mich., which describes properties and uses of 375 industrial pharmaceutical and agricultural chemicals produced by the company, Catalog includes an expanded section on plastics and coatings products

Platinum Products Catalog including standard line of platinum products, chemicals, recovery and refining facilities of the company is available from J. Bishop & Co., Platinum Works, Malpha Co., Platinum Works, Malpha Co., Platinum Works, and Malpha Co., Platinum Works, Malpha Co., vern, Pa. Information on clads and composites of platinum group metals with base metals is included.

#### Cleaning

Hydraulic Jet Cleaners for plant and tank cleaning are described in two bulletins published by Sellers Injector Corp., 1600 Hamilton St., Philadelphia 30, Pa. Bulletin No. 442 describes high pressure and low pressure jet cleaners and sandblast and chemical cleaning equipment are described. Bulletin 432 describes a special head with high ve-locity nozzles. The head rotates the nozzles in both vertical and horizontal planes for cleaning the inside of tanks.

Solvent Cleaning Functions of the Dow Chemical Company will be handled under a newly created division of the company. The division also will provide services and products in the mu-nicipal and industrial waste and water treatment fields. Headquarters will be in Cleveland.

Blast Cleaning, metal abrasives and dust control equipment produced by Pangborn Corp., Hagerstown, Md., will be marketed in Canada by Pangborn Canada, Ltd. Offices will be at 38 Matt-son Rd., Toronto, Ont.

#### Coatings—Inorganic

Totrust Flash-Dry M-50 Primer recently introduced by Wilbur & Williams Co., Inc., 650 Pleasant Street, Norwood, Mass., dries in 15 minutes and penetrates rust pits and other surand penetrates rust pits and other sur-face irregularities to form a bond with the metal surface, according to the company. Rust inhibition of the coating is provided by National Lead Com-pany's M-50 (Basic Lead Silico Chromate) pigment.

#### Coatings—Organic

Wyandotte Chemicals Corp., has developed a new sprayed rigid polyetherbased urethane foam for use in corrosion control and as insulation. New rosion control and as histiation. Average techniques and spraying equipment developed by the DeVilbiss Co., Toledo, Ohio, have been designed to reduce cost of equipment needed to apply the foam. Insulating and corrosion protective qualities indicate use of the product as exterior coating for tanks, pipes and pipe lines.

Dylex KCD-141, a new latex with low roaming advantages for use in metal primers has been announced by the Plastics Division of Koppers Co., Inc., 801 Koppers Bldg., Pittsburgh 19, Pa. Company salt spray tests indicated excellent cellent corrosion resistance, it was claimed. Company bulletin C-9-282 describes the product.

Centrifugal Casting Method is being used to apply coal-tar pipe line enamel to 57 sections of steel pipe, 13 feet in diameter. The enamel, made by Koppers Co., Inc., is applied by insertion of a long wire in the pipe after the pipe has attained a peripheral speed of 900 feet per minute. Hill-Hubbell Company, 3091 Mayfield Drive, Cleveland 18, Ohio, is applicator of the coating. The pipe will carry 50,000,000 gallons of water per hour for an electric generating station. Centrifugal Casting Method is being

Aroplaz 6006 is a new top coating which sets tack free in about five minutes and hardens into a tough, glossy finish without baking, according to the manufacturers, Archer-Daniels-Midland Co., 700 Investors Bldg., Minneapolis 2, Minn. The new resin is a pure oxidiz-2, Minn. The new resin is a pure oxidiz-ing oil modified alkyd, the firm states. Possible uses are for finish coatings of farm and construction machinery, trucks and trailers, metal cabinets and as a repainting coat for autos.

Rez-N-Lac, made by the Schwartz Chemical Co., Inc., 50-01 Second St., Long Island City 1, N. Y., is a new coating formulation developed for fast application and durable colors for products made of high impact styrene ma-

Del Products, made by David E. Long Corp., 220 East 42nd St., New York 17, N. Y., are described in Bulletin 105 N. Y., are described in Bulletin 105 published by the company. The bulletin states Del synthetic rubber compound is waterproof and non-shrinking, has re-silience over a wide temperature range, adheres to most materials, is easily applied and is inert to weathering and most corrosives. A chemical resistance chart is printed as a general guide in selecting the most suitable formulation.

Farboil Company, Baltimore 30, Md., is marketing a new system of protective coatings for the building, industrial tive coatings for the building, industrial and marine fields, called Farboil Epothanes. The paints are said to be resistant to corrosion, abrasion, solvents, impact and chemical attack. They are flexible yet cure to 75 percent the hardness of glass and will adhere to glass, metal, concrete and wood, according to the resulting to the provided transfer to the resulting transfer transf cording to the manufacturer.

Prufcoat Primastic, a protective coating which is said to combine rust-inhibitive primer properties with the chemical restance of a catalyzed epoxy coating, has been developed by Prufcoat Laboratories, Inc., Cambridge, Mass.

#### Chemicals

Manning & Lewis Engineering Co., 30 Ogden St., Newark, N. J., has published an 8-page catalog which describes the company's line of chemical process and heat exchange equipment.

#### Cooling Towers

Water Service Laboratories, Inc., 615 W. 131st St., New York 27, N. Y., have published suggestions on winter opera-tion of outdoor cooling towers. The leaflet is designated Technical Bulletin # 598. The firm specializes in chemical engineering and corrosion prevention

Joy Manufacturing Co., 1201 Macklind Ave., St. Louis 10, Mo., has made their "Safe" switch in a 6-station model for pendant applications. The entire switch including buttons is enclosed in a noncorrosive, waterproof molded synthetic rubber housing which is light in weight.

#### Heat Exchangers

Parallel Exchanger, an impervious graphite heat exchanger for limited volume heating or cooling requirements in handling corrosives, is being made by Falls Industries, Inc., Aurora Road, Solon, Ohio. Both heating and cooling passages are drilled parallel to each other in the exchanger.

#### Heat Treatment

Heat Treatment to relieve stresses in thermostat metal parts is described in a leaflet available from General Plate Products Group, Metals and Controls Division, Texas Instruments, Inc., 34 Forest St., Attleboro, Mass.

(Continued on Page 86)



# Cut Maintenance and Replacement Costs

with TAPECOAT

...the Coal Tar Tape Coating that Adds Years of Service Life to Gas Lines

No wonder more and more distribution engineers are selecting TAPECOAT products as an important part of their program in fighting underground corrosion! Experience shows that quality protection applied during installation prevents huge maintenance and replacement expense at later dates.

Since 1941 when TAPECOAT originated coal tar coating in tape form, it has proved to be the best protection money can buy for combatting corrosion underground or under water. Lines in service TAPECOATED as far back as 17 years ago show no signs of deterioration—a record of uninterrupted service no other type of tape can match.

TAPECOAT comes in rolls of 2", 3", 4", 6", 18" and 24" widths—sized to the job for protecting pipe, pipe joints, couplings, fittings, tanks, conduit, cable and tie rods. TAPECOAT is both bond and protection in one—easy to apply with the flash of a torch.

Write for brochure today.

When primer is specified, use TC Prime-coat, the compatible coal tar primer.







# The TAPECOAT Company

1529 Lyons Street, Evanston, Illinois Representatives in Principal Cities

Manufactured and distributed in Canada by The Tapecoat Co. of Canada, Ltd., 25 Haas Road, Rexdale, Ontario

prodma-

ol. 15

Long
k 17,
105
lletin
nd is
s reange,
v apand
tance

ation.

Md., otecstrial Epoe rerents, are the re to

ating pitive of reoting, abo-

, 30 pub-

615 have pera-The lletin

klind their l for witch nonhetic eight.

vious nited nents made Road, oling each

es in ed in Plate trols

De

#### NEW PRODUCTS

(Continued From Page 84)

#### Heaters

Industrial Radiant Heater engineered Industrial Radiant Heater engineered for quick warm-up and cool-off has been developed by Corning Glass Works, Corning, N. Y., for drying, baking, curing and pre-heating. The tubular unit reaches heating capacity of 800 to 850 F within three minutes, according to the manufacture of the cordinate of the manufacture. cording to the manufacturer.

#### Inhibitors

O'B-Hibit-L 32, a liquid corrosion inhibitor designed for use with muriatic acid, phosphoric and other liquid acids, has been developed by O'Brien Industries, Inc., P. O. Box 72, Caldwell, N. J. Recommended concentration is from 2 to 3 percent by volume with the concentrated acid.

CRC 2-26, a liquid inhibitor designed to displace and seal out moisture and protect against caustic and acid fumes, is described in an illustrated folder published by Corrosion Reaction Con-sultants, 116 Chestnut St., Philadelphia 6, Pa. The product has special application in drying out flooded or damp motors and protecting electrical equip-ment. With one-third the surface ten-sion of water and a high capillary action, CRC 2-26 forms a continuous molecular film that penetrates grain boundaries in metals and penetrates into crevices, makers say.

#### Instruments

Hazegage Combustion Indicators provide continuous and instant information for maintaining optimum combustion. They are made by Photomation, Inc., 90 S. Washington Ave., Bergenfield, N. J. The instrument uses photoelectric cells. Direct reading and recording indi-cators are available and a panel of red and green lights indicate whether combustion conditions are satisfactory.

Long-Life Ionization Gauge using a Long-Lite Ionization Gauge using a thorium-coated iridium filament is described by NRC Equipment Corp., 160 Charlemont St., Newton 61, Mass., in a recent bulletin. The gauge, Model 527, is burn-out resistant, having been subjected with current on to as many as 175 bursts from 1 microu to atmospheric 175 bursts from 1 micron to atmospheric pressure before failure, manufacturers state. Uses expected for the instrument are in vacuum metallizing, vacuum melting and heat treating, space simulation and laboratory investigations.

#### Insulators

Coustifab, a lead containing material for noise abatement in piston engine and jet engine aircraft and other uses, is a lead powder impregnated vinyl coated cotton duck or woven glass fabric. Cordo Chemical Corp., Norwalk, Conn., developed the product.

Universal Insulating Meter Nuts of special size and design are available from Universal Controls Corp., Dallas, Texas, for use on Sprague No. 1A and No. 2 combination meters and regulators. Previous nuts interferred with the regulator spring case or cover of the combination meter.

1/2 ACTUAL SIZE

#### Lubricants

Dag 207, a newly formulated lubricant for high temperature use is described in a leaflet from Acheson Colloids Co., Port Huron, Mich. The lubricant is described as a concentrated dispersion of colloidal molybdenum disulfide in an LB series, fluorocarbon lubricant. Typical uses are for oven conveyors, kiln gears and bearings and for glass making machinery

#### Metals—Ferrous

Republic 50 high strength steel used instead of carbon steel increases payload stead of carbon steel increases payload and combats corrosion on refuse hauling trucks, according to Republic Steel Co., 500 Fifth Ave., New York 36, N. Y. Use of a two-ton chassis instead of a three or three-and-one-half truck chassis is made possible by specifying Republic 50, the firm states.

Carpenter Steel Co., 372 West Bern Street, Reading, Pa., has published a 40-page guide for buyers of specialty steels. It contains detailed information on tool and die steels; stainless steels; high temperature alloys; electronic. magnetic and electrical alloys; special purpose alloy steels; tubing and pipe; and fine wire specialties. A tool steel selector chart which provides a system of matching tool steels is also included.

Potomac A High Strength Steel for use roumac A riigh strength Steel for use in aircraft, missiles and rockets is described in a booklet available from Allegheny Ludlum Steel Corp., Oliver Bldg., Pittsburgh 22, Pa. Known as type H-11, the steel has high strength up to 1000 F.

#### Metals—Non-Ferrous

Ampcoloy 666, a new extruded manganese-bronze alloy for high production jobs, is described in a data sheet available from Ampco Métal, Inc., 1745 South 38th St., Milwaukee 46, Wis. Included are chemical composition, physical properties, resistance to wear and corrosion and advantages of the new

New Corrosion Resistant Alloys have heen developed by Stainless Foundry & Engineering, Inc., 5132 North 35th St., Milwaukee 9, Wis., for handling sulfuric acid. Illium 98, improvement in the original things of the stainless of th acid. Illium 98, improvement in the original Illium G formula, handles 98 percent sulfuric acid up to 110 C and resists all concentrations up to 90 C, the firm states. Illium B in hardness grades of 200 to 360 Brinell is used in wear, bearing or cutting applications where corrosion is a major problem, the company claims claims.

#### Minerals

Lithium Metal technical data is published in Bulletin 101 by Foote Mineral Co., 18 W. Chelten Ave., Philadelphia 44, Pa. Suggested uses of the metal are given. Its physical and chemical properties as an element, combined with other elements or alloys are given.

#### **New Plants**

Cardox Division, Chemetron Corp., Chicago, Ill., is constructing a plant near Philadelphia, Pa., to recover carbon dioxide from ammonia. Production will be about 155 tons of liquid and solid carbon dioxide a day.

(Continued on Page 88)

## NEW POCKET SIZE

### SINGLE-PROBE **THICKNESS GAUGE**



REAR VIEW

THREE SCALES

M.894A 0 - .030" 0 - .010" M.894B M.894C

**ONLY \$58.00** 

Single-probe assures accurate measurements on either flat or curved surfaces. Measures thickness of paint, enamel, lacquer, plastic or any non-ferrous metal coatings without damage to coating. Pointer clamp locks needle for readings on out-of-the-way spots. Gives reading in both inches and millimeters. Complete with durable leather case which fits on belt.

MORE RUGGED

#### THE O. HOMMEL COMPANY

Carnegie, Pennsylvania



Complete domestic service and repair available . . .

. 15

l in Co., deof LB ical ars, ing

inoad ing Co., Y.

olic

ern l a

ion els;

cial pe; eel em

ed.

use

A1-

ver

gth

gaion

ail-745

In-

Si-

nd

&

gi-

all

of aror-

hia are er-

hi-

vill lid

# MIM

# new specialty Wrought Iron offers better low temperature properties and better impact resistance than many steels

Mn (Manganese) Wrought Iron is a brand new specialty wrought iron offering excellent impact resistance at sub-zero temperatures. To define it: Mn Wrought Iron is a highly deoxidized, low carbon alloy wrought iron containing 1% manganese.


New Mn Wrought Iron is not a substitute for 4-D Wrought Iron. Mn was developed *specifically* to meet critical engineering needs for a tough, yet economical metal in low temperature services where the possibility of brittle failure poses design problems.

Independent impact testing of Charpy V-notch specimens from  $\frac{1}{2}$ " plate shows that Mn Wrought Iron has a mean energy absorption of 15 foot-pounds at -58°F. Mn Wrought Iron combines this boost in impact strength with the excellent corrosion resistance and mechanical advantages of 4-D Wrought Iron. Mn can be easily welded or flame cut—in field or shop—without requiring pre-heating or post-heating treatment.


Mn Wrought Iron costs *less* initially than many of the low alloy steels recommended for low temperature service. Available in pipe, plate, and other forms, this new material is well suited for a wide variety of low temperature applications, including such services as tanks and process piping in the refrigeration and petrochemical industries.

Inquiries regarding this specialty wrought iron will receive immediate attention. Write: A. M. Byers Company, Clark Building, Pittsburgh 22, Pennsylvania.

#### Charpy impact values for Charpy V-notch specimens machined from conventionallyproduced ½" Mn Wrought Iron plate in as-rolled condition.



Mean energy absorption: 15 ft-lbs at -125°F, notch parallel.



Mean energy absorption: 15 ft-lbs at  $-58^{\circ}F$ , notch perpendicular.

RYFPS WROUGHT IRON



TUBULAR AND FLAT ROLLED PRODUCTS

#### **PRODUCTS**

(Continued From Page 86)

#### Non-Metallics

Karbate, an impervious graphite, is being used for a valve and modular entrainment separator manufactured by National Carbon Company, division of Union Carbide Corporation.

#### **Pipelines**

Perrault Supply Co., a division of Allied Paint Mfg. Co., Tulsa, has been formed to specialize in materials used to stem pipeline corrosion. V. V. Malcolm is general manager of the new division; Ainslee Perrault is president of Allied Paint. The firm will handle pipeline felt, rock shield, glass pipe wrap, internal coatings and other materials. Malcolm, formerly vice-president and general manager of Perrault Equipment Co. until its recent sale by W. O. Dixon to M. J. Crose Mfg. Co., has had many years of experience in the pipeline protection business. Ainslee Perrault, was one of the founders of Perrault, Inc., a pioneer firm in the pipeline field. Eastern and export representative for Perrault Supply Co. is Andreason-Lundberg Corp., 45 Rockefeller Plaza, N. Y.

#### Piping

Recommended Piping Practice, a wall chart available from Lunkenheimer Co., Beekman, Waverly and Tremont Streets, Cincinnati 14, Ohio, describes basic valve types, end connections normally used, installation and maintenance tools, installation and operation and maintenance.

New Unitrace Fittings for piping with integral steam tracing have been developed by Alcoa. Designed to incorporate Unitrace into standard piping systems, fittings include a flange, adapter flange and 90-degree elbow. A descriptive booklet is available from Aluminum Company of America, 778 Alcoa Bldg., Pitts-burgh, Pa.

#### **Plastics**

Schwartz Chemical Co., Inc., 50-01 Second St., Long Island City 1, N. Y., is making a new acetate cement with a flash point above 100 F to reduce mass production hazards in the bonding of making cellulose acetate or butyrate sections. It will not thicken when applied from open containers, but viscosity can be in-creased for special applications by adding cellulose acetate shavings, according to the company.

Estane VC, a plastic film strong enough to be made into flexible gas tanks for automobiles or rugged rainwear, has been developed by B. F. Goodrich Industrial Products Co., Akron, Ohio, the company states. The thin but tough many stitched. It can be sealed to itself electronically or by a heat seal to form a leakproof cell.

Flange Insulation Sets made of high density polyethylene tubing are being marketed by Central Plastics Distributing Co., P. O. Box 762, Shawnee, Okla. Full length sleeves, fabric reinforced phenolic washers and steel washers, along with one-eighth-inch phenolic, neoprene faced phenolic or Johns-Manville 71 asbestos center gaskets are made by the firm which specializes in corrosion control products.

#### Research

Taylor Fibre Co., Philadelphia, Pa., has organized an advanced materials division to investigate and develop laminated plastics and vulcanized fibre for use in rockets, missiles, jet aircraft, nuclear reactors and other products where high strength-to-weight ration, excellent heat insulation and electrical insulation are important factors.

New Type of Viton, synthetic rubber, has doubled the product's useful life at temperatures from 500 to 600 degrees F and in certain strong chemicals, E. I. du Pont de Nemours & Co., Wilmington, Del., states. Tests at 500 to 600 F showed elasticity of the product was retained twice as long as the former product.

#### Soldering

New Liquid Flux for use with all soft solders has been developed by the research department of All-State Welding Alloys Co., Inc., White Plains, N. Y. It can be used on most metals, including stainless steel, gold and galvanized met-als, except aluminum, magnesium and die cast metals, according to the manufacturer.

#### Valves

Foot Valve Made by Chemtrol, 10872 Stanford Ave., Lynwood, Cal., of all-molded plastic construction is designed to be used in sumps, tanks and other uses where fluid level must be reduced or fluid completely withdrawn. The valve is practically inert to corrosive influences, makers state. The ball-type check valve prevents back flow, and the suction end is protected against debris intake with a large hemispherical plastic screen.

Delsen Corp., 719 W. Broadway, Glendale 4, Cal., has developed an air operated, solenoid controlled valve available for use with the firm's automatic weighing scale, the Autogram. The equipment is designed for weighing and dispensing batches of one or several liquids.

Whittaker Controls, 915 North Citrus Ave., Los Angeles 38, Cal., has developed new gate valves with mechanically loaded and retained plastic seals, roller type clutches and interchangeability of actuators. The valves will be made in quantity, then adapted to meet requirements, rather than being built individually to special specifications.

#### **Water Softeners**

Zeotone, made by the Calgon Company, P. O. Box 1346, Pittsburgh 30, Pa., has been developed to clean and improve the zeolite or resin bed in commercial or industrial water softeners. It is said to be effective for cleaning all softeners regenerated with salt, on resinous ex-change material and on synthetic and natural zeolites.

#### Welding

Arcair's Model H-55 torch has a push button air control valve in the torch button air control valve in the torch handle which provides air on both sides of the electrode. Made by the Arcair Co., P. O. Box 431, Lancaster, Ohio, the torch has primary uses in foundries for flash removal, cutting holes or similar jobs which require frequent reversal of travel direction.

#### AVAILABLE WANTED AND POSITIONS

Active and Junior NACE members and companies seeking salaried employees may run without charge two consecutive advertisements annually under this heading, not over 35 words set in 8 point type. Advertisements to other specifications will be charged for at \$10 a column inch.

#### **Positions Available**

Sales Engineer. New corrosion resistant plastic sales Engineer. New Corrosion resistant pushed tank is being added to old complete corrosion service line, Will require extensive travel in south and southeast. An automobile will be furnished. Commission on sales will be added to base salary. Include complete personal and experience resume. Stetsco Service Co., P. O. Box 3213, Charlotte 3, N. C.

Cathodic Protection Engineer-Good opportunity in sales engineering. Experience in cathodic pro-tection work required. Midwest location with travel. Good salary. Growing company. Send resume of experience, photo. Corrosion Services, Inc., Box 787, Sand Springs, Okla.

#### Manufactures' Agents

Manufacturer of Materials for pipeline protection presently expanding sales force into Northeastern Region, offers permanent, life-time franchises to sales agents contacting pipeline, public utility, refining and chemical industries. New England, North Jersey, Philadelphia, Baltimore, Pittsburgh and Cleveland areas. CORROSION, Box 59-43.

#### **Positions Wanted**


Sales Engineer. 12 years experience—sales, management, engineering—in industrial and municipal water and waste treatment and corrosion control. Prefer Middle Atlantic states. Will consider representation. CORROSION, Box 59-41.

Corrosion-Metallurgical-Equipment Inspection Engineer. Seven years corrosion, metallurgy, equipment and welding inspection major refining, petrochemical plants. Supervisory experience. BS Met. E. Age 30. \$10,000 present salary. Prefer Southwest, South. Other areas considered. COR-ROSION, Box 59-42.

Technical Representative—Age 33. 4 years in research including organic inhibitors. Field experience in coatings and cathodic protection of production equipment. Prefer growing aggressive firm in southwest. Resumé on request. CORRO-SION, Box 59-45.

CYANAMID

# CORROSIONEERING WITH REINFORCED LAMINAC® PLASTIC





Winner of an Award of Merit for design excellence at the 14th Annual Exhibit and Conference of the Reinforced Plastics Division, The Society of the Plastics Industry, Inc.

Four ft. tall and 17% in. in diameter, the horn is produced by Wallace & Tiernan Inc., Belleville, N. J.

#### CAREFREE SENTINEL ON THE GULF OF MEXICO

The man-made oil drilling islands at the mouth of the Mississippi are under continuous corrosive attack by harsh marine atmospheres. So equipment must be made impervious to corrosion. The foghorn, for instance, that warns shipping of the presence of islands, like this Shell Oil Company, Delta Division, oil-drilling rig, is fabricated of rugged glass-reinforced LAMINAC® polyester resin. The reinforced LAMINAC foghorn is completely corrosion resistant, as well as resistant to impact. Weighing just 120 pounds, it can be lifted by one man. The previous metal horn required a crane to move it. And the reinforced plastic horn requires no maintenance.

CYANAMID

#### AMERICAN CYANAMID COMPANY

PLASTICS AND RESINS DIVISION

31 ROCKEFELLER PLAZA, NEW YORK 20, N. Y.

Offices in: Boston • Charlotte • Chicago • Cincinnati • Cleveland
Dallas • Detroit • Los Angeles • Minneapolis • New York • Oakland
Philadelphia • St. Louis • Seattle

In Canada: Cyanamid of Canada Limited, Montreal and Toronto

has ivimifor aft,

on,

15

oer, at F I. ng-F vas

oft reing It ing etind

372 allned ced che ive pe the ris

ble ghent ent ng rus ellly ler of in reid-

ny, nas ove cial cid ers exnd

sh ch les air he or lar

D

m

R

ag

H

#### MEN in the NEWS

V. V. Malcolm is general manager of V. Matcom is general manager of Perrault Supply Co., a division of Allied Paint Mfg. Co., Tulsa formed to operate in the pipeline corrosion protection field. He formerly was vice-president and general manager of Perrault Equipment Co., an engineer and manager for Philip Carey Mfg. Co., Cincinnati and has had long experience in the pipeline protection business.

Frank Donat has joined the chemicals and plastics research department at B. F. Goodrich Company's Research Center, Brecksville, Ohio.

Walter H. Flynn has been appointed general sales manager for Lebanon Steel Foundry, Lebanon, Pa. F. H. Foglesong has been named to the newly created position of manager of alloy sales for Babcock & Wilcox Com-pany's Tubular Products Division, 161 E. 42nd St., New York, N. Y.

Cooper F. Hawthorne, NACE member, has been appointed vice president and general manager of the newly organized Metal Services Inc., Beaumont, Texas,

Henry H. Hemenway has been appointed director of research and engineering for Graver Tank & Mfg. Co., 4809 Tod Ave., East Chicago, Ind.

Lafayette K. Irwin has been appointed chief of the engineering mechanics section of the National Bureau of Standards, Washington 25, D. C.

Earl L. Jolly, NACE member, has been appointed Pacific-Western area manager for the new Corr-Prev Division of Chase & Sons, Inc., at San Francisco.

Charlotte Kraebel has joined the chemical and plastics research department at B. F. Goodrich Company's Research Center, Brecksville, Ohio.

Alexander S. Zelle, NACE member, has been appointed chief engineer of Bridge-

port Rolling Mills Company, P. O. Box 818, Bridgeport, Conn.

Thomas W. Morrison has been appointed director of engineering and research for SKF Industries, Inc., Front Street and Erie Ave., Philadelphia 32,

George K. Nelson has been named manager of Archer-Daniels-Midland Com-pany's chemical products division, 700 Investors Bldg., Minneapolis 2, Minn.

William F. Newbold has been appointed

#### CORROSION ENGINEERING DIRECTORY

# CATHODIC PROTECTION Installation

SURVEYS

#### ENGINEERING CORP.

P.O. Box 1169 • FAirfax 3-6858 • Houston 1, Texas

#### cathodic protection service



CATHODIC

PROTECTION

Twenty cathodic protection engineers with a combined total of over 150 years experience available to serve you with ABILITY and INTEGRITY.

Houston, 4601 Stanford St. BRANCH OFFICES Tulsa • New Orleans • Corpus Christi • Denver

**Electro Rust-Proofing Corp. Engineering Division** 

Corrosion Surveys Cathodic Protection Design Plans . Specifications **Electrolysis Control** Testing

BELLEVILLE 9, NEW JERSEY Atlanta . Chicago . Dallas . Monrovia

#### CATHODIC PROTECTION

• ENGINEERING

 SURVEYS
 CONSTRUCTION Systems for conventional and specialized applications

THE HARCO CORPORATION

4592 East 71st St. VUlcan 3-8787 Cleveland 25, Ohio

#### SOUTH FLORIDA TEST SERVICE

INCORPORATED

Testing—Inspection—Research— Engineers

Consultants and specialists in corrosion, weathering and sunlight testing.

4301 N.W. 7th St. • Miami 44, Florida

FRANCIS W. RINGER ASSOCIATES

Consulting

Corrosion Engineers

MOhawk 4-2863

**Consulting Engineers** 

"WORLD-WIDE ACTIVITIES"

Specializing In

Corrosion Control • F.C.C. Certification Tests
Electromagnetic Interference Studies

Francis Palms Bldg.

#### THE HINCHMAN CORPORATION

Survey . Design . Supervision

Detroit, Mich.

#### WATER SERVICE LABORATORIES, INC.

NARBERTH (Suburb Phila.) PENN.



7 Hampden Ave.

Specialists in **Water Treatment** 

Main Office, 615 West 131st St., N. Y.27, N. Y. Offices Also in Philadelphia, Washington and Richmond, Va.

#### CORROSION SERVICE LIMITED Offers in CANADA

SURVEYS . DESIGNS

INSTALLATIONS

CORROSION RECTIFYING CO., INC. 5310 ASHBROOK • MO 7-6659 HOUSTON 36, TEXAS

A Complete Service in Carrosion Engineering Design and Installation of Cathodic Protection Systems. Resistivity and Electrolysis Surveys Selection and Application of Protective Coatings.

17 Dundonald St., Toronto, Canada

Interprovincial Corrosion Control Company Limited

O Examiner Bldg. CANADA P. O. Box 167 Calgary, Alberta CANADA Burlington, Ont.

CONSULTING ENGINEERS Survey - Design - Materials and Equipment Installations

#### CORROSION ENGINEERING

#### EBASCO SERVICES

INCORPORATED

TWO RECTOR STREET, NEW YORK 6, N. Y. CHICAGO . DALLAS . PORTLAND, ORE. SAN FRANCISCO . WASHINGTON, D. C.

#### A. V. SMITH ENGINEERING CO.

CONSULTING ENGINEERS

Essex Blda. Narberth, Pa.

119 Ann Street Hartford 3, Conn.

You can advertise your engineering services in this directory for about \$1.50 a thousand readers. This is by far the best, least expensive and most convenient way to keep your name before the more than 8000 paid readers of CORROSION. Write for rates, 1061 M & M Bldg., Houston 2, Texas.

1. 15

iase

emit at

has

lge-

Box

ap-

ont 32.

an-

700 1.

ted

director of research for Brown Instruments Division of Minneapolis-Honeywell Regulator Co., Wayne and Windrim Avenues, Philadelphia 44, Pa.

Royce A. Peabody has joined the technical sales and service staff of Resistoflex Corporation, Roseland, N. J.

C. W. Powell has been appointed southern district manager for metallurgical products department of General Electric Company in Atlanta, Ga.

Richard F. Protiva has been appointed market development manager of Heil Process Equipment Corp., Cleveland, Ohio. Robert E. Scheel was named manager of national branch sales.

William A. Wood, Jr., NACE member, has joined the technical sales staff of Carboline Co., P. O. Box 14284, Houston, Texas.

Hartley J. Davis, NACE member, is now eastern division manager of Corrosion Services Inc. His offices will be at 1309 Washington Ave., Cleveland 13, Ohio.

K. A. Phillips, NACE member, has been appointed director of research and development at American Zinc, Lead & Smelting Co., P. O. Box 495, East St. Louis, Ill.

Wilfrid G. Matheson, supervisor of incandescent lamp research for Sylvania Lighting Products, has been named president of the American Vacuum Society.

Walter A. Steiner has been appointed vice president of technology for National Carbon Company, division of Union Carbide Corp., 30 East 42nd St., New York 17, N. Y.

Douglas E. Rood, NACE member, has joined the Corr-Prev division of Chase & Sons, Inc., as manager of the company's southwest area. His office will be in Houston, Texas.

G. W. Rupp, president of Inertol Co., Inc., 480 Frelinghuysen Ave., Newark 12, N. J., is celebrating his 25th year with the company.

Robert E. Siegfried, NACE member, has been appointed assistant engineering manager for Badger Manufacturing Co., Cambridge, Mass. Philip H. Seaver has been appointed manager of engineering sales.

Louis E. Trapasso has joined the chemicals and plastics research department of the B. F. Goodrich Company Research Center, Brecksville, Ohio.

Bruce L. Wilson has been appointed chief of the mechanics division of the National Bureau of Standards, U. S. Department of Commerce, Washington 25, D. C.

Donald S. Arnold has been named manager of research at American Potash & Chemical Corporation's main plant at Trona, Cal.

K. F. Egan is sales representative in the New York district for Wolverine Tube, division of Calumet & Hecla, Inc. His offices will be Room 956, Sibley Tower Bldg., Rochester, N. Y.





## with CARBOMASTIC

#### heavy duty epoxy-tar coatings

Generally, with protective coatings, undercutting begins at a damaged surface and corrosion progresses beneath the coating film. This corrosive loss can be prevented by priming with Carbomastic #3 - unique because it contains inhibiting pigments. In addition, it features good surface wetting and outstanding adhesion.

These tough coatings are economical, too . . . providing lasting protection for less than 1¢ per mil foot. Recommended Carbomastic applications are:

#### **OUTDOOR MAINTENANCE**

An all epoxy-tar system, with excellent weathering characteristics and high resistance to water and brines. Use Carbomastic #3 and Carbomastic #5 (topcoat). Color: aluminum.

#### TANK LININGS AND HEAVY DUTY MAINTENANCE

High resistance to hot water, brines, sour crudes (hydrogen sulfide), acids and alkalis. Use Carbomastic #3 and Carbomastic #2 (topcoat).

Where color topcoats are desired, Carbomastics may be coated over with Phenoline 305 or Carboline Epoxy 150.

WRITE TODAY for Technical Bulletin #803, containing complete information on Carbomastic coatings, including suggested applications, general characteristics and testing results.

#### OFFICES

Atlanta e Boston e Chicago Denvere Detroite Houston e Los Angeles e Mobile e New Orleans New York e Philadelphia Pittsburgh e San Francisco Tampa e Toronto e Tulsa

Coatings with Experience

32-A Hanley Industrial Ct., ST. LOUIS 17, MO.

ing met istr thei nate blo ha

ing

coa ma the aircon ble afte

ext ten ple che for

tha ced wh and

of iso



# TECHNICAL TOPICS

#### Characteristic Properties of

# Polyurethane Protective Coatings\*

POLYURETHANE COATINGS are one of the latest synthetic coating materials developed for protection of metals from corrosion. Urethane chemistry opens up a new field of reactions which have scarcely been examined in their practical applications. The isocyatheir practical applications. The isocya-nates, which are the primary building blocks of the urethane system, are capa-ble of reacting with many materials being used for coatings and thus creating new classes of materials.
Two articles concerning

Two articles concerning urethanes have been published in Corrosion. One described the chemical structure and characteristics of polyurethane coatings. The other presented some new formulations that have been developed.

#### Preparation of Urethane Coatings

There are two main types of urethane coatings, distinguished by the method of packaging: in one or two-component systems.

The one-component systems are similar in handling to orthodox paints; the material may be sprayed or brushed on the surface to be coated and allowed to air-dry in the normal manner. The twocomponent systems are supplied in two separate packages which must be blended just before application and after blending the mixture must be used within a specified time. A rise of visused cosity of the mixture usually takes place after blending. After the pot-life has expired, the material generally sets to an irreversible gel. Two-component systems are already familiar systems, the epoxies being the most familiar exam-

The most durable water-resistant and chemical-resistant coatings have been formed only from the two-component systems. This article deals with the twocomponent systems.

Preparation of a two-component ure-thane coating is a straightforward procedure. The first container of such a system contains a polyester resin dis-solved in suitable solvents. Pigments also are incorporated in this solution when required to provide hiding power and decorative value and to supplement the mechanical and physical properties of the film.

The second component consists of an isocyanate resin also dissolved in dry

\*Revision of a paper titled "Polyurethane Protective Coatings—Properties and Applications" by E. R. Wells, Mobay Chemical Co., New Martinsville, W. Va., presented at a meeting of the Northeast Region Conference, National Association of Corrosion Engineers, Oct. 6-8, 1958, Boston, Massachusetts, and at a meeting of the Detroit Section, National Association of Corrosion Engineers, Oct. 16, 1958, Detroit, Michigan.

solvent. When the two components are blended just before use, the isocyanate reacts with the free hydroxyl groups of the polester resin to form the urethane. reaction is not completed immediately; thus the mixture remains fluid for at least one day's work life. The reaction proceeds slowly throughout the curing period of the applied film, which lasts from a few hours to several days after application, depending on the type and quantity of the reactants.

For optimum performance, the reaction is allowed to proceed as long as possible under normal curing conditions before subjecting the coating to any destructive exposure. However, urethane coatings develop a very high proportion of their ultimate resistance properties after only one day's drying. Urethane films normally dry hard within three to eight hours after application, depending upon formulation, temperature and rela-

tive humidity.
Ultimate coating properties can be readily varied by choice of the polyester and change of the proportion of isocyanate resin to polyester resin.

Since the isocyanate is the more expensive of the two, a standard minimum ratio serves for the majority of uses. The ratio is 10 percent of the isocyanate resin above the stoichiometric equivalent of the two resins. Variation of properties is consequently more economically and is consequently more economically and conveniently achieved by varying the type polyester from highly branched types giving rigid films of maximum chemical resistance to linear polyesters which possess excellent flexibility, abrasion and water resistance but diminished chemical resistance.

Table 1 gives data on some physical properties of six typical urethane coatings and some familiar coatings.

Table 1 shows that the urethane coatings M-1 through M-5 are all extremely

Abstract

Discusses the characteristic properties Discusses the characteristic properties of polyurethane coatings. Gives description of the two-component system. Explains and presents data from chemical and solvent resistance tests, spot tests and other laboratory research.

5.4.5

hard yet show a wide range of flexibility as measured by the impact test. The abrasion loss of the urethanes is the lowest of all the materials tested despite variations of the flexibility.

#### Chemical and Solvent Resistance Tests

Chemical and solvent resistance of urethane coatings have been evaluated in a number of distinct tests. The tests can be grouped under several different categories which differ mainly in length of time necessary to obtain comparative evaluations.

One method of testing is to prepare free films and suspend these in the liquid reagents. However, free films are difficult to prepare and present handling problems. A similar result is achieved by dipping small glass test tubes into the test coatings and allowing them to cure thoroughly. These can then be partially immersed in the test liquids in bottles. Several coatings may be tested together in the same bottle by this method.

Table 2 gives results on three urethane coatings compared with two com-mercial epoxy systems and a commercial The glass probes were coated to give films approximately one mil thick within as close limits as were practicable by adjusting the viscosity and solids of the coating solutions.

Table 2 shows the number of hours which the coatings on the probes failed after immersion in the test tion. Failure was observed by the film's

(Continued on Page 94)

TABLE 1—Typical Physical Data for Corrosion Resistant Coatings

Coating Type	Hard- ness <sup>1</sup>	Abras- ion <sup>2</sup>	Impact <sup>3</sup>	No. of Compo- nents	Remarks
Urethane M-1	68 68 68 48	61 63 54 60	> 160 > 160 > 160	.2 2 2 2 2	Highest chemical resistance Chemically resistant Excellent water resistance Excellent water resistance and flexibility
One-component Urethane	6	137	90	1	Moderate resistance, low cost
One-component Urethane	10	139	4		Moderate resistance and cost
Chlorinated Rubber	12	200	10	1	Chemically resistant
Epoxy	22	120	50	2	Chemically resistant
Vinyl	6	75	120	1	Chemically resistant

Sward, Glass = 100
 Taber, mg. loss per 1,000 cycles
 Reverse, inch-pounds

TABLE 2—Chemical Resistance of Coatings Tested by Glass Probe Method

	Coating Type											
Exposure	M-1	M-4	E-1"	E-2	V	U-ol						
Mineral Acids Hydrochloric (10%) Phosphoric (20%) Sulphuric (30%) Nitric (5%)	>7300 >7300 >7300 >7300 >7300	20 4000 140 20	20 20 3 3	3 3 3 20	50 50 >7300 20	20 20 20 20 3						
Solvents Benzene Xylene Carbon Tetrachloride Methyl Isobutyl Ketone Butyl Acetate Butyl Alcohol	>7300 >7300 >7300 >7300 4000 4000 140	20 20 20 3 20 20	20 20 20 20 20 20 1	20 >7300 >7300 20 20 20	1 1 1 1 20	1 1 1 1 1						
Aqueous Solutions Distilled Water. Salt Water (2%) Tide Solution (2%). Chlorox Solution. Sodium Hydroxide (20%).	>7300 >7300 >7300 >7300 1000 190	170 1000 310 190 140	20 30 >7300 190 170	20 30 20 110 50	20 30 20 190 50	20 30 20 20 1						

#### Polyurethane Coatings-

(Continued From Page 93)

spontaneous disintegration or by the ease of coating removal by scraping with the finger nail or knife blade. Some of the coatings are still intact and in excellent condition; these are designated by the symbol (>7300).

M-I represents a very resistant type coating. M-4 is a general purpose coating which could be used satisfactorily for the exterior of storage tanks to resist fumes and spillage from the weaker chemicals and solvents and also have excellent weatherability for several years in moderate corrosive environments. The third urethane coating is a simple urethane oil. Coatings E-1 and E-2 are two-component epoxy systems from two different commercial sources, and Coat-

ing V is also a commercial article.




Figure 1—Simple arrangement for heat cycling of humidity tank used in laboratory test on urethane coatings.

Spot Tests

The spot test gives rapid evaluation of an unknown coating. This usually consists of laying a few drops of corrosive reagent on the cured coating on a flat panel and observing the time for the chemical to have a noticeable effect on the film. This is a useful test but as frequently carried out is apt to be unsatisfactory, particularly if volatile solvents or strong corrosive acids are being used.

ing used. A simple refinement of the usual technique consists of cutting small one-inch squares from standard microscope slides and using these to cover the liquid drop. This accomplishes several advantages; a well defined square test area is marked instead of an uneven blob; evaporation of volatile solvents is minimized during the test; and strong acids and liquids of good wetting power do not spread at random over the test surface. Results of these tests confirm data in Table 2.

Extended Laboratory Testing

The simple spot and glass-probe tests are useful for comparing coatings rapidly in a variety of laboratory liquids. These methods do not give sufficient information for long-term evaluations. Corrosion engineers generally are interested in only a few of these particular exposures, and such methods are not suitable for stricter evaluations in common maintenance applications where resistance to weathering, high humidity, water immersion and petroleum storage, for example, are matters of daily concern.




Figure 2—Tank for sour-crude petroleum immersion test for coating samples.

Further testing is needed to provide sufficient evidence of merit to warrant proper consideration of a new coatings system. Such tests require application of a complete coatings system to selected steel panels and immersion in baths for frequent inspection and assessment. In such tests water-immersion at room temperature, high relative humidity at 100 to 120 F and sour-crude petroleum bath at variable temperatures have been used as a basis of comparison.

The humidity bath is a convenient and rapid method for screening corrosion resistant coatings. Most alkyd enamels will blister severely in this test after only a few days exposure.

A common method of conducting a humidity test is to heat a layer of water in the tank bottom so that the vapor above the water is at 100 F. This arrangement is not satisfactory because a constant temperature does not permit alternate condensation and evaporation from the test film. This cycling makes the test a severe one. Furthermore, panels located on the walls get condensation whereas those located in the center of the tank get very little condensation and so results are not comparative. A simple arrangement, which permits cycling of temperature between 100 and 120 F while maintaining relative humidity between 95 and 100 percent can be constructed at low cost using two thermostats, relay and immersion heater as shown in Figure 1.

The heat coil is immersed in one of two inches of water in bottom of a suitable covered tank such as that described below in which the test panels are suspended.

For the water immersion test a glass sided aquarium 24 by 12½ by 13 inches deep was used. Panels were supported from paper clip hooks which passed through a small hole ¼ inch from the center of the short top side. Water immersion tests are commonly made at an elevated temperature such as 100 F, but in the present tests the water was allowed to remain at room temperature throughout. The water level was adjusted so that about ¾ of each panel was immersed. The upper smaller area serves as a control surface by which effect on submerged areas could be judged.

For testing exposure to sour crude petroleum, the bath arrangement shown in Figure 2 was devised.

Two-thirds of the test panel is immersed. The upper liquid layer is crude petroleum and the lower layer is 2 percent salt solution, since salt water is frequently found associated with petroleum. The bath is heated three times a day to 130 F by the steam coil on the bottom. At the same time H<sub>2</sub>S gas is blown in to maintain a sour solution. Temperature of the petroleum layer rises to approximately 120 F. This also is a severe test because the bottom layer contains not only salt and H<sub>2</sub>S but also ultimately sulphuric acid from oxidation of the H<sub>2</sub>S.

The

use

cor

pla

sho

ula

cor

nes

inn

isti

exp

qui

pro

Figure 3 shows the effect of water immersion at room temperature for 5700 hours on a commercial vinyl system shown on the left, a three-coat urethane system in the center and a commercial two-component epoxy system on the right. All films were of a total thickness of 5 to 6 mils on cold rolled steel.

Figure 4 shows the effect of humidity cycling between 100 and 120 F for 2600 hours. The urethane panel is in the center.

(Continued on Page 96)

J. B. Dannenbaum, Consulting Engineer of Houston, notes:

# "Bitumastic No. 50 given only minor touch-up in 12 years on Solarobic\* Process tanks"

The Solarobic Process, developed by J. B. Dannenbaum, uses steel for Imhoff, trickling bed and clarifier tanks at considerable saving in construction costs. Thirty such plants have been installed since 1947: the large illustration shows a new plant at Angleton, Texas, built to serve a population of 10,000. The inset photo shows the excellent condition of the Bitumastic® coatings on the pioneer installation.

Mr. Dannenbaum has standardized on a double thickness of Bitumastic No. 50 for corrosion prevention on both inner and outer tank surfaces. The thick dry-film characteristics of this coating system gives it long life: "In 12 years experience with Bitumastic No. 50 on both steel and concrete, no maintenance other than touch-up has been required," states Mr. Dannenbaum.

Bitumastic protective coatings, with their waterproof coal tar base, have long been popular for sewage plant protection. For more information on their applications in this field, fill out the coupon. Koppers Company, Inc., Tar Products Division, Pittsburgh 19, Pa. District Offices: Boston, Chicago, New York, Los Angeles, Pittsburgh and Woodward (Birmingham) Ala. In Canada: Koppers Products, Ltd., Toronto.



# BITUMASTIC

COATINGS AND ENAMELS another fine product of COAL TAR

KOPPERS COMPANY, INC., Tar Products Division Dept. 100M, Pittsburgh 19, Pa.

Please send me your brochure "SEWAGE PLANT PROTECTION." Title\_

Name. Firm.

Address.

City\_

Zone State

Patent pending

the less

iman it in

d to out. that sed. sub-

ude own

imude per-

day oot-

own

s to

seon-

also

tion

700

tem

ane

l. 15 vide rant ings tion lectaths ient. oom y at eum been ient rroentest ga ater apor ause rmit tion akes dencennsative. mits and nidi be herr as e bed suslass ches rted the

lity 600 the

D

to

ap

fo

co

ap

eq

ins

or

un

rol

boi

oxi

Ma




Figure 4—Effect of humidity cycling between 100 and 120 F for 2600 hours. Relative humidity was 95 to 100 percent. Specimen coatings were vinyl (left), 3-coat urethane system (center) and 2-component epoxy system (right).




Figure 5—Effect of sour-crude immersion on three coatings samples, exposed for 2600 hours at temperatures between room temperature and 130 F. Specimen on left is vinyl, center is urethane and right is epoxy.

#### Polyurethane Coatings-

(Continued From Page 94)

Effect of sour-crude immersion on the same three systems in shown in Figure 5 for 2600 hours at temperature cycling between room temperature and 130 F. Failure of the vinyl and epoxy systems was in evidence at a considerably earlier time than that at which the photographs were taken.

A panel of urethane coating in con-




Figure 3—Effect of 5700-hour water immersion on a commercial vinyl system (left), a 3-coat urethane system (center) and a commercial two-component epoxy system (right).

#### PROTECT HOT SURFACES

with CE - CO HI-HEAT **NON-FLAMMABLE** ALUMINUM **PAINT** 

Applications are now in service on surfaces where temperatures exceed 800° F.

NON-TOXIC SPRAYABLE

CE-CO HI-HEAT can be applied DI-RECTLY TO HOT SURFACES for it contains no turpentines, naphtha, conventional paint thinners or solvents. Shut-downs because of paint fire and explosion hazards are eliminated.

CE-CO HI-HEAT is easy to apply by spray, brush or roller — and a little goes a long way. One gallon covers 300 sq. ft. It's easy to mix - quick drying - reduces clean-up time

CE-CO HI-HEAT is specially designed for high-temperature-equipment application for most metal surfaces, as well as for masonry. Manufactured specifically for the petrochemical industry, it is economical, durable, dependable - sure protection. Ask us about your specific requirements.

\*CE-CO HI-HEAT for Hot Surfaces in Standard Aluminum Color Only.
CE-CO ALUMINUM for Ambient Surfaces
Available in 6 Pastel Colors.

Write for complete data and check-list of applications.

FARLEY-BOSCH
COMPANY
1318 NANCE STREET FAIrfax 3-1000
HOUSTON, TEXAS

tinuous water immersion for 13,600 hours (i.e., over 18 months) is shown in Figure 6.

#### Conclusions

Urethane coatings may be prepared from non-toxic isocyanate resins in combination with polyesters and other hy-droxyl bearing materials such as castor oil and its derivatives. Final coatings are obtainable as a single package and as two-component systems. Durable and corrosion resistant types are prepared from the two-component systems. Some of the two-component systems characteristics are listed below:

- 1. High gloss and freedom from blushing and surface irregularities.
- 2. Resistance to weathering.
- 3. Resistance to water, high humidity, weak solvents and chemicals.
- 4. Abrasion resistance.
- 5. Reaction possibilities with orthodox coating raw materials to yield new products.

This combination of properties is needed in the corrosion maintenance and marine fields for the solution of the corrosion engineer's problems.

#### Acknowledgments

Thanks are due to G. A. Hudson and J. C. Hixenbaugh who conducted the experimental work described; to Samuel Steingiser and C. F. Crookshanks for photographic assistance; and to Mobay Chemical Company for permission to publish this article.



Figure 6—Urethane coating panel after 18-month water immersion (13,600 hours).

#### References


- Richard C. Burck. Structure, Characteristics and Uses of Urethane Coatings. Corrosion, 13, 130 (1957) Dec.
   Barnard Goodman, New Formulations Give Versatility to Urethane Coatings. Corrosion, 15, 100 (1959) April.

In 1958, there were over 11 million privately and publicly owned trucks on U. S. streets and highways, representing 17 percent of the total U. S. motor vehicle registrations.

Portland Section's Corrosion Control Short Course will be held April 27-29.

#### A "PRUFCOAT PRODUCT" PROFILE

(one of a series)



you mean I can topcoat Prufcoat

Primer P-62 in one hour or even less?

Go ahead and drool, pal. That's exactly what we do mean. Prufcoat Vinyl-Weld Primer P-62 normally can be vinyl topcoated after only one hour air drying . . . less, if hot spray applied...in minutes if force-dried. It's the ideal primer wherever speed is of the essence: In maintenance. In new construction. In product finishing.

In maintenance and new construction applications, scaffolding shifts are held to an absolute minimum. You save on labor. Jobs are completed faster. The chance of between-coat contamination is substantially reduced. In product finishing applications, production rates have been doubled and tripled -without new capital outlays for additional space and equipment.

Because of P-62's moisture tolerance, you enjoy low-cost insurance against costly coating failures due to unavoidable or hard-to-eliminate surface dampness...failures that can unexpectedly skyrocket your maintenance coating costs.

eristics on, 13,

s Give

n pri-ks on

enting

motor

ontrol

-29

Primer P-62 can be brushed, sprayed, hot sprayed or rolled. It exhibits weld-like adhesion to iron and steel. It bonds firmly to most non-ferrous metals and to old, welloxidized conventional paints. Its resistance to inorganic acids and alkalies is equal to that of many anti-corrosion finish coatings-hence it contributes significantly to the overall chemical resistance and durability of the coating system.

Yet, despite its many cost-cutting benefits, Vinyl-Weld Primer P-62 is not a premium-priced product. It sells for dollars less per gallon than many other vinyl primers.



#### WHY NOT PUT PRUFCOAT PRODUCTS TO WORK FOR YOU?

Your Prufcoat service representative can show you how to put Prufcoat corrosion resistant primers and coatings to most effective, money-saving use. There is no cost or obligation. Just write or call .

#### PRUFCOAT LABORATORIES, INC.

Main Office & Plant: 63 Main St., Cambridge 42, Mass. • New York Sales Office: 50 E. 42nd Street, N. Y. 17, N. Y. Warehouses: Atlanta—Buffalo—New Orleans—San Francisco—Seattle



# COREXIT stops internal corrosion--reduces maintenance costs...

At a cost as low as 50¢ per thousand barrels of throughput, Humble's COREXIT corrosion inhibitors will give you up to 98% protection.

You save money, because COREXIT lengthens the life of expensive equipment, prolongs refinery runs between costly turn-arounds, cuts non-productive downtime to a minimum and promotes increased thermal efficiencies.

Injected into the product stream, COREXIT establishes a durable protective film on internal metal surfaces. This film effectively protects against the causes of corrosion. COREXIT also prevents fouling.

Use COREXIT . . . You'll see a substantial cut in your maintenance costs!

COREXIT is readily available in 55gallon drums and in bulk. Call your nearest Humble bulk plant, or phone or write:

COREXIT 780

Humble Oil & Refining Co. Consumer Sales P. O. Box 2180 Houston 1, Texas

COREXIT is also available through these companies:

In Oklahoma & Kansas: Pet-Chem, Inc. Mayo Building • Tulsa, Oklahoma

In Illinois, Indiana & Kentucky:
T. E. Bennett Chemical Co.
P. O. Box 245 • Salem, Illinois

In Western Canada:
Rice Engineering & Operating Ltd.
10509 - 81 Avenue • Edmonton,
Alberta

HUMBLE OIL & REFINING COMPANY

HUMBLE

#### Introduction

HE LONG Beach Oil Development Company, an operator for the City of Long Beach in the Wilmington Field, began a pilot water flood project in June, began a pilot water flood project in June, 1953 confined to the upper one-third of the "HX" sand in the Upper Terminal Zone, Fault Block V-B. The top of the "HX" sand is at a vertical depth of approximately 3000 feet. The oil is 18 degrees API gravity with a viscosity of 18 c.p. at reservoir temperature. The zone has a porosity of 37 percent and a brine permeability of 700 md. The pilot block contains 65 productive acres and 1672 acre-feet of oil sand. The main fault block contains 250 productive acres and block contains 250 productive acres and 25,000 acre-feet of oil sand.

The flood was begun with two direc-

tionally drilled injection wells. One was located 1900 feet north and the other 2150 feet south of the surface site. They were completed as follows:

Twelve 34-inch surface casing cemented at 354 feet.

Seven-inch, 23 lb and 26 lb, J-55 casing cemented in 105%-inch hole from surface

through proposed injection interval. Seven-inch casing perforated over a 50-foot interval with one \( \frac{3}{8} \)-inch hole per two feet using burrless bullets; 2\( \frac{1}{2} \)inch tubing landed above top of perforated interval.

Injection was begun with all the water being injected down the tubing.

Injection water for the pilot flood supplied from shallow water wells is similar in analysis to sea water, although it is oxygen free (less than 0.12 ppm) and is free of algae, sea weed, etc. Turbidity is approximately 2 to 3 ppm (as SiO<sub>2</sub>) and because of this it is not filtered.

An analysis of water from one of the source wells is given in Table 1.

Source wells all were completed in a like manner with an 1134-inch to 16-inch liner float packed in 28-inch to 40-inch hole. Gravel size varied from Tyler Mesh 12-14 to a mixture of 6-8 mesh and 3/16inch gravel. The last of the four wells and the most successful to date was completed as follows:

36-inch conductor pipe driven to 25-

1234-inch steel liner-landed at 195 feet. Liner perforated with 2-inch by 70inch mesh slots. Liner and perforations coated with a baked-on phenolic plastic 5 mils thick. Liner float packed in 34-inch hole with size 6-8 gravel.

This well recently was redrilled after producing 10,500,000 barrels of water.

One vertical triplex pump was used initially for injection. Three additional pumps, one vertical triplex and two horizontal triplexes were added to the system in May, 1955. The four pumps are capable of an output of 20,000 B/D at approximately 1000 psi pressure. All four have porcelain plungers with aluminum bronze fluid ends.

At the beginning of the flood it was not known if corrosion would be a major problem so the flood was started without a corrosion inhibitor being used in the system. However, it was not long before it was realized that corrosion was a major problem. Some evidence of its seriousness was as follows:

1. The first source well was equipped with a deep well turbine pump with cast

## **Corrosion Control Practices in the** Wilmington Water Flood Operation\*

#### Abstract

ADSTRACT

ADSTRACT

Data are given on the method well completion, volume of water injected, types of pumps and lines used in the Wilmington (Cal.) Water Flood Operation. Manner in which effectiveness of inhibitors for injection into salt flood water is described and some of the results achieved with three organic inhibitors are given. Some reports are made on the corrosion resistance of materials used in pumps and well lines and casings.

2.2.7

iron bowls and impellers in May 1953. The pump was discarded in July 1954 as unrepairable because the cast iron components of the pump had graphitized.

2. The original water source well, B-1, was abandoned in April 1955. The 1134inch liner was recovered and the original 40-mesh perforations had been enlarged to ¼-inch to 5%-inch in width due to corrosion and abrasion.

3. The 2½-inch tubing was removed from injection well FZ-228 in October 1954. The tubing had been in service since July 1953 and had 800,000 barrels of water injected down it. Several joints of tubing were split open and an average corrosion rate of 13 MPY was determined.

4. One of the original injection wells was redrilled in February 1957 after receiving over 5 million barrels of injected water. The 7-inch casing string was washed over and recovered to past the top of the injection interval. The lower side of the interior of the casing was found to be severely corroded in a localized area approximately one inch wide from 3774 feet (depth of bottom of tubing from June 1953 to May 1955) to the total recovered depth (3880 feet) The depth of this corrosion increased from 1/2-inch of wall thickness at 3774 feet to the thickness of the casing at 3817 feet. The casing was completely corroded through from 3851 feet to 3852 feet and at 3866 feet.

#### History of Chemical Treatment

The first chemicals used in the water injection system (starting in June 1953) were sequestering agents of the polyphosphate type to prevent the precipitation in the formation of barium and strontium. It was subsequently determined that no serious plugging of the formation was occurring even with untreated water so the use of these chemi-

cals was stopped.
Other types of chemicals varied greatly in composition and at various times the following types were used in the system: Arsenic compounds, polyphosphates, sodium hydroxide, sodium hypochlorite and organic compounds.

Of the chemicals tested none but the arsenic and organic compounds proved to be effective corrosion inhibitors. Since March 1955 the only chemicals tested in the system have been organic compounds.

In June 1956 a program was initiated to test laboratory screened inhibitors in the field. The inhibitors had been pre-viously tested in the laboratory for two properties: Bactericidal control and corrosion inhibition.

The procedure used for the bacteriostatic test is the method outlined by Allred, Mills and Fisher. The chemicals were tested for corrosion inhibition in the following manner: A 24-inch wheel containing eleven bottles mounted on its periphery was rotated at six RPM in an oven maintained at 150 F. The chemical being tested was added to the source water in the bottle in the desired con-centration. A steel coupon then was placed in the bottle and the bottle sealed. The coupons were tumbled in the bottles on the wheel for five days. A corrosion rate was then determined from the weight loss of the coupons.

The best inhibitors based on the laboratory screening were then tested in the field in the water flood project for six

months to a year.

The following tests were used for field evaluation of the inhibitors:

1. Corrosion Coupons. Both insulated and uninsulated. The coupons are lo-

cated in a discharge line at the source wells and are changed once a month.

2. Millipore Filter Test. Run once a month at the well head of one of the injection wells. The millipore determines the plugging tendency of the water. Also determined from the millipore filters is the amount of filterable solids in the water. A spectographic determination is run on the solids to determine their probable origin.

3. Water Analysis. Run once a month at the well head of one of the injection wells. The dissolved oxygen, iron and sulfide content of the water are deter-

4. Bacteria Count. A sample of the (Continued on Page 100)

#### TABLE 1-Analysis of Injection Water

Radicals	Milligrams Per Liter
Sodium (Na)	10,525.7
Ammonium (NH <sub>4</sub> ) Calcium (Ca) Magnesium (Mg)	414.4 1,221.0
Barium (Ba)	*****
Strontium (Sr)	0.2
Sulfate (SO <sub>4</sub> ) Chloride (Cl)	2,800.0 18,295.8
Carbonate, (CO <sub>3</sub> ) Bicarbonate (HCO <sub>3</sub> ) Borate (B4O <sub>7</sub> )	271.5 8.7
Iodide, (I)	6.3
Salinity as NaCl Total Solids Loss on Ignition	30,162.3 33,543.6 4,900.0
Specific Gravity	1.025 @ 60 F
ResistivitypH Value	19.6 Ohm Cm @ 75 F 7.6

<sup>\*</sup>Revision of a paper titled "Corrosion Considerations in Wilmington Water Flood Operation" by C. H. Jones, Jr., Long Beach Oil Development Co., Long Beach, Cal., presented at a meeting of the Western Region Conference, National Association of Corrosion Engineers, Nov. 17-20, 1958, Los Angeles, Cal.

#### Corrosion Control-

(Continued From Page 99)

water at the injection well is analyzed once a month for sulfate reducing bacteria. The count is reported as so many colonies per ml after 30 days' incubation.

5. Tubing Nipples. Tubing nipples two feet in length are placed at selected locations in the tubing strings of the injection wells. The nipples are cleaned with acid and weighed prior to installation. When the tubing strings are pulled the nipples are cleaned in acid, reweighed and a corrosion rate determined. The corrosion rates determined from the nipples are the best indication of down hole corrosion.

Tables 2, 3 and 4 give a summary of three corrosion inhibitors that have been tested in the water flood system in this manner.

#### Flood Expanded in 1958

The Long Beach Oil Development Company expanded its water flood facilities in 1958 to a capacity of approximately 200,000 B/D.

Two new plants recently have been completed, the Pier A plant with a maximum capacity of 120,000 B/D and the Pier E plant a capacity of 70,000 B/D. Both are similar in design. Shallow source wells are drilled in the immediate area to supply the water. First source wells in the area were completed in a manner similar to that used for the last well completed on Pier B.

After 36-inch conductor pipe was driven to 25 feet, a 34-inch hole was drilled to about 150 feet; 1234-inch steel liner was perforated with 70-mesh slots and coated inside and out with a bakedon phenolic plastic. The liner was float packed in the 34-inch hole with size tyler mesh 6-8 gravel. The deep well turbine pumps used are composed of either nickel alloyed cast iron or SAE-63 bronze material throughout. The shaft driven pumps have 18-8 stainless steel shafting with SAE-63 bronze spiders. The pump columns in the new wells were of wrought iron. It was soon evident that wrought iron was not a noncorrosive material in the water flood system. The 5-inch wrought iron pump column in one source well was discarded after 3½ months' service because of severe corrosion. The well averaged pumping 11,000 B/D during the period. The 5-inch wrought iron pump column in another well pumping approximately 12,000 B/D lasted five months before being discarded. The wrought iron columns have been replaced with steel columns coated inside and out with a baked-on phenolic plastic.

The last four source wells at the new plants were completed with concrete liners. The wells are drilled with a reverse circulation rig which eliminates the use of drilling muds, using as fluid in the operation salt water obtained from other source wells. This eliminates the need of swabbing the wells to remove the mud filter cake and allows the use of larger perforations and a more carefully designed and placed gravel pack which results in better sand control of the produced water. The method also eliminates one possible source of solids (clays in the mud) that could act as a plugging agent in the injection wells. On the basis of limited experience it now appears that this is the most suitable type of completion.

Water Pumped to Tanks

From the source wells the water is pumped through asbestos-cement lines to 3000-barrel storage tanks. The nine tanks are coated inside with a coal tar product. The water moves by gravity from the tanks through a 22-inch steel line (coated inside with a coal tar product) to the injection plant where it is pumped by the injection pumps to the individual injection wells. Asbestos-cement pipe and coated steel lines are used in the low pressure water system where feasible.

Both plants are equipped with 500 HP horizontal quintuplexes equipped with either 4-inch or 5-inch solid ceramic plungers. The fluid ends of the pumps are aluminum bronze with stainless steel valves and seats. The pumps are powered with 500 HP natural gas engines.

The water is pumped by the injection pumps into a two-pressure system. The high pressure pumps (4-inch plungers) pump into a system with a maximum pressure rating of 2000 psi. The low pressure pumps (5-inch plungers) pump into a system with a 1270 psi maximum pressure rating.

Each injection well is coupled into the manifold system so that water can be taken from either the high or low pressure system. The volume of water to each well is controlled by an adjustable flow bean with a maximum opening of 2½ inches. The conical tips and seats of the beans are tungsten carbide. All

lines from the injection pumps to the injection wells are steel with no protective coatings.

The injection wells have all been completed in a like manner: 95%-inch J-55 casing cemented at the top of the zone; 7-inch J-55 casing cemented through the proposed injection interval; 7-inch casing is perforated in the desired injection interval with 3%-inch jet shots at an average of two holes per foot.

The injection wells are completed without tubing in the hole with the water injected directly down the casing. The volume of water injected into each well varies from a 1000 to a maximum of 35,000 B/D. As high as 70,000 B/D has been injected into a single well during a test period.

#### Steel Pipe Used Primarily

As previously mentioned non-corrosive materials have been used in several locations in the injection system. However, the injection well casings and the discharge lines from the injection pumps are steel pipe. To protect this pipe an organic corrosion inhibitor is added to the water in each system before it enters the storage tanks. The corrosion inhibitor injection system at each plant consists of a 250-barrel storage tank, an electrical chemical pump for pumping the chemical from the storage tank into the system, and a positive displacement meter for measuring the amount of daily

(Continued on Page 102)

TABLE 2—Corrosion Coupon Tests

		INHIBITOR	
	A	В	C
Type Concentration Cost Period Tested	amine 20 ppm 2.63 M/B 3-56 to 12-56	amine 20 ppm 2.0 M/B 1-57 to 4-58	amine 14 ppm 2.0 M/B 4-58 to Present
Water Source Well B-3	mpy	mpy	тру
Holder No. 1 Insulated Uninsulated Holder No. 2 Insulated Uninsulated	1.6 8.4 0.89 5.6	1.4 22.5 2.5 15.0	9.5 36.1 2.1 15.0
Water Source Well B-4			
Insulated	4.2 96.0	0.4 3/5	12.7

<sup>\*</sup> No coupons remaining. Five tests (1).

TABLE 3-Water Quality Tests

		INHIBITOR	
	A	В	C
Slope of Millipore Curve Filterable Solids Oxygen Sulfides Iron Sulfate Reducing Bacteria	0.246 3.8 mg/1 0.0 ± (0.12) 0.03 mg/1 2.3 mg/1 Not Reported	0.202 5.5 mg/1 0.0 ± (0.12) 0.02 mg/1 2.2 mg/1 136 Col/ml	0.624 2.7 mg/1 0.0 ± (0.12) 0.13 mg/1 1.3 mg/1 106 col/ml

**TABLE 4—Tubing Nipple Tests** 

			Well I	FZ-228	Well	FZ-229
Inhib	itor	Period Nipples In Service	Bbl Water Injected	Corrosion Rate mpy	Bbl Water Injected	Corrosion Rate mpy
A B		8-56— 1-57 3-57— 2-58 (FZ-228) 1-57— 2-58 (FZ-229)	No Nipples 3,343,609	0.3	1,157,270 3,378,869	2.9 0.3
C	************	2-58-10-58	No Nipples		2,078,614	3.6

1-55 e;

n

d

1e

D

ps in to rs nnt

an ng to



# KONTOL\*CORROSION INHIBITOR TRIPLES TUBE-BUNDLE LIFE AT OHIO REFINERY

Also saves \$96.00 per day on increased BTU's ... The effectiveness of KONTOL\* protection against corrosion and fouling in tube bundles was dramatically demonstrated in the heat exchange equipment of the crude unit at a large refinery in Ohio.

Since the inauguration of a regular KONTOL Corrosion Inhibitor program, the tube bundle life period has been increased by approximately 3 times the bundle life prior to the use of KONTOL.

#### KONTOL'S DETERGENT ACTION ADDS DOLLAR-BONUS TO OPERATION

The detergent action of kontol Corrosion Inhibitor provided a plus benefit for the refinery. A cleaner operation has resulted in the gain of an additional

\*KONTOL is a registered trademark of Petrolite Corporation.

KR-59-1

6,000,000 BTU's per hour—or a savings of about \$96.00 per day.

#### THERE'S A KONTOL PRODUCT FOR YOUR CORROSION PROBLEM

The Kontol product used in this case was based on a careful study of the refinery's specific needs. The Tretolite Company developed and pioneered the application of organic corrosion inhibitors throughout the petroleum industry. No other organization has Tretolite's wealth of experience and know-how in the manufacture and use of these products. This background (Tretolite corrosion en-

gineers, laboratory and research facilities) is always available to you—to help solve your particular corrosion problems. A call will bring you this service—at no obligation.

CANADA: Petrolite Corporation of Canada, Limited, 309 Alexandra Bldg., Edmonton, Alberta

ENGLAND: Petrolite Limited, Heathcoat House, 20, Savile Row, London W. 1.

VENEZUELA: South American Petrolite Corporation, Hotel Avila, Caracas

#### REPRESENTATIVES

BRAZIL: WERCO, Ltda., Avenida Rio Branco 57-s/1410-11, Rio de Janeiro COLOMBIA: W. F. Faulkner, Calle 19, No. 7-30, Office 807, Bogota GERMANY: H. Costenoble, Guiollettstrasse 47, Frankfort, a.M. ITALY: NYMCO S.p.A. 9, Lungotevere A. da Brescia, Rome

JAPAN: Maruwa Bussan KK, No. 3, 2-Chome, Kyobashi, Chuo-Ku, Tokyo KUWAIT: F. N. Dahdah, Box 1713, Al Kuwait MEXICO: R. E. Power, Sierra de Mijes, No. 125, Mexico, D. F.

NETHERLANDS: F. E. C. Jenkins, Hoefbladlaan 134, The Hague PERU: International Gas Lift Company, Apartado 71, Talara TRINIDAD: Neal and Massy, Ltd., P.O. Box 544, Port of Spain

## PETROLITE CORPORATION

## TRETOLITE COMPANY

369 Marshall Avenue, Saint Louis 19, Missouri 5515 Telegraph Road, Los Angeles 22, California

# Simplif PROTECTIVE COATINGS



#### PROVEN IN THE PROCESS INDUSTRIES

- STEEL TANK LINING
- CONCRETE TANK LINING
- PROTECTION OF STRUCTURAL STEEL, FUME DUCTS AND **EQUIPMENT**
- CONCRETE FLOORS
- TANK CARS

## FOR IMMERSION SERVICE FOR HEAVY DUTY MAINTENANCE SERVICE

COLD SET COATINGS

**HEAVY BUILD** using standard spray or brush methods. WIDE CHEMICAL RESISTANCE to acids, caustic solvents, salts, de-ionized water, and aqueous solutions.

HIGH TEMPERATURE RESIST-ANCE not affected by ther-

AIR DRY field applications. EXCELLENT BOND - No Primers on white metal blasted surface.

OTHER PLASITE PRODUCTS

INCLUDE: CAULKING COMPOUNDS

PRIMERS BAKING COATINGS

WISCONSIN

protective coatina



COMPANY GREEN BAY, WIS. REPRESENTED IN PRINCIPAL INDUSTRIAL AREAS

PLASI

#### Corrosion Control-

(Continued From Page 100)

injected chemical. The large storage ca-pacity permits the buying of the inhibitor in bulk quantities resulting in a con-siderable savings. The present inhibitor is being used at a concentration of 20 ppm at an approximate treating cost of 1.55 mills per barrel of injected water.

Effectiveness of the inhibitor in the new systems will be checked by the methods previously used for the pilot flood. It is not planned to use the tubing nipples because no tubing is being used in the injection wells.

Research also is continuing on the use of non-corrosive materials in the system where possible. However, it appears that steel casing will be required in the injection wells and that this will necessitate continued use of corrosion inhibitors.

#### References

Bacteriological Techniques Applicable to the Control of Sulfate Reducing Bacteria in Water Flooding Operations. Producer's Monthly, De-cember, 1954.

#### DISCUSSIONS

Question by Joe Chittum, Whittier, Cal.: Was there plugging from corrosion products? What kind of plugging? Was plugging encountered in injection wells during time corrosion was experienced? What was the evidence for plugging?

Reply by C. H. Jones, Jr.:

The water injection wells have continually suffered a loss in injectivity as shown by the loss in injection rate at a constant pressure. It has been possible to restore the injection wells injectivity by backflowing. This indicates the loss of injectivity is caused by plugging.

Prior to the use of corrosion inhibitors in the system, material backflowed from the injection wells contained primarily iron compounds. This indicated the nature of the plugging material to be corrosion products.

However, since using organic corrosion inhibitors, the plugging material appears to be a mixture of the hydrocarbon carrier used in the inhibitor and fine silts and sands produced from the water source wells. The amount of iron compounds found in the plugging material is very minor.

Question by Brian R. Jackson, Santa Fe Springs, Cal.:

Of the three inhibitors tested, was Inhibitor C the least water-dispersible? H = | 1

Reply by C. H. Jones, Jr.:

Yes.

Question by Gordon S. Schuhmacher, South Gate, Cal.:

Iron in source water. Analysis of source water 0.2 ppm Fe and input water over 2.0 ppm Fe. Any comment on how to account for increase?

Reply by C. H. Jones, Jr.:

Additional data indicate no change in iron content between source well and injection well. The 0.2 ppm of iron reported at the source well is in error because it represents a test run on filtered water. Filterable iron compounds would have been removed.

Questions by L. W. Jones, Pan American Petroleum Corp., Tulsa, Okla.:

1. Test for oxygen: What analytical

method is used for measuring oxygen content of the source water?

2. Are all the inhibitors tested considered to be soluble in the source

Reply by C. H. Jones, Jr.:
1. The analytical method used for measuring oxygen content is the ASTM Umpire Method (D888-49T).

2. All the inhibitors tested are considered to be water dispersible.

Questions by E. W. Wallace, Los Angeles, Cal.:

How were the concrete liners in the source wells perforated? What were inhibitors? What are the names of the inhibitors referred to as A, B and C? How do you know you plug 700 md. sand? How do you explain the plugging of a 700 md. sand formation? Is this the permeability of the extracted core? How do you clean out wells after plugging? What proceeding is used to restore injectivity in wells that are plugged?

Reply by C. H. Jones, Jr.:

1. The concrete liners were precast with 125 mesh slots. The liners are manufactured by the Kelly Well Company at Grand Island, Nebraska.

2. Company policy prevents our giving the names of products we evaluated.

3. It is known that the highly permeable sands plug by the loss of injectivity in the injection wells. The plugging material appears to be a combination of the hydrocarbon inhibitor carrier and fine silts and clays present in the source

water.

3. The injectivity of the wells is restored by backflowing the wells using a formation tester. This method has proved effective in restoring the injectivity to as high or higher than the original injec-

4. The permeability figures are brine permeabilities run on 100 percent wet sands. Extraction would not be necessary as no hydrocarbons are present.

Question by A. V. Louk, Santa Fe Springs, Cal.:

In testing your flood water for plugging tendencies with a Millipore filter, does the water tested contain the inhibitor used and have you evidenced any plug-ging attributable to the inhibitor used?

Reply by C. H. Jones, Jr.:
The millipore filter tests are run on water treated with inhibitor. They do not indicate a plugging tendency by the inhibitor. However, there is evidence that the inhibitor carrier in combination with fine silts and clays is responsible for loss of injectivity in the injection

Questions by Willard R. Scott, Magna Products, Inc., Santa Fe Springs, Cal.: 1. Are you satisfied that the oxygen content of the water is essentially zero

at all times, even though an analysis is made only once a month?

2. What do you believe to be the mechanism of the corrosion observed in

the absence of effective inhibitors?

Reply by C. H. Jones, Jr.: 1. Yes.

2. Analysis of the water shows about 35 ppm CO<sub>2</sub> and the presence of sulfate reducing bacteria.

15

cal gen onrce

for

on-

the

the C? nd.

ing

ow ig?

ast an-

ing

nevity naof and

rce

reg a ved o as jec-

wet

ces-

Fe

ing

itor

ed?

do

the nce tion ible

tion

gna al.:

ero s is

the d in

out



Protecting the cooling system of a giant diesel against corrosion is just one of the jobs handled effectively and inexpensively by corrosion inhibiting compounds containing Mutual chromates. Other applications include: cooling towers, airconditioning systems, boilers and condensers. In virtually every type of recirculating water equipment, you can protect against corrosion best with chromate compounds.

For best results, you should add a chromate inhibiting compound to your recirculating water system from the moment operations start. That way, clean metal *stays clean!* If you add them to older recirculating water systems already coated with rust and scale, they will arrest corrosion.

Compounds containing Mutual chromates offer many advantages: They are stable. They're readily soluble. They're effective against all

City.

types of corrosion and scale forming materials. And they're available in a wide variety, each chemically tailored to a specific task. The best of them have this in common—they're based on Mutual chromates.

For the names of manufacturers of corrosion inhibiting compounds containing Mutual chromates or information on Mutual chromium chemicals, we suggest that you mail the coupon today!

### Mutual® Chromium Chemicals

Sodium Bichromate Sodium Chromate Chromic Acid Potassium Bichromate Potassium Chromate Ammonium Bichromate

Koreon (one-bath chrome tan)

SOLVAY PROCESS DIVISION 61 Broadway, New York 6, N. Y.



MUTUAL Chromium Chemicals are available through dealers and Solvay branch offices located in major centers from coast to coast.

SOLVAY PROCESS DIVISION ALLIED CHEMICAL CORPORATION 61 Broadway, New York 6, N. Y.	11-129
Please send:  List of manufacturers of corrosion inhibiting com Booklet "Mutual Chromium Chemicals"	npounds
Name	
Position	
Company	
Phone	
Street	

Zone

State

OUTHERN PACIFIC Pipe Lines, Inc., started receiving petroleum products at Los Angeles, California and at El Paso, Texas early in 1956 and then pumping them to terminals located at various points along its new 846-mile pipe line. The Phoenix, Arizona, terminal, located approximately at mid-point, receives products from both El Paso and Los Angeles. In addition to the main line, there is a system of 173 miles of 6-inch lateral lines.

During 1957 the pipeline system was expanded by construction of a new 10, 8 and 6-inch products pipe line between Richmond in the San Francisco Bay area and Reno, Nevada, with a 6-inch lateral to Fallon, Nevada. This new system, including laterals, totals 347 miles.

Designed through-put for the new system is 15,000 barrels per day from Richmond to Reno. With planned ad-

ous region which is snowed-in during winter and spring and is not easily accessible at any time. Because the environment in any of these areas could be extremely corrosive, a cathodic protection system had to be put in operation as soon as possible with an absolute deadline in the mountains coinciding with the first snows of the 1958-1959 winter.

Tests begin in February, 1958, showed coating resistance was not as high as expected. Although rock-shield had been used in the rocky areas, rocks damaged the coating in a number of locations. After completion of construction when the line was hydrostatically tested, numerous leaks were found in the section of 10-inch pipe between Concord and Roseville. Many of these were small and not easily pin-pointed, so the line had to be probed so that a vibration recording leak detector could be used. In

were unusual. The first was that of satisfying fairly large current requirements at terminals without causing interference to nearby foreign substructures such as railroads, refineries and other pipe lines. Because it was impossible to install the anodes at great distances from these foreign substructures, the anodes were installed quite close to company facilities (within 5 to 10 feet at times), and the anodes were made large enough so that the resistance was so low that there were practically no anode fields. Large anode beds were over 1400 feet long. Resistance was so low that potential between anode and pipe was about the same as pipe-to-soil potential, some times 1.5 to 2.0 volts.

D

The second problem was to get protection on the section of the pipe line in the High Sierras. The line crosses over Donner Pass and for a distance of ap-

#### Whole System Installed in Nine Months

# Cathodic Protection of Southern Pacific's High-Pressure Products Pipe Line\*

ditional pump units, this rate can be increased to 20,500 barrels per day with a 42,000 barrels per day capacity as far as Roseville.

This line, which transports regular, premium and aviation gasoline plus diesel oil and jet fuel, operates at high pressure so the product can be pumped over the High Sierras. For example, on the western slope of the mountains near Colfax, California, discharge pressure at one of the pump stations is 2160 psi.

Coating System Used

Four different systems of coating materials were used on the pipe. In general, ½-inch plant-applied asphalt base coating was used on all river crossings and major hot spots. Plant-applied double-coat, double-wrap asphalt coating consisting of asphalt primer, enamel with 13-pound asphalt saturated rag felt followed by 20-pound asphalt saturated rag felt, was used in the heavily congested areas. Plant-applied, single-coat, reinforced, single-wrap asphalt coating was used throughout the remainder of the system except for a few short sections in which over-the-ditch wrapping was allowed.

A portion of the line near the coast is under water most of the time. In another area, many miles of the line are through peat lands where the line crosses several rivers and marsh areas. Much of the line is laid alternately through wet and dry areas in farming country, and many more miles are lying in very low resistivity alkali flats where water is present most of the time. In addition, many miles traverse a rough monutain-

Abstract
Various problems encountered and methods used to achieve cathodic protection of a pipe line across central California and Nevada are discussed. Location of rectifiers and anodes used are given. Special problems such as the winter snows, air observation of rectifiers and close proximity to co-axial telephone cable are discussed.

5.2

some cases, probing was done at no greater than 2-foot intervals. The resultant holidays were not repaired. In addition to the holidays, a number of locations were found where the coating is not adequately bounded to the pipe.

#### Cathodic Protection Design

Due to scarcity of usable routes through the Sierras, the pipe line was laid near and closely parallel to an existing co-axial telephone cable. To minimize interference to the cable and to preserve the pipe coating as long as possible, a maximum pipe-to-soil potential of 1.5 volts was decided on. This meant that a greater than normal number of rectifier units was required.

One cathodic protection rectifier unit was designed for each of six terminals and pump stations. Because more current was required at these spots, they were good starting points. Also, no right-of-way problems were involved because all anode beds could be installed on company properties. When these units were installed and operating, locations were selected for the remaining units in the pipeline runs between the terminals and pump stations. Some of the required current was purchased from owners of nearby existing cathodic protection stations, and 21 additional units were installed.

Two Unusual Problem Solutions

Although many of these units were quite ordinary, two problem solutions

proximately 60 miles is either very remote from power or is laid in solid granite. It was determined that three units would be needed in this heavy snow country. The first, with no unusual problems, was installed near Truckee, California uning scrap rail for the angle.

California, using scrap rail for the anode. The second unit had to be located near the only available power and was installed in the conventional manner, except for high resistance soil, using 10 horizontal graphite anodes in a coke backfill. This unit operates at 0.9 ampere and 110 volts d-c output or with an anode resistance of approximately 124 ohms as compared with resistances of 1/10 ohm in the low altitude marsh country.

The site for the third high-country unit was the most difficult of the three units. For the entire distance along which this unit could operate effectively, the pipe line was in granite. However, there was a lake close to the line in which the anode was installed. Due to limited space and especially level cleared ground, the anode was formed of threaded and coupled 3-inch pipe, floated onto the lake as it was assembled. Resistivity of the water in mountain lakes is not as low as might be expected. In this case, it is over 40,000 ohm-cm.

Because of the deep snowpack during winter months, rectifiers were mounted near the tops of poles, with platforms 20 feet high on which to work.

Because the line is patrolled weekly by airplane, failure indicators are being installed for pilot observation on all rectifier units not at a manned terminal or pumping station. Most failure indicators are electric motor driven discs which are connected to the a-c side of the rectifier. As long as the rectifier receives its a-c supply, the disc revolves

(Continued on Page 106)

<sup>\*</sup>A revision of the paper "Blitzkrieg Cathodic Protection of a High Pressure Products Pipe Line" by D. N. Miller, Southern Pacific Lines, Inc., Los Angeles, Cal., presented at the 15th Annual Conference, National Association of Corrosion Engineers, Chicago, March 16-20, 1959.

t of ire-

ing suberies imreat ruc-

uite 5 to vere

ance ally vere

and -soil

proe in

over

ap-

S

olid

ree

avy sual

kee.

ode. ated

was

ner 10 oke

ere

124

of

rsh

itrv

ree

ong ely,

ver.

in to

red

of

ited

Re-

kes

In

ing

ited

rms

kly

all inal

ndiiscs of

re-

ves

#### Cathodic Protection

## **CPS Undertakes Largest** SINGLE PACKAGED Pipe Line Protection Job


Houston Texas Gas and Oil Corporation selected CATHODIC PROTECTION SERVICE to design and install a complete cathodic protection system for their new natural gas pipeline. This line runs from Baton Rouge, Louisiana, to Miami, Florida, covering a distance of 1616 miles.

This is the largest single packaged pipeline cathodic protection job yet undertaken. CPS is in a unique position to handle just such a job . . . serving as a central source . . . for all phases of corrosion mitigation on any new pipeline.




The Maloney type-57 Insulator chosen for the Houston Texas Gas and Oil Corporation pipeline.

CPS has its own engineering crews who obtain the information necessary to complete the detailed design of a cathodic protection system. Plus this, CPS furnishes all materials, labor, equipment and engineering supervision to install cathodic protection on a packaged basis. Because it is a



River weights on Polyken coated 24" line going into the swamps of Florida.



package, CPS can immediately follow the laying contractor, providing complete protection to the pipeline system soon after the last foot of pipe is laid. In addition to the cathodic protection package, CPS also serves as a central source of supply for other materials which were used on this pipeline, i.e., Polyken polyethylene tape, Maloney type 57 plastic casing insulators and the L&M pipeline markers, casing vents and test lead boxes.



The Polyken method that allowed the contractor to lay an average of better than 10,000' of 24" pipe a day.

This represents a package within a package which CPS can deliver: (1) L& M gas line marker (2) Gas vent with cover (3) Test lead box with lead wires.

We at CPS believe a strong relationship is essential among manufacturer, supplier and customer. We know through experience that ties of this sort mean more initial and repeat business. If you are considering a similar big pipeline job, why not talk it over with us and see how our single packaged cathodic protection can give you cost-cutting advantages. It will cost you nothing to find out.

Cable Address — CATPROSERV

## tection service

P. O. Box 6387

CHICAGO 122 S. Michigan Blvd., Rm. 964
WEbster 9-2763
TUlip 3-7264

CORPUS CHRISTI

Houston 6. Texas DENVER (Golden) P. O. Box 291 CRestview 9-2215

JAckson 2-5171 NEW ORLEANS ODESSA 1627 Felicity 5425 Andrews Hwy. 1627 Felicity 5425 Andrews H JAckson 2-7316 EMerson 6-6731

TULSA 4407 S. Peoria

#### Cathodic Protection-

(Continued From Page 104)

to indicate presumbly satisfactory opera-tion. This type of indicator can show the rectifier in service while the d-c

circuit is open.

Because it is more important to know that the pipe line is receiving an ade-quate supply of direct current, indicators were designed to operate on a-c but are controlled also by the d-c. A failure in either the a-c or d-c circuit will cause the indicator to stop revolving. This is accomplished by using a relay which is actuated by a meter relay hooked across the rectifier output shunt. When the relay is closed, an a-c motor turns the indicator. The indicator is shaped like a cone so that it sheds snow and can be seen from both the ground and the air.

#### Summary

Several things have been accomplished:

1. The 21 units required to protect the lines are installed and operating-20 of these were in operation within 9 months of the first design attempts.

2. If anodes need to be installed in

water again, experience gained will permit avoiding many pitfalls.

3. The overall cathodic protection

system, completely designed, installed and put into operation in less than one year will provide complete protection for the pipeline system at a reasonable cost.

## DISCUSSIONS

Glass Fiber Reinforcement for Coatings, by B. A. Graham. Corrosion, Vol. 15, No. 4, 102-104 (1959) April.

Question by Austin K. Long, Glidden Company, Bay Village, Ohio:

Would the author comment on simultan-eous application of sprayed coating and fibers in the reinforced plastics field?

Reply by B. A. Graham:

The simultaneous application of sprayed resin and fibers has a definite place in the reinforced plastics field. It is not a cureall but is an improvement over hand lay-up methods in many cases. I believe it will find its place in short production runs which do not warrant the expense of matched metal dies and also for shapes which are difficult to tailor with cloth or chopped strand mat.

#### Question by Sol M. Gleser, Cincinnati, Ohio:

What is your recommendation for mats to reinforce thin epoxy coatings for protection of concrete floors.

Reply by B. A. Graham:

Because of a limited knowledge of this particular application, I cannot make a recommendation. I will suggest that monofilament mats are worthy of evaluation. The epoxy coating thickness should be greater than the mat thickness, which means greater than 10 mils.

Methods of Installing Cathodic Protection Anodes for Offshore Structures, by Wayne A. Johnson and James T. Condry. Corrosion, Vol. 15, No. 9, 112 (1959) Sept.

#### Question by Dean C. Glass, Chicago, Illinois:

What type electrode is used to check water to steel potential and where is the electrode positioned with respect to the structure (protected) on the typical in-stallation as described?

#### Reply by Wayne A. Johnson:

We generally use a calomel electrode and place it several inches from the structure, obtaining readings at several levels in the water.

## Questions by Robert L. Davis, South Pasadena, California:

1. Have you investigated suspending

magnesium anodes on plastic rope?


2. Have you had any trouble with failure of graphite anodes at the lead wire connection.

P to to C

#### Reply by Wayne A. Johnson:

1. We have had better service with steel cables or Monel if the lengths are not long enough to add excessive resistance to the anode circuit. Nylon rope stretches too much. Polyethylene rope does not stretch as much as nylon. Using plastic ropes, you still need an electrical conductor.

2. Wire connections to the graphite anode are always subject to failure due to penetration by water. We try to get the best type of waterproof joint. We usually cap the top with an epoxy.



# Higher fiber content assures more effective protection against



## Carey asbestos pipeline felt

Heavy soil conditions can really play havoc with pipe line coatings. That's why coatings alone can't give your lines positive protection. The answer is a protective wrapper between soil and coating to prevent transmission of soil stress. Only the best wrap will do this job effectively.

What should you look for in wrapping materials to assure maximum protection? Well, weight contributes greatly to the strength of the wrap, but the controlling factor is the type and percentage of fiber content.

Carey Asbestos Pipe Line Felt, as the

diagrams indicate, has 10 times more fiber than Pipe Wrap "G." This toughens the wrapping material against continual soil stress, protects the coating and consequently prevents the exposure of the pipe to corrosive action. Carey Pipe Line Felt being composed of asbestos fiber will not rot or decay.

Before you buy pipe wrap, compare not just weight but fiber content as well. Carey No. 15 Asbestos Pipe Line Felt or No. 8 Asbestos Pipe Line Felt (No. 8 contains 6 times more fiber than Type "G") assures you better protection and better performance from the coatings you use.



CAREY No. 15 ASBESTOS PIPELINE FELT Total weight per 100 sq. ft.—14 pounds Wt. of Fiber per 100 sq. ft.—10 pounds



PIPE WRAP "G"

Total weight per 100 sq. ft.—12.5 pounds
Wt. of Fiber per 100 sq. ft.—1 pound

REMEMBER,

only Carey Pipeline Feit is AccuRay\* controlled for maximum protection on every inch of underground piping. Get complete information from your Carey Sales Engineer or write Dept. 000.

\*Trademark of Industrial Nucleonics, Inc.

THE PHILIP CAREY MFG. COMPANY, Lockland, Cincinnati 15, Ohio Manufacturers of Carey Asbestos Pipeline Felt, Pipeline Padding, Carey Glass Pipe Wrap and Carey Glass Outerwrap

5

1. 15

(den

oat-

tanand

the urelaye it runs e of apes

s to

this
e a
onoion.
be
nich

roucand ol.

eck the the in-

ode ucvels uth

ailire

reope oes ascal

due get We





Roskote Mastic being applied mechanically to a portion of Oklahoma Pipe Line Constructors, Ltd. spread, on the Trans-Canada 30". Following minor modifications to the hot dope machine shown, an 8-man dope crew averaged 10,000 to 12,000 feet per day. Only one supply kettle was necessary, as Roskote is applied cold.

Built by the La.-Miss. Pipe Line Construction Co., of N. C., Inc., for the City of Shelby, North Carolina, this 6-mile line of 6" pipe will serve the new fiber-glass plant there. To insure complete protection, Roskote Mastic was economically applied with the Roskoter, Royston's one man coating device.



bel

diff

ato

ger

clu

3.2

Ste

# Large jobs, small jobs--cold-applied ROSKOTE offers better pipe protection at lower cost.

ROSKOTE MASTIC, applied cold by line travel machine, Roskoter, spray or brush, effectively and economically protects underground pipe against corrosion. Roskote Pipe Mastics assure lower labor costs, elimination of heating fuel, improved safety conditions, simplified coating operations for all pipeline construc-

tion. Fast drying permits early backfill, speeds work.

Before you write specifications, investigate the ROSKOTE potential. ROSKOTE's chemical, electrical and physical properties are detailed in our technical literature. Write for it or for the prompt services of our field representatives.

ROYSTON LABORATORIES, Inc., Box 112C, Blawnox, PITTSBURGH 38, PA.

ATLANTA • CHICAGO • HOUSTON • SAN DIEGO • TULSA • PHILADELPHIA • ST. PETERSBURG



1. 15

of 15-

oe

00 te

## CORROSION ABSTRACTS

#### INDEX TO CORROSION ABSTRACTS

		Dece					_	-
	ARACTE			IENA				
3.2	Forms							. 109
3.5	Physical	and	Mech	anical	Eff	ects		. 110
3.6	Electroc	hemic	al Ef	fects .				. 110
3.7	Metallu	rgical	Effec	ts				. 112
3.8	Miscello	neous	Princ	iples .				. 112
6. MA	TERIALS	OF	CONS	TRUCT	rio	N		
6.2	Ferrous	Meta	ls and	Alloy	S			. 113
63	Non-Fer							
0.3	Alloys-	-Heavy	y					. 114
			· · · ·					. 114
8. IN	Alloys-	5						
8. INI 8.4	Alloys— DUSTRIES Group 4	5						. 116
8. INI 8.4 8.7	Alloys—							. 116

#### 3. CHARACTERISTIC CORROSION PHENOMENA

#### 3.2 Forms

3.2.2, 3.8.4

Behavior of Hydrogen in Iron (Steel). A. Smialowski. Neue Hütte, 2, No. 10, 621-626 (1957). Translation available from Henry Brutcher, Technical Translations, P. O. Box 157, Altadena, California

Gaps in our present knowledge of the

behavior of hydrogen in iron and steel. Expansion of iron (steel) due to penetration of hydrogen into it, and results of calculations based on measurements of pressure exerted by cathodically liberated hydrogen. Deviation of diffusion coefficient measured at room tempera-ture from values extrapolated from higher temperatures and the associated problem of the conjectured two desorp-tion stages. Probable effect of 'blowhole layer' on the observed values of the diffusion coefficients at room temperature. Nucleation of blowholes. Presence of hydrogen in the iron lattice in the atomic as against the ionic form. 'Metal-

lic' hydrogen, Migration of hydrogen in iron under an electrical potential gradi-ent. Correct thickness of wires and membranes used for measuring hydro-gen desorption and penetration, respec-tively, and, hence, diffusion coefficients at room temperature, as a most important factor in avoiding erroneous con-clusions. 6 figures, 1 table.—HB. 16281

3.2.2, 3.7.3, 6.2.5
Anneal Stainless Tubing for Corrosive Use. J. S. Adelson. Republic Steel Corp. Iron Age, 182, No. 6, 83-85 (1958) August 7.

The main cause of failure in stainless steel tubes are intergranular corrosion, stress-corrosion cracking and pitting. For this reason tubing made from 300 series stainless steels should be given a final solution heat treatment at 1850 to 2050 F after welding or cold forming. The use of a bright annealing furnace for heat treatment so that the original smooth tubing surface is retained is recommended. It is pointed out that the prevention of failures in handling corrosive materials offsets the extra cost of the annealed product.—NSA.

3.2.2, 6.3.11
Origin and Mode of Formation of Certain Local Stains on Silver Tableware. D. Birtles, E. Jackson and M. Thomson. Nature, 179, No. 4559, 557-559 (1957).

When sodium chloride is dropped on a silver surface immersed in hot water containing certain synthetic detergents, it produces local dark spots, which can-not be removed by the proprietary dip cleaners or the aluminum-soda process. Similar stains are produced by sodium

Abstracts in This Section are selected from among those supplied to sub-scribers to the NACE Abstract Punch Card Service. Persons who are interested in reviewing all available abstracts should write to NACE for information on this service.

#### PHOTOPRINTS and/or MICROFILM COPIES

of Technical Articles Abstracted in

#### Corrosion Abstracts

May Be Obtained From

- ENGINEERING SOCIETIES LIBRARY, 29 West 39th Street, New York 18, N. Y.
- CARNEGIE LIBRARY OF PITTSBURGH, 4400 Forbes St., Pittsburgh 13, Pa.
- NEW YORK PUBLIC LIBRARY, New York City.
- U. S. DEPT. OF AGRICULTURE LIBRARY, Office of Librarian, Washington, D. C. (Special forms must be secured).
- LIBRARY OF CONGRESS, Washington, D. C. JOHN CRERAR LIBRARY, 86 East Randolph St., Chicago 1, III.

Persons who wish to secure copies of articles when original sources are unavailable, may apply directly to any of the above for copies. Full reference information should accompany request. The National Association of Corrosion Engineers offers no warranty of any nature concerning these sources, and publishes the names for information only.

NACE will NOT accept orders for photoprint or microfilm copies of material not published by the association.

#### CODE OF AGENCIES SUPPLYING CORROSION ABSTRACTS

Neither NACE nor the sources listed below furnish reprint copies.

- ATS-Associated Technical Services Abstracts, Associated Technical Services, P. O. Box 271, East Orange, New Jersey.
- AWWA—Journal, American Water Works Association, Amer. Water Works Assoc., Inc., 2 Park Ave., New York 16, New
- -Current Technical Literature, Bell Telephone Laboratories, 463 West St., New York 14, New York.
- BTR—Battelle Technical Review, Battelle Memorial Institute, 505 King Ave., Columbus 1, Ohio.
- CDCT—Boletin, Centro de Documentacion Cientifica y Tecnica, Plaza de la Ciu-dadela 6, Mexico 1, D. F.
- -Electroplating and Metal Finishing, 85 Udney Park Road, Teddington, Middlesex, England.
- -Translations, Henry Brutcher, P. O. Box 157, Altadena, California.
- IIM—Transactions of The Indian Institute of Metals, 31 Chowringhee Rd., Calcutta 16, India.
- INCO—The International Nickel Co., Inc., 67 Wall Street, New York 5, New York.
- -Japan Society for the Promotion of Science, Mr. Hayata Shigeno, Secretary, Committee of Preventing Corrosion, c/o Government Chemical Industrial Research Institute, 1 Chome Nakameguro, Meguro-Ku, Tokyo, Japan.
- MA—Metallurgical Abstracts, Institute of Metals, 17 Belgrave Sq., London, SW 1, England

- NSA-Nuclear Science Abstracts, United States Atomic Energy Commission, Technical Information Division, Oak Ridge, Tennessee.
- OTS—Office of Technical Services, U. S. Department of Commerce, Washington 25, D. C.
- PDA—Prevention of Deterioration Abstracts, National Research Council, 2101 Con-stitution Ave., Washington 25, D. C.
- PMR—Platinum Metals Review, Johnson, Matthey and Co., Ltd., Hatton Garden, London, ECI.
- RML—Review of Metal Literature, American Society for Metals, 7301 Euclid Ave., Cleveland 3, Ohio.
- RPI-Review of Current Literature Relating to the Paint Colour, Varnish and Allied Industries, Research Assoc. of British Paint, Colour and Varnish Manufacturers, Paint Research Station, Waldegrave Rd., Teddington, Middlesex, England.
- SE—Stahl und Eisen, Verlag Stahleisen, m.b.H., Breite Strasse 27 (Schliessfach 2590), Dusseldorf, Germany.
- TIME-Transactions of The Institute of Ma rine Engineers, The Memorial Bldg., 76 Mark Lane, London E. C. 3, England.
- —Wear, Elsevier Publishing Co., 110-112 Spuistraat, Amsterdam, Holland.
- —ZDA Abstracts, Zinc Development Association, 34 Berkeley Square, London W. 1, England.

chloride particles on silver immersed in dilute acid or alkaline solutions, or merely in water, but not by an homogeneous sodium chloride solution; similar stains are produced by potassium chloride, ammonium chloride, potassium bromide, or sodium iodide, but not by sodium fluoride. Of 5 solid detergents tested, the only one that did not produce a stain had the lowest hande content.
The stains are composed of silver chloride, silver bromide, or silver iodide.
The recent increased occurrence of the stains is partly due to the chemically clean surface exposed by the detergent to sodium chloride particles. The essential requirement for stain formation is a local concentration of halide at a silver surface, which promotes electrochemical action. CN<sup>-</sup> and CNS<sup>-</sup>, which, like Cl<sup>-</sup>, Br<sup>-</sup>, and I<sup>-</sup>, form insoluble silver compounds soluble in excess anion, give similar stains. To prevent staining, the detergent should be dissolved before the silver, freed from sodium chloride by previous washing, is immersed.—MA

#### 3.5 Physical and Mechanical Effects

3.5.3

Selecting Materials to Avoid Cavitation Damage. William J. Rheingans. Materials in Design Engineering, 48,

Various types of stainless steel and aluminum bronze provide the best resistance to cavitation erosion in hydraulic equipment. There is a wide variation in the resistance of similar materials, and a small change in a ma-terial's chemical content or properties can substantially affect its resistance to cavitation damage.-MR.



3.5.4, 4.7

Transport of Radioactivity by Liquid Sodium in a Stainless Steel Circulation System. D. Fieno and D. Bogart. U. S. National Advisory Cttee. Aeronautics, Research Memo., E54K03, 1955 (De-classified, 1957), 17 pp.

Data were obtained for toroids operating at 900 F (480 C) at a constant sodium velocity of 15 ft/sec. Irradiated 316 or 347 stainless-steel inserts were placed in the toroids. The activity transfer was limited by the diffusion of activated atoms. The transfer from the insert to the toroid wall increased with sodium oxide content of increase in sodium. A 600-hr experiment implying a temperature differential in the toroid resulted in no change after a 1400-hr isothermal run.—MA. 16205

3.5.7. 3.5.8

The Influence of Hydrostatic Pressure on the Tensile Deformation of Single Crystals. P. Haasen and A. W. Lawson, Jr. Z. Metallkunde, 49, No. 6, 280-291 (1958) June.

Effect of 5000 atm hydrostatic pressure on tensile stress-strain curve investigated on single crystals of aluminum, copper, nickel and alpha-brass as well as on polycrystalline nickel. In all cases except nickel single crystals the flow stress increases with pressure. Increase is larger than is expected from change in elastic moduli with pressure. Returning to deformation at 1 atm following strain at 5000 atm the flow stress is still higher than normal. In pure metals rise in flow stress under pressure is interpreted in terms of work done against pressure to produce vol-ume. Volume change due to plastic deformation follows to about 10-4. Residual increase in flow stress at 1 atm after deformation under pressure shows that crystal workhardens more strongly under pressure in favor of decreased volume production. Dislocation theory is discussed. Investigation on zinc single crystals shows that hydrostatic pressure has no effect on deformation twinning, Graphs.—INCO. 16525

3.5.8, 3.5.9, 4.6.2, 6.2.5
Stress Corrosion Cracking of Austenitic Steels at Elevated Temperatures and Pressures. V. P. Sidorov and A. V. Ryabchenko, Metalloved. I Obrabotka Metallov, No. 6, 25-32 (1958) June. Translation Available from Henry Box 157, Altadena, California.

Development of a long-time test for

stress corrosion resistance in aqueous solutions, of steam superheater and steam-pipe steels, simulating their conditions of service. Particulars on authors' testing machine. Steel compositions (austenitic) tested. Effect of composition and concentration of test solutions, with and without access of oxygen; concentration of solutions below which steel does not succumb to stress corrosion failure. Effect of test-ing temperature; range in which stress corrosion occurs; relation between test temperature and time to failure. Stress corrosion resistance as affected by heat treating; true nature of effect of heat treating. Influence of sodium chloride addition to sodium hydroxide solution. 7 figures.—HB. 16645

3.5.8, 2.3.7

Relations Between Direct-Stress and Bending Fatigue of High-Strength Steels. G. Sachs and G. Scheven. Syracuse Univ. Proc. Am. Soc. Testing Materials, 57, 667-681 (1957).

Results of fatigue tests on SAE 4340 heat treated to 210,000 psi and 290,000 psi and tested under various conditions. Direct-stress and rotating-bend tests on smooth and notched specimens were performed leading to failure at ranges between a few and about one million cycles. Each S-N curve extrapolates well to respective static strength of origin. Two characteristic quantities origin. Two characteristic quantities were determined for various cycles: ratio of strength in bending to that in tension (bend-strength ratio) and ratio of strengths of notched to smooth specimens (notch-strength ratio). Bendspecimens (noten-strength ratio). Bendistrength ratio for high numbers of cycles is practically equal to unity, while for low numbers of cycles it is larger than 2 for smooth specimens and between 1-2 for notched specimens, depending on their ductility. Tables, graphs.—INCO. 16337

3.5.8, 2.3.7

Study of Corrosion Fatigue; Method of Measuring Damage Caused by Corrosion Fatigue. (In Japanese.) Kanetoshi Iwamoto. Trans. Soc. Mech. Engrs., Japan, 23, 238-241 (1957) March.

After specimens were corroded with a water steam under various magni-tudes of rotary bending stress and for various times, they were subjected to fatigue tests in air under a stress, which was about 20 per cent larger than the fatigue limit of the material.—MR. 14686

#### 3.6 Electrochemical Effects

Hydrogen Embrittlement of Steel During Cathodic Treatment. M. A. Figel'man and A. V. Shreider, J. Applied Chem. USSR (Zhur. Priklad. Khim.) 31, No. 8, 1184-1193 (1958).

Effect of duration of cathodic polaricalistic and godium hyperstrains.

zation in sulfuric acid and sodium hy-droxide, thickness of zinc coating. droxide, thickness of zinc coains, Chrome-plating conditions, soaking at various temperatures on brittleness of steels is investigated. 1 table, 6 figures, 16488

368 383

Electrochemical Properties and Corrosion Rate of Intermetallic Compounds. N. Ohtani. J. Japan Inst. Metals, 22, No. 4, 212-216 (1958) April.

The electrochemical properties, espethe anodic polarization and the hydrogen overpotential of intermetallic compounds were measured; the anodic polarization was approximately equal to the mathematical mean of two components of the compounds, but the larger the electronegative difference of the components and the higher the melting point of the compound, the smaller was the hydrogen overpotential of the compound. The relation between corrosion rate, anodic polarization and hydro-gen overpotential of various alloys in which compounds are formed, was found to be in fair agreement with re-sults of previous reports.—JSPS. 16597

Corrosion of Metals Connected to Graphite Components. T. K. Ross. British Chem. Eng., 3 368-370 (1958)

Metallic plant components connected to graphite equipment may, in service, undergo severe corrosion. An investigation of this problem and how it can be controlled is discussed.—BTR. 16600 4340 tions. ts on were inges illion lates h of ities cles: at in ratio ooth Bends of nity, it is mens nens, bles, 6337

ol. 15

Cor-lane-lech. with agni-l for d hich the

4686

thod

Steel Aplad. lari-

ting, g at s of ures, 6488

Corınds. 22. spe-the allic

odic al to nporger lting was omsion dro-

s in was 6597 l to

cted vice, tigan be 6600

958)



Wide selection of Transite lengths means a single length completes most any installation.



Transite is quickly, easily installed with reg-ular plumbers' equipment. Lower end is machined with bead . . . for standard caulked lead joint.

V LOW MATERIAL COST V SINGLE-LENGTH INSTALLATION

### You get both savings with **Transite Plumbing Vent Pipe**

You simply can't match Transite® for the different ways it saves you money!

First and most important is its low cost. Look at Transite's cost-per-foot and you see a big reason why it's used by so many builders and plumbing contractors for immediate and substantial savings.

The second way you save is in installation. For you can complete most any plumbing vent installation with a single length of Transite. There's no material waste, no wasted time or motion as you use a 5, 6, 7, 8, 9, or 10-ft. Transite length . . . the size that fits the job.

Made of asbestos-cement, Transite cannot rust, resists weathering. Lightweight, yet is strong and durable. Won't cause staining, stays neat and white always.

Let us send you TR-107A, 4-page brochure on performance and ways to speed installation. Address Johns-Manville, Box 14TC, New York 16, N.Y. In Canada, Port Credit, Ontario.

100 YEARS OF QUALITY PRODUCTS . . . 1858-1958



3.6.6, 3.6.2, 3.6.9

Galvanic Corrosion. J. Boraston. In-pection Engineer, 22, 50-56 (1958) May-June.

Causes, prevention of dissimilar metal corrosion, crevice corrosion, stray current corrosion, 4 references.—MR.

Surface Distribution of the Working Efficiency of a Cathode, under the Conditions of Corrosion with Oxidant Depolarization. (In Russian.) N. D. Tomashov and O. A. Deryagina. J. Phys. Chem., USSR (Zhur. Fiz. Khim. USSR), 31, No. 1, 55-60 (1957).

It was shown before by Tomashov that there is a parabolical relationship between the current density at any point and the cathode area, when the rate of corrosion is determined by the diffusion rate of a depolarizer. The current rate of a depolarizer. The current density decreases with distance from the edge of the cathode. To determine the kinetics of the process Tomashov and Deryagina studied the polarization phenomena at distances of 10-2500  $\mu$  from the edge of a cathode. The limiting current in 0.02 Normal-hydrochloric acid and 0.02 Normal hydrochloric acid plus 0.24 per cent hydrogen peroxide decreased by approximately 5.6 times over a distance of 1000  $\mu$  from the edge of a cathode. The decrease is not linear. On increasing the interelectrode distance both the value of the current and the effect of the distance from the edge increases. This is explained by the increases. This is explained by the change in depolarizer concentration. Minimum depolarizer concentration causes a minimum in current density. The concentration of a depolarizer at the edge of the cathode can be sufficiently high to transfer the control of the mechanism from diffusion to the reduction of the depolarizer. With cathodes sufficiently small and distances between them large, corrosion is controlled by cathodic reactions, but if inclusions are present in the cathode under the same conditions the control-ling factor will be the diffusion rate.— 17063 MA

#### 3.7 Metallurgical Effects

Brazing-Filler Metals Meet High-Brazing-Filler Metals Meet High-Temperature Needs. A. M. Setapen. Iron Age, 181, No. 19, 110-111 (1958) May 8; Steel, 142, No. 20, 140-142 (1958) May 19; Industry and Welding, 31, No. 5, 51-52, 54-55 (1958) May; Tool Engr., 40, No. 6, 119-120 (1958) June.

40, No. 6, 119-120 (1950) June. Recent research indicates that lithium temperature brazing. Addition of a small percentage of the metal markedly improves fluidity and wetting ability of many standard alloys, and makes it pos-sible to braze stainless steel in an atmosphere without flux, at temperatures as low as 1600 F. One lithium-sterling silver alloy is gaining favor for brazing honeycomb panels made of 17-7 PH stainless. Joints of sterling-lithium alloy are more corrosion resistant than those of silver-manganese. Palladium additions to silver increase melting temperature, strength and ability to wet iron and nickel base alloys. Manganese further improves wetting. For joining stainless, Inconel and other heat resisting alloys, a 70 manganese-30 nickel is being sucused. In nickel-silicon-boron and nickel-silicon-chromium-boron group alloys, nickel is the main constituent, with silicon and boron as additions. In two of the alloys part of the nickel is replaced with chromium to provide better oxidation and corrosion resistance. Current interest in gold-nickel-chromium fillers is for lap joints between Inconel and stainless. Compared with high nickel alloys, gold alloys have lower hardness, better ductility and less tend-ency toward intergranular penetration. Photo.-INCO.

3.7.3
Welding Corrosion-Resisting Steels of the 18/8 Chromium/Nickel Type and Heat-Resisting Steels. F. A. Ball. Mond. Sheet Metal Inds., 35, Nos. 374, 375; 349-452, 509-522 (1958) June, July.

Subject is considered primarily from metallurgical viewpoint, but some details of welding procedures are given. Influence of ferrite content on weldability of stainless steels is pointed out. Methods used to determine crack sensitivity of stainless steel weld metal are discussed. Causes of weld decay and methods for overcoming it are considered, reference being made to weld de-cay tests and knife-line attack. Formation and properties of sigma phase are reviewed. Welding procedures discussed with reference to stainless steels are: oxyacetylene welding, atomic-hydrogen welding, metallic-, argon- and submerged-arc welding and resistance welding. Tables, graphs, diagrams.-INCO.

3.7.3, 5.12, 6.2.4

Effect of Heat Treating on Notch
Sensitivity of Chrome-Molybdenum-Vanadium Steel. (In Russian.) Z. N. Petropavlovskaya. Metalloved. I Obrabotka
Metallov, No. 7, 54-58 (1958) July.
Translation available from Henry Bruthear Translation Proposition of Peters cher, Technical Translations, P. O. Box 157, Altadena, Calif.

Effect of heat treating on notch sensitivity of two chromium-molybdenum-vanadium steels during testing for their rupture strength. Steel compositions (1) 0.25 percent carbon, 0.35 manganese, 0.60 silicon, 2.3 chromium, 0.99 molybdenum, 0.45 vanadium; and (2) 0.33 percent carbon, 0.57 manganese, 0.68 silicon, 2.3 chromium, 0.53 manganese, 0.68 silicon, 0.53 achibdonum, 0.24 1.23 chromium, 0.53 molybdenum, 0.24 vanadium. Heat treatments recommended for reduced notch sensitivity and reduced embrittlement at 550 C (1020 F). 5 figures, 2 tables.—HB. 16603

#### 3.8 Miscellaneous Principles

Electrochemical Method for the Study of Corrosion. (In German.) M. Pourbaix. Schweisstechnik, 12, 71-83 (1958)

Thermodynamics of corrosion of metals in aqueous solutions as well as in contact with moist substances, 9 references .- MR.

3.8.2, 3.6.8, 6.3.10

Local Cell Action During the Scaling of Metals. Pt. II. Christa Ilschner-Gensch. J. Electrochem. Soc., 105, No. 11, 635-638 (1958).

If nickel is covered by a borate melt

under an oxygen atmosphere, practically no oxidation takes place. If, however, the nickel sample is in electrical contact with an electronic conductor, e.g., a noble metal gauze, which extends up to the melt-oxygen interface, nickel is at-tacked rapidly by virtue of local cell action. In this case, electron transfer is accomplished by the metal gauze and ions migrate through the borate melt. Electrochemical measurements show that the reaction is controlled mainly by polarization of the cathode where oxygen molecules are reduced to ions.

3.8.3. 6.4.2

Anodic Polarization of Neutral Electrolytes of Alloys of Aluminium with Alkaline Earth Elements. A. L. Seifer. Doklady Akad. Nauk SSSR, 116, 120-122 (1957) September 1. (In Russian.)

The anodic polarization of high purity aluminum alloyed with calcium, strontium, and barium was studied in sea water and in 0.5N solutions of sodium chloride and sodium sulfate. The results are presented graphically.-NSA. 15408

LET Coreco WORK FOR YOU 24 HOURS A DAY TO PROTECT YOUR OIL OR WATER STORAGE TANKS AGAINST COSTLY CORROSION . . .



. 15

bil-

out.

enare and

sid-

de-

maare

are:

gen ubeld-

433

tch Va-

trotka uly. rut-Box

en-

ımneir ons ese.

de-

eron, 0.24

nd-

re-603

udy our 58)

of as 590

ling ner-

No. nelt

ally ver, tact , a to

cell

and

elt.

by

xy-

582

lecvith fer.

120-

rity

on-

sea

ium ults

408

n.)

3.8.3, 3.6.8, 3.2.2, 6.4.2

On the Anodic Polarization Behaviour of Aluminium, P. J. Anderson and M. E. Hocking. J. Applied Chem., 8, Pt. 6, 352-358 (1958) June.

Existence of a critical potential of film breakdown, above which pitting corrosion occurs, has been established.
—BTR.

The Determination of Active-Passive Regions of Austenitic Stainless Steels by Regions of Austentic Stainless Steels by the Measurement of Polarization Characteristics. Preliminary Rept. G. Okamoto, M. Nagayama, Y. Mitani and T. Ishikawa. Corrosion Engineering (Japan), 7, No. 2, 34-36 (1958) March.

Anodic polarization curves were obtained for types 304 and 316 AISI stainless in accrated sulfuric acid solutions by

less in aerated sulfuric acid solutions by using the improved Hickling's potentiostat. The results, interpreted in accordance with Rocha's principle, were presented in terms of 'activepassive' regions dependent on acid concentration and temperature. The self-passivation region determined by this method was analogous to the one obtained with the usual method (i.e. the measurement of the spontaneous potential). The polarization method, however, 1) provides a more rapid mean of determining whether a specimen becomes passive or remains active under a given condition and 2) gives a better quantitative determination of the degree of stability of the specimen in the passive region.-JSPS.

Demonstration of the Thixotropic Protective Layer on Metal. (In German.) Rikuro Otsuka. Kolloid Z., 153, 59 (1957) July.

The formation of a thixotropic by weight) was demonstrated by an experiment in which titanium sheet metal electrodes were immersed in 0.10 N aqueous potassium chloride. Simultaneous pitting and the formation of white, colloidal titanium oxide hydrate are observed on the application of 12 volts at the electrodes. 3 references. -MR. 14850

3.8.4, 6.4.2

Structure of Non-Porous Anodic Films on Aluminium. R. W. Franklin. Nature, 180, No. 4600, 1470-1471 (1957) December 28.

By means of optical and electron microscopy and by preferential chemical dissolution, it has been found that non-porous oxide films formed on aluminum anodic oxidation and aqueous electrolytes are not uniform in thickness and composition. The non-porous oxide films formed when aluminum is polar-ized anodically at either constant current or constant voltage in a variety of aqueous electrolytes (for example, borates, carbonates, tartrates and phos-phates) at room temperature have a pronounced cell type of structure. The surface at both electrolyte-oxide and metal-oxide interfaces is covered with raised domes. The average radius of the raised domes. The average radius of the cells is proportional to the voltage and is approximately equal to the average thickness of the oxide. As the whole surface is covered with cells, the number of cells must decrease as the formation voltage increases. The number and size of the cells appear to be independsize of the cells appear to be independ-ent of the grain orientation of the under-lying metal. As the thickness of the anodic film is not uniform, it must be easier for the oxide to grow at some points of the film than at others. This

indicates that the layer may not be of uniform composition and this has been confirmed. If anodic aluminum films are treated with a hot chromic acid-phosphoric acid solution, part of the oxide dissolves rapidly and part is insoluble. It has been found that the soluble portion occurs in a central column through cells and the insoluble in the region of the junction between the cells. The insoluble material gives sharp electron diffraction patterns and appears to be crystalline  $\gamma'$  aluminum and it is believed that the soluble portion is practically amorphous. As the temperature of foramorphous. As the temperature of formation is increased, the amount of insoluble crystalline oxide increases considerably. It is apparent that this type of construction of the oxide layer can explain the growth of porous films on aluminum.—ALL.

6. MATERIALS OF CONSTRUCTION

6.2 Ferrous Metals and Alloys

Corrosion of Types 347 and 309 SCb Stainless Steels by Simulated "25" Process Waste Solutions at Various Temperatures. Arnold R. Olsen. Oak Ridge National Lab. U. S. Atomic Energy Commission Pubn., CF-54-6-7, June 1, 1954 (Declassified Feb. 14, 1957), 40 pp. Available from Office of Technical Services, Washington, D. C.

Corrosion tests on stainless steels Type 347 and Type 309 SCb exposed to concentrated simulated first cycle raffi-

concentrated simulated first cycle raffi-

first off-shore sulphur production in the



world will move through Reilly-coated lines

Seven miles off Grand Isle, Louisiana, sulphur will be raised by the Freeport Sulphur Company from a mine 2,000 feet be-

low the ocean floor. Reilly Hot Coal Tar Enamels-Hot Service Enamel with HS X-1 Primer - applied by Pipe Line Service Corporation - will protect delivery lines to shore

installations against salt water and other corrosive elements. Inquire at any Reilly Sales Office.

REILLY TAR &

1615 MERCHANTS BANK BUILDING

W

CHEMICAL CORP

INDIANAPOLIS 4. INDIANA

ARMED Protective Coatings

Sales offices in principal cities



#### TECHNICAL REPORTS

#### REFINING INDUSTRY CORROSION

T-8 High-Temperature Hydrogen Sulfide Corrosion of Stainless Steel—A Contribution to the Work of NACE Tech, Group Committee T-8 on Refinery Industry Corrosion, by E. B. Backensto, R. E. Drew, J. E. Prior and J. W. Sjoberg. Pub. 58-3, Per Copy \$.50.

\$.50.

T-8 Compilation and Correlation of High Temperature Catalytic Reformer Corrosion Data—A Contribution to the Work of NACE Tech. Group Committee T-8, by G. Sorell. Pub. 58-2, Per Copy \$.50.

T-58-2 Effect of Sulfide Scales on Catalytic Reforming and Cracking Units. Part 1—Metallographic Examination of Samples From a Catalytic Reforming Unit. Part 2—Intergranular Corrosion of 18-8 Cr-Ni Steel as a Result of Hydrolysis of Iron Sulfide Scale. A Contribution to the Work of NACE Task Group T-58-2 on Sulfide Corrosion at High Pressures and Temperatures in the Petroleum Industry. Per Copy \$.50.

Petroleum Industry, Per Copy 5.50.

T-5B-2 Collection and Correlation of High
Temperature Hydrogen Sulfide Corrosion Data—A Contribution to the Work of
NACE Task Group T-5B-2 on Sulfide Corrosion at High Temperatures and Pressures in
the Petroleum Industry: From M. W. Kellogg
Co., New York by G. Sorell and W. B. Hoyt.
Pub. 36-7. Per Copy \$1.50.

Pub. 56-7. Per Copy \$1.50.

T-58-2 High Temperature Hydrogen Sulfide Corrosion in Thermofor Catalytic Reformers—A Contribution to the Work of NACE Task Group T-58-2 on Sulfide Corrosion at High Temperatures and Pressures in the Petroleum Industry: From Socony Mobil Oil Co., Inc., Res. & Dev. Lab., Paulsboro, N. J. by E. B. Backensto, R. D. Drew, R. W. Manuel and J. W. Sjoberg, Pub. 56-8. Per Copy \$1.00.

T-58-2 Effect of Hot Hydrogen Sulfide Environments on Various Metals—A Contribution to the Work of NACE Task Group T-58-2 on Sulfide Corrosion at High Temperatures and Pressures in the Petroleum Industry: From Sinclair Res. Lab. Inc. Harvey, III. Pub. 57-2. Per Copy \$.50.

III. Pub. 57-2. Per Copy \$.50.

T-5B-2. High Temperature Sulfide Corrosion in Catalytic Reforming of Light Naphthas—A Contribution to the Work of NACE Task Group T-58-2 on Sulfide Corrosion at High Temperatures and Pressures in the Petroleum Industry: From Humble Oil & Ref. Co., Baytown, Texas. Pub. 57-3. Per Copy \$.50.

T-8 Iso-Corrosion Rate Curves for High Temperature Hydrogen-Hydrogen Sulfide—A Contribution to the Work of NACE Tech. Group Committee T-8, by E. B. Backensto and J. W. Sjoberg. Pub. 59-10. Per Copy \$.50.

T-8 Minimum Corrosion for Butane Isomerization Units. A Contribution to the Work of NACE Group Committee T-8 on Refining Industry Corrosion by J. F. Mason, Jr. and C. M. Schillmoller, Pub. 59-11. Per Copy \$5.50.

59-11, Per Copy 3.50.

T-8 Corrosion of Refinery Equipment by Aqueous Hydrogen Sulfide. A Contribution to the Work of Group Committee T-8 on Refining Industry Corrosion by Roy V. Comeaux. Pub. 59-12. Per Copy \$.50.

Precautionary Procedures in Chemi cal Cleaning. A Contribution to the Work of NACE Tech. Unit Committee T-8A on Chemical Cleaning, by Robert A. Stander. Pub. 59-1. Per Copy \$.50.

T-8A Chloride Stress Corrosion Cracking of the Austenitic Stainless Steels—A Contribution to the Work of NACE Task Group T-8A on Chemical Cleaning, by J. P. Engle, C. L. Floyd and R. B. Rosene. Pub. 59-5. Per Copy \$.50.

Remittances must accompany all orders for literature the aggregate cost of which is less than \$5, Orders of value greater than \$5 will be involced if requested. Send orders to National Association of Corrosion Engineer, 1081 M & M Bidg., Houston, Texas. Add 60c per package to the prices given above for Book Post Registry to all addresses outside the United States, Canada and Mexico.

#### NATIONAL ASSOCIATION OF CORROSION ENGINEERS

1061 M & M Bldg. Houston 2, Texas nate (predominantly 2.5 molar aluminum nitrate) from "25" Process at Arco at temperatures from 120 F to boiling have been made. The corrosion rates are distinctly temperature dependent. Severe intergranular attack occurred at temperatures above 180 F disappearing at 150 F for Type 347 stainless steel and at 120 F for Type 309 SCb stainless steel. From the results of these tests it appears that successful long time storage of this waste will require that the solu-tion temperature be maintained below 150 F. (auth)-NSA.

Materials of Construction-Stainless Steels and Other Ferrous Alloys. W. A. Luce and J. H. Peacock. Duriron Co. Ind. Eng. Chem., 50, No. 9, Pt. 2, 1482-

1488 (1958) Sept.

Annual review of published literature ith 137 references covers corrosion, mechanical properties, structure, high temperature properties and applications, welding, manaufacture and surface treat-ment of stainless steels. Survey of literature on high-silicon iron, nickel irons and austenitic iron-manganese steels is included.—INCO. 17472

6.2.5, 8.8.5, 3.7.2

The Effect of Boron on Liquid-Phase Formation in Sintered Steels, Particularly Steels with About 18% Chromium and 8% Nickel. (In German.) Friedrich Benesovsky and Werner Hotop. Stahl und Eisen, 78, No. 3, 149-152 (1958).

A low m.p. nickel-chromium-boron alloy was added to the powders from which sintered steels were made, and the structure and properties after sinterwere examined. Up to 2 per cent addition to 18:8 chromium-nickel steel raises the strength, hardness and im-proves the ductility. The alloys so pro-duced are resistant to corrosion and scaling.-MA.

6.2.5, 8.9.1

Sheet Steels for High-Speed Aircraft and Missiles. A. L. Feild and M. E. Carruthers: Armco Steel Corp. Aero/Space Eng., 17, No. 6, 41-44 (1958) June.

Some of the steels used in manned aircraft and missiles may be classified as being of the martensitic type. Others are stainless steels that strengthen through a change in phase and a sec-ondary hardening mechanism "t" termed precipitation hardening. Still others are austenitic steels strengtnened by precipitation hardening. Among the high strength steels available today, only the precipitation hardening stainless steels precipitation hardening stainless steels have satisfied production honeycomb requirements. Strength-weight comparisons are given for 6A1-4V, Type 422M, PH 15-7 and A286 alloys. Austenitic stainless steels, such as A286, are the most corrosion resistant, but they are not competitive strengthwise with other steels at temperatures below 1000 F. Of the high strength sheet steels used in aircraft and missiles, the PH 17-7 stainless steel has been most widely used and produced in the greatest tonnage. Be-cause of its higher strength at room and elevated temperatures, the PH 15-7 molybdenum stainless steel is being designed into many of the advanced weapons systems. Superior resistance to corrosion and better feasibility of production of aircraft parts also account for its acceptance in preference to the stronger hot work die steels and martensitic stainless. Graphs, tables.-INCO

#### 6.3 Non-Ferrous Metals and Alloys-Heavy

6.3.10. 3.7.4

Investigation of the Alloys of the Ternary System Nickel-Aluminium-Tungsten. (In Russian.) P. B. Budberg. Zhur. Neorg. Khim., 3, 694-698 (1958) March

Investigation on alloys of ternary system nickel-aluminum-tungsten with up to 30 aluminum and up to 40 tungsten. By the metnod of thermal analysis, a part of the freezing curve of the binary system NiAl-W was determined and the eutectic character of the relationship between that curve and the formation of the limited solid solution of tungsten in NiAl was demonstrated. Phase-region boundaries in the investigated part of the system were determined at different temperatures by microstructure studies. Isothermal sections of the system at 1200, 1000 and 800 C were constructed. -INCO.

6.3.10, 3.7.4, 3.7.2

Superstructure and K-State in the Nickel-Chromium System. (In German.) H. G. Baer. Z. Metallkunde, 49, No. 12, 614-622 (1958) Dec. Superstructure Ni₂Cr has been de-

tected in nickel-chromium system. It is associated with a decrease in resistance and change in Hall constant. It exists at approximately 25-36 at.-per cent chromium. Critical ordering temperature is 580 C for alloy with 33.7 at.-per cent chromium. Upon cooling, transformation occurs just below 500 C. Order is destroyed by cold working. Resistivity increases. On the other hand, for alloys with lower chromium content, which form K-state, resistivity decreases. Solu-bility curve for chromium has been determined. Tables, graphs.—INCO. 17166 6.3.10, 4.7

Depletion of Minor Constituents from Coast Metals No. 52 (89 Ni-5 Si-4 B-2Fe) and No. 53 (81 Ni-8 Cr-4 B-4 Si-3 Fe) Brazing Alloys During Various Exposures. D. H. Jansen. Oak Ridge National Lab. U. S. Atomic Energy Commission Pubn., CF-58-10-86, October 23, 1059 15 1059 1958, 15 pp. Available from Office of Technical Services, Washington, D. C. Corrosion tests were made on nickel-

base brazing alloys containing boron and silicon in fused fluoride fuels, liquid metals and oxidizing atmospheres. Impoverished regions, after the tests, contained approximately one third the original amount of boron and silicon that was present before the tests.—NSA.

6.3.10, 5.3.4

What Electroless Nickel Can Do for You. R. J. Girard. Paper before Am. Electroplaters' Soc., Springfield Branch, Jan. 1958. Plating, **45**, No. 12, 1234-1238 (1958) Dec.

Physical properties of electroless nickel considered considered include: structure, appearance, corrosion resistance, buffability, hardness, composition, ductility, receptiveness and porosity. Plating tanks, ventilation, preparation of plating solutions, racking of components, deposition of nickel, operating conditions and their control (temperature, pH, agita-tion) and filtration are reviewed. Cycle operation is outlined. Limitations, advantages and economic appraisal are considered. Table compares hardness, elongation and tensile strength of electroless nickel with other types of nickel deposits.-INCO.

15

the m-

rg. 58)

vs-

up en. a

arv

hip

ion

ten

ion

ent

ies.

at

286

the

n.)

12,

de-

is

nce ists

ro-

is ent

de-

in-

ovs

lu-

166 om

B-Bi-3 Ex-

Na-

m-23, of C. keluid Imon-

igi-

hat 380

for

١m.

238

kel

ffa-

itv. ing

ing

and

ita-

vcle ons,

are ess.

lec-

403

6.3.11, 3.4.6, 3.5.9

The Solid-State Reactions of the Noble Metals and Their Alloys with Oxygen at Elevated Temperatures. (In German.) Ernst Raub and Werner Plate. Z. Metallkunde, 48, No. 10, 529-537 (1957).

Silver, gold, palladium, platinum and rhodium and their alloys in the series silver-gold, palladium-silver, platinum-gold, platinum-rhodium, and platinum-iridium were heated at 900-1300 C (always below the melting point of the material) in a current of oxygen, in air, and in oxygen-containing nitrogen, and studies were made of their changes in weight in relation to temperature and time of heating, and the influence of oxygen on the surface structure. An initial weight gain results from oxide formation; these oxides then volatilize with increasing time and/or temperature, and the weight loss is approximately linear with time. Gold does not appear to react with oxygen. Silver volatilizes appreciably at 600 C; trace impurities in the metal oxidize and then volatilize. Platinum volatilizes faster than palladium and rhodium at 900-1100 C, but at 1300 C this difference vanishes; alloying of platinum with palladium and rhodium reduce volatilization, while alloying with iridium increases it; gold up to 75 per cent has little effect, probably owing to the wide miscibility gap in the platinum-gold system. Gold and platinum reduce the volatilization of silver. At high temperature, palladium and rhodium dissolve considerable amounts of oxygen; at 1200 C > 0.4 at per cent oxygen is soluble in palladium. The thermal etching of these materials is illustrated and discussed. 17 refer-

6.3.11, 7.7

The Care of Platinum Thermocouples.
H. E. Bennett. Platinum Metals Rev.,
2, No. 4, 120-123 (1958) October.
Platinum and its alloys will withstand much more adverse conditions than will

base metal thermocouples, but they none the less have their limitations. Melting the less have their limitations. Melting point of platinum is 1769 C and that of its highest melting rhodium alloy is about 1890 C. Harmful effects of prolonged heating, contamination by metallic vapors and embrittlement due to oil and grease are discussed. Results of creep tests on platinum-rhodium thermocouples are given. Photomicrographs, graphs.—INCO. 17158

6.3.15, 1.6

6.3.15, 1.6

Symposium on Titanium. Am. Soc. for Testing Materials. Presented at the Second Pacific Area National Meeting of the Society Held at Los Angeles, Calif. on 17-18 September 1956. A.S.T.M. Special Technical Pubn. No. 204, 208 pp., 1958. Available from the Society, 1916 Race Street, Philadelphia 3, Penn. Contents: F. R. Schwartzberg, N. D.

Williams and R. I. Jaffee, Variables Affecting the Thermal Stability of Three Titanium Alloys; F. C. Holden, H. R. Ogden and R. I. Jaffee, The effect of Temperature on the Uniform Elongation of Titanium Alloys; H. R. Ogden, F. C. Holden and R. I. Jeffee, The Effect of Composition and Annealing Treatment on the Thermal Stability of Chromium-Molybdenum Alloys of Titanium; W. M. Parris, R. G. Sherman and H. D. Kessler, Elevated-Temperature Properties of the 6 per cent Aluminum-4 per cent Vanadium-Titanium Alloy;

F. A. Crossley, W. F. Carew and H. D. Kessler, Development of Titanium-Base Alloys for Elevated-Temperature Application; E. P. Klier and N. J. Feola, The Effects of Carbon and Nitrogen Contamination on the Notch-Tensile Properties of Titanium; F. C. Holden, H. R. Ogden and R. I. Jaffee, A Micro-Notched-Bar Impact Test for Titanium Alloys; W. H. Graft and W. Rostoker, The Measurement of Elastic Modulus of Titanium Alloys; J. B. Rittenhouse, The Corrosion and Ignition of Titanium in Fuming Nitric Acid; H. H. Barry and L. Schapiro, Unalloyed Titanium Sheet is Improving; Chester R. Smith, How Statistical Techniques Helped Achieve Better Uniformity in Unalloy Titanium; L. B. Stark, Properties and Fabrication Characteristics of Wrought Titanium Alloys for Elevated-Temperature AppliProducts; R. L. Folkman and M. Schussler, Development of Standardized Specimen Preparation and Testing Techniques for Unalloyed Titanium Sheet; R. M. Fowler, Determination of Gaseous Elements in Titanium.—MA.

6.3.15, 3.4.8

Corrosion of Titanium by Chloride and Sulfate Anions, Revealed by Electrode Potential Measurements. (In English) F. M. Khairy and M. M. Fl. lish.) E. M. Khairy and M. M. El-Khatib. Egyptian Journal of Chemistry, 1, No. 2, 263-285 (1958). Experiments with spectroscopically pure titanium rods in buffered and un-

buffered hydrochloric acid-sodium chloride and sulfuric acid-sodium sulfate solutions. The corrosion is explained by



unusual marine

requirement

THE PAINTING OF SHIPS

International Paint Company, Inc.

New York 6, N. Y., 21 West St., Phone: WHitehall 3-1188 New Orleans 15, La., 628 Pleasant St., Phone: TWinbrook 1-4435 So. San Francisco, Cal., So. Linden Ave., Phone: PLaza 6-1440

copy of our recently re-

vised booklet "The Paint-ing of Ships." It is an outline of the latest ap-

proved practices in all

marine maintenance.

D

ne

ti

g

n

m

aı

pe

di

th

re

to

el

W

iz

8.

te

Si

of

ag

fa

te 20

va

m

til

th

DI

ca

of

di ro

SO

ca

tic

8.8

pe

in

the action of chlorine-ions or sulfateions, respectively. 11 references.-RML.

6.3.15, 3.4.8, 3.2.2

Utilization of Low-Grade Titanium Utilization of Low-Grade Titanium Sponge Produced by the Kroll Process. Pt. 3. Corrosion of Titanium-Iron Alloys in Hydrogen Sulfide Atmosphere at High Temperature. (In Japanese.) K. Hirayama, N. Gamo and T. Takei. Sci. Res. Inst., Tokyo, Repts., 33, 228-233 (1957) Luly. (1957) July.

Corrosion resistance was not influenced by iron content, and was far suthat of 18-8 stainless Appreciable corrosive attack by hydrogen sulfide was observed at 600 C and above. A relatively compact film of me-tallic sulfide was formed during the corrosion process and the process was controlled by mutual diffusion of metallic and gaseous ions through the sulfide film. Corrosion rendered the alloys somewhat brittle, the degree of brittleness being proportional to the time and temperature. This embrittlement is attributed to the absorption of hydrogen. 7 references .- MR.

6.3.20

Second Interim Report on the Zirconium Alloy Corrosion Problem. J. G. Goodwin. Westinghouse Electric Corp. Goodwin. Westinghouse Electric Corp. U. S. Atomic Energy Commission Pubn., WAPD-NCE-4512, May 1, 1957, 32 pp. Available from Office of Technical Serv-

ices, Washington, D. C.
The Zircaloy-3 corrosion problem is associated with white or tan stringers found in the black matrix oxide of Zircaloy-3 samples corrosion tested for 14 days in 750 F steam. The stringers are parallel to the direction of rolling. A similar effect is noted in the cladding of corrosion tested fuel elements manufac-tured from strip showing this behavior. Because the stringers are noted in the fuel elements and could lead to possible difficulties, an investigation was begun to determine the reasons for the stringers and to determine methods for eliminating them. (auth).-NSA.

#### 8. INDUSTRIES

#### 8.4 Group 4

Additional Considerations on the Use of Lithium Hydroxide in PWR. J. C. Rengel. Westinghouse Electric Corp. U. S. Atomic Energy Commission Pubn., WAPD-PWR-PFM-868, August 29,

## COKE BREEZE

**Backfill for Anodes** 

ideally suited for use with anodes. Has a high carbon content and comes in sizes of  $\frac{1}{2}$ -inch x 0 to  $\frac{4}{2}$  x  $\frac{1}{2}$  inch. In bulk or sacks. Prices on other sizes on request.

**National Carbon Anodes** 

**Magnesium Anodes Good-All Rectifiers** 

#### HOLESALE COKE COMPANY

PHONE GARDENDALE, ALA. HEmlock 6-3603

P. O. Box 94

Mt. Olive, Ala.

1957, 8 pp. Available from Office of Technical Services, Washington, D. C.

Lithium hydroxide was recommended as the reference condition for the Pres-surized Water Reactor coolant. An in-vestigation of the possibility of caustic stress-corrosion cracking arising from the use of lithium hydroxide is presented.—NSA. 17050

8.4.5, 4.6.1

The Inter-Relation of Loop or Reactor System Transport and Dynamic Corrosion in Water. C. G. Lindquist. Knolls Atomic Power Lab. U. S. Atomic Energy Commission Pubn., KAPL-M-CGL-1, Sept. 12, 1958, 12 pp. Available from Office of Technical Services, Washington, D. C.

The conditions in which the flow of fluid past a corroding surface could the corrosion rate are outlined, and the formulation of these factors is discussed. In addition, an analysis of transport in dynamic corrosion loop systems is presented.—NSA. 17442

8.4.5, 4.6.1, 3.5.4, 6.3.20, 3.2.2

Metallurgy in Nuclear Engineering. Survey of the Literature in 1957. J. Burkett, Metallurgia, 58, No. 345, 32-35

(1958) July.

Discussion of stress corrosion cracking problems of materials in homogeneous reactor tests include results of corrosion runs on titanium, zirconium 2 and stainless steel. Corrosion of alloys over range 240-360 C in high tempera-ture water was studied. Armco 17-4PH, Armco 17-7PH and Hastelloy F alloys were the most resistant materials at 730 and 540 C. AISI 316 was susceptible to stress corrosion cracking at 730°C. Car-bon steel, carbon steel weldments, nickel steel, high-strength steel and high-purity iron were irradiated in the MTR. Neutron irradiation increases yield and tensile strengths of structural steels but decreases their ductility, possibly changing behavior of steels as materials for structural components. Zirconium as a reactor material is discussed.—INCO.

8.4.5, 4.6.1, 3.5.8, 6.2.5
Stress-Corrosion Failure of a High-Pressure Water/Water Cooler in the Dynamic Corrosion Loop at Capenhurst. G. E. Marchment. United Kingdom Atomic Energy Authority, July 14, 1958. 14 pp. Available from: United Kingdom Atomic Energy Authority, Industrial Group, Capenhurst Works, Capenhurst, England. (IGR-TN/CA-974).

Failure occurred in a stainless steel water/water cooler, of the shell-and-coil type, used to cool a water flow from 300 to 40 C in the dynamic corrosion loop. The failure is attributed to stress corrosion in the presence of dissolved chlorides, which occurred in areas where steam is likely to be forming continuously. Although the best long-term solution is to introduce a regenerative heat exchanger to reduce the temperature of the inlet water, an amended design of cooler is suggested for immediate use in the loop. (auth).-NSA.

8.4.5, 4.6.2

Effect of In-Pile Local Boiling on Surface Deposition and Corrosion. Kurt Katz and Walter E. Hopkins, Jr. Westinghouse Electric Corp., Pittsburgh. Nuclear Sci. and Eng., 4, No. 5, 673-689 (1958) Nov.

Many advantages can be realized by operating a pressurized water reactor at

steady-state local boiling conditions. However, before this mode of operation can be factored into the thermal and hydraulics of reactor design, its effect on cladding corrosion and surface crud deposition must be established. The evaluation of a local boiling test at pH 7, for crud deposition and corrosion is described. (auth)-NSA.

8.445, 8.9.5

The Power Plant for the First Nuclear Merchant Ship N. S. Savannah. J. W. Landis. Paper before Nuclear Merchant Ship Symposium, Washington, D. C., Aug. 21, 1958. J. Am. Soc. Naval Engrs., 70, No. 11, 629-641 (1958) Nov.

Detailed description of nuclear reactor for N. S. Savannah. Reactor is pressurized water reactor operating at 1750 psia and fueled with uranium dioxide of about 4 per cent enrichment clad in boron-containing Type 304. Control rods are of composite design with plate of boron-containing stainless steel sand-wiched between 2 ordinary stainless steel plates. Rod spacing is maintained by small tubular stainless steel ferrules brazed in place. Pressure vessel is made of 6 in. carbon steel plate clad on inside with Type 304. Inconel X is used for fuel element springs. Steam generators each consist of uranium-shell, uraniumtube boiler section containing about 800 stainless steel tubes ¾ O.D. All primary piping is made from Type 304 hollow forgings. Numerous diagrams.—INCO.

The Preparation and Reprocessing of Plutonium-Aluminum Alloy. W. L. Lyon. General Electric Co., Hanford Atomic Products Operation, U. S. Atomic En-ergy Commission Pubn., A/CONF.15/ P/546, 7 pp. Prepared for the second U. N. International Conference on the Peaceful Uses of Atomic Energy, 1958. Available from Office of Technical Serv-

ices, Washington, D. C.

An alloy of plutonium and aluminum offers an attractive reactor fuel material since the technology of the matrix is sound, the alloy is readily produced and fabricated, it has good nuclear and physical properties, and it is acceptable with water coolant as regards heat transfer and corrosion rate. The alloy may be produced by direct alloying of the metals, or by reduction of plutonium fluoride or oxide in aluminum. The latter method, wherein PuO2 and cryolite mixtures are added to molten aluminum, employing the technique of Saller and Runnalls, is expected to find extensive application in the production of fuel loadings for power reactors. The chemical reprocessing of plutonium-aluminum fuel may be accomplished by adapting aqueous methods for which sound technical bases exist. On the other hand, this material may lend itself to processing by one of several interesting pyrochemical schemes. Some of these are described together with brief comments regarding the economics of plutonium fuel processing. (auth)—NSA. 1745 17459

#### 8.8 Group 8

8.8.5. 6.2.2

Experimental Study of Electric Furnace Refining of Magnesium Treated Cast Iron Under Reducing Atmosphere. (In Japanese.) M. Homma, H. Meguro, Y. Abe and R. Ono. J. Japan Foundry-men's Soc., 30, No. 8, 597-602 (1958) . 15

tion and

fect

rud The pH

355

W. ant

C., TS.,

ac-

of

ods of eel by

les

ade

ide ors

800 ary ow 439

of on.

nic Ennd the 58. rv-

ım ial

nd nd ble

15-

he

ım

at-

ite

nd ve

d-

cal

nel

1e-

cal

by

cal ed

ng

59

ed

ro,

y-8)

In manufacturing magnesium treated nodular cast iron, the effect of reduc-tion-refining with acid or basic electric are furnace on its properties was investigated. Strong desulfurizing and deoxidizing actions were observed. The necessary amount of magnesium for manufacturing ductile iron with cupola is about 0.4 per cent, but the magnesium amount could be reduced to 0.11-0.17 amount could be reduced to 0.11-0.17 per cent with basic furnaces and with acid furnaces to 0.18-0.23 per cent. Both dross and depth of shrinkage cavity in the ingots were reduced by reduction refining with electric furnace. The test piece for mechanical property was taken from Type JIS No. 4 iron which was cast into green sand mold and annealed to such extent as ferrite structure revealed. Tensile strength, yield point and elongation obtained from specimens from basic and acid processes are given. Sulfur content of the original material was 0.024-0.031 per cent. It was however desulfurized in the basic furnace by 65-96 percent retaining sulfur content only between 0.001 and 0.010 per cent, while in the acid furnace only 63-89 per cent of the above content was desulfurized retaining it between 0.03 and 0.011 per cent.—INCO.

8.8.5, 6.2.2, 3.7.2

Gray Iron Chemisty—How It Affects Casting Quality. F. L. Arnold. Carver Foundry Inc. Foundry, 86, No. 12, 86-89 (1958) Dec.

Reviews influence of carbon, silicon, sulfur, manganese and phosphorus con-tents on quality of castings, and defines significance of carbon equivalent. Some of most common casting defects—shrinkage, internal porosity, hot tearing and mis-runs—caused by wrong metal analysis, are discussed. Avoiding hard surfaces in thin sections, and control of fluidity are considered.—INCO. 17170

8.8.5, 6.3.10

Some High-Temperature Properties of Nickel-Alloy Powder. Extrusions Containing Nonmetallic Dispersions. E. Gregory and C. G. Goetzel. Trans, Met. Soc. AIME (Am. Inst. Mining & Met. Engrs.), **212**, No. 6, 868-874 (1958) Dec.

Experimental powder-metallurgy materials made by extrusion consist of 80-20 nickel-chromium alloy matrices with various hard-phase additions. Several methods of obtaining a uniform dispersion of a hard phase throughout a ductile metal matrix are reviewed, although the metal matrix are reviewed, although the mechanical mixing method is the principal one employed. Stress-rupture tests on the extruded materials were carried out at both 1500 and 1800 F and showed that high-temperature strength of matrix could be increased considerably with certain oxide and carbide additions. High temperature ductility and room-temperature impact values of some of these materials were low in compari-son with cast and wrought alloys. Optical and electron microscopical examina-tions revealed variations in structure which resulted from changes in condi-tions and methods of manufacture. Photomicrographs, graphs.-INCO.

8.8.5, 6.3.17

Arc-Melting of Uranium-Rich Alloys. W. H. Britton and W. B. Haynes. Nuclear Metallurgy, 4, 63-66 (1957).

The technique has been limited to experimental metal of small ingots and as a pre-alloying melt to precede vacuum-induction-melting. Consumable-electrode arc-melting of uranium-molybdenum alloys in an argon-helium atmosphere yields sound, homogeneous ingots, but of uranium-niobium is more difficult, since the wider solidification range leads to microsegregation associated with poor aqueous corrosion-resistance.—MA.


5.8.5, 6.4.1

Economic Design of Light-Alloy Castings. P. A. Broadbent. Foundry Tradel J., 105, No. 2201, 737-744 (1958) Dec. 18.

Light alloy castings can already be produced to consistently close limits by

well-established die-casting methods, so the post-war developments of precision moulds are of more benefit to the other non-ferrous and ferrous foundry indus-tries. Furthermore, the special light al-loy foundry techniques, the heat treat-ment and other processes, and the free-cutting properties of light alloys

should be related to design and costs of production. Test-bar specifications for a number of aluminum and magnesium alloys are given and are discussed in relation to strength and weight of castings, to certain features of design and to the cost of a machined casting in cast iron and various light alloys. High tensile steel bolts are necessary to shear screw threads in light alloys and results screw threads in light alloys and results of tensile tests on inserts and fastenings are given, together with estimates of cost of each method of assembly. Where inserts and fastenings are used, precautions to avoid galvanic action between dissimilar metals are necessary only on exposed junctions, while for corrosion generally, precautions are just as necessary for the common light alloys as for the common iron and steel constructhe common iron and steel construc-tional materials and components. (auth)



## HOW TO STOP CORROSION OF TANKS & HEATER TREATERS

Field experience has proved that cathodic protection offers a reliable, low-cost way to stop corrosion on steel tanks, heater treaters, filters and free-water knockouts-both externally and internally. It is effective even on vessels in contact with the most corrosive of oil field

Corrosion is stopped by projecting an electrical current onto the tank surface to be protected—using either magnesium anodes or rectifiers as the current source.

The drawing shows five of the methods by which such protection can be set up. For internal protection, anodes can be suspended from the top; inserted through side openings; or bolted to or set on wooden supports at the bottom. External protection of tank bottoms is usually achieved by burying anodes in the soil near the tank.

CSI engineers are pioneers in this work. They offer expert engineering and installation services, plus a complete line of quality supplies for both rectifier and anode installations. Prices are competitive. Call or write today.




Cleveland 13, Ohio 1309 Washington Ave. Tel. CHerry 1-7795

#### CORROSION SERVICES INCORPORATED

General Office: Tulsa, Okla. Mailing Address: Box 787, Sand Springs, Okla. Tel. Circle 5-1351

# ELECTRUNITE "Dekoron-E.M.T. resists corrosion...moisture...




#### REPUBLIC PRODUCTS SOLVE CORROSION PROBLEMS...



REPUBLIC X-TRU-COAT STOPS PIPELINE CORROSION. High Density Polyethylene is extruded over a special pressure sensitive undercoat. This forms a moisture-proof, elastic bond with Republic Continuous Butt Weld or Electric Resistance Weld Pipe. Bright yellow coating reflects the heat. Available in sizes from  $34^{\prime\prime}$  through  $5\%^{\prime\prime}$  O.D. Write for complete information, details, and data.




REPUBLIC GALVANNEALED SHEETS solve corrosion problem in Kathabar® units manufactured by Surface Combustion Corporation to raise or lower air humidity through evaporation or absorption of moisture. Galvannealed takes all forming operations, provides dependable strength, long, reliable service, resists corrosion and rust. Send coupon for additional data and facts.



REPUBLIC ELECTRUNITE STAINLESS STEEL TUBING means major savings in corrosive and sanitary applications. Wide range of resistance to corrosion, temperature, pressure, physical damage. Uniform wall thickness, diameter. Meets requirements of ASTM or ASME. Available in tubing sizes from ¼" through 5" O.D. and a complete range of pipe sizes in schedules 40S, 10S, and 5S.

# Coated" chemical action





REPUBLIC ELECTRUNITE "Dekoron-Coated" E.M.T. outlasted standard galvanized carbon steel conduit ten to one over a six-year period at the Charmin Paper Products Company, Green Bay, Wisconsin. Major maintenance problems were eliminated.

#### REPUBLIC "DEKORON-COATED" E.M.T. **OUTLASTS STANDARD CONDUIT 10 TO 1**

Republic ELECTRUNITE® "Dekoron®-Coated" E.M.T. protects vital wiring systems, reduces costly electrical raceway replacement-maintenance costs.

Where fumes, gases, steam, other corrosive materials destroy standard conduit in a matter of months, "Dekoron-Coated" E.M.T. is still in service seven, eight, ten years and more.

ELECTRUNITE, the steel raceway core of "Dekoron-Coated" E.M.T., is produced from highest quality flat-rolled, open-hearth steel, made in Republic's own mills to Republic's rigid manufacturing specifi-

Armor-tough, corrosion-proof polyethylene is applied over the galvanized finish. Every length is fully protected from end-to-end. Couplings and fittings can be protected by plastic tape.

"Dekoron-Coated" E.M.T. is easy to cut, easy to bend, easy to install. It is available in a full range of E.M.T. sizes, and rigid conduit sizes, and meets the requirements of electrical codes and specifications.

To learn more about the installation advantages and economies of Republic "Dekoron-Coated" E.M.T., and Rigid Steel Conduit, call your Republic representative. Or, mail coupon below.

# REPUBLI STEEL

World's Widest Range of Standard Steels and Steel Products

## REPUBLIC STEEL CORPORATION

1441 REPUBLIC BUILDING . CLEVELAND 1, OHIO

Please send information on the following Republic products:

□ "Dekoron-Coated" E.M.T. ☐ Republic X-TRU-COAT

☐ Galvannealed Sheets ☐ Stainless Steel Tubing and Pipe

Name. Title

Company\_

Address

Vol. 15

## INDEX TO ADVERTISERS

December, 1959

Page Page Amchem Products, Inc. 4 Koppers Company, Inc. Amercoat Corporation .... Inside Front Cover American Cyanamid Co., Plastics and Resins Div. ..... 89 Bridgeport Brass Company ...... 5 Minnesota Mining & Manufacturing Co.... 9 Byers, A. M. Company National Association of Wrought Iron Corrosion Engineers ...... 10, 75, 81, 114 Calgon Company, Division of National Carbon Company Hagan Chemicals and Controls, Inc. 11 Division of Union Carbide Corporation. 77 Carboline Company ..... 92 Pittsburgh Coke and Carey Manufacturing Co., The Philip ..... 107 ..... Back Cover Chemical Co. . Polyken Products, Dept. of Corrosion Engineering Directory .... 90 Positions Wanted and Available .......... 88 Corrosion Services, Inc. 117 Reilly Tar & Chemical Corporation.... Dowell ..... 1 Duriron Company, The ..... Inside Back Cover Farley-Bosch Company ...... 96 Solvay Process Division Good-All Electric Manufacturing Co. . . . . 110 Standard Pipeprotection, Inc.................................91 Humble Oil and Refining Company..... 98 International Nickel Co., Inc. The ...... 73

Johns-Manville Corporation

8.10.2, 6.3.17, 6.3.21, 6.7.2 Powder Metallurgy of Uranium and Thorium. A. Blainey. Metal Progress, 74, No. 2, 79-85 (1958) August.

Presents brief summary of recent British work on powder metallurgy of uranium and thorium. Uranium powder is produced by direct reduction of urania with calcium or magnesium. Calciumreduced uranium powder was extruded into 1/4-in rods through Stellite or cemented titanium carbide dies at 800 C. Stellite was sometimes attacked by erosive action of gamma uranium, titanium carbide was liable to fracture. Troubles were corrective by using Nimonic-80 or 90 dies coated with 0.005-in. layer of zirconium alloy. Technique developed for hot compacting long bars from cold compacted pellets of waxed powders utilizes opposing plungers in Stellite split tapered sleeve die and electrically heated Nimonic-80 bolster. Fabrication of ceramic fuels is reviewed. Nickel, iron, cobalt and uranium binders were explored during fabrication of UC cermets, Nickel and iron may find application in fast reactors.—INCO. 1731

8.10.2, 6.3.10

Recovery of Nickel from Converter Mattes. (In Russian.) L. L. Chermak. Tsvetnye Metal. (Non-Ferrous Metals), No. 9, 37-39 (1958).

Author has attempted to determine activity of nickel and sulfur in sulfide fusions by measuring electromotive

force, using an amalgam type cell. Electrodes of cell, body of which was manufactured from high-quality chamotte, are sulfide fusions of nickel; electrolyte is liquid mixture of potassium and nickel chlorides (potassium chloride replaced by more volatile barium chloride above 1000 C). Fusions, saturated with nickel, served as comparison solutions in each of tests. Conducted investigation showed that in transition from standard fusions to one with high sulfur contents, coefficient of nickel activity is reduced by 10 times and coefficient of sulfur activity grows by 100 times. Behavior of nickel and sulfur is characterized by very high deviations from ideal solutions. Table gives data obtained for 1200 C. A quantitative relationship is established between sulfur content in converter matte and temperature of finishing process. Advisability of obtaining nickel and copper-nickel converter mattes with in-creased sulfur contents is indicated. Presented data show that it is sufficient to lower temperature at which finishing of converter matte is carried out, to 1000-1050 C.—INCO. 17209

Tube-Kote, Inc. ..... 80 

Wisconsin Protective Coating Co........... 102

8.10.2. 3.5.9

8.10.2, 3.5,9 High-Temperature Metallurgy Today. L. P. Jahnke and R. G. Frank. Gen. Elec. Co. Metal Progress, 74, Nos. 5, 6; 77-82; 86-91 (1958) Nov., Dec.

Mechanisms for strengthening alloys (dislocation pinning by solute atoms, by short-range order, by cold work and by

2nd phase particles) which have resulted in improved elevated-temperature materials are reviewed. These considerations are carried into discussion of development of improved superalloys and refractory metal compositions. Properties of some of the best superalloys (A-286, M-308, D-979, Unitemp 212, René 41, DCM, L-605, V-36, etc.) are presented, and future performance of sented, and future performance of refractory metal alloys predicted. Best alloys among light metals (aluminum, magnesium and titanium) and steels (Halmo, Potomac M, VascoJet 1000, AM 355, PH 15-7 Mo, 17-7 PH, Lapelloy) are reviewed. Until oxidation problem is solved or by possed nickel alloyed. lem is solved or by-passed, nickel alloys will dominate applications in 1000-2000 F range. On basis of strength-to-weight ratios: aluminum becomes slightly more attractive up to 500 F; titanium is generally competitive at low temperatures with semi-austenitic stainless steels; nickel-base alloys are still best above 1000 F and molybdenum dominates applications above 1600 F despite its higher density; and niobium has crept up on molybdenum and unalloyed tungsten has fallen below niobium. Numerous tables and graphs.-INCO.

8.10.2

No. 12

Iron and Nickel by Carbonyl Treatment. R. M. Lewis, J. W. Cookston, L. W. Coffer and F. M. Stephens, Jr. J. Metals, 10, No. 6, 419-424 (1958)

Recovery of nickel and iron from lateritic nickeliferous ores by formation and decomposition of their carbonyls. Thermodynamic studies of reactions involving nickel and carbon monoxide and iron and carbon monoxide are summarized. Experimental work on carbonyl treatment was performed on samples of several different ores, in-cluding an analysis similar to material now being treated at the Nicaro plant now being treated at the Nicaro plant using ammonia leach process. It was found that 95 nickel and 90 iron could be reduced with 10 times stoichiometric quantity of hydrogen in 2-hr treatment at 700 C. When treated with carbon monoxide under pressure of 375 psig at 100 C, up to 69 nickel and 62 iron were converted to carbonyls. In subsequent treatments mixtures of ammonia and carbon monoxide were used, as adand carbon monoxide were used, as addition of ammonia inhibited catalytic decomposition of carbon monoxide and eliminated slagging condition. Effects of temperature and ore characteristics and considered. To eliminate adverse effect of adsorbed films of carbonyls on ore, -65 mesh ore was slurried with mixed iron and nickel carbonyls, slurry was stirred in autoclave under carbon monoxide pressure of 375 psig and tem-perature of 100 C for 16 hrs. Conver-sions of 65 nickel and iron were ob-tained. Both wet (slurry) treatment and dry treatment were used to in-vestigate effects of temperature and pressure on carbonyl formation reactions. Separation of carbonyls by distillation is discussed. Nickel carbonyl was decomposed at 200-260 C under pressures of 30-760 mm mercury, while iron carbonyl was decomposed at 250-300 C under pressures of 30 mm to 150 psig. All steps leading to production of nickel and iron metals by wet carbonyl process were technically feasible in small-scale batch operations; integration of system into semicontinuous operation was successful. Tables, flowsheet, equipment diagrams.-INCO. 16942

# Duriron impressed current Anodes

consumption rate practically "nil" after 5 years of cathodic protection

Another impressed current anode material failed after 1½ years in this service because it was impossible to maintain backfill in river bottom quicksand (approximately 3000 ohmcm. soil). Those anodes were replaced by DURIRON, which promises a minimum of 15 years' service, even without backfill.

Difficult to believe? We thought so, too, when the Duriron Anode at the far left was removed from a ground bed in river bottom quicksand after the first year of continuous service. Compare it with the new and unused Duriron Anode at right.

The average readings on the nine anodes in this installation were 33.3 amperes at 36 volts with an average consumption rate of 0.7 lbs./ampere year. Another inspection was made after 3 years, and the Duriron Anodes continued to function in a predictable manner although the consumption rate had increased to 0.9 lbs./ampere year.

Today, after five years of service, these anodes continue to perform in a very satisfactory manner at a very minimum consumption rate. Estimated life expectancy is conservatively in excess of 15 years.

For latest data and case histories on fresh water, salt water and ground bed applications write for Bulletin DA/6.

make Duriron Anodes your assurance for cathodic protection.

THE DURIRON COMPANY, INC. DAYTON, OHIO



DURIRON ANODES
After 1 year New and of service unused

hile 250-150 ion arible ite-

ted

deind er-(A-

relest

im, eels 000, peloboys 000

ght

enires els;

ove apher

on has oles

eat-

on,

58)

ion

yls. ons

ide

are on

on

inrial

ant

was

tric

ent

at

ose-

ad-

ytic

and

tics erse

011

rith

rry

em-

ob-

ent

inand acdis-

nyl

der

942


# Where's <u>Your</u> Toughest Corrosion Problem?



UNDERGROUND STEEL?



CHEMICAL SPILLAGE?



WASTE TREATMENT?

# There's a time-tested **TARMASTIC** coating to lick each one—economically and "for keeps!"


There's hardly a corrosion problem in your plant that can't be stopped dead-in-its-tracks with a Pitt Chem Tarmastic coal tar coating. There are seven different Tarmastic coatings to select from. Each one is formulated to solve a specific type of corrosion problem.

These tough, heavy-duty coatings are so resistant to moisture and industrial corrosion that they'll outlast a dozen applications of ordinary protective paints. Yet they cost no more per gallon. Tarmastic coatings are readily applied by brush, spray or roller.

Begin cutting corrosion costs at your plant

with a complete Tarmastic protection program! No other type of coating can do such a complete job of protection . . . at so little cost!

The first step is to call your local Industrial Distributor who handles Pitt Chem Industrial Coatings. Write for his name . . . or check the "Yellow Pages" of your telephone directory.



\* PITT CHEM "Tarset" Coal Tar-Epoxy Resin Coatings

★ PITT CHEM "Tarmastic"® Coal Tar Coatings



## INDEX TO TECHNICAL AND TECHNICAL TOPICS SECTIONS

## CORROSION

**VOLUME 15** 

JANUARY 1-DECEMBER 31

1959

### CONTENTS

Tables of Contents
Alphabetical Subject Index
Alphabetical Index to Authors

#### PAGE NUMBERS BY MONTHS

Pages		Pages	
1t- 48t	January	239t-394t	
49t-100t	February	395t-446t	August
101t-166t	March	447t-502t	September
167t-220t	April	503t-556t	October
221t-282t		557t-618t	November
283t-338t	June	619t-646t	December

## **Tables of Contents**

Dec

May

An E r n A C c

CORROSION Technical and Technical Topics Sections, Volume 15, 1959

January Pag	e February—Continued	Page A	oril—Continued	Page
Topic of the Month—Corrosion of Valve Seat Ring Results in Flexible Metal by J. E. Prior	Bregman and T. R. Newman	ent Ion- by J. I.	Refinery Applications of T Synthetic Coatings by R. V W. B. Cook and R. B. MacQ Discussion: Page 642t. rrosion Rate Measurement by	W. Maier, Jueen171
High Temperature Corrosion Product Films on Aluminum by V. H. Troutner. Observations on the Mechanisms and Kinetics of Aqueous Aluminum Corro-	Technical Topies Cathodic Protection for Naval Experimental Studies by L. J. M. H. Peterson and M. C. E Advantages of Reinforced Poly	Vessels— Waldron, loom 87	rrosion Kate Measurement by Effusion in Dynamic Aqueous at Elevated Temperature a sure by M. Krulfeld, M. C. B R. E. Seeboldsual Observations on the Wat-	s Systems and Pres- Bloom and 179
sion (Part 1—Role of the Corrosion Product Film in the Uniform Aqueous Corrosion of Aluminum) by V. H. Troutner	Use on Highway Tank Tr James M. Brady Applications of Lead-Acid Brick in Chemical Plants by E. J. 1	Systems fullarkey. 98 Mi	in an Elevated Temperature locity Loop by R. E. Seebold. nimum Corrosion for Butane zation Units—A Contribution	High Ve- 
Observations on the Mechanisms and Kinetics of Aqueous Aluminum Corro- sion (Part 2—Kinetics of Aqueous Alu- minum Corrosion) by R. L. Dillon 13		Page	Work of NACE Group Common Refining Industry Corrosi F. Mason, Jr., and C. M. Sch Publication 59-11	ion by J. hillmoller. 185
Discussion: Page 642t  'recautionary Procedures in Chemical Cleaning—A Contribution to the Work of NACE Technical Unit Committee T-8A on Chemical Cleaning by Robert A. Stander. Publication 59-1	Equipment and Procedure for E of Stress Corrosion Susceptib Wrought Copper Base Alloy Smith	valuation lity of a by G. B.	rrosion of Refinery Equip. Aqueous Hydrogen Sulfide— bution to the Work of NAC Committee T-8 on Refining Corrosion by Roy V. Comeat Cation 59-12	A Contri- CE Group Industry ux. Publi-
A. Stander. Publication 59-1. It diuminum Cooling Towers and Their Treatment by A. J. Haygood and J. Dean Minford	The Corrosion of Zirconium in chloric Acid at Atmospheric by W. E. Kuhn	Hydro- Son Pressure	me Experiments on Internal of Nickel Chromium Alloys Copson and F. S. Lang	Oxidation by H. R.
Critical Analysis of Pitting Corrosion by N. D. Greene and M. G. Fontana 2:	try by Richard Benes. Fred	J. Hol-	entification of Corrosion Pro Copper and Copper Alloys—A NACE Technical Unit Commi	nducts on Report of ttee T-3B
rosion in Stainless Steels (Part 1—Pit Growth) by N. D. Greene and M. G. Fontana	Chemical Resistance of Poly Coatings—A Report of NAC Group T-6A-5 on Polyethylen	rethylene EE Task Ev e. Publi-	on Corrosion Products. Publica aluation of Steam Resistant for Carbon Steel Hospital Wi G. Bobalek, W. R. R. Park, I	Coatings are by E.
n Electrochemical Study of Pitting Corrosion in Stainless Steels (Part 2—Polarization Measurements) by N. D. Greene and M. G. Fontana	cation 59-7	of Cor- Various De E Tech-	and W. R. Dawson	gth Steels
peterioration of Wood by Marine Boring Organisms by H. Hochman	nical Unit Committee T-3C or Losses Due to Corrosion Pi	Annual Th	e Effect of Sigma Phase vs C Carbides on Intergranular Co Type 316 and 316L Stainb (Part 1—A Survey of the Li	Chromium rrosion of ess Steel
Inderground Corrosion—A Summary of 45 Years of NBS Research	ment—A Report Prepared b Task Group T-3G-3 on Catho	y NACE It die Pro- Publica-	Donald Warren  Technical Topics	
tubber-Base Transformer Finish for Severe Environments by Ralph Hockridge11 tecovery of Graphitically Embrittled Nickel by Walter A. Szymanski11	1 Iso-Corrosion Rate Curves for H perature Hydrogen-Hydrogen	gh Tem- Sulfide— of NACE -8 by E. Ne org. Pub-	uterials Selection and Design n a Nickel-Cobalt Extracti yy C. S. Simons w Formulations Give Versu Urethane Coatings by Barna nan	on Plant atility to ard Good-
ebruary Pag	Mha Englandina at Castala Orman	ic Nitro- Glanhibitors - Berman.128t I	ass Fiber Reinforcement for  —Characteristics and Cost Fi B. A. Graham  Discussion: Page 106 of Decer	Coatings actors by
sistance of Oil Well Tubing by F. A. Prange	Products Pipe Line by Ro	bert H.	ssue.	
nfluence of Service Temperature on the Resistance of Wrought Aluminum- Magnesium Alloys to Corrosion by E. H. Dix, Jr., W. A. Anderson and M.	Test on Tin-Plate Steel by R. son and G. L. Stragand High Temperature Oxidation	M. Hud- of Chro-	•	Pag
Byron Shumaker	M. Cohen	ce of 200 Steels in Steesses by	e Effect of Sigma Phase vs C Carbides on the Intergranul sion of Type 316 and 316L Steel (Part 2—Laboratory 1 tion) by Donald Warren	ar Corro- Stainless Investiga- 22
with Direct Current Corrosion Meters by W. Searle Woodward	A. C. Hamstead and L. S. linder	f Petro-	lecting Corrosion and Scale for Cooling Water by Hobar L. V. Sorg and R. L. Stutz	t Shields,
Austenitic Stainless Steels—A Contribu- tion to the work of NACE Task Group T-8A on Chemical Cleaning by J. P. Engle, G. L. Floyd and R. B. Rosene.	ble Inhibitors by M. R. Ba G. Haskell and R. L. Piehl Technical Topics	usch, L.	mmary of Questionnaire Re Corrosion in HF Alkylation Report of NACE Task Grou on HF Corrosion. Publication	Units—A p T-5A-6
Publication 59-5 6: Vell Completion and Corrosion Control of High Pressure Gas Wells—A Status Report of NACE Task Group T-1B-1 on High Pressure Well Completion and Corrosion Mitigation Procedure, Publi-	Behavior of Tin Alloys in Atr Exposures by Robert T. Gor Improved Methods Plus Hot Sp Application of Saran Coatings land A. Morley.	ay Speed by Har-	rrosion Prevention in Tanl Storage Tanks by Fogging tion With an Inhibitor Solut C. D. Oosterhout, M. E. Sta W. S. Quimby	or Flota- tion by J. anley and 24
cation 59-6	Aerial Pipeline Crossing Pro Gordon Davis	blem by	Corrosion of Carbon Steel A by Liquid-Phase Fuming Ni by John B. Rittenhouse and Mason  Actoelectric Information Selec	AISI 1020 itric Acid David M.
Discussion: Page 643t. orrosivity of Soil by N. D. Tomashov	April	Page	N. Ride and P. J. Knuckey. assification of Topics Relatin	25
and Y. N. Mikhailovsky	Topic of the Month-Automot	ive Cor- La	rosion by Miss D. M. Brashe boratory Methods for Determi rosion Rates Under Heat Flu tions by A. O. Fisher and F.	er25 ining Cor- ux Condi-
Effect of Molten Boron Oxide on Selected High Temperature Alloys by David Roller and C. R. Andrews	Corrosion Problems Associat Uranium Refining by F. H. M	ed With eyer, Jr., In:	ney, Jr. fluence of Temperature on Fatigue by I. Cornet and Sime	Corrosion

age

171t

179t

183t

85t

.89t .94t

99t

02t

07t

13t

95

100

102

ge

21t

33t

37t

11t

15t 51t

54t

57t 52t

				-		
May—Continued	Page	June—Continued	Page	August—Continued	Page	
Erosion of Materials by Cavita tack by D. Peckner	Pickling r to Lin- wards, L. r	Technical Topi Solving Corrosion Problems a Generating Plants by L. E Five Case Histories on Corr lems in Nitric Acid and Nitrate Production and St. M. Carr  Methods of Testing Charac Polyethylene Jackets for St. H. M. McDaniel Corrosion Keeps Knife Shar Canning Machine by S. H. Industrial Coating Performanc by Good Design by C. G. M.	t Electrical saskette 95 osion Prob- Ammonium orage by D. 99 teristics of eel Pipe by	Cracking of Copper Alloys by D. Thompson  Stress Corrosion Cracking of Oil Count Tubular Goods by R. L. McGlasson at W. D. Greathouse. Discussion: Page 646t. Corrosion of Type 310 Stainless Steel Synthetic Fuel Oil Ash by Hugh Logan  Technical Topics  Filming Amines Control Corrosion Utility Plant Condensate System Edward E. Galloway.  Offspore Platform Shows Corrosion Ra		
Comparative Effectiveness of for Offshore Drilling Structur G. Munger	res by C.	July	Page	of Carbon Steel in Gulf of Mex Exposure by Dean Patterson		
		Comparisons of Wagner's Cathodic Protection With	Analysis of	Material Selection in Chemica Process by W. C. Rockwell	d Milling	
June	Page	Data for Ships by J. H. Gr. Corrosion Resistance of Tit	eenblatt339t	vinylchloride Plastisols by J. Wai		
Impedance Characteristics of I Aluminum Oxide Films by D. Lennan	F. Mac-	Zirconium in Chemical Pl ures by P. J. Gegner and W Discussion: Page 643t. Corrosion of Types 316 and 3 Steel by 75 Percent and Phosphoric Acid by Albert	7. L. Wilson.341t 17 Stainless 85 Percent	Refinery Isomerization Unit	by John	
Rates of Dissolution and Passi Hafnium-Free Zirconium in fluoric Acid by M. E. Straun	1 Hydro-	Jr. Discussion: Page 644t. Summary of Replies to Quest	351t	September	Page	
J. James and A. S. Neiman.  Performance of Organic Coat Tropical Environments by A. ander, B. W. Forgeson at Southwell Discussion: Page 643t.	ings in L. Alex- nd C. R.	Handling of Chlorine Mixty port of NACE Task Group Chlorine, Publication 59-15 Corrosion in Sour Water S J. F. Mason, Jr., and C. moller	trippers by M. Schill-	Corrosion Inhibitors for Carb chloride—Water Vapor Atmos K. W. Calkins and R. W. H Evaluation of Performance o ing Tests of Inhibitors to	spheres by awley447 f Screen- Prevent	
Stress Corrosion Crack Paths Aluminum Bronze in Amme Steam Atmospheres by J. F.	onia and Klement,	Corrosion Protection Features perion Ocean Outfall by Keeling	of the Hy- Harry J.	Chloride Stress Corrosion Phillips and W. J. Singley Factors Influencing Corrosion Akimov	by G. V.	
R. E. Maersch and P. A. Tul Factors Affecting the Corrosion by Oil-Brine-Hydrogen Sulf tures by Donald W. Shant James E. Boggs	of Steel ide Mix-	The Classical Potentiostat: I tion to the Study of Pass D. Greene	ivity by N	Action of the XON-4 Inhibitors Cartledge		
An Analytical Procedure for Te Effectiveness of Hydrogen Su rosion Inhibitors by Donald non and James E. Boggs	lfide Cor- W. Shan-	Waters by R. W. Staehle, and M. G. Fontana Corrosion of Reinforcing St.	F. H. Beck 	Corrosion Processes in Carbona erage Cans by E. L. Koeh Daly, Jr., H. T. Francis at Johnson	ler, J. J. nd H. T.	
A Laboratory Method for E Corrosion Inhibitors for Secon covery by T. R. Newman	valuating dary Re-	crete in Marine Atmospher Lewis and W. J. Copenhag Cathodic Protection of	ren382t Lead Cable	Principles and Criteria for Cath tection of Steel in Sea Wate view by M. H. Peterson	er—A Re-	
Wash Primer Development and teristics by L. R. Whiting	Charac-	Sheath by W. H. Bruckn G. Jansson Discussion: Page 644t.	er and Ole	Planning a Maintenance Coai gram for a Pulp and Paper M. W. Belue, Jr	Plant by	
Evaluation of Protective Coal Ship Bottoms by J. R. Brow	tings for n315t	Technical Topi		Four-Tower Water Treatment cility by R. G. Murray an	d M. E.	
Evaluation of Organic Corrosio tors for Special Applications leum Refining by R. B. Thon F. Stedman, Charles Wanka	in Petro- apson. R. t and R.	A Field Method for Screenin for Prevention of Water rosion by Charles C. Wrigh Use of Plastics and Synthetic	Flood Cor- nt 97 Elastomers	Tester Use of Magnesium for Cathodi tection of Pipe Lines in High ity Soil by A. W. Peabody.	c Protec- Resistiv-	
C. Henry	Velocity Pipelines Sulfuric	for Underground Coatings Partridge  Mechanism of Stress Corrosic by Hugh L. Logan	on Cracking	Technical Topics  Mechanisms and Some Theore pects of Stress Corrosion Cr. Austenitic Stainless Steels t	etical As- acking of	
Acid by T. F. Degnan Corrosion of Die Casting Alloy tergent Solutions Measured by cal Resistance Method by H.	s in De- Electri- J. Smith	Coatings Engineers Help in I Planning by W. J. Prather		Brooks  Methods of Installing Cathodition Anodes for Offshore Stru Wayne A. Johnson and	c Protectures by James T.	
and R. L. Hadley Progress Report on Inhibiting rosion of Steel in a Reinforced	the Cor- Concrete	August	Page	Condry Discussion: Page 106 of Decemissue.	nber 1959	
Bridge by R. F. Stratfull  DISCUSSIONS		Corrosion of Aluminum Alloy Water Cooling Systems by I ster	N. S. Demp-	Rapid Field Measurement of Su Corrosion of Aluminum by Godard	Hugh P	
Development of the Redox Pro Technique: L. P. Sudrabin, P. Reply by F. E. Costanzo	obe Field age 335t;	Notch Sensitivity Effects in rosion and Hydrogen En Tests on High Strength S	Stress Cor-	Case Histories of Differential Corrosion in Underground Cables by David T. Jones	Telephone	
Coatings for Underwater Metal in Fresh Water Exposures: W Palmer, Page 335t; Reply I Gleser	Varren D. by S. M.	F. Brown Uses and Abuses of Alux Wooden-Hulled, Aluminu Minesweepers by T. H. Rog	minum in	October	Page	
Failure of Type 316 Stainless St clave Components: C. P. Dill 336t; Rep'y by J. P. Hugo a	eel Auto- on, Page nd L. G.	Minesweepers by T. H. Rog K. Chinn	s by E. A.	Engineering Approach to a Pa ing Program—Justification a nomics by D. A. Ballard an Voltaning	nd Eco-	
Observations on the Mechanic Kinetics of Aqueous Alumin rosion: George Panter, Pa	sms and um Cor-	Corrosion Problems Associated Gas Condensate Production Fincher	d With Sour	Volkening  Methods for Investigating the teristics of Reactive Coatings Kronstein	Charac-	
Reply by R. L. Dillon  Influence of Service Temperatur Resistance of Wrought Al	re on the uminum-	The Internal Cathodic Proc Large Steel Pipes Carrying by John H. Morgan	Sea Water	Analysis of Industrial Roof Con and Maintenance by J. C. and W. G. Craig	Lemmon513	
Magnesium Alloys to Corrosic Nowak, Page 337t; Reply b Dix, Jr. W. A. Anderson Byron Shumaker	on: S. K. by E. H. and M.	Duct Anode Development and in Protection of Undergro From Corrosion by J. E. Jo Discussion: Page 646t.	und Cables	Corrosion Inhibitor Evaluation thodic Polarization Measurer R. A. Legault and Norman man	From Ca- ments by Hacker-	

A

Page					
9-	December—Continued	Page	November—Continued	Page	October—Continued
L. Dillon, Page	Corrosion): P. M. Aziz and Page 642t; Reply by R. 642t,	Ships by Cdr. mpster and A.	Electrical Bonding of Cathod tected to Unprotected Shi G. A. Bennett, N. S. Demp	E	Some Fundamental Aspect Materials Deterioration IN THE ATMOSPHER
Stanbury, Emile SuWayne Christ-	Oil Refinery Applications of thetic Coatings: Charles M. E. Habib, Austin K. Long, offerson, Page 642t; Replies Page 642t.	ty of Cathodi- Hydrogen Em- Bruckner and	J. Wallace	Metals P. M.	Mechanisms by Which Ferrous Corrode in the Atmosphere by Larrabee
Boer, Page 643t; 1, Page 643t.	Impedance Characteristics of num Oxide Films: F. E. De Reply by D. F. MacLenna	ctive Ships by	Some Platinum Anode Desig thodic Protection of Activ H. S. Preiser and B. H. T	oyed in of At-	Aziz and H. P. Godard Principles and Procedures Emplo the Design and Interpretation
Anodes in So- J. L. Robinson,	Behavior of AZ 63 Alloy a 1 Percent Manganese Allo; dium Chloride Electrolyte: 643t; Reply by J. H. Green	J. Slunder601t	The Residual Oil Ash Corr- lem—A Review—by C. J. S	Polluted	mospheric Corrosion Tests by Copson Deterioration of Materials in F Atmospheres by John E. Yocom
ings in Tropical Fiebach, Page	Performance of Organic Coat Environments; Seymour J 643t; Reply by A. L. Alexa	in Automotive Cessna607t	Electrical Resistance Method ing Corrosion Inhibitors in Anti-Freezes by J. C. Cess	s Pub-	Recent Metals Corrosion Article lished in CORROSION
Exposures: E. G. age 643t; Milton op. Page 644t;	Corrosion Resistance of Titaninum a conium in Chemical Plant Exposures Frink, Wayne H. Keller, Page 643t; Stern and Claude R. Bishop. Page Replies by P. J. Gegner, Pages 6: 644t.  Corrosion of Types 316 and 317 Stainle by 75 Percent and 85 Percent Pho		Effect of Silicon on High T Oxidation of Stainless Stee F. Radavich	Nickel R. B.	Corrosion Experience Associated Hydrometallurgical Refining of at Sherritt Gordon Mines by McIntosh  Simple Screening Test for Determ
	644t.	tack Chemical	Accumulated Residues Attac Distilling Column by H. Gi	y John	of Inhfbitor Film Persistence b A. Knox and Roy Stout
cent Phosphoric age 644t; Reply		11-100	Can Corrosion Problems by Jr		Technical Topics A Resume of Procedures for
Cable Sheath: age 644t; Vernon J. J. Pokorny,	Cathodic Protection of Leac R. B. Mears, L. C. Eddy, P. B. Pike, Frank E. Kulmar Page 645t; Replies by W. Pages 644t, 645t, 646t.	ler and J. B.	Some Properties and Uses of Polyether by C. S. Miller Martin	Foster 85	and Evaluating Chemical R. Coatings and Linings by R. S. and V. B. Volkening  New Bonding Process Gives Adde satility to Cladding by R. A. D.
					Potentialities and Applications of cial Corrosion Resistant Refra
d Cables from	Duct Anode Development an Protection of Undergroun Corrosion: David T. Jones,	Page	December	oble 92	by Roy W. Brown and H. G. N
d Cables from Page 646t. of Oil Country Craig, Jr., Joe	Protection of Undergroun	oon Conversion 6	Corrosion in a Hydrocarbon System by F. A. Prange An Industrial Experience of Metals by Synthesis Gas Fro	Page	by Roy W. Brown and H. G. N
d Cables from Page 646t. of Oil Country Craig, Jr., Joe R. L. McGlas-	Protection of Undergroun Corrosion: David T. Jones, Stress Corrosion Cracking Tubular Goods: H. Lee Chittum, Page 646t; Reply son, Page 646t.	oon Conversion 6	Corrosion in a Hydrocarbon System by F. A. Prange An Industrial Experience of	Page	November  Controlling Internal Corrosion o
d Cables from Page 646t.  Page 646t.  Of Oil Country Craig, Jr., Joe R. L. McGlas- cs  olyurethane Wells93	Protection of Undergroun Corrosion: David T. Jones, Stress Corrosion Cracking Tubular Goods: H. Lee Chittum, Page 646t; Reply son, Page 646t.  Technical Topi Characteristic Properties of P Protective Coatings by E. F.	oon Conversion  of Attack on From Methane F. Eberle and 622t oration in At- Carbon-Monox-	Corrosion in a Hydrocarbon System by F. A. Prange An Industrial Experience of Metals by Synthesis Gas Fr. Oxygen Combustion by F. R. D. Wylie High Temperature Deterlora mospheres Containing Car	Page  f Tank557t	November  Controlling Internal Corrosion of Ships by J. Franklin Koehler Discussion: Page 560t.
d Cables from Page 646t.  Page 646t.  G Oil Country Craig, Jr., Joe R. L. McGlas- es olyurethane . Wells 93 n the Wil- ttion by C.	Protection of Undergroun Corrosion: David T. Jones, Stress Corrosion Cracking Tubular Goods: H. Lee Chittum, Page 646t; Reply son, Page 646t.  Technical Topi Characteristic Properties of P Protective Coatings by E. E Corrosion Control Practices i mington Water Flood Oper	on Conversion  of Attack on From Methane- F. Eberle and contains in At- Carbon-Monox- B. Hoyt and	Corrosion in a Hydrocarbon System by F. A. Prange An Industrial Experience of Metals by Synthesis Gas Fro Oxygen Combustion by F. R. D. Wylie High Temperature Deteriora	Page f Tank557t for Ul- k Ship	November  Controlling Internal Corrosion of Ships by J. Franklin Koehler.
d Cables from Page 646t.  of Oil Country Crais, Jr., Joe R. L. McGlas- es olyurethane Wells	Protection of Undergroun Corrosion: David T. Jones, Stress Corrosion Cracking Tubular Goods: H. Lee Chittum, Page 646t; Reply son, Page 646t.  Technical Topi Characteristic Properties of P Protective Coatings by E. F Corrosion Control Practices i mington Water Flood Open H. Jones, Jr	oon Conversion  of Attack on From Methane- F. Eberle and 622t  oration in At- Carbon-Monox- B. Hoyt and 627t  ndapam Camp, oalan, M. Sun- nalai. 631t	Corrosion in a Hydrocarbon System by F. A. Prange  An Industrial Experience of Metals by Synthesis Gas Fro Oxygen Combustion by F. R. D. Wylie  High Temperature Deteriora mospheres Containing Car ide and Hydrogen by W. F. R. H. Caughey  Corrosion of Metals at Manda India by K. S. Rajagopala daram and P. L. Annamalication.	Page  f Tank557t  for Ul- lak Ship Evans561t  prosion Hydro- Hydro- Hy Bliy	November  Controlling Internal Corrosion of Ships by J. Franklin Koehler. Discussion: Page 560t.  New Instruments and Techniques transonic Measurement of Tan
d Cables from Page 646t.  of Oil Country Craig, Jr., Joe R. L. McGlas-  solyurethane Wells 93  in the Wil- ution by C.  orn Pacific's ppe Line— ine months  104	Protection of Undergroun Corrosion: David T. Jones, Stress Corrosion Cracking Tubular Goods: H. Lee Chittum, Page 646t; Reply son, Page 646t.  Technical Topi Characteristic Properties of P Protective Coatings by E. F Corrosion Control Practices i mington Water Flood Oper H. Jones, Jr Cathodic Protection of South High-Pressure Products F Whole System Installed in N by D. N. Miller	on Conversion  of Attack on From Methane F. Eberle and Carbon-Monox B. Hoyt and 627t  ndapam Camp, palan, M. Sun- nalal	Corrosion in a Hydrocarbon System by F. A. Prange An Industrial Experience of Metals by Synthesis Gas Fr. Oxygen Combustion by F. R. D. Wylie High Temperature Deteriora mospheres Containing Car ide and Hydrogen by W. E. R. H. Caughey Corrosion of Metals at Manda India by K. S. Rajagopala daram and P. L. Annamal. Case Histories and Ratings v. of Polyester Fiber Glass Ec. Robert E. Barnett and	Page  f Tank	November  Controlling Internal Corrosion of Ships by J. Franklin Koehler Discussion: Page 560t.  New Instruments and Techniques transonic Measurement of Tan Corrosion Losses by Dwight J. I Effects of Foreign Metals on Co of Titanium in Boiling 2M chloric Acid by Boger Buck, II W. Sloope and Henry Leidhelse Instruments for Measurements in ground Cerrosion Work by K. G.
d Cables from Page 646t.  of Oil Country Craig, Jr., Joe R. L. McGlas- es olyurethane Wells	Protection of Undergroun Corrosion: David T. Jones, Stress Corrosion Cracking Tubular Goods: H. Lee Chittum, Page 646t; Reply son, Page 646t.  Technical Topi Characteristic Properties of P Protective Coatings by E. F Corrosion Control Practices i mington Water Flood Open H. Jones, Jr	oon Conversion  of Attack on From Methane- F. Eberle and 622t oration in At- Carbon-Monox- B. Hoyt and 627t ndapam Camp, balan, M. Sun- nalal	Corrosion in a Hydrocarbon System by F. A. Prange  An Industrial Experience of Metals by Synthesis Gas Fro Oxygen Combustion by F. R. D. Wylie  High Temperature Deteriora mospheres Containing Cardie and Hydrogen by W. F. R. H. Caughey  Corrosion of Metals at Manda India by K. S. Rajagopals daram and P. L. Annamal: Case Histories and Ratings v. of Polyester Fiber Glass Ec.	Page  f Tank	November  Controlling Internal Corrosion of Ships by J. Franklin Koehler. Discussion: Page 560t. New Instruments and Techniques transonic Measurement of Tan Corrosion Lossos by Dwight J. I Effects of Foreign Metals on Co of Titanium in Boiling 2M chloric Acid by Boger Buck, II W. Sloope and Henry Leidheles Instruments for Measurements in

## Alphabetical Subject Index

CORROSION Technical and Technical Topics Sections, Volume 15, 1959

NOTE: The index is being expanded this year to include Technical Topics as well as Technical Section articles. Designation of Technical Section articles will be made by the appropriate "t" number as has been the custom in the past. For Technical Topics articles both the issue number of Corrosion and the page number will be given. For example, the notation 9-116 would mean September issue (9th month) of Corrosion, page 116. The notation 10-101 would mean October issue, page 101.

Abrasion, starch granules vs hard rubber and resins, 113t

Abrasion resistance, plastics, 11-108

" ", refractories, 10-92

1. 15

age

m-

ical Zir-

teel oric

non

my.

ner.

99

104

Re-

Abrasives, anchor pattern profile in blast cleaning related to, 428t

Abstract cards, 254t

" ", photoelectric information se-lector used with, 251t

Abstracts, metals corrosion arti-cles recently published in COR-ROSION, 546t

Accelerated testing, steel reinforced by mortar in salt spray, 382t

" ", atmospheric corrosion of metals, 533t

Acetals, production of, 311t

Acetylenic alcohol-inhibited pick-ling bath for steel pipe, 275t

Acetic, stainless steel (200 and 300 series) vs. 147t

" " (Types 316 and 316L) vs. 221t

Benzoic, inhibition of hydrogen sulfide with, 303t

Carbonic, iron vs, 526t

Chromic, inhibiting effect of on aluminum, 7t

wash primers formed from,

Citric, stainless steel (Types 316 and 316L) vs, 221t

Formic, stainless steel (Types 316 and 316L) vs, 221t

Hydrochloric, austenitic stain-less steel equipment chemi-cally cleaned with, 69t

butane isomerization units vs.

loys in starch production vs. 113t ", high nickel-molybdenum al-

", mill scale removed with, 17t

", nickel tubing vs, 1-112

", organic coatings for oil well tubing tested in, 5-121

", pumping of into sour gas wells, 413t

", titanium and zirconium re-sistance to, 341t

", titanium coupled to foreign metals in, 566t

", zirconium at atmospheric pressure vs, 103t

Hydrofluoric, fuming nitric acid corrosion of AISI 1020 af-fected by, 245t

", in HF alkylation units, 237t

", rates of dissolution and pas-sivation of hafnium-free zir-conlum in, 286t

#### A-Continued

Nitric, passivation of hafnium-free zirconium in HF after tree zirconium addition of, 286t

", production and storage of, 6-99

", stainless steel (200 and 300 series) vs. 147t

", " " (Type 304) vs, 257t

" " (Types 316 and 316L) vs,

", titanium and zirconium resist-ance to, 341t

itric (fuming), carbon steel AISI 1020 vs, 245t

Oxalic, stainless steel (Type 316 and 316L) vs. 221t

Perchloric, effect of in corrosion of AISI 1020 by furning nitric acid, 245t

Phosphoric, aluminum alloys tested in, 63t

", inhibiting effect of on alumi-num, 7t

", ship bottom coatings exposed to, 315t

", stainless steel (Type 316) vs, 257t

", ". 221t " " (Types 316 and 316L) vs.

", 351t " " (Types 316 and 317) vs,

", wash primers formed from, 311t

Sulfuric, aluminum oxide films formed in presence of, 283t

, effect of in corrosion of AISI 1020 by fuming nitric acid, 245t

", lead-acid brick vs, 2-98

", material in nickel extraction plant vs, 4-95

", starch production equipment vs, 113t

', stainless steel (Types 316 and 316L) vs, 221t

", titanium and zirconium resist-ance to, 341t

", titanium coupled to foreign metals in, 566t

", valve seat ring (Type 316 SS) vs in water treating system, 1t

", velocity of in steel pipe lines,

Sulfurous, stainless steel (Type 304) vs, 113t

Acid cleaning of scale and corro-sion products, 17t

Acid stripper tower, HF vs, 237t

Acid theory of pitting corrosion, Acidic environments, inhibitors for steel in, 321t

Acidization of sour gas wells, 413t

Intergranular attack of stainless steels in, 213t

Mineral, polyurethane coatings vs.

#### A-Continued

ACIDS (Continued) Organic, stainless steels vs, 147t Polyesters vs, 635t

Polyethylene coatings vs, 117t Refractories used in, 10-92

Additives, oil ash corrosion from fuel reduced by use of, 5-126

", oil ash corrosion reduced with, 601t

Adhesive pipe-plastic coating, 6-100 Admiralty metal, ammonia and hy-drogen sulfide vs, 321t

"", cooling waters vs. 233t

" ", inhibited cooling tower water

" ", inhibitors to protect, 321t

Admiralty tubes, HF vs. 237t

Admiralty tubing, stress corrosion cracking of, 433t

Adsorbed films in pipe lines, be-havior of, 158t

Adsorbed particles in inhibitors,

dsorption, inhibitor film persist-ence related to, 554t Adsorption,

Adsorption theory of pitting corrosion, 25t Adsorptive power of nitrogen com-pound inhibitors, 128t

Aeration, phosphoric acid attack of stainless steel measured under conditions of, 351t

soil corrosivity to buried metals affected by, 1-107

stress corrosion cracking of cop-per alloys related to, 433t

Aerial pipe line crossing, corrosion problems of, 3-118

Aging of wash primers, 311t

Air, nickel-chromium alloys oxi-dized in, 194t

Air observation of products pipe line, 12-104

Air oxidation, aqueous corrosion of aluminum related to, 9t

Air pollution, 541t Air preheater tubes, deposits on, 5-126

Aircraft, high strength steels for,

Aircraft fuels, inhibitors for in pipe lines, 158t

Aircraft industry, materials selec-tion in chemical milling process, 8-105

Aircraft oil cooler, aluminum tubing corrosion of, 395t

Alclad, good resistance of to per-foration in cooling towers, 20t Alcohols, acetylenic, inhibiting of pickling bath with, 275t

Aldehydes, stainless steels vs. 147t Alkalies, polyesters vs. 635t

, polyethylene coatings vs, 117t , refractories used in, 10-92

Alkaline solution vs lead, 389t Alkyd-melamine coating, chemical resistance of at ambient tempera-tures, 1-111

#### A-Continued

Alkyd-phenolic resins, tropical en-vironments vs. 291t

Alkyds, high-film-build, application of, 171t

Alkyds, steam resistance of, 202t Alkylation units, HF, corrosion in, 237t

Alloying, steel for industrial and marine atmospheres, 526t

stainless steel, resistance to pitting affected by, 25t

Aluminum, aqueous corrosion of, 9t, 13t

", electrochemical study of, 63t

", high purity water in at tem-peratures above 150 C, 7t

", milling process use of, 113t

", nuclear reactors of in low purity water, 83t

", selection of for cooling tow-ers, 20t

Aluminum-magnesium (wrought), temperature vs, 337t

Aluminum bronze, stress corro-sion crack paths in, 295t

" ", wrought, testing of for stress corrosion cracking sus-ceptibility, 101t

AZ 63 and Mg-1 percent Mn anodes in NaC1 electrolyte, 76t Chrome-nickel, tubes of for de-hydrogenation, 619t

Copper, identification of corro-sion products on, 199t

", stress corrosion cracking re-sistance of, 433t

Die casting, detergent solutions vs. 327t

Heterophase and monophase, 455t High nickel-molybdenum vs HC1,

Lead-silver, ship anodes of, 581t Molten boron oxide vs at high temperatures, 85t

Nickel-chromium, internal oxidation of, 194t

Nickel-chromium - iron - molyb-denum, for heat exchangers, 9-103

Nickel-copper, atmospheric cor-rosion of, 533t

", titanium coupled with in HC1,

Oil ash corrosion resistant, 601t Sour water stripper components, selection of materials for, 358t Tin, atmospheric exposure of, 3-113

Wrought aluminum - magnesium, influence of service tempera-ture on, 55t

Alpha aluminum bronze, stress cor-rosion crack paths in, 295t

Alumina, bonded fused and fused-cast beta, high temperatures vs, 10-92

", insulating brick of, 10-92

#### -Continued

Aluminizing for high temperature exposure, 10-92

Aluminizing vs oil ash corrosion,

#### ALUMINUM

Alloy of in glycol-water cooling systems, 395t

Alloys containing vs molten boron oxide, 85t

Anti-freezes vs, 607t

Appearance of in corrosion prod-uct formed when AZ 63 ex-posed to NaC1, 76t

Aqueous corrosion of, 336t, 642t Atmospheric corrosion of, 529t

Compounds of added to residual fuel oil, 601t

Corrosion of in India, 631t

Electrochemical study of, 63t

Fencing material of for marine atmospheres, 6-95

High temperature corrosion prod-uct films on, 7t

Magnesium alloying of vs temper-ature, 55t

Mechanisms and kinetics of our corrosion of, 9t, 13t of aque

Milling system for, 8-105

Minesweeper with frames of, 403t

Pitting corrosion of, 25t

Sour water stripper components made of vs hydrogen sulfide, 358t

Sub-surface corre ments on, 9-114 corrosion measure-

Sulfur dioxide vs. 541t

Stress corrosion of, 455t

Titanium coupled with in HCl,

2S. in oxygen-saturated water at 50C, 13t

Aluminum-magnesium alloys (wrought), service temperatures affect, 337t

Aluminum alloy, M-388, deionized water vs. 13t

Aluminum alloys, detergent s tions and tap water vs, 327t

" ", M-388 for nuclear reactors,

" ", X2219 for nuclear reactors,

" ", 1245 for nuclear reactors, 83t

Aluminum brass tubing, st rosion cracking of, 433t stress cor-

Aluminum bronze, alpha, stress cor-rosion crack paths in, 295t

" ", sulfurous acid vs, 113t

"", wrought alloys of vs stress corrosion cracking, 101t

Aluminum cooling towers and their treatment, 20t

Aluminum oxide films, characteristics of, 283t impedance Aluminum oxide films, isolated,

Aluminum tanks, ammonium nitrate stored in, 6-99

Amino inhibitors in water flood operation, 12-99

Amine scrubber unit, inhibitors in.

Amines, filming, in utility plant condensate system, 8-99

", sour water strippers protected with. 358t

mines, glycol-water solution in-hibited with, 607t

Amines as inhibitors, 517t

Ammonia, leach solutions of, 547t

', stress corrosion crack paths of alpha aluminum bronze in atmosphere of, 295t

stress corrosion copper alloys in, 433t ", stress cracking of

#### -Continued

Ammonia leach process in nickel refining, 547t

Ammonium fluoride, addition of af-fects dissolution rate of Zr in HF. 286t

Ammonium nitrate, production and storage of, 6-99

Analysis of variance in determin-ing effects of low purity water in nuclear reactors, 83t

Anchor pattern profile, effect of on paint performance, 428t

Annealing, lag time of steel influenced by, 135t

Annealing, stress corrosion crack-ing of copper alloys affected by, 433t

", weldments, steel, affected by, 2t

Annealing temperature of zirconium influences corrosion rate in HC1, 103t

Anode assemblies, reinforced con-crete bridges having, 331t

Anode beds, magnesium, 497t

node cathode relationship between welds and their parent metals, 2

#### ANODES

AZ 63 alloy and Mg—1 percent Mn alloy in NaC1 electrolyte, 76t

Duct. underground, 423t

Graphite, duct, 646t

", failure of at lead wire con-nection, 12-106

", for ships, 581t

", products pipe line protected with, 12-104

", underground cable with, 423t protected

Lead-silver alloy for ships, 581t

Magnesium for ships, 581t

". in high resistivity soil, 497t

", naval vessels protected with, 2-87

", steel process equipment pro-tected with, 123t

", tank ship, 557t

Magnesium-manganese, 643t

Offshore structure installation of,

Platinum, for ships, 581t, 596t ", submarine protected with, 2-87

Sacrificial, steel pipe sewer out-fall in ocean unsuitable for fall 363t

Ship, 339t, 581t, 587t

Silicon iron, underground cable protected with, 423t

Steel, for ships, 581t

Steel pipe protected with inside mounting of, 417t

Zinc, chemical process equipment protected with, 123t

(sacrificial), aluminum frame minesweeper use of, 403t

with during installation, 363t

Anodic behavior, aluminum alloys tested by repetitive oscillographic method, 63t

dic reactions in pitting of etals, 25t Anodic

Anti-freezes, automobile, inhibition

titanium coupled with Antimony, tit in HC1, 566t

#### APPLICATION

Chlorinated polyether, 11-108

Coal tar-epoxy resins for under-ground pipe, 7-101 Coatings on steel structures, 6-

Hot spray coating of Saran. 3-

#### -Continued

APPLICATION (Continued)

Polyvinylchloride plastisols, 8-107 Pulp plant coatings, 488t

Steam resistant coatings to

bon steel hospital ware, 202t

Thick-film synthetic coatings in oil refineries, 171t

Application techniques, polyethylene coatings, 117t

Applied potential, effect of on cor-roding aluminum, 9t

Aqueous corrosion, aluminum, 642t " ", aluminum and its alloys, 7t, 9t, 13t

Aqueous hydrogen sulfide vs re-finery equipment, 189t

Aqueous uranyl nitrate vs stainless steels, 168t

Aqueous systems, dynamic, hydro-gen effusion measurements in

Aromatics, polyethylene vs. 6-100 Arsenic, flood water inhibited with, 12-99

Artificial pit specimens, use of in pitting studies on stainless steels, 32t

Artificial pits, use of in study of pitting corrosion, 25t

Asphalt coatings, underground pipe,

Asphalt emulsion, offshore structure

Asphalt mastic, rubberized, coatings of on offshore drilling structures, 5-131

Asphalt roofing, 513t

Atmosphere, industrial and marine vs ferrous metals, 526t

', inland, organic coatings vs in tropics, 291t

marine, org tropics, 291t organic coatings vs in

Atmospheres, carbon monoxide and hydrogen containing, metals vs, 627t

", polluted, materials deterioration in. 541t

#### ATMOSPHERIC CORROSION

Coatings selection against, 10-85

Ferrous metals vs. 526t

Industrial, reinforced concrete cracks in, 382t

Inhibitors to combat, 447t

Materials deterioration from, 541t

Tests, 533t

Tin alloys, 3-113 Titanium, zirconium and other metals, 341t

Zinc and galvanized steel, 409t

Zinc, copper and mild steel in India, 631t

Atmospheric corrosivity in differ-ent countries, 533t

Atmospheric salinity, metals corrosion related to, 631t

Augelite forms as corrosion product on aluminum alloys, 7t

utocatalytic nature process in metals, 25t Autocatalytic of pitting

Autoclave, oxidation, lead-acid brick used to reline, 2-98 Autoclaves, leaching stainless steel, 547t leaching, Type 316

Automobile anti-freezes, inhibition of, 607t

Automobile paint, air pollution vs. Automotive corrosion resistance.

AZ 63 alloy and Mg-1% Mn alloy anodes in NaC1 electrolyte, 76t

Backfill, gypsum moulding plaster,

Bacteria, underground corrosion ac-celerated by, 1-107

Bactericides, actericides, aluminum compatible with in cooling towers, 20t

Baffles, reaction gases vs. 622t

Baking, hydrogen eliminated from high strength steels by, 207t

Bentonite clay emulsions for in-dustrial roofing, 513t

Bibliography, abstracts of metals corrosion articles recently pub-lished in CORROSION, 546t

Biological corrosion, marine boring organisms vs wood, 45t

Bismuth, titanium coupled with in HC1, 566t Bitumen, roofing of, 513t

Bitumens, tropical environments vs,

Bituminous coatings, steam resist-ance of, 202t

Blast cleaning rates on steel, 428t

Bleed steam system, materials selec-tion for, 4-95

Boehmite, formation of in ano-dized aluminum, 283t Boehmite forms as corrosion prod-uct film on aluminum alloys, 7t

Boiler, waste heat type, 622t

Boiler water, inhibition of, 450t

Boilers, alkalies vs. 455t oil ash corrosion problems in, 601t, 5-126

Bolts, aluminum, sea water exposure of, 403t

Bonding, electrical, of ships, 587t ", lead to steel, 4-95

Bonding process, cladding versatil-ity increased by, 10-88

Borax, inhibition of anti-freezes with, 607t

Boron oxide, molten, high tempera-ture alloys vs, 85t

Brass, anti-freezes vs, 607t

", atmospheric corrosion of, 533t ", cast high tensile, erosion resist-

Breakaway corrosion, zirconium in HCl. 103t

Breaks in rate curves related to stainless steel scaling, 141t

rick, bubble alumina insulating, 10-92 Brick. ", lead-acid, in chemical plants,

paving, impingement tests on

Bridge caulking technique solves aerial pipe line crossing probaerial pipe line crossing prob-lem, 3-118

Bridges, reinforcing steel in con-crete corrodes in marine atmos-pheres, 382t Brine, flood water containing, 307t

Brine-hydrogen sulfide systems stress corrosion cracking in, 437t Brine-oil-hydrogen sulfide mixtures

vs steel, 299t, 303t Brine solution, corrosion fatigue of steel in, 262t

Brittle fracture, pipe at low temperature, 591t

Bronze, alpha aluminum, stress corrosion crack paths in, 295t ", aluminum alloyed, wrought.

stress corrosion cracking of, 101t ', atmospheric corrosion of, 533t

Bronze compared to copper under nickel/chromium, 3-113 Bronze under copper and nickel,

resistance of, 3-113 Bubble caps, residues vs, 11-99

Buff Buil

Dec

Bull in 9t Bun pi

But But But

But

"C" Cal Cal

Ca

Ca

Ca

Ca Ca Ca

C

15

ac-

ble

in-

ng

in

PS.

st-

c.

0

d-

n.

1-

in

#### -Continued

Buffering in inhibitor evaluation,

Building materials vs sulfur diox-ide, 541t

Bulk and barrier films, aluminum in aqueous solutions related to, 9t

Bunker-C oil, oil ash problems involving, 601t corrosion

Butane dehydrogenation process, 619t

Butane isomerization units, mini-mum corrosion for, 185t

utoxy resins, underground pipe protected with, 7-101

utyl rubber, underground pipe coated with, 7-101

#### C

"C" factor in inhibitor evaluation inside pipe lines, 131t

Cable sheath, lead, cathodic pro-tection of, 389t

", measurements on, 571t

Cables, bare, in sea water, coatings for. 7-101

", underground, differential aeration

", ", duct anodes to protect, 423t Cadmium, synergized polyphosphate containing, 97t

", plating of on aircraft steels, 207t

", tin as undercoat on, 3-113

', titanium coupled with in HC1.

Calcium, compounds of added to residual fuel oil, 601t

Calcium chloride, titanium and zirconium resistance to, 341t

Calcium phosphate, deposition of in cooling tower water, 97t

Canned product processing, 11-100

Canned-motor type centrifugal pump, 473t

Canning, fruit, cutter blade sharpened by corrosion, 6-100

Cans, carbonated beverage, 477t ", corrosion of, 11-100

Carbide precipitation, intergranular corrosion of stainless steels re-lated to, 213t

Carbon dioxide and atmospheric corrosion, 541t

Carbon dioxide in electric utility plants. 8-99

Carbon monoxide as a hydrogen sulfide inhibitor, 303t

Carbon monoxide, atmospheres containing, metals vs, 627t

" ", internal oxidation of nickelchromium alloys in, 194t

" ", lag time of tin-plate steel in-

fluenced by, 135t Carbon pick up, avoiding of on clad

sheet welding, 10-88 Carbon tetrachloride-water vapo

atmospheres, inhibitors for, 447t Carbonated beverage cans, 477t

Carburization attack, tubing affected by, 627t

Carburization in methane-oxygen combustion, 622t

Carburization in 80-20 nickel chromium, 194t

Cargo tanks, protection of, 557t

Casing, high pressure gas well, ma-

Catalytic reforming process, hydrogen sulfide vs steels in, 125t

Catalytic reforming units, inhibiton of, 189t

#### **Continued**

Catalyst cured phenolics and epolics in refinery applications, 17

Catalyst cured epoxy-modified pho cs, refinery applications of, nolic:

Catalyst tube, materials selection for, 619t

Cathode electrode area, polarization characteristics of pit specimens related to, 39t

Cathode ray tube, ultrasonic res-onance device, 561t

Cathodic inhibitors, cooling tower water treated with, 97t

#### CATHODIC PROTECTION

AZ 63 alloy and Mg-1% Mn alloy anodes in NaC1 electrolyte, 76t

Duct anode development, 646t

uct anodes for underground cable, 423t High pressure products pipe line,

12-104 Inhibitor evaluation from meas-urements from, 517t

Lead cable sheath, 389t, 644t

Minesweepers, aluminum - frame,

Naval vessels, 403t, 2-87

Offshore structures, 9-112

Pipe lines in high resistivity soil,

Pipe lines in soil, 335t

Process equipment, 123t

Reinforcing steel in concrete.

Ship operating data compared with Wagner's analysis, 339t

Ships, 339t, 403t, 483t, 557t, 581t, 587t, 596t, 2-87

oil corrosivity measurements, methods used in making, 77t

Steel in reinforced concrete bridge, 331t

Steel in sea water, 483t

Steel pipes carrying sea water, 417t

Steel pipe sewer outfall in ocean, 363t

Stray current potentials measured.

68t

Stress corrosion cracking of magnesium alloy stopped by, 7-106 Structure-to-soil potentials, 576t

Tank ships, 557t

Underground corrosion reduced by (NBS summary), 1-107

Underground telephone cables,

Cathodically protected steel, hydrogen embrittlement of, 591t

Cations, metallic, effect of on po-

tential of titanium in HCl, 566t Caulking materials, application of, 3-118

Causes of underground corrosion, NBS investigations of, 1-107

Caustic embrittlement, iron and

steel, 455t Cavitation attack, erosion of ma-

terials by, 269t

Cells, corrosion, peculiarities of, 76t

Cement mortar, steel pipe sewer outfall in ocean coated with.

Cement ratio to water, variation of for reinforced steel, 382t

Central point anode system in coated pipe, 417t Centrifuging of fuel reduces oil

ash corrosion, 5-126 Ceramic coatings vs fuel oil ash corrosion, 601t

#### C-Continued

Ceramic materials, wood and glass, annual purchases of by indus-tries, 121t

Ceramic-ware vs chlorine mixtures,

Ceramics, special corrosion resistant refractories, 10-92

". valve trim. 4-95

Characteristics of reactive coatings, 508t

Chemical and process industry, numps for, 473t

Chemical cleaning, safety in, 17t

Chemical distilling column, accumulated residues attack, 11-99

Chemical industry, annual pur chase of corrosion resistant materials by, 121t

" " cathodic protection of process equipment in, 123t

Chemical injection, in flood water,

" ", in sour gas wells, 413t

Chemical manufacturing processes 200 and 300 series stainless steels in, 147t

Chemical milling, materials selection in, 8-105

Chemical plants, lead-acid brick systems in, 2-98

" ", paint testing program in, 503t

" ", titanium and zirconium resistance in, 341t

Chemical stability of metals, 455t Chemical treatment, water flooding, 12-99

Chemical treatment of filled cans, 11-100

Chloride ions in pitting of metals, 25t

Chloride ions, aluminum alloy behavior in presence of, 63t

Chloride stress corrosion cracking, stainless steel, 69t, 450t

#### CHLORIDES

Aluminum aircraft cooler vs. 395t Austenitic stainless steel, stress cracking in, 373t

Heat exchanger tubing exposed to 6-99

Heat exchangers vs. 9-103 Sour water strippers vs. 358t

Stainless steel tank vs. 547t

Stainless steels (200 and 300 series) vs, 147t Steel-reinforced concrete vs. 382t

Uranium refining corrosion associated with, 168t Chlorimet 3, chemical plant expos-

ures vs, 341t Chlorinated polyether, properties of,

11-108

Chlorinated rubber mastic for offshore structures, 5-131

Chlorinated rubber over wash prim-Chlorinated rubber, properties of,

12-93 Chlorine, hot, silicon carbide vs,

10-92 ", titanium and zirconium vs. 341t Chlorine mixtures, materials used

to handle, 355t Chloroprene rubber modified, on transformers, 1-111

Chlorosulphonated polyethylene, underground pipe coatings of, 7-101

" ", pump linings of, 473t° Chromate type inhibitors, 469t

#### C-Continued

CHROMATES

Aluminum cooling towers inhib-ited with, 20t

Cooling waters inhibited with,

Inhibiting effect of on aluminum,

Inhibition with, 455t

Pitting attack inhibited with, 269t

Reactive coatings based on, 508t Chrome magnesia, high tempera-tures vs. 10-92

Chromic phosphate in PVB forms wash primers, 311t

Chromizing alloys vs oil ash corro-sion, 601t

Chromium, oxidation of in nickel alloys, 194t

Chromium alloying of steel, 526t Chromium carbides, stainless steel (Types 316 and 316L) affected

by, 213t, 221t Chromium enrichment in metal-oxide interface on stainless steel, 613t

Chromium-nickel alloys, high temperature vs, 619t

Chromium-nickel steels, high tem-perature oxidation of, 141t

Citrates enhance corrosion of alu-

Clad material, Type 316 ELC, 547t Clad plate, size and thickness of,

lad platinum anodes for ships,

Cladding, new bonding process in,

Cladding materials, new types of available, 10-88

Classification of topics relating to corrosion, 254t

Clay-bonded silicon carbide liners, 10-92 Cleaning, chemical, HC1 vs stain-

less steel, 69t Cleaning, lag time of tin-plate steel

influenced by, 135t Climatic conditions, metals testing related to, 631t

Cleaning techniques for steel to be painted, 428t

Coal tar and asphalt coatings, glass fiber reinforcement of, 4-102

#### COAL TAR

Enamel for steel pipe in ocean, 363t

Epoxies, underground corrosion of pipe reduced with, 7-101

Linings for water tanks, 12-99 Systems in tropical sea water, 291t

Underground corrosion reduced with, 7-101 Wrap, offshore drilling structures

coated with, 5-131 Coal-to-oil synthesis plant, corrosion in, 627t

COATINGS Aerial pipe line crossing, problems in, 3-118

Aluminum box for sea water exposure, 403t

Annual purchases of by industries, 121t

Baked phenolic, 1-107 Baked phenolic-epoxy, on oil wells, 49t

Bituminous, underground tests on,

Carbonated beverage can interior,

#### -Continued

COATINGS (Continued)

Cement-mortar on steel pipe in ocean, 363t

Chemical resistant, testing of,

Chlorinated polyether, properties of, 11-108

Coal tar enamel with fiber glass reinforcing, 368t Concrete reinforced with steel,

Design factors on structures im-prove efficiency of, 6-102 Economics of paint test program,

Enamel, underground corrosion tests on, 1-107

Epoxy-phenolic for steel pipe, 275t

Fuel oil ash corrosion attack re-duced by, 601t

Galvanized on buried iron and steel, 1-107

Glass fiber reinforcement of, 4-102

Gunite on sour water strippers,

High pressure products pipe line, 12-104

Hot spray, Saran, shipyard ap-plication of, 3-116

Maintenance of in chemical mill-ing process, 8-105

Metallic, mild steel sterilizers tested having, 202t ", steel in industrial and marine atmospheres, 3-113

aqueous

". zinc and aluminum, ac hydrogen sulfide vs, 189t Offshore drilling structure, 5-131

Oil-modified phenolic, transformers using, 1-111

Organic, for oil and gas well tub-ing, 5-121

". in tropical environments, 291t

", polyethylene v vs acids, alkalies

Plastics and synthetic elastomers for underground coatings, 7-101

Plastics for high pressure gas well tubing, 73t

Polyethylene jackets for steel pipe, 6-100

Polyurethane, properties of, 12-93 Polyvinylchloride plastisols, 8-107

Power generating plant equip-ment, 6-95

Power plant, 7-107

Pulp and paper plant, 488t

Reactive, characteristics of, 508t

Resistances of on pipe lines in high resistivity soils, 497t

Rubber, underg tests on, 1-107 underground corrosion

Ship bottom, 315t

Ship hull, 483t, 587t

Sprayed, 12-106

Sprayed zinc in marine environ-ments, 409t

Steam-resistant for carbon steel hespital ware, 202t

Steel pipe interior for carrying sea water, 417t

Synthetic rubber and vinyl, 643t Tank ship internal structure, 557t

Thick-film, 642t

", synthetic, oil refinery, 171t

Tin coated plate, 11-100

Underground steel pipe, cost of,

#### C-Continued

COATINGS (Continued)

Underwater metal for fresh water exposure, 335t

Urethane, 4-100

Water storage tank, 12-99

Coatings engineers, role of in power plant designing, 7-107

Coatings plus cathodic protection, potential profiles of, 576t

Cobalt, titanium coupled with in HC1, 566t

Cobalt-base alloys, Stellite 25 vs molten boron oxide at 1957F, 85t Coding of corrosion information, 251t, 254t

Coils, carbon steel, in nickel re-fining, 547t

Columbium, nickel chromium alloys containing, 194t

Completion methods on sour gas wells, 413t

Completion practices in high pres-sure gas wells, 73t

Composite coatings for offshore drilling structures, 5-131

Compounding, polyethylene coatings modified by, 117t

Compression of sour gases, 413t

Concrete, leaching of, 547t Concrete, steel reinforced, 331t

", sulfur dioxide fumes vs. 113t

Concrete flooring, epoxies for, 12-106 Concrete liners at source wells.

Concrete pipe in power plants, 6-95 Concrete reinforced with steel, 382t

Condensate, sour gas, 413t

ondensate system, utility p filming amines used in, 8-99

Condenser tube corrosion, 6-95

Condenser tubes, steel, water con-taminated with hydrogen sulfide vs. 189t

", stress corrosion cracking of,

Conductor pipe, steel, offshore plat-form, 8-103

Conduit systems, telephone cable, 9-116

Contactor shells, HF vs. 237t Conversion system, hydrocarbon,

ooling system, glycol-water, alu-minum alloy in, 395t minesweeper, metals selection

for, 403t " ", nuclear fuel element jacketing of, 83t

Cooling towers, aluminum, treat-ment of, 21t

polyvalent ion - polyphosphate inhibitors in, 97t

", thick-film synthetic coatings

Cooling water, 233t, 413t, 417t, 547t,

#### COPPER

Anti-freezes vs, 607t

Atmospheric corrosion of, 529t

Canned goods containing, 11-100 Corrosion of in India, 631t

Corrosion products identified on,

Deposits of on aluminum air-craft cooler, 395t

Filming amines used to protect in condensate cycle, 8-99

High temperature gases vs, 622t

Steels containing for atmospheric exposure, 533t

Sulfides vs, 529t

Sweet corrosion cracking of, 437t Titanium coupled with in HC1,

#### -Continued

Copper alloying of steel, 526t

Copper alloys, soils vs. 1-107

stre corrosion cracking of, 101t. 433t

Copper containing compounds vs marine borers, 45t

Copper evaporator tubes, failure of in starch production service, 113t

Copper heating coils in zinc ch ride concentrating tanks, 123t

Copper ion displacement test, in-hibitor rating by, 554t Copper removal in nickel refining, 547t

Copper tubing, water tower, 492t

Corn wet milling industry, corrosion in, 113t

Corrosion fatigue, 262t, 455t

Corrosion product films on alumi-num, 7t, 9t

Corrosion products on copper alloys, identification of, 199t

Corrosivity of soil, 77t

Couples, titanium-foreign metals in HC1, 566t

Crack growth behavior of modified Type 422 steel, 399t

Crack initiation, mechanism of austenitic stainless steels in chlo-rides, 373t

", propagation and fracture in high strength steels, 207t

Crack propagation pattern, stresse austenitic stainless steel in chio rides, 373t

Cracking, notch specimens of high strength steels, 207t

", reinforced concrete in marine atmospheres, 382t

transgranular, austenitic less steels in chlorides, 69t

", tube sheets, 6-99

reep data fo ether, 11-108 for chlorinated poly-

Creosoting of wood to marine borer attack, 45t reduce

revice corrosion, Type 316 less steel in starch, 113t 316 stain-

revices, elimination of in design-ing industrial structures, 6-102 Cravices

Anode design for ships, 596t

Cathodic protection, cement mor-tar coated steel pipe in ocean, 363t

", pipe lines in high resistivity soils, 497t

" ", process equipment, 123t

" ", ships, 581t

, steel pipe water, 417t carrying sea

steel pipe in sea water, 483t

Crude and refined petroleum prod-ucts industry, annual purchase of corrosion resistant materials by,

Crude petroleum and natural gas production industry, annual pur-chase of corrosion resistant ma-terials by, 121t

Crystalline structures of corrosion product films on aluminum, 7t

Crystallization of barrier films in air on aluminum, 9t

Cupro nickel (70-30), stress corro-sion cracking, 433t Curing of cement for reinforcing steel, 382t

#### C-Continued

Current measurement, underground corrosion, 571t

Current shields, polychloroprene, on ships, 581t

Cyanides in chemical cleaning. dangers from, 17t

Cycling oxidation and reduction,

#### D

corrosion, classification of, 254t

", photoelectric selector for, 251t

DC technique, ship bottom coatings evaluated by, 315t

Debutanizer systems, HF vs. 237t

Delayed failure of high strength steels, 207t

Depropanizer system, HF vs, 237t

Cathodic

Coating efficiency on structures in connection with, 6-102

Heat exchanger tubing, 6-99

Offshore drilling platforms, 6-102

Power plant, role of coatings en-gineers in, 7-107

Pump, 473t

Refinery isomerization unit, nickel alloy lining for, 8-109

Streamlining reduces cavitation attack, 269t

Tank truck reinforcement, 2-94 Design factors in chloride stress corrosion of austenitic steel, 69t

Design problems, in high pressure gas well installation, 73t

", in nickel-cobalt extraction plant, 4-95

Dew point, depressing of in Diesel engine fuel, 5-126

Dezincification of brass, 455t Diaphragm type pumps, 473t

Diesel engines, oil ash corrosion of, 5-126

Diesel fuel, oil ash corrosion prob-lems of, 601t, 5-126

Die casting alloys in detergent so-lutions, 327t

Diethylenetriamine as a hydrogen sulfide inhibitor, 303t

Differential aeration, metal surface in soil, 77t

Dip coating of polyvinylchloride plastisols, 8-107

Dispersants, inhibitor, fiue gas used as, 241t Dissolution and passivation of haf-nium-free zirconium in HF. 286t

Dehydration of sour gases in proc-essing plants, 413t

Dehydrogenation process, butane, 619t

Denison method, soil corrosivity measured by, 77t

athodic protection system for pipe lines, 497t

Heat exchangers, 9-103

Platinum anodes for ships, 596t

Sour gas plant, 413t

Detergent solutions, die casting alloys in, 327t

Detinning, internal, 11-100

Diamine, cyclic, preparation of,

Dichromate sealer, 508t

Diethanolamine, hydrogen sulfide stripped from solutions of, 358t

Differential aeration corrosion in underground telephone cables, 9-116

Dimensional stability of chlorinated polyether, 11-108

Dry Duc p

Dece

Disti

po

by Dra

Dril

5-

Dru

Docl

Duc Duc 6

Du

Du Dy Dy

Dy

Du

EC

. 15

on

ing.

ion.

of.

ngs

7t

oc-

ine.

gth

vity

71

for

102

Gt

en-

kel

lon

ess 59t

ire

on

al-

sel

of,

of,

b-

de

en

in

20

ed

le

d

#### -Continued

Distilling column, chemical, residues vs, 11-99

K alloy (aluminum), electrode potential behavior of in buffer solutions, 63t

Docks and piers, boring organisms vs. 45t

Dolomite, oil ash corrosion reduced by addition of, 601t

Drainage, atmospheric corrosion testing, 533t

Drilling mud (high pH), organic coating for tubing tested in, 5-121

Drums, propane, lining of, 171t

Drydock variables affect ship bottom coatings, 315t

Duct anodes, graphite, 646t

Duct anodes, underground cables protected with, 423t

Ductility, transverse, relationship of to failure of oil well tubing strings, 49t

Ductwork, polyester fiber glass for, 635t

Duomeen 12 D as a hydrogen sul-fide inhibitor, 303t

Duplex corrosion films on oxidized aluminum, 9t

Duralumin, atmospheric corrosion of. 533t

electrode potential behavior of in phosphoric acid and buffer solution, 63t

Duranickel bolting, HF vs. 237t

Duriron, high temperature vs. 619t

Dust, red oxide, in dehydrogena-tion process, 619t

Dye, Azo, effect of on corrosiveness of soft drinks, 11-100

Dves, ozone vs. 541t

Dynamic aqueous systems, hydro-gen effusion measures corrosion gen effusion rate in, 179t

#### E

#### ECONOMICS

nnual purchases of corrosion resistant materials by indus-tries, 121t

Anode installations for destroyers,

Boiler fouling and corrosion, 5-

126 Cathodic protection of process equipment, 123t

Coatings and linings, 10-85

Coatings for underground pipes, 7-101

Engineering approach to a paint testing program, 503t

lass fiber rei coatings, 4-102 reinforcement for

High pressure gas well comple-tion methods, 73t

Industrial roofing replacement vs maintenance, 513t

Internal cathodic protection of pipes carrying sea water, 417t

Membrane linings for brick, 2-98

Nickel alloy lining in refinery is-omerization units, 8-109

Plastic reinforcement of tank trucks, 2-94

Pulp plant coating program, 488t Reconditioning and coating underground steel pipe, 279t

Saran coating by hot spray, 3-116

Tank ship corrosion, 557t

Titanium and stainless steel pumps, 473t

#### -Continued

Elastomers, air poliutants vs. 541t synthetic, underground coatings of. 7-101

Electric drain of stray currents,

Electric furnace Mullite, high tem-perature vs, 10-92

Electric light and power industry, annual purchase of corrosion re-sistant materials by, 121t

Electric utility plant, filming amin-used in condensate system of 8-99

Electric-weld tubing, use of in oil wells, 49t

#### ELECTRICAL

Bonding of cathodically protected to unprotected ships, 587t

Characteristics of aluminum oxide films, 283t

Circuit analogy, 576t

Generating plants, 6-95

Electrical resistance method, anti-freeze inhibitors studied with, 607t

". die casting alloy corrosion in detergent solutions measured by,

"", flood water corrosion in-hibitors rated by, 7-97

", use of to measure corrosion,

#### ELECTROCHEMICAL

Aspects of pitting corrosion, 25t Behavior of passive metals, 369t

Control in pitting corrosion of stainless steels, 25t

Method, soil corrosivity measured by, 77t

Reactions in aqueous hydrogen sulfide corrosion of steel, 189t

Study of aluminum and its alloys, 62t Study corrosion in

udy of pitting corrosistainless steels, 32t, 39t Theory of iron corrosion, 526t

Electrode kinetics in inhibitor study,

Electrodes, calomel, offshore struc-ture use of, 12-106

". reference, 576t

", ", on ships, 581t

", ", underground corrosion meas-urements involving, 571t

Electrolytic method, soil corrosivity measured by, 77t

Electron microscopy used to study corrosion product films on alu-minum, 7t

Enamel lifting from cans, 11-100

Enamels, synthetic, tropical marine atmospheres vs. 291t

Energies and entropies of activa-tion compared in aluminum corro-sion, 13t

Engineering approach to a paint testing program, 503t

Epoxies, catalyzed, caulking materials of, 3-118

', concrete floors protected with, 12-106

", modified, steam resistance of, 202t

", tropical environments vs, 291t Epoxy, amine cured, testing of for oil well tubing coating, 5-121

", catalyst cured, refinery applica-tion of, 171t

", properties of, 12-93

Epoxy coatings, catalyzed, offshore drilling structure use of, 5-131

Epoxy liner, field joints of steel pipe in ocean used with, 363t

#### -Continued

Epoxy modified phenolics, catalyzed, 6421

" ", refinery applications of, 171t " ", testing of for oil well tub-ing coating, 5-121

Epoxy resins, suitability of for reducing underground corrosion, 7-101

Epoxy-phenolic coating, starch production equipment protected with, 113t

" ", steel pipe protected with, 275t

Equivalent electrical circuit analogy of structure-to-soil potentials, 576t

Erosion of materials by cavitation attack, 269t

Erosion-corrosion, turbines in elec-tric utility plants vs, 8-99

Esters, stainless steels with, 147t Etchants in chemical milling process, 8-105

Ethylene diamine, brass in glycol-water solution inhibited with 607t

Ethylene glycol vs mild steel, 607t Evacuation system. HF vs. 237t

Evaluating inhibitors from cathodic polarization measurements, 517t

Evaluating the economy of recondi and coating underground steel pipe, 279t

Evaluation of organic nitrogen com-pounds as inhibitors, 128t

Evaluation of inhibitors inside pipe lines, 131t

Evaluation of steam resistant coatings for carbon steel hospital ware, 202t

Evaluation program, chemical re-sistant coatings and linings, 10-85 Exhaust fumes, lead-acid brick vs.

Extraction of nickel by Moa Bay process, 4-95

Fabrication, clad plate, 10-88

Fabrication procedure, nickel alloy lining for refinery isomerization unit, 8-109

Factors influencing corrosion, 455t Factors influencing rate-of-pickling test on tin-plate steel, 135t

tigue, corrosion, i emperature on, 262t influence of Fatigue.

Fatigue curves, static, high strength steel, 207t

Fence, galvanized, marine atmos-phere vs, 6-95

Ferric ion concentration, tendencies steels, 32t of with stainless

Ferric oxide rust on cans. 11-100

Ferrocyanide ion addition to poly-phosphate for cooling tower water inhibition, 97t

'errous metals, atmosphere vs,

" ", soils vs, 1-107

tion, 7-97

Ferrous oxide, hydrogen embrittle-ment in presence of, 591t

Fiber glass, polyester, 635t

Fiber types, glass, comparison of, 4-102

Field measurements of sub-surface aluminum corrosion, 9-114 Field method to screen inhibitors for water flood corrosion preven-

Film, corrosion information re-corded on for quick sorting, 251t

#### -Continued

Film persistence, inhibitor, 554t

Filming amines control corrosion in utility plant condensate system,

#### FILMS

Aluminum oxide, 283t, 643t

Corrosion product, role of in uni-form aqueous corrosion of alu-minum, 9t

" ", on aluminum in high purity water, 7t

Oxide, on iron, 526t

", on stainless steels at high temperatures, 613t

Protective, phenomena on steels, 526t

Thin, on stainless steel, 613t

Zirconium in HC1 forms various types of, 103t

Zirconium oxide, protective prop-erties of in HC1, 103t

Filters, carbon steel, for nickel refining, 547t

", pipe line, 131t

Finish, rubber base, for protecting transformers, 1-111

Fireclay, high temperatures vs. 10-92

ish oil, coatings of on offshore drilling structures, 5-131

Fitting anodes on ships, 581t Flame cleaning of bubble caps, 11-99

Flexible metal results from corro-sion of Type 316 valve seat rings, 1t

Flood waters, 12-99

Flotation, inhibition in tankers and storage tanks, 241t

Flue gas, effect of additives on in boilers, 5-126

Fluorides, uranium refining equip-ment vs. 168t

" (alkali), passivation of hafnium-free zirconium in HF after addi-tion of, 286t

Fluorine, polymers containing, pipe protected with, 7-101

Fluoro chloro hydrocarbon, proper-ties of, 11-108 Fluozirconates, solubilities of, 286t

Fogging, inhibitors in tankers and storage tanks, 241t

Food packing, can corrosion prob-lems in, 11-100 Food processing, corn wet industry vs corrosion, 112t milling

" ", tin plate as containers in, 135t

Food product corrosivity to cans, testing of, 11-100 Foreign metal ions, titanium in boil-ing HC1 affected by presence of,

566t Formulations of urethane coatings,

Formvar, steam resistance of, 202t

Fouling, boiler, 5-126 ", reduction of on aluminum with copper-base paints, 403t

corrosion on high strength steels, 399t Fracture, mechanical and

Fruit canning, cutter blade sharp-ened by corrosion in, 6-100

Fuel oil ash, synthetic, Type 310 stainless steel vs. 443t Fuel oils, residual, oil ash corro-

sion from, 601t Fume scrubber, polyester fiber glass,

Furnace linings, 10-92

Fused-cast refractories. 10-92

G

Galvanic corrosion, a craft oil cooler, 395t aluminum air-

Galvanic couple test, 533t

Galvanic current in beverage cans, 477t in carbonated

Galvanic experiments made to test suitability of steel weldments for parent metals, 2t

Atmosphere of, lag time on tinplate steel affected by, 135t

Feed and effluent, metals vs, 627t

Methane-oxygen combustion, metals vs, 622t

Sniff (chlorine), materials used for handling, 355t Transmission line, reco and coating of, 279t reconditioning

Utilities industry, annual pur-chase of corrosion resistant materials by, 121t

Wet and dry, inhibitors fogged with, 241t

Gases, cell (chlorine), used for handling, 355t materials

", high temperature, refractories for handling, 10-92

Gaskets, chlorine mixtures vs ma-terials used in, 355t

Gasoline, inhibitors used in, 158t

Gathering system for sour gas, design of, 413t

Generator, gas, 622t

Generators, steam, stress corrosion cracking of, 450t

Girbotol unit, steel equipment in corrodes, 189t

Glass, hydrogen fluoride vs. 541t

", plate, impingement tests on, 10-92

fused-cast refractory use ", tank, fu of, 10-92

Glass-lined steel vs chlorine mix-tures, 355t

Glass fiber reinforcement for coatings, 4-102

Glass probe method of testing coat-ings, 12-93

Glycol solutions in sour gas proc-

essing, 413t Glycol-water cooling system, alu-minum alloy in, 395t

Gold, titanium coupled with in HCl,

Gradient cell, use of, 644t

Gradient test cell, cathodic lead cable requirements for sheath defined with, 389t

Grain boundary segregation in alu-minum bronze alloys, 295t

Graphite anodes for ships, 581t

Graphitic embrittlement of nickel tubing at high temperatures, 1-112

Gravel surfacing in industrial roofing, 513t

Greases, suitability of for alumi-num-frame minesweepers, 403t

Green salt process in uranium re-fining, 168t

Grit blasting, steel prepared for painting by, 428t

Grooving, HF alkylation units, 237t

Gunite, offshore drilling structures coated with, 5-131

ur water strippers coated with,

Gypsum moulding plaster backfill,

Hafnium, zirconium corrosion in HCl not affected by presence of, 103t

H-Continued

afnium-free zirconium, rate of dissolution and passivation of in HF. 286t

Halides, pitting corrosion influenced by presence of, 25t

Harbor corrosion problems, marine borers vs wood, 45t

Hardness, effect of on accelerated testing of chromium steels, 269t ". relation of to sulfide stress cor-rosion cracking of steel, 437t

fardness testing, oil well tubing evaluated by, 49t

Hastelloy A and B, HCl vs butane isomerization units, 85t

Hastelloy C, chemical plant ex-posures vs. 341t

Heat effects in steel weldment related to failure, 2t

Heat exchanger, design of, 9-103 " ", nickel tube shell components fail in, 1-112

" ", nitric acid vs tubing of, 6-99

" ", tubing for, 6-95, 6-99 Heat flux conditions. determ corrosion rates under, 257t determining

Heat recovery problems in nickel extraction plant, 4-95

Heat-resistant alloys for use with residual fuels, 601t

Heat-shock resistance of refrac-tories, 10-92

HEAT TREATMENT

Aluminum-magnesium alloys, 337t Nickel tubing from heat exchang-ers, 1-112

Stainless steel (Types 316 and 316L), 221t

Stainless steel (200 and 300 series), 147t

Steel alloys against sulfide cor-rosion cracking, 437t

Valve seat ring (Type 316 SS) for water treating system, 1t

Heating, metallurgical structures of wrought aluminum-magnesium al-loys affected by, 55t

Heterocyclic nitrogen compounds as corrosion inhibitors, 128t

High film-build alkyds, application

High flow velocity loop, use of in dynamic aqueous systems, 179t

High pressure gas wells, well com-pletion practices in, 73t

High pressure products pipe lin cathodic protection of, 12-104

High resistivity soil, magnesium anodes in, 497t

High strength steels, delayed failure of, 207t

High temperature (See Temperature, high)

High velocity loop, water stream in, 183t

Hoods, polyester, fiber glass, 635t

Hospital ware, carbon steel, steam resistant coatings for, 202t

Hot spray coatings, Saran applied in shipyards, 3-116

lot spray vinyl coatings in re-finery, 171t

Hot vinyl prime, 642t

Humidity, critical, for steel, 526t

", ", principle of, 529t

Humidity bath test of coatings,

Hydrocarbon conversion system,

H-Continued

HYDROGEN Absorption of by steel during pickling, 135t

Atmospheres containing vs metals, 627t

Attack by in HF alkylation units,

Content of in tin plate steel in-fluences lag time, 135t

High strength steels, concentra-tion of in, 207t Hydrogen sulfide determination in,

Stress corrosion cracking affected

by, 9-103 ydrogen dislocation and corrosion cracking, 9-103 and stress

Hydrogen effusion in dynamic aqueous systems, corrosion rate measurement by, 179t

HYDROGEN EMBRITTLEMENT

Bend test of for acetylenic al-cohol concentration, 275t

Cathodically protected steel, 591t High strength steel, 207t, 399t

Oil well tubing subjected to, 49t Tubing steel, oil country, 437t

Hydrogen evolution from Hf-free Zr in HF, 286t Hydrogen fluoride, air pollution from, 541t

" ", glass vs, 541t

Hydrogen fluoride in HF alkylation units, 237t

Hydrogen peroxide vs iron, 526t

HYDROGEN SULFIDE

Air pollution from, 541t

Aqueous, refinery equipment vs.

Cooling water in sour gas proc-essing, presence of in, 413t

Disposal of in refineries after water stripping, 358t

Iso-corrosion rate curves for at high temperatures, 125t

Nickel vs. 529t Oil well tubing subjected to, 49t

Screening of inhibitors to reduce,

Water flooding problems compli-cated by, 307t Hydrogen sulfide-brine systems

stress corrosion cracking in, 437t Hydrogen sulfide-oil-brine mixtures vs steel, 299t, 303t

Hydrogen sulfide-water mixtures, organic coatings tested in, 5-121 Hydrogen swells in cans. 11-100

Hydrometallurgical refining of nickel, 547t

Hyperion ocean outfall, corrosion protection of, 363t Hypochlorite, titanium and zircon-ium resistance to, 341t

Identification of corrosion products on copper and its alloys, 199t

Impedance characteristics of iso-lated aluminum oxide films, 283t Imperfection theory of pitting cor-

rosion, 25t Impressed current, naval vessels protected with, 2-87

" ", steel pipe sewer outfall in ocean protected with, 363t

"", use of in study of pitting corrosion, 25t Impingement tests on non-metallics,

I-Continued

INCONEL

Chemical plant exposures vs. 341t Cladding, welding of, 10-88 High temperature vs. 619t High temperature gases vs. 622t Oil ash corrosion vs, 601t

Resistance of in hydrofluorination reactor, 168t Index, numerical, abstract punch card, 254t

India, metals testing in, 631t Indicators, use of in pitting cor-rosion studies, 25t

Indium, titanium coupled with in HCl, 566t

Industrial atmospheres, metals in,

" ", non-ferrous metals vs, 529t

" ", steel vs, 526t " ", tin alloys in, 3-113

Industrial corrosives, polyesters vs, 635t

Industrial roof construction, 513t Influence of temperature on corrosion fatigue, 262t

Information selector, photoelectric,

Inhibiting effects of phosphate on aluminum, 7t

Inhibition of pitting corrosion on stainless steels, nitrates affect, 32t

Inhibition of pitting corrosion with nitrates, 25t

INHIBITORS

Aluminum alloy corrosion in gly-col-water reduced by, 395t

Amines (filming) used on carbon steel sour water stripper com-ponents, 358t

Anodic and cathodic, 455t

Automobile anti-freeze, 607t

Carbon tetrachloride-water vapor atmospheres, 447t

Chromates to reduce cavitation attack, 269t

oncrete reinforced with steel, suitability for, 382t Concrete

Cooling water, 233t

Evaluation from cathodic polarization measurements, 517t

Filming amines in utility plant condensate systems, 8-99

Fogging or flotation with, in tankers and storage tanks, 241t

High pressure gas wells treated with, 73t

Hydrogen sulfide attack of steel reduced with, 299t, 303t Inside a products pipe line, 131t

Oil soluble, 241t Oil soluble for petroleum prod-ucts pipe lines, 158t

Organic, colloid, 455t

Pickling operation, 275t

", nitrogen compound, 128t ", in petroleum refining industry, 321t

Polyvalent ion-polyphosphate cooling to ments, 97t tower system treat-

Recirculating cooling waters sys-tems treated with, 20t

Screening of for oil field equip-ment, 303t Secondary recovery, evaluation of, 307t

Sour gas well corrosivity reduced with, 413t Sour naphtha lines, use on, 189t Stress corrosion cracking, 450t

Tank ship, 557t Water dispersable, for tankers, 241t

Water flood, 12-99

Wa XO Inhib Inhib ica Inhib

Dece

INHI

Initia tin Injec Injec Injec Inorg ma

Insta

INST Al Cl DO

Po

Sh

So

U U Insu st

INT A E

Inte

Inte D .. .. Inte

n

Inte

ion: IR

Iric IRO

1. 15

341t

622t

tion

cor-

in

t

VS.

cor-

rie,

on

on

ect,

ith

gly-

por

ion

eel.

ri-

int

41t

ted

eel

31#

d-

s-

on

ed 9t

t

#### -Continued

INHIBITORS (Continued)

Water flood corrosion, screening of, 7-97

Water soluble (sodium nitrite) for pipe lines, 158t

XON-4, action of, 469t

Inhibitor film persistence, 554t

Inhibitors for acids used in chemical cleaning, 17t

Inhibitor squeeze process, 554t

Initiation and growth during pit-ting corrosion, theory of, 25t

Injection water, oil well, 12-99

Injection well tubing string, 413t

Injection wells, 12-99

Inorganic zinc silicate plus vinyl mastic system protects offshore drilling structures, 5-131

Installation of anodes on offshore structures, 9-112

#### INSTRUMENTS

Aluminum sub-surface corrosion measuring, 9-114

Classical potentiostat for study of passivity, 369t

DC corrosion meters with varis-tors to measure potentials in stray current areas, 68t

Potential measuring device for pipe carrying sea water, 417t

Ship hull potential measuring, 587t

Soil corrosivity measuring device for field conditions, 77t

Ultrasonic for tank ship cor-rosion loss measurements, 561t Underground corrosion measure-

Insulating materials, chloride stress corrosion cracking of austenitic stainless steel, 69t

Insulation, deterioration on for duct anodes, 423t

Interaction in analysis of variance,

### INTERGRANULAR CORROSION

Aluminum-magnesium alloys at service temperatures, 55t

Effect of sigma phase vs chro-mium carbides in Type 316 and 316L stainless steel, 221t

Stainless stee 316L), 213t steel (Type 316 and

" ", (200 and 300 series), 147t

Type 302 stainless steel vessels in sulfuric-organic acid, 123t

Valve seat ring, Type 316 SS, in water treating system, 1t

Intergranular penetration corrosion of aluminum, 9t

Internal cathodic protection of pipes carrying sea water, 417t

Internal corrosion, inhibitors inside a products pipe line, 131t

" ", products pipe lines, 158t

" ", tank ships, 557t

Internal oxidation of nickel chro-mium alloys, 194t

Ion exchange theory of pitting cor-rosion, 25t

lons and molecules of Type XON-4 as inhibitors, 469t

Ions in aqueous solution affecting uniform corrosion of aluminum, 9t

IR drop method on ships, 587t

Iridium, titanium coupled with in HCl, 566t

### IRON

Alloys containing vs molten boron

Atmospheric corrosion of, 526t

### -Continued

IRON (Continued)

ast, buried specimens of vs soils, 1-107

", chlorine mixtures vs, 355t

", erosion resistance of, 269t

", molten salt vs. 257t

Condensate cycle corrosion of, 8-99

Hydrogen sulfide vs with respect to pH, 189t

Inhibitors of Type XON-4 for, 469t Nickel chromium alloys contain-ing, 194t

Pure, HCl vs, 517

Soft, corrosion fatigue of in sea water, 455t

Stress corrosion cracking sus-ceptibility of aluminum bronze alloys affected by content of, 295t 295t

Titanium coupled with in HCl,

Zirconium corrosion in HCl af-fected by content of, 103t

Iron-containing rolled zinc, marine environments vs, 409t

on content analysis, corrosion inhibitor efficiency in high pres-sure gas wells evaluated through,

Iron in source water, 12-99

Iron phosphatizing, 508t

Iron pick up in carbonated bever age cans, 477t

Iso-corrosion rate curves for high temperature hydrogen-hydrogen sulfide, 125t

Isobutane fractionating system, HF

Isomerization units, butane, mini-mum corrosion for, 185t

" ", nickel alloy lining for, 8-109

J-55, oil well tubing composed of.

, stress corrosion cracking tests on, 437t

Jackets, polyethylene, for steel pipe, 6-100

Joints, field, on steel pipe in ocean,

#### K

Kel-F, steam resistance of, 202t Kerosene, inhibitor evaluation in-volving use of, 517t

Kinetic constants for oxidation of aluminum, 13t

Kinetic data in terms of oxidation mechanism on aluminum, 13t

Kinetics of aqueous aluminum cor-rosion, 13t

K-Monel vs HF, 237t

Kyanite, converted, high tempera-tures vs, 10-92

#### L

abor force, efficiency of in pulp plant costing program, 488t

and materials costs in conditioning underground steel pipe, 279t

Laboratory methods, determining corrosion rates under heat flux conditions, 257t

", identifying corrosion products on copper, 199t

Laboratory tests for intergranular corrosion of austenitic stainless steels. 213t

#### L-Continued

Lag time test for tin-plate steel, 135t

Laminates, polyester fiber glass, physical properties of, 635t

Leaching of chlorides onto metal surfaces, 69t

Leaching, nickel refining by, 547t Leaching system in nickel extrac-tion plant, 4-95

Cable sheaths, cathodic protec-tion of, 389t, 423t, 644t, 9-116

Electrode, field use of not rec-ommended on cable sheath, 389t

Linings, for nickel extraction plant equipment, 4-95

Pickled panels affected by pres-ence of, 275t

Soils vs in burial tests, 1-107 Titanium coupled with in HCl,

Lead-acid brick systems in chemi-cal plants, 2-98

Lead-silver alloy anodes for ships, 581t

Lead sheathed telephone cable, 9-116

Leather, sulfur dioxide vs. 541t Library, corrosion reference, 251t,

Light oil tanks, accelerated atmos-pheric corrosion of, 171t

Limnoria vs wood, 45t

#### LININGS

Exchanger tube, 627t

Furnace, 10-92

Miscellaneous, annual pof by industries, 121t purchases

Nickel alloy, in refinery isomeri-zation unit, 9-109

Plastic, for starch production service, 113t

Pump, 473t

Steel pipe, pretreatment prior to,

Tank, chemical resistant, 10-85 ", polyester, fiber glass, 635t Liners, clay-bonded silicon carbide,

Liquid phase fuming nitric acid vs carbon steel AISI 1020, 245t

Liquid phase butane isomerization, Literature, metals corrosion arti-cles recently published in COR-ROSION, abstracts of, 546t

Literature survey, sigma phase vs chromium carbides of intergran-ular corrosion of 316 and 316L stainless steel, 213t

Low temperature separation of sour gas, 413t

#### M

(aluminum), electrode behavior of in phos-M22 alloy potential phoric acid, 63t

Macro-cells in corroding reinforced concrete, role of, 382t

Macro-galvanic corrosion reinforced concrete bridge, 331t

Macro-and-micro-corrosion cells, corrosivity of soil related to for-mation of, 77t

#### MAGNESIUM

Aluminum alloyed with us temperature, 55t

Atmospheric corrosion of, 529t

#### M-Continued

MAGNESIUM (Continued)

Cathodic protection of pipe lines with, 497t

Milling system for, 8-105

Soluble anodes of, 643t

Stress corrosion cracking mech-anism in alloy of, 7-106

Magnesium anode/inhibitor spray system, tank ship, 557t

nesium-1% manganese alloy odes in NaCl electrolyte, 76t Magnesium - 1%

Magnesium sulfate, addition of to residual fuel oil, 601t Magnetic theory of pitting corrosion, 25t

Magnetostrictive test for cavitation

attack, 269t Maintenance, industrial roofing,

Maintenance coating program, pulp and paper plant, 488t

Maintenance program, power plant,

Management's role in pulp plant coating program, 488t

Management, paint testing program involving, 503t

Mandapam Camp, India, metals tested at, 631t

Manganese, effect of in low phos-phorous 0.3% copper steels, 533t

Manganese phosphatizing, 508t Manganese alloyed with magne-sium, anodes of exposed to NaCl electrolyte, 76t

Manholes, telephone, drainage of,

9-116 Marine atmospheres, metals in, 533t

", reinforcing steel in concrete in, 382t

" '', steel vs. 526t Marine boring organisms vs wood.

### MARINE ENVIRONMENT

Carbon steel in offshore platform,

8-103

" ", steel in sea water, 483t " ", vessels, naval, 2-87

Coatings, offshore drilling struc-ture, 5-131

", ship bottom, 315t

Electrical generating plants, 6-95 Internal corrosion of tank ships,

Lead-silver alloy anodes for ship cathodic protection, 581t

Non-ferrous metals in, 529t

Organic coatings tested for use in tropics, 291t

Pipe, cement mortar coated steel for sewer outfall vs, 363t Rubber-base paint used to pro-tect transformer in, 1-111

Steel in, 526t Steel reinforced concrete bridge vs, 331t

Tank ship corrosion loss meas-urement, 561t

Tin alloys in, 3-113 Wooden hulled aluminum-frame minesweepers, design of for, 403t

Zinc in, 409t Mask composition in chemical mill-ing, 9-105

Mastics, annual purchase of by in-dustries, 121t

Materials, pump, 473t Materials deterioration in polluted atmospheres, 541t

Materials of construction, nickel refining process, 547t

MATERIALS SELECTION

Automobile, 167t

Chemical milling process, 8-105

Minesweeper, 403t

Nickel-cobalt extraction plant,

Oll field tubing, 437t

Mean tide exposure of organic coatings in tropics, 291t

Measurement, ship hull potentials,

", tank ship corrosion losses, 561t

", underground corrosion, 571t

", underground electrical current,

easurement of anchor patte profile on grit blasted steel, 42

Mechanical fracture, distinguishing of from stress corrosion fracture.

Mechanical properties, oil well tubing, 49t

#### MECHANISM

Action of XON-4 inhibitors, 469t

Aluminum alloy corrosion from copper deposition, 395t

Aqueous aluminum corrosion, lation of to corrosion product film, 9t

"", by use of kinetic data,

Aqueous hydrogen sulfide corro-sion of steel, 189t

Atmospheric corrosion of non-ferrous metals, 529t

Carbon tetrachloride-water vapor vs mild steel, 447t

Carbonated beverage can corro sion, 477t

Cavitation attack, 269t

Chloride stress corrosion cracking of austenitic stainless steel, 69t

Corrosion fatigue of steels, 262t Ferrous metal corrosion in at-mosphere, 526t

Fuming nitric acid's role in cor-rosion of metals, 245t

Inhibitors, oil soluble, 158t

Magnesium alloy anodes dissolved in NaOl electrolyte, 76t

Molten boron oxide vs high tem-perature alloys, 85t

Oil ash corrosion, 601t

Oil ash mixtures (synthetic) vs Type 310 stainless steel, 443t Oxidation resistance of stainless steel from silicon, 613t

Passivation of hafnium-free zir-conjum in HF, 286t

Pitting corrosion of metals, 25t

Pitting corrosion of stainless steels, 39t

Reinforcing steel in concrete in marine atmospheres, 382t

Stress corrosion cracking, alpha aluminum bronze in ammonia and steam atmospheres, 295t

" ", AZ31 B magnesium, 7-106 "", steel, austenitic stainless, 373t, 9-103

Weldments, steel, corrosion of in NaCl, 2t

Zirconium, corrosion of in HCl,

Melaprene, transformers coated with, 1-111

Mercury, ammonium nitrate storage tanks contaminated with, 6-99

Metal treatment, steel reinforcing concrete in marine atmospheres, 382t

#### -Continued

Metal-alcohol coating, 275t Metal dusting, 619t, 622t, 627t

Metal finishing plating solutions, polyesters vs, 635t

Metals corrosion articles published recently in Corrosion, abstracts of. 546t

Metals, foreign, effect of on tita-nium corrosion in boiling HCl,

fetallic cations, inhibitive effect obtained by addition of to cooling tower systems, 97t Metallic

Metallic coatings vs fuel oil ash corrosion, 601t

Metallurgical factors, pitting corro-sion related to, 25t

Meters, DC corrosion, potential measurements with in stray current areas, 68t

Methane-oxygen combustion, attack on metals by synthesis gas from, 622t

Micro-chemical identification of cor-rosion products on copper, 199t

Mill scale, hydrogen embrittlement related to, 591t ", removal of from structures,

Milling, chemical, material selection in, 8-105

Mines, nickel, 547t

Minesweepers, aluminum used in, 403t

Minimum corrosion for butane isomerization units, 185t

Mixed-base alloys, Multimet N-155 vs molten boron oxide, 85t Moa

oa Bay Process, extraction of nickel by, 4-95 Modified disc-heat flux technique,

Moisture, lag time on tin-plate steel affected by, 135t

", scaling of steels affected by, 141t ", steel reinforced concrete bridge

Moisture penetration of concrete re-inforced with steel, 382t

Molding of chlorinated polyether, 11-108

Molten metals, refractories for, 10-92

#### MONEL

Atmospheric corrosion of, 533t

Cast, erosion resistance of, 269t Chemical plant exposures vs, 341t

High temperature gases vs, 622t HCl vs in butane isomerization units, 185t

HF vs. 237t

Sour water strippers of vs hydro-gen sulfide, 358t

Monel cable for magnesium anodes, 12-106

Monoethanolamine inhibits carbon tetrachloride attack of mild steel, 447t

torpholine, glycol-water solutions containing, 607t Morpholine,

Morpholine type inhibitor in sour gas processing system, 413t

Morpholines, N-substituted, effect of on inhibition, 128t

Moulds, casting of PVC in, 8-107 Mullite brick, electric furnace, high temperatures vs. 10-92

## N

N-80, oil well tubing composed of, 49t

stress corrosion cracking tests on, 437t

#### -Continued

N-substituted morpholines, effect of on inhibition, 128t

Naphtha, light crude, 189t

National Bureau of Standards 45-year summary of, 1-107

Naval vessels, cathodic protection of, 2-87

Neoprene, pipe for underground service coated with, 7-101

Atmospheric corrosion of, 529t,

Graphitically embrittled, recovery of, 1-112

High temperature gases vs. 622t HCl vs in butane isomerization units, 185t

Hydrometallurgical refining of,

Oil ash corrosion vs, 601t Titanium coupled with in HCl, 566t

Nickel alloy lining in refinery iso-merization units, 8-109 Nickel and nickel alloys, cladding

of. 10-88 Nickel and stress corrosion crack-ing, 9-103

NICKEL BASE ALLOYS

Hastelloy C for starch production service, 113t

Hastelloy R-235 vs molton boron oxide at 2052 F, 85t

Haynes Stellite No. 1 for corn oil processing equipment, 113t Inco 702 vs molten boron oxide, 85t

Inconel vs molten boron oxide, 85t Nimonic 75 oxide, 85t 75 vs molten boron

Nickel chromium alloys, internal oxidation of, 194t

Nickel-cobalt extraction plant, ma-terials in, 4-95

Nickel-copper alloys, atmospheric corrosion of, 533t Ni-Resist, Type 1, hydrochloric acid vs, 185t

Nitrate additions, pit activity on stainless steels after, 32t

Nitrate concentration at various chloride levels, inhibitors related to, 450t

Nitrates, effect of on soft drink corrosivity, 11-100

", pitting corrosion inhibited with,

Nitric acid recovery system, corro-sion of equipment in, 168t

Nitride-bonded silicon carbide shades, 10-92 HCl exposed to, 103t

Nitrogen compounds, organic, as inhibitors, 128t

Nitrogen dioxide, effect of on corro-sion of AISI 1020 by fuming ni-tric acid, 245t

Non-destructive testing, inspection methods used in high pressure gas wells, 73t

Non-destructive thickness measure-ments on tank ships, 561t

Non-ferrous metals, atmospheric corrosion of, 529t " ", cladding of, 10-88

Non-reactive wash primers, 311t Notch sensitivity, oil well tubing failure related to, 49t

Notch sensitivity effects in stress corrosion test on high strength steels, 399t

Notched specimens, stress corrosion cracking tests on, 437t

" ", high strength steel, testing of,

## -Continued

Nylon, properties of, 11-108 Nylon rope for anodes, 12-106

#### 0

Offshore drilling structures, coatings for, 5-131

Offshore platform, carbon steel in corrodes, 8-103 cathodic pro-

Offshore structures, catho tection anodes on, 9-112 electrodes to check potentials

on, 12-106 Oil additives, oil ash corrosion vs,

Oil and gas well tubing, organic coatings for, 5-121

Oil ash, synthetic fuel, Type 310 stainless steel vs, 443t

Oil ash corrosion, 443t, 601t, 5-126 Oil-brine-hydrogen suifide mixtures vs steel, 299t, 303t

l country tubular goods, stress corrosion cracking of, 437t Oil refinery applications of thick-

film synthetic coatings, 171t Oil soluble inhibitors for product pipe lines, 131t, 158t

Ore, nickel, corrosion problems involving, 4-95

", ", refining of, 547t

Ore refinery processing of uranium,

Organic coated beverage cans, 477t Organic coatings in tropical envi-ronments, 291t

Organic materials, polyethylene coating's resistance to, 117t

Organic nitrogen compounds as inhibitors, 128t

Organo-nitrile process vs Types 201, 202, 304 and 316 stainless steel, 147t

Organo-nitrogen compounds vs stainless steels (200 and 300 series), 147t

Organized studies, aluminum and aluminum alloys, electrochemistry of, 63t

Orthophosphate to reduce corrosity of cooling tower water, 97t Orthophosphates, cooling tems treated with, 20t cooling water sys-

Oscillographic method, aluminum in chlorides studied with, 63t

Outfall, ocean, corrosion protection of, 363t Oxidation, chromium-nickel steels at high temperatures, 141t

", high temperature, 622t ", internal, of nickel chromium alloys, 194t

", stainless steel at high tempera-tures, effect of silicon on, 613t

Oxidation process of aluminum in air and water, 13t Oxide films, air-formed, on tin plate steel, 135t

" ", on iron, 526t

", on stainless s temperatures, 613t steels at high

## Oxidizing agents, polyethylene coat-ing's chemical resistance to, 117t

OXYGEN Atmospheric, passivation by with XON-4 inhibitors, 469t

Carbonated beverage can corrosion related to, 477t

Condensate at electrical utility plant, content of related to corrosivity of, 8-99 Dissolved, flood water containing,

", underground cables vs, 9-116 Exclusion of in canning, 11-100

High temperature water systems affected by, 183t Influence of on corrosion, 455t

U Oxy Oxy

Dec

OXX

S

Oxy

Oxy

Pac Pac Pai Pai

PA

Pa

OXYGEN (Continued)

Soft drink corrosiveness related to, 11-100

Underground corrosion stimulated by, 1-107

kygen concentration, corrosion fatigue of steels related to, 262t Oxygen content, weldment corrosion rate related to, 2t

Oxygen diffusion rate in soil influences corrosivity of soil, 77t

Oxygen reduction in pitting corrosion, 25t

Oxygen scavengers, tests with on inhibitors, 450t

Ozone and photo-chemical smog. 541t

Pack-calorized materials, 622t Packing glands, pump, 473t Paint program, pulp plant, 488t

Paint testing program, engineering approach to, 503t

#### PAINTS

Aluminum cooling tower components, use on, 20t

Anti-corrosive for aluminum ex-posed to sea water, 403t

Anchor pattern profile, eff on performance of, 428t effect of

Automobile, 167t, 541t

", air pollution of, 541t

Hydrogen sulfide vs. 541t

Moisture on reinforced concrete bridges reduced by, 331t

Rubber base transformers coated with, 1-111

Selection of for chemical resist-ance, 10-85

Ship hull, 587t

Underwater metal surfaces coated with, 335t

Zinc-rich vs sea water, 409t

Palladium, titanium containing. 644t

", titanium coupled with in HCl, 566t

Paper plant, coatings in, 488t Paper, sulfur dioxide vs. 541t

#### PASSIVATION

Aluminum alloys in acid media,

Austenitic stainless steel surfaces in chlorides, 69t

Carbon stee acid, 245t steel in fuming nitric

Hafnium-free zirconium in HF,

Steel in co concrete, factors affect-

Zirconium in HF, 286t

Passivity, classical potentiostat used in study of, 369t

Pearson Null Bridge, 571t

Pearson null circuit potential break curve, 576t

Penetration theory of pitting cor-rosion, 25t

Peptization theory of pitting cor-rosion, 25t

Perchlorate ion, pitting tendencies of with stainless steels, 32t

Pertechnetate ion as an inhibitor,

Petroleum refining industry, annual purchase of corrosion resistant materials by, 121t

#### P-Continued

aluminum alloy behavior in chlorides affected by, 63t

", effect of on corrosion, 455t

flood water corrosivity related to, 307t ", flood

iron in hydrogen sulfide, corro-sion of related to, 189t

metallic lead cathodic protec-tion requirements vary with, 389t

", water, aluminum corrosion in re-lated to, 9t

Phenol formaldehyde, testing of for oil well tubing coating, 5-121

Phenolic wastes, removal of from refineries, 358t

#### PHENOLICS

Baked, tubing in condensate and high pressure oil wells prohigh pressure tected with, 49t

Catalyst-cured, refinery applica-tion of, 171t

Catalyzed, epoxy, 642t

Modified, steam resistance of, 202t

Tropical environments vs, 291t

Phosphate treated water, 492t nosphates, aluminum corrosion in water inhibited with, 7t, 9t

coatings of on mild steel sterilizer shells, 202t

', cooling waters inhibited with,

Phosphatizing treatments, 508t

Phosphorylated lecithin solutions, reactive coatings from, 508t

Photoelectric information selector,

Physical properties of polyethylene coatings, 117t

Pickling and dipping solutions, poly-esters vs. 635t

Pickling bath, pretreatment with prior to lining steel pipe, 275t

Pilot plant testing, refinery equip-ment for processing nickel, 547t

Pin holes, can, 11-100

Asbestos-cement, underground corrosion vs. 1-107

Bare, cathodic protection of, 417t

Red brass, stress corrosion crack-ing of, 433t

Steel, cathodically protected, low temperature bend testing of. 591t

", injection systems, 12-106

", pickling bath for prior to lining, 275t

", polyethylene jackets for, 6-100

", sea water holding, cathodic protection of, 417t

", underground coatings for, 7-101

", ", evaluating economy of re-conditioning and coating, 279t

#### PIPE LINES

Bridge 3-118 caulking technique in,

Cathodic athodic protection of in high resistivity soil, 497t

Petroleum products, 158t

Product, inhibitor testing inside, 131t

Soil corrosivity toward, 77t

teel, effect of velocity on with sulfuric acid, 326t

Submarine, steel, sewage disposal,

#### -Continued

Piperidine, effect of on inhibition,

Piping, industrial structure, coating of, 6-102

Pit growth in stainless steels, 32t

it inertia and pit memory on stainless steels, 32t

Pit interaction in study of pit growth on stainless steels, 32t Pit measurement on tankers, 557t

#### PITTING

Aluminum 52S in glycol-water,

Atmospheric corrosion test speci-mens, 533t

Copper tubing for recirculated water, 492t

Corrosion fatigue of steels related to 262t

Evaluation of paints in terms of,

HF alkylation units, 237t

High temperature alloys in molten boron oxide, 85t

Metals in glycol-water solution,

Stainless steel, an electrochemical study of, 32t, 39t

" ", austenitic, in chlorides, 69t

" ", (Type 310), exchanger tub-ing of, 627t " ", soot-blower tube of, 622t

Steel, Type 316 ELC, 547t

Zirconium in HCl, 103t

Pitting corrosion, critical analysis of, 25t

Pitting distribution and loci, 25t

Chlorinated polyether, properties and uses of, 11-108

oatings for offshore drilling structures, 5-131

Corn wet milling industry equip-ment protected from acids by use of, 113t

Epoxy liner for field joints of steel pipe in ocean, 363t

Linings of, annual purchases of by industries, 121t Organic coatings for oil well tub-ing, testing of, 5-121

Organic coatings in tropical en-vironments, 291t

Polyester fiber glass equipment,

Polyethylene jackets for steel pipe, 6-100

Pump linings, 473t

einforced, sprayed resins and fibers in, 12-106

Rigid or reinforced, annual prochases of by industries, 121

Steam resistant coatings for car bon steel hospital ware, 202t

Tank trucks reinforced with,

Thermosetting resins (reinforced) vs chlorine, 355t

Thick-film synthetic coatings, refinery applications of, 171t

Tubing for high pressure wells protected by coa-with, 73t coatings

Underground coatings of, 7-101

Plastic cell test to evaluate water flood corrosion inhibitors, 7-97

deformation and crystal

Plastic film method in tank ship corrosion measurements, 561t

growth, 9-103

### -Continued

Plastic rope for anodes, 12-106

Plastisols, polyvinylchloride, appli-cation of, 8-107

Plating, tin-zine, 3-113

Platinum anodes for ships, 581t.

Platinum coupled with titanium in HCl, 566t

Plugging tendencies of flood water, 12-99 Polarization current, measurement

Polarization measurements. odic. inhibitor evaluation from,

Polarization measurements in stain-less steel pitting corrosion study, 39t

Polluted atmospheres, 541t

Polyamid, oil well tubing coating of, 5-121

Polybischloromethyl oxetane, prop-erties of, 11-108

Polyester fiber glass equipment, 625t

#### POLYESTERS

Industrial corrosives vs, 635t Metal finishing plating solutions vs. 635t

Pickling and dipping solutions vs.

Reinforced, highway tank trucks using, 2-94

Stripping solutions for salvage vs, 635t

Polyethylene, coating resistance of to acids and alkalies, 117t

", jackets of for steel pipe, 6-100 ", rope of for anodes, 12-106

', tapes of for underground pipe, 7-101

Polyphosphates, addition of to cooling waters, 20t

Polysulfide elastomers, underground pipe protection with, 7-101

Polysulfides, bolt caps filled with,

## POLYVINYL CHLORIDE

Chlorine environments vs. 355t Piping of vs chemical attack, 8-105

Plastisols, application of, 8-107 Sheet, plasticized, for modified starch service, 113t

Tapes, for underground pipe, 7-

Polyurethane, oil well tubing coated with, 5-121 Polyurethane coatings, properties

of. 12-93

Polyurethane tube coatings, 4-100 Potassium dichromate as a gen sulfide inhibitor, 303t a hydro-

Potassium fluoride, rate of dissolu-tion of Zr in HF affected by, 286t

Potential measuring device on pipe, design of, 417t

Potential profiles, 576t

Potential studies used in pitting phenomena study, 25t

Potential-time curves of Zr in HF,

Potentials, anode-to-hull, 587t ", pH vs for lead, in cathodic pro-tection of cable sheath, 389t

", zirconium in HF, 286t Potentiometer, commercial portable null, 571t

Potentiometer-voltmeter, 571t

Potentiostat, classical, application of to study of passivity, 369t

coatel pro-

ol. 15

tials zanie

310

5-126 ures tress hick-

duct inlum. 477t

lene in-201

nvi-

stry sivsys-

n in

tion eels al-

in late igh

171

ith TO-

16

100

ms

ower plant, coatings engineer's role in design and planning of, 7-107

" ". electrical generating, 6-95

Preheater exchanger, tube failure in, 627t

Preheater tubing, deterioration of, 627t

Pressure, high, organic coating tested at for oil well tubing, 5 121

Pretreatment prior to lining steel

Prime, hot vinyl, 642t

Primers, all aluminum alkyd paint er blast cleaned steel, 1981

rubber-base paints applied with for transformers, 1-111

", wash, 311t, 315t

", ", ship bottom, 315t

Probability, stress corrosion crack-ing of copper alloys, 433t

Process equipment, cathodic pro-tection of, 123t

Processing, chemical, 200 and 3 series stainless steels in, 147t

Products pipe line, cathodic protection of, 12-104

" ", inhibitors inside, 131t

" ", oil soluble inhibitors for,

Program, coating and lining selec-tion, 10-85

, maintenance coating for pulp and paper plant, 488t

", paint testing, 503t

Properties needed in offshore ing structure coatings, 5-131

Pulp and paper, maintenance coaing program in plants of, 488t

"", industry, annual purchases of corrosion resistant materials by, 121t

Pump and valve material, chlorine vs. 355t

Pumps, design and materials for.

Pumps, iron, flood waters vs. 12-99

Punch cards, NACE abstract, 251t, 254t

" ", " ", photoelectric selector for,

### Q

Quantitative measurement of pitting attack, 25t

Questionnaire replies, corrosion in HF alkylation units, 237t

" ", material for handling chlorine mixtures, 355t

#### R

R alloy (aluminum), electrode po-tential behavior of in phosphoric acid, 63t

Racks, atmospheric corrosion test-ing, 533t

adioactive tracers, leaks in bonded lead lined vessels located with, 2-98 Radioactive

ain, atmospheric, corrosion test panels exposed to, 533t

", non-ferrous metals corrosion related to, 529t

Rate-of-pickling on tin-plate steel.

Rate of solution movement, in-fluence of on corrosion, 455t

Reactive coatings, 508t

#### R-Continued

Reactive wash primers, 311t Reactors, low purity water used in,

Recirculating coolant tests, 395t

Reconditioning and coating under-ground steel pipe, 279t

Records and reports of pul; plant maintenance coating program, 488t

Recovery of graphitically embrittled nickel, 1-112

Rectifiers, on ships, 581t

", products pipe line, 12-104

Redox probe field technique, 335t

inhibition of cooling water in, 233t

nickel alloy lining for isomeriza-tion unit, 8-109 ", oil, thick-film synthetic coatings

sour water stripper corrosion in, 358t

Refinery equipment, aqueous hydro gen sulfide vs, 189t

Refining, nickel, 547t

petroleum, organic inhibitors for,

Refining industry, butane isomeriza-tion units, 185t

". HF alkylation units, 237t

Refining of uranium, corrosion problems in, 168t

Refractories, special corrosion resistant, 10-92 Regenerator, copper liquor, 547t

Reinforced concrete bridge, in ing attack of steel in, 331t inhibit-

Reinforced polyesters for highway tank trucks, 2-94

Reinforcement, glass fiber for coatings, 4-102

Reproducibility of atmospheric corrosion test results, 533t

Residual fuel, oil ash corrosion problems in, 443t, 601t, 5-126 Residues attack chemical distilling column, 11-99

Resins, polyester, 635t

. sprayed, 12-106

", thermosetting, reinforced, chlo-rine mixtures vs. 355t

Resonance type instruments for tank ship corrosion loss measure-ment, 561t

Rhodium, titanium in HCl exposed to, 566t

Rigid plastisols, 8-107

Ringworm corrosion, oil well tub ing attacked by, 49t

Rivets, coating of, 6-102

Roof construction and maintenance, industrial, 513t

Rope, plastic, for anode suspension, 12-106

Rotational casting of plastisols, 8-

Rotrode technique on reactive coatings. 508t

#### RUBBER

Air pollutants vs. 541t

atural, steel vessels lined with for sodium hypochlorite service, 113t Natural,

Silicone, underground pipe pro-tected with, 7-101

Synthetic, 643t

', tropical sea water vs. 291t

Urethane ethane, new formulations give versatility to, 4-100

Rubber base coatings, steam resistance of, 202t

Rubber base paints, protected with, 1-111 transformers

#### -Continued

Rubber linings, annual purchases of by industries, 121t

Rubberized asphalt mastic coatings for offshore structures, 5-131

Rust, types of on polished steel, 526t

Rusting, internal can surfaces,

#### S

S2 alloy (aluminum), electrode po-tential behavior of in phosphoric acid, 63t

#### SAFETY

In chemical cleaning, 17t

Polyethylene coating application related to, 123t

Sour gas condensate production, methods of achieving in, 413t

Toxicity of boiler deposits, 5-126 Salinity of atmospheres, metals corrosion related to, 631t

#### SALT

Concentration of on oil well steel, 299t

Concentration of on re steel in concrete, 382t reinforcing

Content, steel reinforced concrete bridge affected by, 331t deposits of on ferrous metals.

Solutions, lead for cable sheath tested in, 389t

Solutions, titanium and zirconium resistance to, 341t

Salt crock testing of polyethylene, 6-100

Salt spray cabinet test on reinforc-ing steel in concrete, 382t

Salt water (see Water, salt)

Salt-fog, resistance of rubber-base paint to, 1-111

Salts, neutral, influence of on corrosion, 455t

", polyethylene coar resistance to, 117t coating chemical

Sand blasted steel, anchor patterns on, 428t

Saran, hot spray application of in shipyards, 3-116

Scale, cargo tank removal of, 557t outer oxide, on stainless steel.

", removal of by acids, 17t

", removal of from steel pipe, 275t Scale deposits, HCl used in removal of from steel, 69t

Scale inhibitors for cooling water, 233t

Scales, inner oxide, on stainless steel, 613t

Scales on steels (Types 302, 309 and 330), 141t

Scaling, chromium-nickel steel, 141t Scanning device, photoelectric for corrosion data, 251t

Scraper trap deposits, pipe line, 131t

Scrapers, pipe line, 158t

Screening effects in pitting corro-sion, 25t

Screening of inhibitors, chloride stress corrosion, 450t

" " , oil well equipment, 303t

" " , water flood corrosion, 7-97 Screening tests for chemical resist-ant coatings, 10-85

Screening test for inhibitor film persistence, 554t

### -Continued

Screens, filter, pipe line, 131t Screw shell failure from stress cor-rosion cracking, 433t

Scrubbing tower, steel fogging type. lead-acid brick used to reline,

Search systems, corrosion data,

Sea water (see Water, salt)

Secondary recovery, inhibitors for evaluated, 307t

Sediment, inhibitors for pipe lines evaluated by measuring of, 158t Sensitizing, stainless steels, 200 and 300 series, 147t

". " ", cladding, 10-88

Service life, industrial roofing, 513t ", sulfuric acid pipe lines, rela-tion of to velocity, 326t

vere environments, rubber-base transformer finish used in, 1-111 Sheath, lead, telephone cable, 9-116 Shelter, atmospheric corrosion test racks having, 533t

Sheltered and open tests, metals in India, 631t

Shepard's cane, earth res measurements with, 571t resistivity

Sherritt Gordon Mines, nickel refining at, 547t Ships. cathodic protection of, 339t, 403t, 483t, 557t, 581t, 587t, 596t, 2-87

". coatings for bottoms of, 315t

", coatings for hulls of, 483t

". tank, 561t, 557t

", wooden - hulled aluminum - frame minesweepers, 403t

nipyards, hot spray application of Saran in, 3-116 Shipyards.

Sigma phase, effect of on inte granular corrosion of Type 3 and 316L stainless steel, 221t inte

", in Types 316 and 316L stainless steel, 213t

Silica, accumulation of at metal/ scale interface for nickel steels, 141t for chromium-

on, aluminum alloys affected trace elements of, 63t

compounds of added to residual fuel oil, 601t high temperature oxidation of steel affected by content of, 613t

nickel chromium alloys containing, 194t

carbide, refractories of,

Silicon iron anode in ducts to pro-tect cable, 423t

Silicone rubbers, underground pipes coated with, 7-101 Silicones, steam resistance of, 202t

Silt, ducts containing, 423t ", recircula ing, 492t recirculating water system hav-

titanium coupled with in lver, tita: HCl, 566t

Skin temperatures, Type 316 stain-less steel, 257t

Slag, inclusions of in welding, 2t ", molten, metals vs, 10-92

", oil-fired boilers containing, 5-126 steel tubes accumulate on heating of vanadium compounds, 443t

Slurries, abrasive, in pumps, 473t

Slurry, nickel powder, 547t Slush moulding of plastisol parts, 8-107

Smog, photo-chemical, 541t

Smoke, air pollution from, 541t

Sodium, oil ash corrosion related to presence of, 5-126

Sodium benzoate, inhibition of anti-freezes with, 607t

ir Sod ri

Dec

Sodi

ar

ti

" "

Sodi

Sodi

Sod

fr

ti

H

Sod 1-

Sod

Sod Sod g Sod Sod

Sod

Soc

Sof

SO

So

Sc Se Sc

Se Se Si

S S

Sodium carbonate, air pollution from, 541t

Sodium chloride, anodes of AZ 63 and Mg-1% Mn alloy vs, 76t

", steel wires have corrosion fa-tigue in, 262t

" ", stressed austenitic stainless steels vs, 373t

Sodium dichromate, pitting reduced by addition of, 269t Sodium dinonylnaphthalene, anti-freezes containing, 607t

Sodium fluoride, rate of dissolu-tion of Zr in HF affected by addition of, 286t

", titanium-platinum couples in HCl containing, 566t

Sodium hydroxide, nickel tubing vs, 1-112

Sodium hypochlorite vs natural rubber linings, 113t

odium metasilicate, anti-freezes inhibited with, 607t

Sodium nitrate for steel as chlo-ride stress corrosion inhibitor, ride 450t

Sodium nitrate, anti-freeze inhibi-tion with, 607t

Sodium nitrite as inhibitor in products pipe lines, 158t

Sodium pyrophosphate as a hydro-gen sulfide inhibitor, 303t

Sodium silicate, inhibition of anti-freezes with, 607t

Sodium sulfate, oil ash corrosion related to, 601t

Sodium sulfate-vanadium pentoxide mixture vs Type 310 stainless mixture vs steel, 443t

Sodium sulfite for steel as chloride stress corrosion inhibitor, 450t

Sodium tetrasilicate plus sodium tetraborate, corrosion of alumi-num in glycol-water inhibited by, 395t

Soft drinks, effect of copper on corrosiveness of, 11-100

Cathodically protected steel in,

Corrosivity classification system

Corrosivity of measured, 77t

Corrosivity of to buried metals, 1-107

Electrical measurements in, 576t High resistivity, cathodic protec-tion of pipe lines in, 497t

Lead vs. 389t

Specific resistivity of measured, 77t

Soil resistivity, instruments for measuring, 571t

" " survey of, 497t

Solid particulates in air pollution, 541t

Solvents, polyurethane coatings vs. 12-93

Soot blower tubes, 622t

Sorting machine, photoelectric, 251t

Sound velocity, tank ship corrosion loss measurements involving, 561t

Sour gas condensate production, 413t

Sour water strippers, corrosion in, 358t

Sour-crude immersion, polyure thane coatings tested by, 12-93

Snow, cathodic protection of prod-ucts pipe line in, 12-104

Spalling of reinforced concrete in marine atmospheres, 382t

Spectrographic examination of cor-

#### -Continued

vs. 601t

Spot tests on polyurethanes, 12-93 Spraying, metal, oil ash corrosion

Stability limits of metals in solid solutions, 455t

Stable static potential, obtaining of on lead electrode, 389t

Stack, polyester, fiber glass, 635t Staining, internal, can surface,

Starch granules, abrasive action vs hard rubber and phenolic resins, 113t

Static electrode potential behavior of aluminum alloys, 63t

Static water drop test. mpound inhibitors evaluated by,

tatistical analysis, cracking sus-ceptibility variables in oil coun-try tubing, 437t

"", low purity water as a corrosion factor in nuclear reactor cooling systems, 83t

Steam, oil soluble inhibitors fogged with, 241t

, stress corrosion crack paths of alpha aluminum bronze in atmos-phere of, 295t

eam generators, stress corrosion cracking of, 450t Steam generators Steam resistant coatings for car-bon steel hospital ware, 202t

Sterilizers, steam resistant coat-ings for, 202t

#### STEEL

Alloy, buried specimens of vs soils, 1-107

AOI 5LX-52, pipe sewer outfall composed of for use in ocean, 363t

Cathodic protection of in sea water, 483t hydrogen

Cathodically protected, embrittlement of, 591t

Chlorine mixtures vs. 355t

Chromium, accelerated cavitation of related to hardness, 269t

(0-5 percent), hydrogen sul-ide iso-corrosion curves for, fide 125t

Chromium-low nickel-manganese, for chemical manufacturing processes, 147t

Cold rolled, physical properties of, 635t

Concrete bridge reinforced with, 331t

Copper, low phosphorous, effect of manganese in, 533t

Galvanized. alvanized, atmospheric corro-sion of, 409t

Grit blasted, paint performance on. 428t

High phosphorous, atmospheric corrosion of, 533t

High strength, delayed failure of,

" ", stress corrosion and hydro-gen embrittlement tests on, 399t

Inhibitor evaluation on in acidic environments, 321t

Marine atmosphere vs. 526t

Milling systems for, 8-105

N-80, hydrogen embrittlement of, 591t

Nickel (low), oil well tubing com-posed of, 49t

Oil-brine-hydrogen su tures vs. 299t, 303t sulfide mix-

Pompton and Utica, corrosion fatigue of, 262t

#### -Continued

STEEL (Continued)

Reinforcing in concrete in marine atmospheres, 382t

SAE 1010, iron phosphate coat-ings on, 508t

Spring (1095), fruit cutter blade of, 6-100

Structural, coatings of, 6-102 ", fracture of, 591t

", power plants use, 6-95 Sulfur dioxide vs, 541t

Tin coated for foods, 11-100

Tin-plate, factors influencing rate-of-pickling test on, 135t Type 422, net fracture stress of vs temperature, 399t

Type 446, high temperature gases vs. 622t

Type XON-4 inhibitors to protect, 469t

#### STEEL, ALLOY (LOW)

Atmospheric corrosion vs. 533t Industrial atmospheres vs. 526t Oil well tubing composed of, 49t Tank ships, use on, 557t

Weldments of vs NaC1, 2t

#### STEEL, CARBON

Filters of, 547t

HF vs, 237t

High temperature vs. 619t

High temperature gases vs, 627t High temperature water systems vs. 183t

Liquid-phase fuming nitric acid vs. 245t

Low, cooling waters vs. 233t

Low, hydrogen effusion rates on, 179t

Offshore platforms of corrode, 8-103

Sour water vs in refineries, 358t Steam resistant coatings for hos-pital ware composed of, 202t

Sulfuric acid-containing pipe lines of. 326t

Weldments of vs NaCl, 2t

### STEEL, MILD

Carbon tetrachloride vs. 447t Chemical plant exposures vs,

Corrosion of in India, 631t

Ethylene glycol vs, 607t HCl vs. 517t

In 73% caustic, cathodic protec-tion of, 123t

Inhibitor fogging and flotation with coupons of, 241t

naphtha process equip-ent using, 189t Light naphtha

SAE 1010, cooling tower water vs, 97t

#### STEEL, STAINLESS

Cladding of, 10-88

200 and 300 series in chemical manufacturing processes, 147t

Aluminum - frame uminum - frame mineswee having components of, 403t

Ammonium nitrate stored in, 6-99 Atmospheric corrosion of, 533t Cast, erosion resistance of, 269t

Effect of cathodic reaction on pitting behavior of, 25t

Chromium-nickei (18-8) vs alde-hydes, organic acids, organic esters, chlorides, sulfates, and organo - nitrogen compounds,

#### -Continued

STEEL, STAINLESS (Continued)

Chromium-nickel, high tempera-ture oxidation of, 141t

Electrochemical study of pitting corrosion in, 32t, 39t

Industrial atmospheres vs. 526t Nickel refinery equipment of,

No. 20 alloy, sulfuric and sul-furous acids vs, 113t

Pit growth in when exposed to ferric chloride, 32t

Pitting corrosion of, 25t

Polarization measurements in when exposed to ferric chloride, 39t

Type 330, oxidation of, 141t

Silicon's effect on high temperature oxidation of, 613t

Uranium refining process vs. 168t

## STEEL. STAINLESS, AUSTENITIC

Chloride stress corrosion cracking of 69t

High temperature oxidation of, 141t

Hydrogen sulfide curves for, 125t sulfide iso-corrosion

Stress corrosion cracking of, 373t, 9-103

Type 302, cathodic protection of in sulfuric-organic acid, 123t

" ", oxidation of, 141t Type 302B, dehydrogenation proc-ess headers of, 619t

" ", high temperature vs. 619t

Type 304, nitric acid vs. 257t

", sulfurous acid fumes vs, 113t

oxidation of at 2000 F. 141t

Type 310, dehydrogenation proc-ess catalyst tubes of, 619t

" ", high temperature vs, 619t

" ", hot gases vs, 622t

" ", molten boron oxide vs, 85t .", synthetic fuel oil ash vs,

" ", tubing deterioration of, 627t

Type 316, high temperature vs, 619t ", in 77% H<sub>3</sub>PO<sub>4</sub> at various skin temperatures, 257t

", sour water strippers of vs hydrogen sulfide, 358t

stress corrosion cracking of,

" ", sulfur dioxide vs, 113t valve seat rings of fail in

water treating system, 1t Type 316 and 316L, intergranular corrosion of, 213t, 221t

Types 316 and 317, phosphoric acid vs, 351t

Type 321, high temperature vs. 619t

Type 347, high temperature vs. 619t

" ", hot gases vs, 622t stress corrosion cracking of,

Vs aldehydes, organic acids, or-ganic esters, chlorides, sul-fates and organo-nitrogen com-pounds, 147t

Steel-tin beverage cans, 477t teel and copper compounds aluminum cooling towers, 20t

Steel cable for magnesium anodes, 12-106

Steel piping, water tower, 492t Steel wires, corrosion fatigue of, 262t

ne. ta. for

or-

15

nd 13t la-

111 116 est in

Gt

ity

on 16 n-1/

ne

ed al of n-

f, 0-00 21

V-

in

n. 26

## S—Continued

Storage, canned goods, 11-100

nitric acid and ammonium ni-trate, 6-99

Stray currents, underground struc-tures vs. 455t

" ", underground corrosion related to, 1-107

Stray current areas, DC corrosion meters used in, 68t

Strength, high tensile, materials for, 10-88 Stress, high tensile, steel specimens vs. 207t, 591t

STRESS CORROSION CRACKING

Alpha aluminum bronze in onia and steam atmospheres, 295t

Aluminum vs. 455t

Aluminum bronze alloys, wrought,

Aluminum-magnesium alloys, 55t,

Ammonium nitrate storage tanks,

Copper alloys, 433t

In HF alkylation units, 237t

Inhibitors screening to prevent,

Mechanism of in AZ 31B mag-nesium alloy, 7-106

country tubular goods, 437t, Oil

Oil well tubing, 49t

Steels, high strength, 399t

STRESS CORROSION CRACKING, STEELS, STAINLESS

200 and 300 series for chemi manufacturing processes, 147t Austenitic, in chlorides, 69t, 373t,

", Type 316 ELC tank, 547t

", Type 316 tubes in corn syrup evaporator, 113t

Strippers, sour water, 358t Stripping solutions for salvage, polyesters vs. 635t

Structural design plus coatings, 6-102

Structure-to-soil potentials, 576t

Submarine test cable, use of wateel pipe line in ocean, 363t

Sub-surface corrosion of aluminum, field measurement of, 9-114

Sugar and syrup production, ma-terials of construction for, 113t

Sulfate ion, pitting tendencies of with stainless steels, 32t

Sulfates, stainless steels (200 and 300 series) vs. 147t

Sulfated orange oxide vs metals, 168t

Sulfide corrosion cracking of steels, heat treatment used against, 437t

Sulfide ions, hydrogen embrittle-ment of steel related to, 591t Sulfide precipitation of nickel and

cobalt, 547t

Sulfides, cooling water contami-nated by, 547t ", removal of from refinery waters, 358t

Sulfite, oil ash fied by, 5-126 ash corrosion intensi-

Sulfur. canned goods containing, 11-100

", iron containing, atmospheric cor-rosion of, 526t

", residual fuel oils containing,

Sulfur content of fuel related to oil ash corrosion, 5-126

-Continued

Sulfur dioxide, atmospheric cor-rosion of non-ferrous metals by, 529t

", atmospheric corrosion of iron by, 526t

Sulfur dioxide and trioxide, air pollution from, 541t

Sulfur pollution, non-ferrous metals exposed to, 529t

Sulfurous compounds, accelerated corrosion of zinc by, 533t

Suppliers, pulp plant coating, 488t Surface finishing, cavitation attack related to, 269t

", Types 201 and 202 stainless steel,

SURFACE PREPARATION

Aluminum cooling towers for painting, 20t

Anchor pattern profile affects paint performance, 428t

Carbon steel for exposure to fum-ing nitric acid, 245t

Polyethylene coating use related to, 117t

Pulp plant, 488t

Refinery metal coatings, 171t for thick-film

Wash primers, connection of with, 311t Surface preparation for painting,

Surface treatment, stainless steel (Type 309), 141t

", steam resistant coating fectiveness influenced by, 202t

" ", steel pipe prior to lining, 275t ", zirconium corrosion rate in HCl affected by, 103t

Surge protection cell, 497t

Synergized polyphosphate treat-ments in cooling tower systems, 97t

Synthesis gas, attack on metals by from methane-oxygen combustion, 622t

Synthetic coatings, thick-film, oil refinery applications of, 171t

Synthol process, metals deteriora-tion in, 627t

weet corrosion cracking of oil field tubing, 437t

T

Tank ships, inhibitors for, 241t

" ", internal corrosion of, 557t measuring corrosion loss on,

Tank trucks, highway, reinforced polyesters for, 2-94

Coal tar lined, 12-99

Linings for, 10-85

Polyester fiber glass, 635t

Stainless steel (Type 316 ELC) stress corrosion cracking of 547t

Storage, inhibitors for, 241t

", coating of, 6-102

Tantalum, platinum clad anodes of for ships, 596t

Tantalum resistance to calcium chloride, 341t

Tapes, annual purchases of by industries, 121t

", plastic, underground corrosion of pipe combatted with, 7-101

Tar system lines, HF vs. 237t

Teflon, steam resistance of, 202t

-Continued

Telephone cables, differential aera-tion of, 9-116

TEMPERATURE

Aluminum-magnesium alloys vs.

Critical, high temperature alloys in molten boron oxide, 85t

Influence of on corrosion fatigue,

Influence of on corrosion rate, 455t

ow, bend test of cathodically protected steel pipe, 591t

Oil well tubing tested for effect of, 49t Service, influence of on wrought aluminum - magnesium alloys, 55t

Zirconium corrosion rate in HC1 affected by, 103t

TEMPERATURE, HIGH

Aluminum-magnesium alloys at,

Attack on metals by synthesis gas from methane-oxygen com-bustion, 622t

Corrosion in a hydrocarbon con-version system, 619t

Corrosion product films on alu-minum, 7t

Determining of corrosion rates under heat flux conditions, under 257t

Graphitic embrittlement of nickel heat exchanger tubing, 1-112

Hydrogen effusion measurement in dynamic aqueous systems, 179t

Intergranular corrosion of Type 316 and 316L stainless steel. 213t

Iso-corrosion rate curves for hydrogen-hydrogen sulfide, 125t

Metal deterioration in atmos-pheres containing carbon mo-noxide and hydrogen, 627t

Molten boron oxide vs alloys, 85t

New bonding process gives added versatility to cladding, 10-88

Nickel-chromium alloys, internal oxidation of, 194t

Nitric acid vs heat exchanger tubing, 6-99

Oil ash corrosion problems, 443t, 601t, 5-126

Organic coatings tested at for oil well tubing, 5-121

Oxidation of chromium-nickel steels, 141t

Silicon's effect on oxidation of stainless steel at, 613t

Special corrosion resistant re-fractories, 10-92

Type 310 stainless steel vs synthetic fuel oil ash (in laboratory), 443t

Water, system of, 183t

Temperature dependence on time in aqueous corrosion of aluminum,

Temperature differential in heat exchangers, 6-99

Temperature inversion, air pollu-tion related to, 541t

Tensile strength, high temperature alloy, change of in molten boron oxide, 85t

Tensile testing of atmospheric corrosion test specimens, 533t Teredo vs wood, 45t

-Continued

Testing, atmospheric corrosion, procedures employed in, 533t

", cladding materials, 10-88

", long and short term, zirconium in HC1, 103t

TESTING, LABORATORY

Aluminum and alloys by repeti-tive oscillographic method, 633

Aluminum in water, 9t, 13t

Aluminum-magnesium alloys service temperatures vs stress corrosion cracking, 55t

Anchor pattern profile relation to paint performance on steel, 428t Automobile anti-freeze inhibitors,

Behavior of construction materials for minesweepers, 403t

Carbonated beverage can perfora-

tion, 477t Cathodic protection, lead cable sheath, 389t

mild steel in 73% caustic,

" ", steel pipe carrying water, 417t

Cavitation-erosion of materials. 269t

Chemical and solvent resistance of polyurethane coatings, 12-93 Coatings for chemical plants,

Coatings, ship bottom, 315t

Cooling tower system inhibitors evaluated, 97t

Copper condenser tubes water treatment, 492t

Corrosion fatigue, in temperature on, 262t influence of

Criteria for cathodic protection of steel in sea water, 483t

Determining of corrosion rates under heat flux conditions,

ie casting alloys vs detergent solutions, 327t

Effect of silicon on high tempera-ture oxidation of stainless steel, 613t

Fuming nitric acid vs AISI 1020, 245t

High temperature corrosion prod-uct films on aluminum, 7t

ligh temperature oxidation chromium-nickel steels, 141t

HCl vs austenitic stainless steel, Hydrogen embrittlement of cathodically protected steel, 591t

Hydrogen sulfide at high temper-atures vs steels, 125t

Impedance characteristics of iso-lated aluminum oxide films 283t films.

Inhibitor evaluation from cathodic polarization measurements, 517t

Inhibitor film persistence, 554t Inhibitor fogging and flotation,

Inhibitors, aluminum glycol-water cooling system, 395t

", carbon tetrachloride - wat vapor (for mild steel), 447t

", cooling water, 233t

secondary recovery, evaluation of, 307t

Intergranular attack of austenitic stainless steels, 213t

TEST

Decer

Mat 6

N-8 Nic

Oil Oil Org

Or Pa Ph

1. 15

sion,

nium

63t

ress

n to 428t

ors.

eri-

ora-

tie

als.

its.

ors

for

on

18.

nt

el.

0,

of

ı,

#### -Continued

TESTING. LABORATORY (Continued)

Intergranular corrosion of Type 316 and 316L stainless steel, 221t

Materials selection for dehydro-genation process catalyst tubes,

N-80 and low alloy materials in 5% NaC1 plus carbon dioxide, 49t

Nickel-chromium alloys oxidized in air, 194t

Oil ash (synthetic fuel) vs Type 310 stainless steel, 443t

Oil-brine-hydrogen suifide mix-tures vs steel, 299t

Organic coatings for oil well tubing, 5-121 Organic inhibitors for petroleum refining, 321t

Organic nitrogen inhibitors, 128t compounds as

Paint for chemical nint systems plants, 503t

Phosphoric acid vs Types 3 and 317 stainless steel, 351t

Pickling bath inhibitors for steel pipe, 275t

Pit growth in 18-8 stainless steel exposed to ferric chloride, 32t

Platinum for active ship anodes,

Polarization measurements for study of pitting corrosion in stainless steel exposed to ferric chloride, 39t

Polyesters v sives, 635t vs industrial corro-

Polyethylene pipe, 6-100 jackets for steel

Rates of dissolution and passiva-tion of Hf-free Zr in HF, 286t

Reactive coatings thickness measurement, 508t

Reinforcing steel in concrete vs salt spray, 382t

Screening tests of inhibitors to prevent chloride stress corrosion, 450t

Steam resistant coatings for car-bon steel hospital ware, 202t

Steels, high strength (4340), effect of hydrogen concentration on, 207t

Stress corrosion crack paths i alpha aluminum bronze, 295t

ress corrosion cracking, 31B magnesium alloy, 7-106

" " N-80 and J-55, 437t

" ", stainless steel, austenitic, in chloride waters, 373t

" " ", steel, Type 422, 399t

Tin plate steel, lag time of de-termined, 135t

Titanium and zirconium resist-ance to calcium chloride, alkali solutions, chlorine, hypochlorite, sulfuric acid, nitric acid, HCl and NaCl, 341t

Weldments, carbon and low alloy steel, NaCl vs. 2t

Wrought aluminum bronze loys, stress corrosion cracking susceptibility of, 101t

Zirconium vs HCl at atmospheric pressure, 103t

#### TESTING, ON LOCATION

Aluminum sub-surface corrosion,

Atmospheric corrosion of metals,

ection, steel pipe water, 417t Cathodic thodic protection, carrying sea water

#### -Continued

TESTING, ON LOCATION

Coatings for chemical plants, 10-

Criteria for cathodic protection of steel in sea water, 483t Element

lement spacing in duct anodes for cables, 423t

Filming amines vs iron and copper in condensate cycle, 8-99

Inhibition of low temperature hy drogen sulfide corrosion is pipe still, 189t

Inhibitor fogging and flotation,

Inhibitors, cooling water, 233t

", product pipe line, 131t, 158t Materials for butane dehydro-genation process, 619t

Materials for gas generator-waste heat boiler, 622t

Metals in tropical marine en-vironments, 631t

Monel, Inconel, steel, alumini and copper corrosion rates water reclaimer tower, 358t aluminum

Organic coatings in tropical en-vironments, 291t

amt systems for chemical plants, 503t

hosphoric acid vs Types 316 and 317 stainless steel, 351t

Platinum anodes for ships, 596t active

Polyesters vs industrial corrosion.

Screening inhibitors for water flood corrosion prevention, 7-97

Soil corrosivity, 77t

Soils vs buried metals and coat-ing materials, 1-107

team resistant coatings for carbon steel hospital ware, 202t

Steels. stainless (200 and 300 series) for chemical processing,

Sweet corrosion cracking of cop-per, 437t

ranium refining process vs metals corrosion, 168t

in marine environments,

Textiles, ozone vs, 541t

", sulfur dioxide vs, 541t

Theoretical concepts of pitting corrosion, 25t

Thermal conductivity of refractories, 10-92

Thermal convection loop, use of in aqueous dynamic systems, 179t

Thermocouple wires, molten boron oxide vs. 85t

Thermoplastics, properties and uses of. 11-108

Thick-film synthetic coatings in oil refinery applications, 171t

Thickness, tank ship plate, measure-ment of, 561t

Tin, titanium coupled with HCl.

Tin alloys in atmospheric exposure, 3-113

Tin-nickel alloy resistance, 3-113

Tin plate, staining of, 11-100

Tin plate steel, rate of pickling on, 135t

Tin-steel on carbonated beverage cans, 477t

Tin sulfide on cans, 11-100

### T-Continued

TITANIUM

Alloys containing vs molten boron oxide, 85t

Chemical plant exposure of, 341t,

Dissolution rate of in HF, 286t HCl vs. 566t

Milling system for, 8-105

Nickel-chromium alloys contain-ing, 194t

Platinum clad anodes of for ships,

Tubing in nickel extraction plant,

Titanium and stainless steel pumps, 473t

Topography, air pollution related to. 541t

Tower footings, transmission, 6-95 Towers, water treatment, 492t

Toxic hazards in chemical clean-ing, 17t Toxicity of boiler deposits, 5-126

Transformers, rub coatings on, 1-111 rubber-base paint

Treatment of water, 492t Triethylenetetramine as

hydrogen sulfide inhibitor, 303t Tropical environment, metals test-ed in, 631t

, performance of organic coatings in, 291t

", synthetic rubbers and vinyls in, 643t

Trusses, steel, coating of, 6-102

Tube sheets, nitric acid vs, 6-99 ubes, 27-chrome alloy, high tem-perature vs, 619t

", urethane coatings for, 4-100

#### TUBING

Aluminum, on minesweepers, 403t Copper, water, stress corrosion cracking of, 433t

water tower, silt deposits on,

Nickel, heat exchanger, graphi-tic embrittlement of, 1-112

Nipple tests, 12-99 Oil and gas well, organic coatings for, 5-121

Oil well, mechanical properties of, 49t

Preheater, Type 310, determina-tion of, 627t

Sour gas well, resistance of, 413t Special alloy, high pressur wells protected with, 73t pressure gas

Stainless steel (Type 31 thetic oil ash vs. 443t 310), syn-

Tubular goods, oil country, s corrosion cracking of, 437t stress

Tubular heat flux corrosion tests,

Turbines, filming amines used to protect, 8-99

', gas, treatment of residual oil in, 601t

Turbine oil test (ASTM), 321t

Turbine type rust tests on in-hibitors, 131t

Ultrasonic measurement of tank ship losses, 561t

Undercoating for marine atmos-pheres, 3-113

Underground cable, differential aer-ation on, 9-116

#### -Continued

Underground corrosion, 576t

cathodically protected steel, 5911

" ", duct anodes protect cables from, 423t

instruments for measuring. 571t

" ", piping, 547t

", plastics and synthetic tomers for coatings, 7-101 synthetic elas-

Summary of 45-year Nat Bur of Standards research on, 1-107

Underground structures, 68t, 455t

Underwater metal surfaces in fresh water, 335t

Uranium. corrosion problems in refining of, 168t

Urethane, coatings of, new formulations for, 4-100

", " ", properties of, 12-93

", steam resistance of, 202t

Utility plant condensate system, filming amines control corrosion in, 8-99

Vacuum annealing, zirconium cor-rosion rate in HC1 affected by, 103t

Vacuum bonding process, 10-88

Vacuum tube millivoltmeter (DC), 571t

Valve seat rings fail in water treat-ing system, 1t Valves, chlorinated polyether, pres-sure temperature ratings of, 11-

108 Valves, chlorine mixtures vs, 355t Vanadium.

anadium, oil ash corrosion re sulting from, 443t, 601t, 5-126 ", titanium coupled with in HCl,

Vanadium-containing fuels, oil ash corrosion problems with, 601t

Vanadium pentoxide, oil ash cor-rosion from, 601t, 5-126

Vanadium pentoxide-sodium sulfate mixtures steel, 443t vs Type 310 stainless

Vapor condensation condition, stress corrosion of austenitic stainless steels in chloride waters during 373t

Vapor phase butane isomerization,

Variables in paint testing, 503t Variable interaction: a statistical

solution, 83t Varistors, DC corrosion meters used with, 68t

Velocity, steel pipe line life in sul-furic acid affected by, 326t

water treatment system affected by, 492t

Velocity problems, steel suitability for handling chlorine mixtures in terms of, 355t Vibratory method, erosion resist-ance of alloys determined by.

Vinyl chloride, unplasticized, properties of, 11-108

Vinyl mastic coating for offshore drilling structures, 5-131

Vinyl prime, hot, 642t Vinyl resin, testing of for oil well tubing coating, 5-121

Vinyls, properties of, 12-93

", steam resistance of, 202t ", tropical environments and sea water vs. 291t, 643t

#### V—Continued

Visual observations on water stream in high temperature veloc-ity loop, 183t

Voltmeter, dual sensitivity, 571t

" moving coil deflection, 571t

", portable DC vacuum tube, 571t

". potentiometer, 571t

#### W

Wagner's analysis of cathodic pro-tection compared with operating data for ships, 339t

Wash primers, development and characteristics of, 311t

" ". components of, 508t

#### WATER

Aluminum alloys in cooling tow-ers vs, 20t

Anode installations in to protect product pipe lines, 12-104

Chloride containing, austenitic stainless steels in, 9-103

" ". stress corrosion of austenitic stainless steels in, 373t

Circulating, corrosion by, 492t

Color of in loop streams, 183t

Cooling, 233t, 413t, 417t, 547t, 9-103

", chlorides in, 9-103

", inhibition of, 233t

Deionized, aluminum alloys vs.

", nuclear reactor fuel element jacketing corroded by, 83t

Distilled, inhibitor screening tests for aluminum protection,

395t Effect of in corrosion of AISI 1020 in fuming nitric acid, 245t

Fresh, cathodic protection of naval vessels in, 2-87

", organic coatings in tropics tested in, 291t

", ship bottom coatings vs. 315t

High purity, aluminum alloys in,

Hot, boehmite formed on alumi-num in presence of, 283t

Low purity, nuclear reactor fuel element jacketing corroded by,

Polyurethane coatings vs. 12-93 oil corrosivity measured by chemical analysis of, 77t

Stress corrosion cracking of cop-per alloys in, 433t

### W-Continued

WATER (Continued)

Stripped, disposal of in refineries,

Tap and distilled vs aluminum, 9t

Tap, distilled and sea: chemical resistance of polyethylene coatings to, 117t

Tap, nuclear reactor fuel ele-ments jacketing corroded by, 83t

Underground telephone cables exposed to, 9-116

Urethane coatings exposed to,

#### WATER, SALT

Carbon steels vs on offshore plat-forms, 8-103

Cathodic protection of naval ves-sel in, 2-87

Cathodic protection of steel in, 483t

Cathodic protection of steel pipes carrying, 417t

Cement mortar coated steel pipe sewer outfall vs, 363t Coatings for ship bottoms vs. 315t

Concrete reinforced with steel vs, 382t

Inhibitors for use in, 241t

Organic coatings tested in pres-ence of in tropics, 291t

Platinum anodes in for active ships, 596t

Power generating plants affected by, 6-95

Wooden hulled aluminum-frame vs, 403t

Ships vs, 581t, 587t

Titanium and zirconium resist-ance to, 341t

Water flood operation involving, 12-99

Weldments, steel, testing of in,

Zinc exposed to, 409t

Water absorption of acidic gases from hydrocarbons in refineries, 385t

Water boxes of condensers suffer graphitization, 6-95

Water condensate tank vs chlo-rides, 69t

Water drainage of telephone cable conduits, 9-116

Water flood, inhibitors for second-ary recovery, 307t

" ", inhibitors screened for pre-vention of corrosion by, 7-97

Water flooding, corrosion control practices in, 12-99

#### W-Continued

Water pollution, electrical generat-ing plant, 6-95

", elimination of in refineries, 358t

Water quality tests, 12-99

Water reclaimer towers, inhibitor injection into, 358t

Water stream in elevated tempera-ture high velocity loop, 183t

Water treatment, 547t ", in aluminum cooling towers,

", inhibitors for water cooling tower systems, 97t

", system, valve seat ring (Type 316 SS) fails in after 9 months,

", test facility, four-tower, 492t Water vapor, atmospheres containing carbon tetrachloride, inhibitors for, 447t

", non-ferrous metals exposed to, 529t

" ", non-ferrous metals vs, 529t Waterproofing of industrial roofing, 513t

Wax coating for underground steel pipe, 279t

Weather, air pollution related to, atmospheric corrosion testing re-

lated to, 533t Weather conditions, metals corro-sion in India related to, 631t

Weld decay, HF alkylation units,

Weld splatter, removal of, 6-102 Welding, cost of on underground steel pipe, 279t

', phosphoric acid vs stainless steel samples subjected to, 351t

", Types 316 and 316L stainless steel, effect on, 221t

Welding clad plate, 10-88

Welding practices on industrial structures, 6-102

Welding techniques related to frac-ture of steel weldments, 2t Weldments, steel, NaCl solution

Welds, zirconium of in HCl, 103t zirconium, corrosion rates

Wellhead chokes, failure of in sour gas production, 413t

#### WELLS

as, high pressure, well com-pletion and corrosion control in, 73t

Oil, inhibitors for secondary re-covery, 307t

", polyurethane coatings for equipment used in, 4-100

", water flood operation of, 12-99

#### W---Continued

WELLS (Continued)

Sour condensate, tubing for, 49t Sour gas, 413t

Sour oil, tubing for, 49t Sweet oil, tubing for, 49t

completion and corrosion rol of high pressure gas Well control o

Wetting units, reinforced concrete bridge protected with, 331t

Wire and sheet, relative corrosion rates of, 533t

Wood, aluminum used with on minesweepers, 403t marine boring organisms vs. 45t

Wrought aluminum magnesium, alloys of vs temperature, 55t

#### X

XON-4 inhibitors, action of, 469t X-ray diffraction, oxide films on stainless steel studied by, 613t

## Z

ZINC

Atmospheric corrosion of, 529t

Corrosion of in India, 631t Detergent solutions vs. 327t

Inhibitive effects of synergized polyphosphate increased by ad-dition of, 97t

pH of in solutions determines corrosion rate of, 455t

Tin as undercoat on, 3-113 Titanium coupled with in HCl,

566t nc chromate, aluminum box painted with for exposure to sea water, 403t Zinc

Zinc chromate primer, 508t

Zinc in marine enviroments, 409t Zinc lead silicate for offshore drill-ing structures, 5-131

Zinc oxide, wash primer pigment replaced with, 508t

Zinc phosphatizing, 508t Zinc spray, offshore drilling struc-tures protected with, 5-131

inc tetraoxychrome-polyvinyl bu-tyral primer, reactive coatings of on steel, 508t

Zinc-pigmented coating inside tank ships, 557t

### ZIRCONIUM

Chemical plant exposure of, 341t,

Hafnium-free, rates of dissolution and passivation of in HF, 286t HCl vs at atmospheric pressure, 103t

Sodium and potassium hydroxides vs. 103t

Titanium coupled with in HCl,

acto Allen Tes

Akim

Alexa

Perfe Co: En Fo So Disc:

Ta Disc And And

> And And Dis

# Alphabetical Author Index

ol. 15

r, 49t

osion gas acrete osion

9t on 3t

9t

ized adines

ic-

nk

CORROSION, Technical and Technical Topics Sections, Volume 15, 1959

A	<b>B</b> —Continued	<b>B</b> —Continued	C—Continued
Akimov, G. V. Factors Influencing Corrosion	Benes, Richard Corrosion in the Corn Wet Milling Industry, with Fred J. Holsinger and Russell E. Pierson	Bruckner, W. H. Cathodic Protection of Lead Cable Sheath, with Ole G. Jansson	Comeaux, Roy V. Corrosion of Refinery Equipment by Aqueous Hydrogen Sulfide—A Contribution to the Work of Group Committee T-8 on Refining Industry Corrosion. Publication 69-12
Alexander, A. L. Performance of Organic Coatings in Tropical Environments, with B. W. Forgeson and C. R. Southwell	Unprotected Ships, with N. S. Dempster and A. J. Wallace	Buck, Koger III Effects of Foreign Metals on Corrosion of Titanium in Boiling 2M Hydrochloric Acid, with Billy W. Sloope	Compton, K. G. Instruments for Measurements in Underground Corrosion Work
Discussion—Controlling Internal Corrosion of Tank Ships	Bigos, Joseph Anchor Pattern Profile and Its Effect on Paint	and Henry Leidheiser, Jr566t  Bundy, Alfred D.  Discussion—Some Properties	Condry, James T. See Johnson, Wayne A9-112 Cook, A. R.
Andrews, C. R. See Roller, David 85t	Performance	and Uses of Chlorinated Polyether	Discussion—Controlling Internal Corrosion of Tank Ships560t
Anderson, E. A. Zinc in Marine Environments. 409t	Discussion—Corrosion Resistance of Titanium and Zirconium in Chemical Plant Exposures	Discussion—Corrosion in Sour Water Strippers362t	Cook, W. B. See Maier, R. W171t
Anderson, Thomas F. See Barnett, Robert E635t	Bloom, M. C. See Krulfeld, M	Burd, Byron B. Discussion—The Corrosion of Zirconium in Hydrochloric	Copenhagen, W. J. See Lewis, D. A382t
Anderson W. A.           See Dix, E. H., Jr.         55t           Discussion         338t	See Waldron, L. J2-87  Bobalek, E. G.	Acid at Atmospheric Pressure112t	Copson, H. R. Some Experiments on Internal Oxidation of Nickel Chromium Alloys, with
Annamalai, P. L. See Rajagopalan, K. S631t	Evaluation of Steam Resistant Coatings For Carbon Steel Hospital Ware, with W. R. R. Park, E. G.	Calkins, K. W.	F. S. Lang
Aziz, P. M. Mechanism by Which Non- Ferrous Metals Corrode in the Atmosphere, with	Bell and W. R. Dawson 202t  Boggs, James E. See Shannon, Donald W 299t	Corrosion Inhibitors for Corrosion Tetrachloride— Water Vapor Atmospheres, with R. W. Hawley447t	and Interpretation of Atmospheric Corrosion Tests
H. P. Godard529t Discussion—Observation on the Mechanisms and Kinetics of Aqueous Aluminum Corrosion642t	See Shannon, Donald W303t  Bowen, H. C. Variable Interaction: A Statistical Solution, with	Caplan, D.  High Temperature Oxidation of Chromium-Nickel Steels,	Corely, John J. Discussion—Wash Primer Development and Characteristics
Backensto, E. B. Iso-Corrosion Rate Curves for High Temperature	C. Groot and J. L. Jaech 83t  Brady, James M.  Advantages of Reinforced Polyesters for Use on Highway Tank Trucks2-94	with M. Cohen	Cornet, I. Influence of Temperature on Corrosion Fatigue, with Simcha Golan
Hydrogen-Hydrogen Sulfide—A Contribution to the Work of NACE Technical Group Committee, T-8, with J. W. Sjoberg.	Brasher, D. M. (Miss) Classification of Topics Relating to Corrosion254t Bregman, J. I.	Cartledge, G. H. Action of the XO4 <sup>n-</sup> Inhibitors	Craig, H. Lee, Jr. Discussion—Stress Corrosion Cracking of Oil Country Tubular Goods
Publication 59-10125t  Ballard, D. A. Justification and Economics Engineering Approach to a	Developments in Cooling Tower System Treatments (Part 1— Polyvalent Ion-Polyphos- phate Inhibitors), with T. R. Newman	Caterson, Alan G.  Discussion—The Corrosion of Zirconium in Hydrochloric Acid at Atmospheric Pressure	Craig, W. G. See Lemmon, J. C513t  Creed, S. H. Corrosion Keeps Knife Sharp on
Paint Testing Program, with V. B. Volkening503t  Barnard, K. N.	Brink, E. G. Discussion—Corrosion Resistance of Titanium	Caughey, R. H. See Hoyt, W. B	Fruit Canning Machine 6-100
Service Experience with Lead- Silver Alloy Anodes in Cathodic Protection of Ships, with G. L. Christie and D. G. Gage581t	and Zirconium in Chemical Plant Exposures	Cessna, J. C. Electrical Resistance Method for Studying Corrosion Inhibitors in Automotive	Daly, J. J., Jr. See Koehler, E. L
Barnett, Robert E. Polyester Fiber Glass Equipment, with Thomas F. Anderson	Brooks, W. B. Mechanisms and Some Theoretical Aspects of	Anti-Freezes	Davis, Gordon Bridge Caulking Technique Helps Solve Aerial Pipeline Crossing Problem3-113
Barusch, M. R. Control of Internal Corrosion of Petroleum Products Pipelines with Oil Soluble Inhibitors, with L. G.	Stress Corrosion Cracking of Austenitic Stainless Steels9-103 Brown, B F. Notch Sensitivity Effects in	Chittum, Joe Discussion—Stress Corrosion Cracking of Oil Country Tubular Goods	Davis, R. A. New Bonding Process Gives Added Versatility to Cladding
Haskell and R. L. Piehl158t  Baskette, L. Solving Corrosion Problems at Electrical Generating	Stress Corrosion and Hydrogen Embrittlement Tests on High Strength Steels	Practices in the Wilmington Water Flood Operation12-102 Christie, G. L.	Davis, Robert L.  Discussion—Methods of Installing Cathodic Protection Anodes for Offshore Structures12-106
Plants	Brown, J. Rl Evaluation of Protective Coatings for Ship Bottoms315t	See Barnard, K. N	Dawson, W. R. See Bobalek, E. G202t
Behn, D.R. Discussion—Corrosion in Sour Water Strippers362t	Brown, John R. Discussion—Mechanical Properties and Corrosien Resistance of Oil Well	Discussion—Oil Refinery Applications of Thick-Film Synthetic Coatings642t	Dean, Mills III Discussion—Principles and Criteria for Cathodic
Bell, E. G. See Bobalek, E. G	Tubing 53t  Brown, Roy W.	Clarke, John M. Discussion—Design and Materials for Reduced Pump Corrosion476t	Protection of Steel in Sea Water—A Review487t
Belue, M. W., Jr. Planning a Maintenance Coating Program for a Pulp and Pener Plant	Potentialities and Applications of Special Corrosion Resistant Refractories, with H. G.	Cohen, M.	Dean, Roy O. Equivalent Electrical Circuit Analogy of Structure-To- Sail Potentials

Decem

Koehles Control of Ta

Kronsto Method Char Coati

Krulfel Corrosi by Hy Dyna Eleva Press

Kuhn, The Co Hyd: Atm

Kuima Discus of L

Lande Discus Proj Resi Tub

Lang, See C

Larra Mecha Met Atn

Law, Discu Ma

Legar Corro from Mes

Leidi See E Lemi Anal Cor wit

Lewi Corre in At:

Loga Corresto Oi Mecl

Long Disc Ch Disc A) Sy Disc R

Lou Disc P

> Mac Cor W

> Mad Imp I: F Dis

Ma See

Mei Mei is

Me Dis Z Dis f

<b>D</b> —Continued	F	<b>G</b> —Continued	HContinued
DeBoer, F. E. Discussion—Impedance Characteristics of Isolated Aluminum Oxide Films643t	Fiebach, Seymour J. Discussion—Performance of Organic Coatings in Tropical Environments643t	Golan, Simcha See Cornet, I	Hudson, R. M. Factors Influencing the Rate-of- Pickling Test on Tin-Plate Steel, with G. L. Stragand135t
Degnan, T. F. Effect of Velocity on Life Expectancy of Steel Pipelines in Commercial Strengths of Sulfuric Acid	Fincher, D. R. Corrosion Problems Associated With Sour Gas Condensate Production	New Formulations Give Versa- tility to Urethane Coatings. 4-100 Gore, Robert T. Behavior of Tin Alloys in Atmospheric Exposures3-113	Hugo, J. P. Discussion
De Lorenzo, John F. Nickel Alloy Lining Cuts Costs in a Refinery Isomerization Unit	Firestone, John Tom Discussion—New Bonding Process Gives Added Versatility to Cladding10-90	Graham, B. A. Glass Fiber Reinforcement for Coatings	J Jackson, Brian R.
Dempster, N. S. Corrosion of Aluminum Alloy in Glycol-Water Cooling Systems	Fisher, A. O. Laboratory Methods for Determining Corrosion Rates Under Heat Flux Conditions, with F. L. Whitney, Jr257t	Greathouse, W. D. See McGlasson, R. L	Discussion—Corrosion Control Practices in the Wilmington Water Flood Operation12-192 Jaech, J. L.
Dexter, George T. Discussion—New Bonding Process Gives Added Versatility to Cladding10-90	Floyd, G. L. See Engle, J. P 69t  Fontana, M. G. See Greene, N. D 25t	Behavior of AZ 63 Alloy and Magnesium—1 Percent Manganese Alloy Anodes in Sodium Chloride Electrolyte, with E. Zinck	See Bowen, H. C
Dial, Roy E. Discussion—Potentialities and Application of Special Corro- sion Resistant Refractories.10-92	See Greene, N. D.       32t         See Greene, N. D.       39t         See Staehle, R. W.       373t         Forgeson, B. W.	Analysis of Cathodic Protec- tion With Operating Data for Ships	Jansson, Ole G. See Bruckner, W. H389t  Jasek, Albert W. Discussion—Control of Internal
Dillon, C. P. Discussion—Failure of Type 316 Stainless Steel Autoclave	See Alexander, A. L291t  Foster, R. S. A Resume of Procedures For	Greene, N. D. A Critical Analysis of Pitting Corrosion, with M. G. Fontana	Corrosion of Petroleum Products Pipelines with Oil Soluble Inhibitors165t  Jenkins, Vance N.
Components	Testing and Evaluating Chemical Resistant Coatings and Linings, with V. B. Volkening	An Electrochemical Study of Pitting Corrosion in Stainless Steels (Part 1—Pit Growth), with M. G. Fontana 32t An Electrochemical Study of	Discussion—Wash Primer Development and Characteristics
Aluminum Corrosion (Part 2—Kinetics of Aqueous Aluminum Corrosion)	Francis, H. T. See Koehler, E. L	Pitting Corrosion in Stainless Steels (Part 2—Polarization Measurements), with M. G. Fontana	Johnson, J. E.  Duct Anode Development and Experience in Protection of
Dix, E. H., Jr. Influence of Service Temperature on the Resistance of Wrought Aluminum-Magnesium Alloys to Corrosion. with W. A. Anderson and M. Byron Shumaker 55t Discussion 338t	High Strength Steels212t  Freedman, A. J. Discussion—Corrosion Prevention in Tankers and Storage Tanks by Fogging or Flotation with an Inhibitor Solution244t Discussion—Corrosion in Sour Water Strippers362t	Application to the Study of Passivity	Underground Cables from Corrosion
Dravnieks, A. Discussion—Iso-Corrosion Rate Curves for High Temperature Hydrogen-Hydrogen Sulfide.126t Discussion—Mechanism of Stress	Gage, D. G. See Barnard, K. N	See Bowen, H. C 83t Discussion—The Corrosion of Zirconium in Hydrochloric Acid at Atmospheric Pressure	Jones, C. H. Corrosion Control Practices in the Wilmington Water Flood Operation
Corrosion of Austenitic Stainless Steels in Chloride Waters381t Discussion—An Industrial Experience of Attack on	Galloway, Edward E. Filming Amines Control Corrosion in Utility Plant Condensate System	Gross, William F. Discussion—Wash Primer Development and Characteristics	Jones, L. W. Discussion—Corrosion Control Practices in the Wilmington Water Flood Operation12-102
Metals by Synthesis Gas from Methane-Oxygen Combustion. 626t	Garner, Cordell High Temperature, High Pressure Testing of Organic Coatings for Oil and Gas Well Tubing5-121	Habib, Emile E. Discussion—Oil Refinery Applications of Thick-Film Synthetic Coatings	Jones, David T. Discussion—Duct Anode Development and Experience in Protection of Underground Cables from Corrosion646t Case Histories of Differential
Eberle, F. An Industrial Experience of Attack on Metals by Synthesis Gas from Methane-Oxygen Combustion, with R. D. Wylle	Gegner, P. J. Corrosion Resistance of Titanium and Zirconium in Chemical Plant Exposures341t Discussion	Hackerman, Norman         517t           See Legault, R. A	Aeration Corrosion in Under- ground Telephone Cables9-116
Ebling, H. Discussion—Comparative Corrosion Resistance of 200 and 300 Series Stainless Steels in Chemical Manufacturing Processes	Gilman, Harry Discussion—New Bonding Process Gives Added Versatility to Cladding10-90 Accumulated Residues Attack Chemical Distilling Column.11-99	Hamstead, A. C. Comparative Corrosion Resistance of 290 and 300 Series Stainless Steels in Chemical Manufac- turing Processes, with L. S. Van Delinder	Kato, T. R. See Meyers, F. H., Jr168t Keeling, Harry J. Corrosion Protection Features of the Hyperion Ocean Outfall.363t
Eddy, L. C. Discussion—Cathodic Protection of Lead Cable Sheath644t	Glass, Dean C. Discussion—Methods of Installing Cathodic Protection Anodes for Offshore Structures12-106	Haskell, L. G. See Barusch, M. R158t Hawley, R. W.	Keller, Wayne H. Discussion—Corrosion Resistance of Titanium and Zirconium in Chemical Plant Exposures643t
Edwards, K. N. Acetylenic Alcohol-Inhibited Pickling Bath as a Pretreat- ment Prior to Lining Steel Pipe, with L. J. Nowacki and E. R. Mueller	Gleekman, Lewis W. Discussion—Design and Materials for Reduced Pump Corrosion.476t Gleser, Sol M. Discussion	See Calkins, K. W	Khairy, E. M. An Electrochemical Study of Aluminum and Aluminum Alloys, with M. Kamal Hussein 63t Klement, J. F.
Ellis, Wayne P. Discussion—Filming Amines Control Corrosion in Utility Plant Condensate System8-103	Discussion—Methods of Testing Characteristics of Polyethylene Jackets for Steel Pipe6-100 Discussion—Glass Fiber Reinforcement for Coatings.12-106	Henry, R. C. See Thompson, R. B321t  Hochman, H. Deterioration of Wood by Marine Boring Organisms 45t	Stress Corrosion Crack Paths in Alpha Aluminum Bronze in Ammonia and Steam Atmos- pheres, with R. E. Maersch and P. A. Tully295t
Engle, J. P. Chloride Stress Corrosion Cracking of the Austenitic Stainless Steels—A Contribu- tion to the Work of NACE Task Group T-8A on Chemical	Godard, Hugh P. Discussion—Influence of Service Temperature on the Resistance of Wrought Aluminum-Magnesium Alloys to Corrosion	Hockridge, Ralph Rubber-Base Transformer Finish for Severe Environments1-111 Holsinger, Fred J.	Knox, John A. Simple Screening Test for Determination of Inhibitor Film Persistence, with Roy Stout
Cleaning, with G. L. Floyd and R. B. Rosene Publication 59-5 69t	See Aziz, P. M	See Benes, Richard113t  Hoyt, W. B. High Temperature Metal	Knuckey, P. J. See Ride, R. N
Evans, Dwight J. New Instruments and Techniques for Ultrasonic Measurement of Tank Ship Corrosion Losses.561t	Corrosion	Deterioration in Atmospheres Containing Carbon-Monoxide and Hydrogen, with R. H. Caughey627t	Corrosion Processes in Carbonated Beverage Cans, with J. J. Daly, Jr., H. T. Francis, and H. T. Johnson477t

ol. 15

.135t .336t .63t

83t 286t 389t

165t

314t 177t

23t

112 106

99

02

6t

8t

3t

t

t

K—Continued	M—Continued	M—Continued	P—Continued
Koehler, J. Franklin Controlling Internal Corrosion of Tank Ships557t Kronstein, Max	McGlasson, R. L. Discussion—Mechanical Properties and Corrosion Resistance of Oil Well Tubing	Munger, C. G. Comparative Effectiveness of Coatings for Offshore Drilling Structures	Peterson, M. H. Principles and Criteria for Cathodic Protection of Steel in Sea Water—A Review483t See Waldron, L. J2-87
Methods for Investigating the Characteristics of Reactive Coatings	Country Tubular Goods, with W. D. Greathouse437t Discussion646t	Improved by Good Design.6-102  Murray, R. G. Four-Tower Water Treatment Test Facility, with M. E. Tester	Phelps, E. H. Discussion—Mechanism of Stress Corrosion of Austentitic Stainless Steels in Chloride Waters
by Hydrogen Effusion in Dynamic Aqueous Systems at Elevated Temperature and Pressure, with M. C. Bloom and R. E. Seebold	McIntosh, R. B. Corrosion Experience Associated With Hydrometallurgical Refining of Nickel at Sherritt Gordon Mines547t	N Neidhard, Richard D. Discussion—Filming Amines	Phillips, J. H. Evaluation of Performance of Screening Tests of Inhibitors to Prevent Chloride Stress Cor-
Kuhn, W. E. The Corrosion of Zirconium in Hydrochloric Acid at Atmospheric Pressure103t	Maersch, R. E. See Klement, J. F295t  Maier, R. W. Oil Refinery Applications of	Control Corrosion in Utility Plant Condensate System. 8-103 Neiman, A. S. See Straumanis, M. E 286t	rosion, with W. J. Singley450t  Piccardo, Jack E. Design and Materials for Reduced Pump Corrosion473t
Kulman, Frank E. Discussion—Cathodic Protection of Lead Cable Sheath645t	Thick-Film Synthetic Coatings, with W. B. Cook and R. B. MacQueen	Nel, L. G. Discussion	Piehl, R. L. See Barusch, M. R158t
L	Martin, J. B. See Miller, C. S	Newman, T. R. See Bregman, J. I 97t A Laboratory Method for	Pierson, Russell E. See Benes, Richard113t
Landers, J. E. Discussion—Mechanical	Mason, David M. See Rittenhouse, John B245t	Evaluating Corrosion Inhibitors for Secondary Recovery307t Noble, H. G.	Pike, Vernon B. Discussion—Cathodic Protection of Lead Cable Sheath645t
Properties and Corrosion Resistance of Oil Well Tubing	Mason, J. F., Jr. Minimum Corrosion for Butane Isomerization Units—A	See Brown, Roy W10-92 Norris, R. S.	Podlipec, F. J. See Meyers, F. H., Jr168t
Lang, F. S. See Copson, H. R194t	Contribution to the Work of NACE Group Committee T-8 on Refining Industry Corrosion,	Solving Some Oil Ash Corrosion Problems5-126	Pokorny, J. J. Discussion—Cathodic Protection of Lead Cable Sheath645t
Larrabee, C. P. Mechanisms by Which Ferrous Metals Corrode in the Atmosphere	with C. M. Schillmoller Publication 59-11	Nowacki, L. J. See Edwards, K. N275t  Nowak, S. K. Discussion—Influence of Service	Prange, F. A. Mechanical Properties and Corrosion Resistance of Oil Well Tubing
Law, R. J. Discussion—Design and Materials for Reduced Pump Corrosion476t	Mears, R. B. Discussion—Cathodic Protection of Lead Cable Sheath644t	Temperature on the Resistance of Wrought-Aluminum- Magnesium Alloys to Corrosion	Corresion in a Hydrocarbon Conversion System619t Prather, W. J. Coatings Engineers Help in
Legault, R. A. Corrosion Inhibitor Evaluation from Cathodic Polarization Measurements, with Norman Hackerman	Meyer, F. H., Jr. Corrosion Problems Associated with Uranium Refining, with F. J. Podlipec and T. R. Kato168t	Oakes, Ed W.	Power Plant Planning7-107  Preiser, H. S.  Some Platinum Anode Designs  for Cathodic Protection of
Leidheiser, Henry, Jr. See Buck, Roger III566t	Meyer, Robert H. Corrosion Inhibitor Testing Inside a Products Pipe Line.131t	Discussion—Planning A Mainte- nance Coating Program for A Pulp and Paper Plant491t	Active Ships, with B. H. Tytell596t
Lemmon, J. C. Analysis of Industrial Roof Construction and Maintenance,	Myles, K. M. See Bruckner, W. H591t	Oosterhout, J. C. D. Corrosion Prevention in Tankers and Storage Tanks by Fogging or Flotation with an Inhibitor	Corrosion of Valve Seat Ring Results in Flexible Metal 1t Puckett, George J. Discussion—The Corrosion of
with W. G. Craig513t  Lewis, D. A. Corrosion of Reinforcing Steel	Mikhailovsky, Y. N. See Tomashov, N. D 77t	Solution, with M. E. Stanley and W. S. Quimby241t	Zirconium in Hydrochloric Acid at Atmospheric Pressure112t
in Concrete in Marine Atmospheres	Miller, C. S. Some Properties and Uses of Chlorinated Polyether, with J. B. Martin11-108	Palmer, Warren D.	Quimby, W. S.
Corrosion of Type 310 Stainless Steel by Synthetic Fuel Oil Ash	Miller, D. N. Whole System Installed in Nine Months—Cathodic Protection of Southern Pacific's High-Pressure	Discussion—Coatings for Underwater Metal Surfaces in Fresh Water Exposures335t Discussion—Some Corrosion Problems of Tank Trucks and Their Solutions2-96	See Oosterhout, J. C. D241t  Radavich, John F.
Long, Austin K. Discussion—Wash Primer Development and Characteristics	Products Pipe Line12-104  Minford, J. Dean See Haygood, A. J 20t	Panter, George Discussion—Observations on the Mechanisms and Kinetics of	Effect of Silicon on High Temperature Oxidation of Stainless Steels
Discussion—Oil Refinery Applications of Thick-Film Synthetic Coatings	Moore, K. L. Discussion—Corrosion Prevention in Tankers and Storage Tanks by Fogging or Flotation with	Aqueous Aíumínum Corrosion.336t  Park, W. R. R. See Bobalek, E. G202t	Corrosion of Metals at Mandapam Camp.India, with M. Sundaram and P. L. Annamalai631t
Louk, A. V. Discussion—Corrosion Control Practices in the Wilmington	An Inhibitor Solution244t  Morgan, Albert R., Jr. Corrosion of Types 316 and 317 Stainless Steel by 75 Percent	Parker, Ivy M.  Discussion—Control of Internal Corrosion of Petroleum Products Pipelines with Oil Soluble Inhibitors 165t	Rench, Joe E. Discussion—Wash Primer Development and Characteristics
Water Flood Operation12-102	and 85 Percent Phosphoric Acid	Partridge, E. G. Use of Plastics and Synthetic	Renshaw, W. G. Discussion—Comparative Corrosion Resistance of 200
MacEwan, J. U. Corrosion of Steel Weldments, with H. H. Yates 2t	Morgan, John H. Internal Cathodic Protection of Large Steel Pipes Carrying Sea Water	Elastomers for Underground Coatings	and 300 Series Stainless Steels in Chemical Manufacturing Processes156t
with H. H. Yates 2t  MacLennan, D. F. Impedance Characteristics of Isolated Aluminum Oxide	Morley, Harland A. Improved Methods Plus Hot Spray Speed Application of	Offshore Platform Shows Corrosion Rate of Carbon Steel in Gulf of Mexico Exposure8-103  Peabody, A. W.	Ride, R. N. Photoelectric Information Selector, with P. J. Knuckey
Films	Saran Coatings3-116  Morrison, A. V. Discussion—Design and Materials for Reduced	Use of Magnesium for Cathodic Protection of Pipe Lines in High Resistivity Soil497t	Rittenhouse, John B. Study of Chemical Factors Affecting Corrosion of Carbon Steel AISI 1020 by Liquid-
See Maier, R. W171t  McDaniel, H. M.	Pump Corrosion476t  Mueller, E. R.	Peckner, D. Erosion of Materials by Cavitation Attack269t	Phase Fuming Nitric Acid, with David M. Mason245t Robinson, J. L.
Methods of Testing Character- istics of Polyethylene Jackets for Steel Pipe	See Edwards, K. N275t  Muir, Parke Denton  Discussion—Simple Screening  Test for Determination of	Pedlow, J. Watson Recent Developments in Applying Polyvinylchloride Plastisols	Discussion—Behavior of AZ 63 Alloy and Magnesium—1 Per- cent Manganese Alloy Anodes in Sodium Chloride
Discussion—The Corrosion of Zirconium in Hydrochloric Acid at Atmospheric Pressure 112t Discussion—Design and Materials for Reduced Pump Corrosion 476t	Inhibitor Film Persistence.556t  Mullarkey, E. J.  Applications of Lead-Acid Brick Systems in Chemical Plants.2-98	Pemberton, George M. Evaluating the Economy of Reconditioning and Coating Underground Steel Pipe279t	Electrolyte

R—Continued	S—Continued	S—Continued	V—Continued
Rogers, T. H. Uses and Abuses of Aluminum in Wooden-Hulled, Aluminum- Frame Minesweepers, with W. K. Chinn	Shaw, Homer L. Discussion—Filming Amines Control Corrosion in Utility Plant Condensate System8-103 Shields, Hobart	Straumanis, M. E. Rates of Dissolution and Passivation of Hafnium-Free Zirconium in Hydrofluoric Acid, with W. J. James and A. S. Neiman	Volkening, V. B.         See Ballard, D. A
Roller, David Effect of Molten Boron Oxide on	Selecting Corrosion and Scale Inhibitors for Cooling Water,	Stutz, R. L.	W
Selected High Temperature Alloys, with C. R. Andrews. 85t	with L. V. Sorg and R. L. Stutz233t	See Shields, Hobart233t	Waldron, L. J. Experimental Studies of Cathodic
Rosene, R. B. See Engle, J. P 69t	Shumaker, M. Byron See Dix, E. H., Jr	Sudrabin, L. P. Discussion—Development of the Redox Probe Field Technique	Protection for Naval Vessels, with M. H. Peterson and M. C. Bloom2-87
Roth, Stanley Discussion—Wash Primer	Discussion338t	Suman, Robert P. Discussion—High Temperature,	Wallace, A. J. See Bennett, G. A587t
Development and Characteristics314t	Simons, C. S. Materials Selection and Design Problems in a Nickel-Cobalt Extraction Plant4-95	Discussion—High Temperature, High Pressure Testing of Organic Coatings for Oil and Gas Well Tubing5-124	Wallace, E. W. Discussion—Corrosion Control Practices in the Wilmington
Rowe, Leonard C. Automotive Corrosion Resistance —Past and Present167t	Singley, W. J. See Phillips, J. H450t	Sundaram, M. See Rajagopalan, K. S631t	Water Flood Operation12-102
- I dot did I resoluti	See Phillips, J. H450t Sjoberg, J. W.	Szymanski, Walter A. Recovery of Graphitically	Wankat, Charles See Thompson, R, B321t
S	See Backensto, E. B125t	Embrittled Nickel1-112	Warren, Donald The Effect of Sigma Phase vs
Scheil, M. A. Discussion—Mechanical	Sloope, Billy W. See Buck, Roger III566t		Chromium Carbides on the Intergranular Corrosion of Type 316 and 316L Stainless
Properties and Corrosion Resistance of Oil Well	Slunder, C. J.	T	Steel (Part 1-A Survey of
Tubing	The Residual Oil Ash Corrosion Problem—A Review601t	Tester, M. E. See Murray, R. G492t	the Literature)213t The Effect of Sigma Phase vs Chromium Carbides on the
Corrosion Resistance of 200 and 300 Series Stainless Steels in Chemical Manufacturing	Smith, G. B. Equipment and Procedure for the Evaluation of Stress	Thompson, D. H. Probability as Related to Stress Corrosion Cracking of	Intergranular Corrosion of Type 316 and 316L Stainless Steel (Part 2—Laboratory
Processes	Corrosion Susceptibility of a Wrought Copper Base Alloy, 101t	Copper Alloys433t Thompson, R. B.	Investigation)2219 Wells, E. R.
Problems Associated with Uranium Refining170t	Smith, H. J. Corrosion of Die Casting Alloys	Evaluation of Organic Corrosion Inhibitors for Special Applica- tions in Petroleum Refining,	Characteristic Properties of Polyurethane Protective
Schillmoller, C. M. See Mason, J. F., Jr185t See Mason, J. F., Jr358t Discussion—Corrosion of Types 316 and 317 Stainless Steel by	in Detergent Solutions Measured by Electrical Resistance Method, with R. L. Hadley	with R. F. Stedman, Charles Wankat and R. C. Henry. 321t Discussion—Corrosion in Sour Water Strippers	Coatings
75 Percent and 85 Percent Phosphoric Acid644t	See Shields, Hobart233t	Tomashov, N. D. Corrosivity of Soil, with Y. N. Mikhailovsky 77t	Whiting, L. R. Wash Primer Development
Schuhmacher, Gordon S. Discussion—Corrosion Control Practices in the Wilmington	Southwell, C. R. See Alexander, A. L291t	Tonetti, Serge (Lt. Col.) Discussion—Planning a Mainte-	and Characteristics3111 Whitney, F. L., Jr.
Water Flood Operation12-102	Spalding, James C., Jr. Discussion—High Temperature,	nance Coating Program for a Pulp and Paper Plant491t	See Fisher, A. O
Schwoegler, E. J. The Evaluation of Certain Organic Nitrogen Compounds as Corrosion Inhibitors, with L. U. Berman	High Pressure Testing of Organic Coatings for Oil and Gas Well Tubing5-124	Troiano, Alexander R. Delayed Failure of High Strength Steels207t	Wilson, W. L. See Gegner, P. J341t Discussion—Potentialities and Applications of Special Corrosion Resistant Refractories.10-98
Scott, Willard R. Discussion—Corrosion Control Practices in the Wilmington	Staehle, R. W. Mechanism of Stress Corrosion of Austenitic Stainless Steels in Chloride Waters, with F. H.	Troutner, V. H. High Temperature Corrosion Product Films on Aluminum. 7t Observations on the Mechanisms	Woodward, W. Searle Uses for Varistors With Direct Current Corrosion Meters 680
Water Flood Operation12-102 Seebold, R. E. See Krulfeld, M	Beck and M. G. Fontana373t  Stanbury, Charles M.  Discussion—Oil Refinery	and Kinetics of Aqueous Aluminum Corrosion (Part 1— Role of the Corrosion Product Film in the Uniform Aqueous	Wright, Charles C. A Field Method for Screening Inhibitors for Prevention of
Visual Observations on the Water Stream In an Elevated	Applications of Thick-Film Synthetic Coatings642t	Corrosion of Aluminum) 9t Tully, P. A.	Water Flood Corrosion7-97 Wright, Kenneth E.
Temperature High Velocity Loop183t	Stanley, M. E.	See Klement, J. F295t	Discussion—Wash Primer Development and
Segraves, William B.	See Oosterhout, J. C. D241t	Tytell, B. H. See Preiser, H. S596t	Characteristics314t
Discussion—Corrosion in a Hydrocarbon Conversion System	Stedman, R. F. See Thompson, R. B321t		Wylie, R. D. See Eberle, F622t
Severance, W. A.	Stern, Milton Discussion—Corrosion Resistance	Van Delinder, L. S.	
Discussion—Wash Primer Development and	of Titanium and Zirconium in Chemical Plant Exposures644t	See Hamstead, A. C147t Van Orden, Jerold Miles	Yates, H. H.
Characteristics314t Shannon, Donald W.	Stout, Roy See Knox, John A554t	Discussion—Delayed Failure of High Strength Steels212t	See MacEwan, J. U 2t Yocom, John E.
Factors Affecting the Corrosion of Steel by Oil-Brine-Hydrogen Sulfide Mixtures, with James E. Boggs	Stragand, G. L. See Hudson, R. M	Vollmer, L. W. Discussion—Influence of Temperature on Corrosion Fatigue	Deterioration of Materials in Polluted Atmospheres 541t
U 12. 130880		~ ~ ~ ~ ~ · · · · · · · · · · · · · · ·	
An Analytical Procedure for Testing the Effectiveness of Hydrogen Sulfide Corrosion	Stratfull, R. F. Progress Report on Inhibiting	Vore, Herbert G. Discussion—New Bonding	z

.503t 10-85

dic . 2-87

-10:

321t

213t

221t

2-93

313t

57t 41t

-98

68t

-97

l4t 2t